



2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

		Invoice Number: 10190565010322 Invoice Date: 3/31/2020 Location: 46 Work Order Number: 2050356 Payment Type: Finance
Bus: Prv: Mob:(620)229-3194	Bus: Prv: Mob:(620)229-3194	Tech: Page: 1 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	2873	1H09770SJA0741150	168841PLP	

PWR/9002S/590 Retail
CORRECTION:
STS standard combine inspection

Performed a complete inspection on the machine.

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$1,466.25	Sub-Total: \$1,466.25
----------------------	----------------------	-------------------------	-------------------------	------------------------------

9770STS/4177/E/10 Retail
CORRECTION:
02 GUIDE FEEDER HOUSE UPPER - REMOVE/INSTALL/ADJUST

Loosened and removed feeder house drive chain
Removed and installed feeder house drive chain guides
Reinstalled drive chain and tightened to specification
Ran and verified operation

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H234586	Support	1.00	71.79	70.38	\$70.38	N
H234587	GUIDE	1.00	33.77	30.98	\$30.98	N

Labor: \$0.00	Parts: \$101.36	OL&M: \$0.00	Misc: \$33.35	Sub-Total: \$134.71
----------------------	------------------------	-------------------------	----------------------	----------------------------

9770STS/3051/10 Retail
CORRECTION:
03 SLIP CLUTCH - REMOVE & INSTALL

Loosened chain tension
Removed and replaced complete slip clutch assembly
Reassembled on combine



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH225742	Slip Clutch	1.00	534.42	526.52	\$526.52	N

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

		Invoice Number: 10190565010322 Invoice Date: 3/31/2020 Location: 46 Work Order Number: 2050356 Payment Type: Finance
Bus: Mob:(620)229-3194	Prv:	Bus: Mob:(620)229-3194
		Tech: Page: 2 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	2873	1H09770SJA0741150	168841PLP	

9770STS/3051/10 Retail	H219634	Chain Sprocket	1.00	82.76	82.76	\$82.76	N
Labor:	Parts:	OL&M:	Misc:	Sub-Total:			
\$0.00	\$609.28	\$0.00	\$175.95	\$785.23			

9770STS/3353/SAB/25 Retail
CORRECTION:
04 BEVEL GEAR SHOE AUGER BACKLASH - *** ADJUST #1 & 2 ONLY ***

Applied PM38654 where gears were and spun for full coverage
Installed the woodruff keys
Aligned gears until they were fully meshed and backed off 075 mm or 1/32 in
Tightened clamps
Did job code xxxx/3352/SA/10 in reverse

Labor:	Parts:	OL&M:	Misc:	Sub-Total:			
\$0.00	\$0.00	\$0.00	\$203.55	\$203.55			

9770STS/5154/SPHU/25 Retail
CORRECTION:
05 SINGLE POINT HOOK UP - ADJUST & LUBRICATE CABLE & PINS

Removed the latch pin covers. Cleaned dirt out from around pins and lubed pins really well. Worked handle back and forth until they freed up. Reinstalled covers.

Labor:	Parts:	OL&M:	Misc:	Sub-Total:			
\$0.00	\$0.00	\$0.00	\$67.85	\$67.85			

9770STS/6404/HFL/10 Retail
CORRECTION:
06 CHAIN FEEDER HOUSE CONVERYOR ADJUST & REMOVE HALF LINKS IF NEEDED

Adjusted the feederhouse chain to spec. There was not enough adjustment yet to remove 1/2 links.

2300 W 9th
 Winfield KS 67156
 Phone: (620) 221-1770
 Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

				Invoice Number: 10190565010322 Invoice Date: 3/31/2020 Location: 46 Work Order Number: 2050356 Payment Type: Finance Tech:
Bus: Mob:(620)229-3194	Prv:	Bus: Mob:(620)229-3194	Prv:	Page: 3 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	2873	1H09770SJA0741150	168841PLP	

9770STS/6404/HFL/10 Retail

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$135.70	Sub-Total: \$135.70
----------------------	----------------------	-------------------------	-----------------------	----------------------------

9770STS/3351/LHFA/10 Retail

CORRECTION:
 07 BEARING LEFT HAND FEED ACCELERATOR - REMOVE & INSTALL

- Removed bearing locking collar
- Removed bearing with flange from shaft
- Removed bearing from flange
- Reassembled in reverse order

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH223756	Wheel	1.00	30.42	28.04	\$28.04	N
AXE60582	Ball Bearing	1.00	51.30	51.30	\$51.30	N
HXE118484	HOUSING	1.00	130.28	130.28	\$130.28	N

Labor: \$0.00	Parts: \$209.62	OL&M: \$0.00	Misc: \$126.50	Sub-Total: \$336.12
----------------------	------------------------	-------------------------	-----------------------	----------------------------

9770STS/3351/R/10 Retail

CORRECTION:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

				Invoice Number: 10190565010322 Invoice Date: 3/31/2020 Location: 46 Work Order Number: 2050356 Payment Type: Finance	Page: 4 of 11
Bus: _____ Prv: _____ Mob:(620)229-3194		Bus: _____ Prv: _____ Mob:(620)229-3194			

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	2873	1H09770SJA0741150	168841PLP	

9770STS/3351/R/10 Retail
08 BEARING ROTOR - REMOVE & INSTALL

Lowered feeder house all the way down and shut machine off
 Removed top two doors on feeder house
 Removed dust suppression cover
 Removed bearing protection bracket, grease line, tone wheel, lock collar and bearing
 Replaced parts as necessary
 Reassembled in reverse order
 Adjusted sensor to specifications

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE42868	Bearing With Housing	1.00	270.51	270.51	\$270.51	N
Labor: \$0.00		Parts: \$270.51	OL&M: \$0.00	Misc: \$379.50	Sub-Total: \$650.01	

9770STS/3105/CSP/46 Retail
CORRECTION:
09 GEAR CASE PRIMARY COUNTER SHAFT - FLUSH

Drained oil out of case
 Flushed case out with solution
 Verified all solution was out
 Filled case with new oil

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26372	80W140 Synthetic Gear Lube qt	2.00	17.35	17.35	\$34.70	N
Labor: \$0.00		Parts: \$34.70	OL&M: \$0.00	Misc: \$67.85	Sub-Total: \$102.55	



9770STS/1357/CPR/10 Retail
CORRECTION:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

		Invoice Number: 10190565010322 Invoice Date: 3/31/2020 Location: 48 Work Order Number: 2050356 Payment Type: Finance
Bus: _____ Prv: _____ Mob:(620)229-3194	Bus: _____ Prv: _____ Mob:(620)229-3194	Tech: _____ Page: 5 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	2873	1H09770SJA0741150	168841PLP	

9770STS/1357/CPR/10 Retail
12 BELT CHOPPER REAR - REMOVE & INSTALL

Removed shields
Released tension on chopper belt
Replaced belt and checked alignment

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H223212	V-Belt	1.00	209.06	209.06	\$209.06	N
Labor: \$0.00		Parts: \$209.06	OL&M: \$0.00	Misc: \$67.85	Sub-Total: \$276.91	

9770STS/7551/CRL/10 Retail
CORRECTION:
13 BEARING CHOPPER ROTOR LEFT SIDE - REMOVE & INSTALL

Removed shield and released belt tension
Removed belt
Raised chopper all the way up and removed bolt on pulley
Removed pulley and woodruff key
Removed sensor mag from lock collar
Removed collar
Loosened top nuts and removed sensor
Supported rotor, unbolted and removed bearing
Made necessary repairs
Installed in reverse order

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

SERVICE INVOICE

Invoice To Account No: 123592

Deliver To:

		Invoice Number: 10190565010322 Invoice Date: 3/31/2020 Location: 46 Work Order Number: 2050356 Payment Type: Finance	
Bus: Mob:(620)229-3194	Prv:	Bus: Mob:(620)229-3194	Prv:
		Tech:	Page: 6 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	2873	1H09770SJA0741150	168841PLP	

9770STS/7551/CRL/10 Retail						
AH232688	Bearing	1.00	193.63	193.63	\$193.63	N
Labor: \$0.00		Parts: \$193.63	OL&M: \$0.00	Misc: \$405.95	Sub-Total: \$599.58	

9770STS/5160/UCF/10 Retail
CORRECTION:
14 SHEAVES UPPER CLEANING FAN - REMOVE & INSTALL

- Loosened belt tension
- Removed bolt and bushing from lower end of adjuster arm and let arm swing out of the way
- Loosened tension on counter shaft drive belt and removed belt
- Removed bolt, washer, and outer sheave half
- Removed bolts holding inner sheave half to jackshaft
- Removed inner sheave half
- Reassembled in reverse order
- Torqued hardware to proper specification

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
11M7021	COTTER PIN	1.00	0.35	0.35	\$0.35	N
24M7047	Washer	1.00	0.75	0.74	\$0.74	N
H161051	Pulley	1.00	354.16	354.16	\$354.16	N
HXE100089	Hook Bolt	1.00	33.40	32.90	\$32.90	N
Labor: \$0.00		Parts: \$388.15	OL&M: \$0.00	Misc: \$351.90	Sub-Total: \$740.05	

9770STS/1357/SFA/25 Retail
CORRECTION:
15 BELT SHOE FAN & CONVEYOR AUGER - ADJUST

- Adjusted shoe, fan and conveyor auger belt to specification



WWW.PRAIRIELANDPARTNERS.COM

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225



WWW.AGRIVISIONEQUIPMENT.COM



Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

[Redacted]		[Redacted]		Invoice Number:	10190565010322
[Redacted]		[Redacted]		Invoice Date:	3/31/2020
[Redacted]		[Redacted]		Location:	46
[Redacted]		[Redacted]		Work Order Number:	2050356
[Redacted]		[Redacted]		Payment Type:	Finance
Bus:	Prv:	Bus:	Prv:	Tech:	Page: 7 of 11
Mob:(620)229-3194		Mob:(620)229-3194			

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	2873	1H09770SJA0741150	168841PLP	

9770STS/1357/SFA/25 Retail

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$33.35	Sub-Total: \$33.35
---------------	---------------	--------------	---------------	--------------------

9770STS/1909/FRP/10 Retail

CORRECTION:
17 VALVE AIR BLEED - REMOVE & INSTALL

Removed fuel return line and changed bleed valve.
Reinstalled fuel line.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Inc
RE528864	BLEED VALV	1.00	136.68	125.40	\$125.40	N
Labor: \$0.00	Parts: \$125.40	OL&M: \$0.00	Misc: \$101.20	Sub-Total: \$226.60		

//Diagnose-1 Retail

CORRECTION:
18 EGR COOLER STEEL LINE LEAKING - REPLACE LINE AND SENSOR

Drained coolant from machine. Removed shields from engine compartment. Removed old line and sensor. Installed new sensor and new line. Reinstalled shields and filled back up with coolant.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Inc
R524513	HOSE CLAMP	2.00	7.10	6.54	\$13.08	N
RE522824	Temperature	1.00	65.78	64.81	\$64.81	N
RE546588	Tube	1.00	108.64	99.68	\$99.68	N
Labor: \$0.00	Parts: \$177.57	OL&M: \$0.00	Misc: \$172.50	Sub-Total: \$350.07		

//Diagnose-2 Retail

CORRECTION:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 10190565010322
				Invoice Date: 3/31/2020
				Location: 46
				Work Order Number: 2050356
				Payment Type: Finance
				Tech: Page: 8 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	2873	1H09770SJA0741150	168841PLP	

//Diagnose-2 Retail

19 Diagnose: GRAIN TANK LIGHT NOT WORKING

Found that the bulb was bad. Replaced the bulb and the light still did not work. Traced the wiring harness for broken wires and all wires tested good. Checked voltage at the controller and found that when you first turn the key on there was 12v to the light wire but when I turned on the light switch the voltage went away. This told me that the controller was bad because it would not hold voltage under a load. Replaced the power controller with a new one and the problem was fixed.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH208904	BULB	1.00	14.52	14.31	\$14.31	N
AH224250	Electronic Control Unit	1.00	391.04	384.36	\$384.36	N
Labor: \$0.00		Parts: \$398.67		OL&M: \$0.00		Misc: \$402.50
						Sub-Total: \$801.17

//Diagnose-3 Retail

CORRECTION:
20 HYDRO HANDLE NEUTRAL SAFETY SWITCH - ARMREST PLASTIC WARPED

Removed the arm rest from the combine. Disassembled all components and installed all of the components in a new plastic housing. Reinstalled the arm rest in the combine. Ran and tested operation.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H227553	Cover	1.00	93.08	91.25	\$91.25	N
Labor: \$0.00		Parts: \$91.25		OL&M: \$0.00		Misc: \$31.63
						Sub-Total: \$122.88

9770STS/7702/53 Retail

CORRECTION:
21 FUEL FILTER - CHANGE

Shut fuel tank off
Removed and cleaned pre cleaner filter
Reinstalled and turned fuel on
Removed and replaced primary and secondary filters
Bled fuel system and started

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE523785	BOWL	1.00	45.33	41.78	\$41.78	N

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 10190565010322
				Invoice Date: 3/31/2020 Location: 46 Work Order Number: 2050356 Payment Type: Finance
				Tech: Page: 9 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	2873	1H09770SJA0741150	168841PLP	

9770STS/7702/53 Retail	RE525523	Filter Element	1.00	91.55	91.55	\$91.55	N
Labor: \$0.00	Parts: \$133.33	OL&M: \$0.00	Misc: \$67.85	Sub-Total: \$201.18			

9770STS/1250/46 Retail
CORRECTION:
22 FUEL SYSTEM - FLUSH

- 1 Changed primary and secondary fuel filters
 - 2 Primed fuel system and start engine
 - 3 Run engine long enough to get to operating temperature
 - 4 Shut down engine
 - 5 Disconnected fuel supply to primary fuel filter
 - 6 Connected 6' red hose (supply) to primary filter using appropriate adapter in kit
 - 7 Disconnected fuel return to fuel tank
 - 8 Connected 6' black hose (return) to tank line using appropriate adapter in kit
 - 9 Connected other end of red 6' hose to bottom fitting of flush tank Open valve on tank
 - 10 Connected other end of black 6' to return side of flush tank so that return fuel flows through flush kit filter
 - 11 Filled reservoir with full contents of flush solvent
 - 12 Key on to check for leaks and verify return fuel is coming back to flush tool If flush tank fuel level drops quickly shut off and check to make sure all of return fuel is getting back to the tool reservoir
- Keyed on to check for leaks.
Verified return fuel is coming back to flush tool.
If flush tank fuel level dropped quickly shut off and checked to make sure all of return fuel was getting back to the tool reservoir.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
2295HD	HD DIESEL INJ SERVICE KIT	1.00	234.99	234.99	\$234.99	N
Labor: \$0.00	Parts: \$234.99	OL&M: \$0.00	Misc: \$377.20	Sub-Total: \$612.19		

9770STS/1409/E/10 Retail
CORRECTION:
23 LIGHT BULB - RIGHT REAR ARM FLASHER - REMOVE & INSTALL

Removed cover and installed a new bulb on the right hand flasher arm.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

[Redacted]		Invoice Number: 10190565010322	
		Invoice Date: 3/31/2020	
[Redacted]		Location: 46	
[Redacted]		Work Order Number: 2050356	
[Redacted]		Payment Type: Finance	
Bus:	Prv:	Bus:	Prv:
Mob:(620)229-3194		Mob:(620)229-3194	
		Tech: Page10 of 11	

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	2873	1H09770SJA0741150	168841PLP	

9770STS/1409/E/10 Retail						
AD2062R	BULB	1.00	3.00	2.96	\$2.96	N
Labor: \$0.00	Parts: \$2.96	OL&M: \$0.00	Misc: \$27.60	Sub-Total: \$30.56		

//9770 CMBS291 Retail
CORRECTION:
24 Shoe auger, R&R X2

Removed the left two shoe augers and replaced augers with new bearings and roll pins. The old augers were wore where the roll pins are installed allowing a lot of slop in the augers.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7375	FLANGE NUT	2.00	0.36	0.36	\$0.72	N
34H286	SPRING PIN	2.00	0.62	0.59	\$1.18	N
34H333	SPRING PIN	2.00	1.19	1.17	\$2.34	N
AH146786	Auger	2.00	151.24	151.24	\$302.48	N
AH163056	BEARING HO	2.00	49.94	49.94	\$99.88	N
AH214862	Ball Bearing	2.00	17.24	17.24	\$34.48	N
H103264	Pressed Flanged Housing	4.00	2.24	2.24	\$8.96	N
JD8554	ECCENTRIC	4.00	5.48	5.48	\$21.92	N
Labor: \$0.00	Parts: \$471.96	OL&M: \$0.00	Misc: \$546.25	Sub-Total: \$1,018.21		

PWR/9002S/CC Retail
CORRECTION:
25 STS Combine Crop Changeover Package


Concaves, R&R.
Remove every other wire in front 2 concaves if required.
Calibrate concaves.
Set machine for next crop per Operator's Manual.

PRAIRIELAND

PARTNERS
WWW.PRAIRIELANDPARTNERS.COM

AGRIVISION
EQUIPMENT GROUP

WWW.AGRIVISIONEQUIPMENT.COM

 **JOHN DEERE**

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

[Redacted]		Invoice Number: 10190565010322	
		Invoice Date: 3/31/2020	Location: 46
Bus: Prv:		Work Order Number: 2050356	Payment Type: Finance
Mob:(620)229-3194		Tech: Page:11 of 11	

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	2873	1H09770SJA0741150	168841PLP	

PWR/9002S/CC Retail

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$417.45	Sub-Total: \$417.45
---------------	---------------	--------------	----------------	---------------------

ATTENTION: Part(s) values for this invoice have changed. Original Invoice Parts Sale Value = \$2585.19
INVOICE CONTAINS \$49.73 DISCOUNT

Miscellaneous Charges:
Service Accessories

\$85.00

Finance Information


Customer PO No:	Type: Multi-use Acct US	Auth. No: 684469	Labor: \$5,659.73
Tax Exempt No: 2019	Merchant No: 37000393		Parts: \$2,585.19
Advisor: Russell Gottlob	Card No: xxxxxxxxxxxx2788		OL&M: \$0.00
	Bill Code: 784 - PERFORMAX INSPECTION - COMBIN		Misc: \$85.00
	Credit Plan: 11441 - DEERE AG NO PAYMENTS/NO INTEREST WAIVER UNTIL		Sales Tax: \$0.00
			Grand Total: \$8,329.92

*** DOCUMENT COPY ***

TERMS AND CONDITIONS

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by: Date:



2300 W 9th
 Winfield KS 67156
 Phone: (620) 221-1770
 Fax: (620) 221-0225

WWW.AGRIVISIONEQUIPMENT.COM

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

[Redacted]		Invoice Number: 10573992010322	
		Invoice Date: 7/30/2021	
Bus: Prv:		Location: 46	
Mob:(620)229-3194		Work Order Number: 2101480	
Bus: Prv:		Payment Type: Finance	
Mob:(620)229-3194		Tech: Page: 1 of 3	

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS		1H09770SJA0741150	168841PLP	

PWR/9002S/590 Retail

CORRECTION:

01 STS standard combine inspection

Inspect machine.

Includes:

Adjust chains.

Adjust belts.

R & R chaffer element.

Inspect frame.

Software evaluation.

Labor Quote.

Parts Quote.

Reminder: Contact Precision Ag PLP specialist if machine has a display and receiver to address customer data and any display or receiver updates

*Inspection price does not include the following upsells:

Oil analysis.

Service Batteries.

Grease machine.

Concave, adjust & re-level.

Calibrate concaves.

Set for next crop.

Software updates.

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$1,530.00	Sub-Total: \$1,530.00
---------------	---------------	--------------	------------------	-----------------------

9770STS/6906/UF/10 Retail

CORRECTION:

02 SHEET UPPER FLOOR - REMOVE & INSTALL

-

Raised and locked feeder house

Removed hardware attaching floor sheet

Removed and installed floor sheet

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Incl
14M7296	FLANGE NUT	6.00	1.30	1.30	\$7.80	N
H219180	Plate	1.00	246.40	246.40	\$246.40	N

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 10573992010322
				Invoice Date: 7/30/2021
				Location: 46
				Work Order Number: 2101480
				Payment Type: Finance
				Tech: Page: 2 of 3

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS		1H09770SJA0741150	168841PLP	

9770STS/6906/UF/10 Retail						
H223214	Bolt	6.00	1.75	1.75	\$10.50	N
Labor: \$0.00	Parts: \$264.70	OL&M: \$0.00	Misc: \$847.20	Sub-Total: \$1,111.90		

9770STS/3352/SANA/10 Retail
CORRECTION:
03 FRONT BEARING SHOE AUGER NEW STYLE ALL - REMOVE & INSTALL

Removed & Installed all shoe auger new style front bearings
 Removed right hand wheel(s)
 Loosened nuts to relieve belt tension and removed belt
 Removed nut, sheave and woodruff key
 Loosened set screw and removed locking collar
 Removed nuts and outside flangette and bearing
 Repeated for left side
 Installed new bearing and put together in reverse
 Adjusted drive gears
 Ran and checked operation

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH163056	BEARING HO	4.00	44.95	44.95	\$179.80	N
AH214862	Ball Bearing	4.00	17.79	17.79	\$71.16	N
H103264	Pressed Flanged Housing	8.00	2.32	2.32	\$18.56	N
JD8554	ECCENTRIC	8.00	5.58	5.58	\$44.64	N
Labor: \$0.00	Parts: \$314.16	OL&M: \$0.00	Misc: \$847.20	Sub-Total: \$1,161.36		

9770STS/1357/CPF/10 Retail
CORRECTION:
04 BELT CHOPPER FRONT - REMOVE & INSTALL

Removed & Installed front chopper belt
 Removed shields
 Released tension on chopper belt
 Replaced belt and checked alignment

2300 W 9th
 Winfield KS 67156
 Phone: (620) 221-1770
 Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

		Invoice Number:	10573992010322
		Invoice Date:	7/30/2021
		Location:	46
		Work Order Number:	2101480
		Payment Type:	Finance
Bus:	Prv:	Bus:	Prv:
Mob:(620)229-3194		Mob:(620)229-3194	
		Tech:	Page: 3 of 3

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS		1H09770SJA0741150	168841PLP	

9770STS/1357/CPF/10 Retail

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE10501	V-Belt	1.00	269.51	269.51	\$269.51	N
Labor: \$0.00		Parts: \$269.51		OL&M: \$0.00		Misc: \$169.20
						Sub-Total: \$438.71

//Diagnose-1 Retail

CORRECTION:

05 Diagnose: Leak at Pro Drive Valve Body

Washed the valve body off and dirt and dobris out to be able to see where the leak was coming from. Started combine and checked to find leak. Found it was inside the valve which you would have to tear down all the way. At this point we are letting it go.

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$420.00	Sub-Total: \$420.00
----------------------	----------------------	-------------------------	-----------------------	----------------------------

ATTENTION: Part(s) values for this invoice have changed. Original Invoice Parts Sale Value = \$-231.63

Miscellaneous Charges:

Service Accessories \$85.00

Customer Information		Finance Information		Summary	
Customer PO No:		Type: Multi-use Acct US	Auth. No: 749312	Labor:	\$3,813.60
Tax Exempt No:	2019	Merchant No: 37000393		Parts:	(\$231.63)
Advisor:	Mark McCaslin	Card No: xxxxxxxxxxxx2788		OL&M:	\$0.00
		Bill Code: 784 - PERFORMAX INSPECTION - COMBIN		Misc:	\$85.00
		Credit Plan: 11483 - DEERE AG 270 DAYS NO PAYMENTS/NO INTEREST		Sales Tax:	\$0.00
*** DOCUMENT COPY ***				Grand Total:	\$3,666.97

TERMS AND CONDITIONS

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by: Date:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

[Redacted]		Invoice Number: 10678675010322	
		Invoice Date: 12/21/2021	Location: 46
Work Order Number: 2114321		Payment Type: Finance	
Bus: Prv:	Bus: Prv:	Tech:	Page: 1 of 16
Mob:(620)229-3194	Mob:(620)229-3194		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3243	1H09770SJA0741150	168841PLP	

//SER Retail
CORRECTION:
Service Call

Round Trip Mileage: 18 X 2 trips at 36 total miles

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$192.78	Sub-Total: \$192.78
---------------	---------------	--------------	----------------	---------------------

//Diagnose-1 Retail
CORRECTION:

02 Diagnose: Unloading auger won't extend all of the way out.

The customer called in and said the unloading auger would not go in or out. Went out to the location of the machine and found some pieces of the bushings were hanging from the auger swivel. Was able to use the crane on my truck to swing in so the customer could move fields. He said he had 80 acres left to cut for the season. Once he got to the other field he was able to swing the auger out and leave it out until he was done cutting and then bring it to shop for repairs. I then removed the shields and removed the left grain bin extension. Removed the upper auger support and attached two cranes to the unloading auger. Removed bolts from auger housing and lifted auger up and replaced plastic bushings. Set the auger back down. Reinstalled the bolts with new metal rings. Reinstalled the upper support with new bushing then reinstalled grain bin extension. Ran and tested operation.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H202433	BUSHING	2.00	23.06	23.06	\$46.12	N
H217859	Wear Ring	2.00	40.45	40.45	\$80.90	N
H217909	RETAINER	3.00	25.06	25.06	\$75.18	N

Labor: \$0.00	Parts: \$202.20	OL&M: \$0.00	Misc: \$2,374.05	Sub-Total: \$2,576.25
---------------	-----------------	--------------	------------------	-----------------------

PWR/9002S/590 Retail
CORRECTION:

03 STS standard combine inspection

Performed combine inspection and went over findings with the customer.

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 10678675010322	
				Invoice Date: 12/21/2021	
				Location: 46	
				Work Order Number: 2114321	
				Payment Type: Finance	
				Tech:	
				Page:2 of 16	

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3243	1H09770SJA0741150	168841PLP	

PWR/9002S/590 Retail

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$1,695.75	Sub-Total: \$1,695.75
---------------	---------------	--------------	------------------	-----------------------

//Diagnose-2 Retail

CORRECTION:

04 Diagnose: Oil leak at transmission

Ran the combine out side and blew it off. Brought back inside and removed both shields on the bottom side of transmission. Spent some time cleaning the area since it had been leaking for a long time and had a lot of dirt built up. Took the combine outside and ran it around the lot for about 30 minutes. Brought it back inside and was able to find the leak on the park brake valve. Ordered a seal kit. Removed the valve and resealed. Reinstalled the valve back in valve block. Reinstalled both shields. Ran and tested operation.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
KV26542	Seal Kit	1.00	7.18	7.18	\$7.18	N

Labor: \$0.00	Parts: \$7.18	OL&M: \$0.00	Misc: \$1,070.65	Sub-Total: \$1,077.83
---------------	---------------	--------------	------------------	-----------------------

9770STS/7555/UF/10 Retail

CORRECTION:

05 SEAL FEEDER HOUSE UPPER FLOOR - Remove & Install.

Unlatched and lowered feed plate
Removed and Installed upper floor seal
Assembled in reverse order

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H173904	SEAL	1.00	71.24	71.24	\$71.24	N

Labor: \$0.00	Parts: \$71.24	OL&M: \$0.00	Misc: \$87.78	Sub-Total: \$159.02
---------------	----------------	--------------	---------------	---------------------

9770STS/7281/STT/23 Retail

CORRECTION:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 10678675010322	
				Invoice Date: 12/21/2021	
				Location: 46	
				Work Order Number: 2114321	
				Payment Type: Finance	
				Tech: Page: 3 of 16	

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3243	1H09770SJA0741150	168841PLP	

9770STS/7281/STT/23 Retail
06 DOOR STONE TRAP - Repair.

-
Raised feeder house up and put cylinder lock down
Closed stone trap door
Removed cotter pins
Removed pins from stone trap door
Removed stone trap from combine
Repaired or replaced as needed
Installed in reverse order

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$156.94	Sub-Total: \$156.94
---------------	---------------	--------------	----------------	---------------------

9770STS/5182/SP/10 Retail

CORRECTION:
07 CARTRIDGE SINGLE POINT - Remove & install.

Removed old cartridge
Installed new cartridge

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE21789	VALVE	1.00	160.27	160.27	\$160.27	N

Labor: \$0.00	Parts: \$160.27	OL&M: \$0.00	Misc: \$46.55	Sub-Total: \$206.82
---------------	-----------------	--------------	---------------	---------------------

9770STS/4177/CVP/10 Retail

CORRECTION:
08 GUIDES CONVEYOR PLASTIC - Remove & Install.

Removed top doors from feeder house
Removed 3 bolts from plastic strips
Installed new strips with new bolts

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7783	SCREW	3.00	1.20	1.20	\$3.60	N

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

[Redacted]		Invoice Number: 10678675010322	
		Invoice Date: 12/21/2021	Location: 46
Bus: Prv:		Work Order Number: 2114321	Payment Type: Finance
Mob:(620)229-3194		Tech: Page: 4 of 16	
Bus: Prv:			
Mob:(620)229-3194			

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3243	1H09770SJA0741150	168841PLP	

9770STS/4177/CVP/10 Retail						
H171960	STRIP		3.00	18.70	18.70	\$56.10 N
Labor: \$0.00	Parts: \$59.70	OL&M: \$0.00	Misc: \$312.55	Sub-Total: \$372.25		

9770STS/3351/CSL/10 Retail
CORRECTION:
09 BEARING (LH) CLEANING SHOE PITMAN ARM - Remove & Install.

Loosened belt idler and removed belt from sheave
Removed cap screws, and sheave
Removed cap screw and hub
Removed nuts and bolts, and flanged housing
Removed snap ring
Removed eccentric
Eccentric is a press fit
Removed nuts and bolts to separate flanged housing halves
Removed bearing
Assembled bearing in flanged housing halves
Installed bolts and nuts
Ran and verified operation.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH125975	Ball Bearing	4.00	83.82	83.82	\$335.28	N
Labor: \$0.00	Parts: \$335.28	OL&M: \$0.00	Misc: \$312.55	Sub-Total: \$647.83		

9770STS/3351/PIL/10 Retail
CORRECTION:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 10678675010322
				Invoice Date: 12/21/2021
				Location: 46
				Work Order Number: 2114321
				Payment Type: Finance
				Tech: Page:5 of 16

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3243	1H09770SJA0741150	168841PLP	

9770STS/3351/PIL/10 Retail
10 BEARING PITMAN SHAFT LEFT SIDE - Remove & Install.

Removed cap screws holding on arm
 Removed cap screws holding pitman bearings
 Removed pitman bearings
 Removed shaft key
 Removed lock collar
 Removed flange housing with bearing
 Installed new bearing in flanges and installed on shaft
 Installed key on shaft
 Installed pitman arm shaker bearings
 Installed hardware to shaker arms
 Ran and verified operation

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AL14674	ECCENTRIC	2.00	16.57	16.57	\$33.14	N
AXE61820	Ball Bearing	2.00	37.88	37.88	\$75.76	N
H133621	Pressed Flanged Housing	4.00	10.59	10.59	\$42.36	N
Labor: \$0.00		Parts: \$151.26		OL&M: \$0.00		Misc: \$235.41
						Sub-Total: \$386.67

9770STS/5105/UAD/10 Retail
CORRECTION:
11 CYLINDER UNLOADING AUGER DRIVE - Remove & Install.

Relieved pressure to unloading auger engage cylinder and removed hoses
 Removed pins at each end of cylinder
 Removed & reinstalled in reverse order as required & tested

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH176248	HYDRAULIC	1.00	507.75	507.75	\$507.75	N
R26448	O-RING	2.00	1.91	1.91	\$3.82	N
T77613	O-RING	1.00	1.40	1.40	\$1.40	N

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 10678675010322
				Invoice Date: 12/21/2021
				Location: 46
				Work Order Number: 2114321
				Payment Type: Finance
				Tech: Page: 6 of 16

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3243	1H09770SJA0741150	168841PLP	

9770STS/5105/UAD/10 Retail
T77814 O-RING

Quantity	1.00	List Price	1.29	Net Price	1.29	Extended Price	\$1.29	Taxed Ind	N
Labor:	\$0.00	Parts:	\$514.26	OL&M:	\$0.00	Misc:	\$78.47	Sub-Total:	\$592.73

9770STS/5105/RGCV/10 Retail
CORRECTION:
12 CYLINDER ROTOR VARIABLE DRIVE - Remove & Install.

-
Removed hose and fitting
Removed lock nut and washer
Removed and installed cylinder
Tightened lock nut to specifications
Install fitting and hose

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind			
AHC11302	HYDRAULIC	1.00	699.65	699.65	\$699.65	N			
Labor:	\$0.00	Parts:	\$699.65	OL&M:	\$0.00	Misc:	\$107.73	Sub-Total:	\$807.38

9770STS/5160/ROVD/10 Retail
CORRECTION:
13 SHEAVES ROTOR VARIABLE DRIVE - Remove & Install.

-
Relieved rotor drive cylinder pressure
Removed rotor variable drive belt from drive pulley
Removed variable drive hydraulic hose from rotary union
Removed nut from rotary drive shaft holding variable assembly on to shaft

Reinstalled in reverse order and tested

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind			
R1225R	O-RING	2.00	3.41	3.41	\$6.82	N			
Labor:	\$0.00	Parts:	\$6.82	OL&M:	\$0.00	Misc:	\$509.39	Sub-Total:	\$516.21

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

[Redacted]		Invoice Number: 10678675010322	
		Invoice Date: 12/21/2021	Location: 48
Bus: Prv:		Work Order Number: 2114321	Payment Type: Finance
Mob:(620)229-3194		Tech: Page: 7 of 16	

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3243	1H09770SJA0741150	168841PLP	

9770STS/5160/ROVD/20 Retail
CORRECTION:
14 SHEAVES ROTOR VARIABLE DRIVE - Recondition.

Recon rotor variable drive sheaves
Disassembled rotor variable drive and resealed
Rebushed and replaced worn parts as required
Reassembled in reverse

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH136497	SEAL	1.00	20.13	20.13	\$20.13	N
AH144147	SEAL	1.00	16.03	16.03	\$16.03	N
AH144149	SEAL	1.00	49.82	49.82	\$49.82	N
R1225R	O-RING	2.00	3.41	3.41	\$6.82	N
R26543	O-RING	1.00	9.32	9.32	\$9.32	N
R89326	SEAL	1.00	16.36	16.36	\$16.36	N

Labor: \$0.00	Parts: \$118.48	OL&M: \$0.00	Misc: \$509.39	Sub-Total: \$627.87
---------------	-----------------	--------------	----------------	---------------------

9770STS/6080/A/18 Retail
CORRECTION:
15 DISCHARGE BEATER STRIPS ALL - Rotate.

Raised chopper up and lowered bottom plate
Loosened and removed drive belt
Removed bolts from strips and removed
Rotated strips
Installed and put together in reverse order
Verified operation

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$392.35	Sub-Total: \$392.35
---------------	---------------	--------------	----------------	---------------------

9770STS/6064/CP/10 Retail
CORRECTION:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 10678675010322
				Invoice Date: 12/21/2021
				Location: 46
				Work Order Number: 2114321
				Payment Type: Finance
				Tech: Page:8 of 16

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3243	1H09770SJA0741150	168841PLP	

9770STS/6064/CP/10 Retail
16 HAMMER CHOPPER - Remove & Install.

R&I chopper hammer
Raised chopper and lowered plate
Removed nut, bolt, washers, bushings and knives
Installed in reverse order

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Inc
AH225937	Straw Chopper Paddle Blades	6.00	145.09	145.09	\$870.54	N

Labor: \$0.00	Parts: \$870.54	OL&M: \$0.00	Misc: \$610.47	Sub-Total: \$1,481.01
---------------	-----------------	--------------	----------------	-----------------------

9770STS/6951/FEA/10 Retail
CORRECTION:
17 TENSION ARM FEED ACCELERATOR - Remove & Install.

R&I feed accelerator tension arm
Removed tension arm, idler and spring
Installed tension arm, idler and spring

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Inc
AH150900	Idler	2.00	73.49	73.49	\$146.98	N

Labor: \$0.00	Parts: \$146.98	OL&M: \$0.00	Misc: \$187.53	Sub-Total: \$334.51
---------------	-----------------	--------------	----------------	---------------------

9770STS/3351/CSR/10 Retail
CORRECTION:
18 BEARING CLEANING SHOE PITMAN ARM (RH)- Remove & Install.

R&I cleaning shoe pitman arm right side bearing
Loosened belt idlers and removed belts
Removed sheave to access pitman arm
Removed pitman arm and disassembled
Removed bearing
Installed bearing
Reassembled in reverse order
Tested

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: _____ Prv: _____ Mob:(620)229-3194		Bus: _____ Prv: _____ Mob:(620)229-3194		Invoice Number: 10678675010322
				Invoice Date: 12/21/2021
				Location: 46
				Work Order Number: 2114321
				Payment Type: Finance
				Tech: _____ Page: 9 of 16

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3243	1H09770SJA0741150	168841PLP	

9770STS/3351/CSR/10 Retail

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$547.96	Sub-Total: \$547.96
---------------	---------------	--------------	----------------	---------------------

9770STS/3351/PIR/10 Retail

CORRECTION:
19 BEARING PITMAN SHAFT RIGHT SIDE - Remove & Install.

-
Loosened belt idlers and removed belts
Removed sheave to access pitman arm
Removed cap screws holding arm
Removed cap screws holding pitman bearings
Removed pitman bearings
Removed shaft key
Removed lock collar
Removed flange housing with bearing
Installed new bearing in flanges and installed on shaft
Installed key on shaft
Installed pitman arm shaker bearings
Ran and verified operation.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H150268	SHAFT KEY	1.00	15.24	15.24	\$15.24	N

Labor: \$0.00	Parts: \$15.24	OL&M: \$0.00	Misc: \$469.49	Sub-Total: \$484.73
---------------	----------------	--------------	----------------	---------------------

9770STS/6952/TDE/10 Retail

CORRECTION:
20 TENSIONER TAILING ELEVATOR DRIVE - Remove & Install.

-
Loosened belt
Replaced tensioner
Adjusted belt to gauge

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 10678675010322
				Invoice Date: 12/21/2021
				Location: 46
				Work Order Number: 2114321
				Payment Type: Finance
				Tech: Page:0 of 16

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3243	1H09770SJA0741150	168841PLP	

9770STS/6952/TDE/10 Retail

AH85276	Idler	1.00	38.45	38.45	\$38.45	N			
Labor: \$0.00		Parts: \$38.45		OL&M: \$0.00		Misc: \$78.47		Sub-Total: \$116.92	

9770STS/4018/FT/10 Retail
CORRECTION:
21 VENT FUEL TANK - Remove & Install.

Removed the fuel screen and cleaned and reinstalled back on machine.

Labor: \$0.00		Parts: \$0.00		OL&M: \$0.00		Misc: \$78.47		Sub-Total: \$78.47	
----------------------	--	----------------------	--	-------------------------	--	----------------------	--	---------------------------	--

//Diagnose-5 Retail
CORRECTION:
22 Diagnose: Code for EGR Valve

Pulled the code up on service advisor and performed diagnostics. Found all of the wiring to be good. Removed the old EGR valve and replaced. Performed a calibration.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind			
DZ111267	Exhaust Gas Recycling Valve	1.00	539.37	539.37	\$539.37	N			
Labor: \$0.00		Parts: \$539.37		OL&M: \$0.00		Misc: \$675.64		Sub-Total: \$1,215.01	

//Diagnose-6 Retail
CORRECTION:
23 Diagnose: Code for turbo actuator

Performed some diagnostics and found the wire harness to be good. Replaced the actuator and calibrated.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RM100084	Actuator Reman	1.00	723.40	723.40	\$723.40	N

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 10678675010322
				Invoice Date: 12/21/2021
				Location: 46
				Work Order Number: 2114321
				Payment Type: Finance
				Tech: Page 1 of 16

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3243	1H09770SJA0741150	168841PLP	

//Diagnose-6 Retail						
RM100084-CR	CORE for:Actuator Reman	-1.00	50.00	50.00	(\$50.00)	N
Labor: \$0.00	Parts: \$673.40	OL&M: \$0.00	Misc: \$565.25	Sub-Total: \$1,238.65		

9770STS/4059/LA/10 Retail

CORRECTION:
24 HOUSING LOADING AUGER - Remove & Install.

Removed tube
Removed auger
Removed bearing
Removed bracket
Switched bearing holder and latches to new spout
Reinstalled tube and auger with new bearing
Test ran

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH217983	TUBE	1.00	785.51	785.51	\$785.51	N
Labor: \$0.00	Parts: \$785.51	OL&M: \$0.00	Misc: \$235.41	Sub-Total: \$1,020.92		

9770STS/6927/LA/10 Retail

CORRECTION:
25 AUGER LOADING AUGER - Remove & Install.

Removed lock pin, nuts, and shield
Removed spacer and bearing
Removed auger from housing
Installed new auger
Assembled in reverse order

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$140.98	Sub-Total: \$140.98		
----------------------	----------------------	-------------------------	-----------------------	----------------------------	--	--

9770STS/3351/LA/10 Retail

CORRECTION:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 10678675010322
				Invoice Date: 12/21/2021
				Location: 46
				Work Order Number: 2114321
				Payment Type: Finance
				Tech: Page:2 of 16

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3243	1H09770SJA0741150	168841PLP	

9770STS/3351/LA/10 Retail
26 BEARING LOADING AUGER - Remove & Install.
-
Removed cover from end of auger
Removed bearing support and removed bearing
Reversed procedure for installation

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
JD10384	Bearing	1.00	43.46	43.46	\$43.46	N
N15764	Pressed Flanged Housing	2.00	3.49	3.49	\$6.98	N

Labor: \$0.00 Parts: \$50.44 OL&M: \$0.00 Misc: \$78.47 Sub-Total: \$128.91

9770STS/4466/LA/10 Retail
CORRECTION:
27 DRIVE LOADING AUGER - Remove & Install.
-
Unlatched the loading auger housing and set it to the open position
Removed retaining nut from the unloading auger drive pawl
Removed the drive pawl
Installed a new drive pawl and torqued to spec
Raised and latched the loading auger housing in the closed position

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7291	FLANGE NUT	1.00	3.30	3.30	\$3.30	N
H136186	DRIVER	1.00	60.80	60.80	\$60.80	N

Labor: \$0.00 Parts: \$64.10 OL&M: \$0.00 Misc: \$62.51 Sub-Total: \$126.61

9770STS/4164/CGEU/10 Retail
CORRECTION:

2300 W 9th
 Winfield KS 67156
 Phone: (620) 221-1770
 Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 10678675010322
				Invoice Date: 12/21/2021
				Location: 46
				Work Order Number: 2114321
				Payment Type: Finance
				Tech: Page:3 of 16

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3243	1H09770SJA0741150	168841PLP	

9770STS/4164/CGEU/10 Retail
 28 SPROCKET CLEAN GRAIN ELEVATOR UPPER - Remove & Install.

R&I clean grain elevator upper sprocket
 Verified which direction the chain is running in the elevator for later reassembly
 Removed the clean grain elevator drive belt
 Located and removed the master link to split chain
 Lowered to ground
 Removed lock collars and bearings
 Slid shaft out and removed sprocket
 Replaced shaft and sprocket
 Installed new bearings and lock collars
 Reinstalled chain and drive belt
 Adjusted tension
 Test ran

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Inv			
26M6787	SHAFT KEY	1.00	10.27	10.27	\$10.27	N			
49M6480	SHAFT KEY	1.00	3.45	3.45	\$3.45	N			
AH133191	ECCENTRIC	2.00	14.55	14.55	\$29.10	N			
H153308	Pressed Flanged Housing	4.00	6.96	6.96	\$27.84	N			
H220121	Shaft	1.00	109.57	109.57	\$109.57	N			
H228385	Chain Sprocket	1.00	49.94	49.94	\$49.94	N			
JD39104	Ball Bearing	2.00	34.30	34.30	\$68.60	N			
Labor: \$0.00		Parts: \$298.77		OL&M: \$0.00		Misc: \$626.43		Sub-Total: \$925.20	

9770STS/7335/NS/10 Retail
 CORRECTION:
 29 SWITCH NEUTRAL SAFETY - Remove & Install.
 -
 Removed command touch armrest
 Separated armrest to gain access to circuit board
 Unplugged connections as required for neutral start switch replacement
 Reinstalled in reverse
 Tested for proper operation

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 10678675010322
				Invoice Date: 12/21/2021 Location: 46 Work Order Number: 2114321 Payment Type: Finance
Make/Model: JOHN DEERE 9770 STS				Tech: Page 4 of 16

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3243	1H09770SJA0741150	168841PLP	

9770STS/7335/NS/10 Retail

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH161154	Switch	1.00	50.99	50.99	\$50.99	N
Labor: \$0.00						
Parts: \$50.99						
OL&M: \$0.00						
Misc: \$117.04						
Sub-Total: \$168.03						

9770STS/1250/46 Retail

CORRECTION:

30 FUEL SYSTEM - Flush.

Flushed fuel system

- 1 Change primary and secondary fuel filters
 - 2 Prime fuel system and start engine
 - 3 Run engine long enough to get to operating temperature
 - 4 Shut down engine
 - 5 Disconnect fuel supply to primary fuel filter
 - 6 Connect 6' red hose (supply) to primary filter using appropriate adapter in kit
 - 7 Disconnect fuel return to fuel tank
 - 8 Connect 6' black hose (return) to tank line using appropriate adapter in kit
 - 9 Connect other end of red 6' hose to bottom fitting of flush tank Open valve on tank
 - 10 Connect other end of black 6' to return side of flush tank so that return fuel flows through flush kit filter
 - 11 Fill reservoir with full contents of flush solvent
 - 12 Key on to check for leaks and verify return fuel is coming back to flush tool If flush tank fuel level drops quickly shut off and check to make sure all of return fuel is getting back to the tool reservoir
- Keyed on to check for leaks.
Verified return fuel is coming back to flush tool.
If flush tank fuel level dropped quickly shut off and checked to make sure all of return fuel was getting back to the tool reservoir.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE525523	Filter Element	1.00	88.68	88.68	\$88.68	N
2295HD	HD DIESEL INJ SERVICE KIT	1.00	263.15	263.15	\$263.15	N
Labor: \$0.00						
Parts: \$351.83						
OL&M: \$0.00						
Misc: \$436.24						
Sub-Total: \$788.07						

//Diagnose-3 Retail

CORRECTION:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 10678675010322
				Invoice Date: 12/21/2021
				Location: 46
				Work Order Number: 2114321
				Payment Type: Finance
				Tech: Page 5 of 16

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3243	1H09770SJA0741150	168841PLP	

//Diagnose-3 Retail

31 Diagnose: Code VTI 38 8316.12, 38 8316.11

Went through service advisor and found these codes are for the 2600 but the actual codes numbers are not good codes. I would say there is a internal issue with the 2600 display.

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$206.15	Sub-Total: \$206.15
---------------	---------------	--------------	----------------	---------------------

//Diagnose-4 Retail

CORRECTION:

32 Diagnose: Concave adjustment bowl.

Checked all of the moving parts to the concave adjust. Everything seemed to be good and working as they should. Checked the sensor and drive motor and all seemed to be working as they should. I did not find any issues.

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$279.30	Sub-Total: \$279.30
---------------	---------------	--------------	----------------	---------------------

9770STS/3105/LA/10 Retail

CORRECTION:

34 GEAR CASE LOADING AUGER - Remove & Install.

Removed loading auger housing
Removed shielding & rear cross auger cover from grain tank

Removed belt
Removed drive pulley
Unbolted and removed gear case
Installed gear case
Torqued bolts
Installed pulley and belt
Installed removed shields

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Inc
14M7589	LOCK NUT	1.00	3.37	3.37	\$3.37	N
DE32601	GEAR CASE	1.00	1,831.18	1,831.18	\$1,831.18	N

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 10678675010322
				Invoice Date: 12/21/2021
				Location: 46
				Work Order Number: 2114321
				Payment Type: Finance
				Tech: Page:6 of 16

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3243	1H09770SJA0741150	168841PLP	

9770STS/3105/LA/10 Retail								
TY26372	80W140 Synthetic Gear Lube qt	4.00	22.62	22.62	\$90.48	N		
Labor: \$0.00	Parts: \$1,925.03	OL&M: \$0.00	Misc: \$469.49	Sub-Total: \$2,394.52				

ATTENTION: Part(s) values for this invoice have changed. Original Invoice Parts Sale Value = \$4828.99

		Finance Information			
Customer PO No:		Type: Multi-use Acct US	Auth. No: 449594	Labor:	\$13,947.64
Tax Exempt No: 2019		Merchant No: 37000393		Parts:	\$4,828.99
Advisor: Jason Kerwin		Card No: xxxxxxxxxxxx2788		OL&M:	\$0.00
		Bill Code: 784 - PERFORMAX INSPECTION - COMBIN		Misc:	\$0.00
		Credit Plan: 12004 - DEERE AG 360 DAYS NO PAYMENTS/NO INTEREST		Sales Tax:	\$0.00
				Grand Total:	\$18,776.63

*** DOCUMENT COPY ***

TERMS AND CONDITIONS

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by: Date:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

[Redacted]		Invoice Number: 1000361107	
		Invoice Date: 9/20/2022	Location: 46
Bus: Prv:		Work Order Number: 2185440	Payment Type: Finance
Mob:(620)229-3194		Tech: Corey Borders	
Bus: Prv:		Page: 1 of 11	
Mob:(620)229-3194			

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3284	1H09770SJA0741150	168841PLP	

//SER Retail
CORRECTION:
01 Service Call
Location:
(Miles Round Trip)

Labor: \$101.19	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$101.19
-----------------	---------------	--------------	--------------	---------------------

ALL/9010/38P Retail
CORRECTION:
02 Diagnose machine will not start. customer feels it is neutral safety switch.

During inspection, found that the tab was bent where the hydro handle engages the neutral safety switch, I don't know how this tab is getting bent, I re adjusted the switch and started the combine over a dozen times moved the hydro handle back and fourth from forward to reverse several times and i cant get it to act up now again. Customer needs to understand that the tab on the switch is just a little flimsy piece of pot metal and maybe to be a little more gentle on the hydro handle.

Labor: \$236.63	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$236.63
-----------------	---------------	--------------	--------------	---------------------

ALL/9010/2/38P Retail
CORRECTION:
03 Assess damage to cleaning fan for repairs.

Inspected the cleaning fan and noticed the tabs were worn on the fan blades and it had come apart and damaged several others. Also noticed the bearings were original bearings so figured now would be a good time to change them.

Labor: \$69.24	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$69.24
----------------	---------------	--------------	--------------	--------------------

9770STS/1356/CF/10P Retail
CORRECTION:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

[Redacted]		Invoice Number: 1000361107	
		Invoice Date: 9/20/2022	Location: 46
Bus: Prv:		Work Order Number: 2185440	Payment Type: Finance
Mob:(620)229-3194		Tech: Corey Borders	
Bus: Prv:		Page: 2 of 11	
Mob:(620)229-3194			

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3284	1H09770SJA0741150	168841PLP	

9770STS/1356/CF/10P Retail

04 FAN BLADE CLEANING FAN - Remove & Install
R&I cleaning fan fan blade
Removed body panels as necessary
Cleaned fan shear plate
Cleaned fan belt
Rotated cleaning fan so that appropriate fan blade can be accessed from underneath machine
Removed fan divider vanes
Released clips from fan blade and removed blade
Reassembled in reverse order
Adjusted cleaning fan belt

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H206345	FAN BLADE	12.00	75.57	75.57	\$906.84	N

Labor: \$1,095.92 Parts: \$906.84 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$2,002.76

9770STS/3351/CFR/10P Retail

CORRECTION:

05 Cleaning fan bearing (RH) - Remove & Install
Removed & Installed cleaning fan right side bearing.
Released belt tension and removed belt.
Removed sheaves from shaft.
Removed bolts from bearing flanges.
Removed bearing.
Replaced parts as necessary.
Reinstalled in reverse order.
Adjusted belt.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH139297	Ball Bearing	1.00	51.96	51.96	\$51.96	N
AL14674	ECCENTRIC	1.00	18.25	18.25	\$18.25	N
H113625	Pressed Flanged Housing	1.00	10.21	10.21	\$10.21	N
H113626	Pressed Flanged Housing	1.00	12.70	12.70	\$12.70	N

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

[Redacted]		[Redacted]		Invoice Number:	1000361107
[Redacted]		[Redacted]		Invoice Date:	9/20/2022
[Redacted]		[Redacted]		Location:	46
[Redacted]		[Redacted]		Work Order Number:	2185440
[Redacted]		[Redacted]		Payment Type:	Finance
[Redacted]		[Redacted]		Tech: Corey Borders	Page: 3 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3284	1H09770SJA0741150	168841PLP	

9770STS/3351/CFR/10P Retail	JD7788	LUBRICATIO	1.00	1.30	1.27	\$1.27	N
Labor: \$469.49	Parts: \$94.39	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$563.88			

9770STS/1357/LCF/10P Retail
CORRECTION:
06 Lower cleaning fan belt - Remove & Install
Removed & Installed lower cleaning fan belt.
Released belt tension by slowing fan speed all the way.
Removed bolt & bushing and swing speed control arm out.
Removed & Installed belt.
Reassembled and tested operation

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H230909	V-Belt	1.00	103.96	103.96	\$103.96	N
Labor: \$235.41	Parts: \$103.96	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$339.37		

9770STS/3351/CFL/10P Retail
CORRECTION:
07 Cleaning fan bearing (LH) - Remove & Install
Removed & Installed cleaning fan left side bearing.
Removed locking collar.
Removed flange and bolts.
Removed bearing.
Cleaned shaft.
Installed new bearing.
Installed flanges and bolts.
Installed new lock collar.
Verified operation.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH225510	Bearing	1.00	31.25	31.25	\$31.25	N
AN50686	Pressed Flanged Housing	1.00	8.39	8.39	\$8.39	N
JD7788	LUBRICATIO	1.00	1.30	1.27	\$1.27	N

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

[Redacted]		[Redacted]		Invoice Number:	1000361107
[Redacted]		[Redacted]		Invoice Date:	9/20/2022
[Redacted]		[Redacted]		Location:	46
[Redacted]		[Redacted]		Work Order Number:	2185440
[Redacted]		[Redacted]		Payment Type:	Finance
Bus:	Prv:	Bus:	Prv:	Tech: Corey Borders	Page: 4 of 11
Mob:(620)229-3194		Mob:(620)229-3194			

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3284	1H09770SJA0741150	168841PLP	

9770STS/3351/CFL/10P Retail							
N52258	Pressed Flanged Housing	1.00	4.76	4.76	\$4.76	N	
Labor: \$117.04	Parts: \$45.67	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$162.71			

9770STS/6339/LCF/10 Retail
CORRECTION:
08 SHAFT LOWER CLEANING FAN - Remove & Install
R&I LOWER CLEANING FAN SHAFT
Loosened tension on cleaning fan belt
Removed belt from lower sheaves
Removed body shields as necessary
Loosened shaft clamps on both sides
Removed locking collar, speed sensor, tone wheel, and bearing from LH side of shaft
Removed bolts from support bracket on RH side
Removed shaft w/ sheave, bearing, and support bracket still attached to shaft
Removed sheaves, bearing, and support bracket if necessary
Installed in reverse

Had to remove the shaft to replace one of the supports where the cleaning fan came apart.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H201773	Wheel	1.00	67.72	67.72	\$67.72	N
H203514	INSERT	1.00	21.66	20.43	\$20.43	N
H210903	PLUG	8.00	1.13	1.13	\$9.04	N
Labor: \$1,215.40	Parts: \$97.19	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,312.59		

Gen-1 Retail
CORRECTION:
09 General check over for high wear items for mid season checkover.


Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
P5340140	SERVICE DISCOUNT ALLOWED	-1.00	303.45	303.45	(\$303.45)	N
Labor: \$606.89	Parts: \$0.00	OL&M: \$0.00	Misc: (\$303.45)	Sub-Total: \$303.44		



WWW.PRAIRIELANDPARTNERS.COM



WWW.AGRIVISIONEQUIPMENT.COM



2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

[Redacted]		Invoice Number: 1000361107	
		Invoice Date: 9/20/2022	
[Redacted]		Location: 46	
[Redacted]		Work Order Number: 2185440	
[Redacted]		Payment Type: Finance	
Bus: [Redacted]	Prv: [Redacted]	Bus: [Redacted]	Prv: [Redacted]
Mob:(620)229-3194		Mob:(620)229-3194	
		Tech: Corey Borders	
		Page: 5 of 11	

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3284	1H09770SJA0741150	168841PLP	

9770STS/6906/UF/10P Retail

CORRECTION:

10 SHEET UPPER FLOOR - Remove & Install
R&I UPPER FLOOR SHEET-
Raised and locked feeder house
Removed hardware attaching floor sheet
Removed and installed floor sheet

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE24554	FLOOR	1.00	1,447.94	1,447.94	\$1,447.94	N
Labor: \$938.98						
Parts: \$1,447.94						
OL&M: \$0.00						
Misc: \$0.00						
					Sub-Total: \$2,386.92	

9770STS/6404/FHD/10P Retail

CORRECTION:

11 CHAIN FEEDER HOUSE DRIVE - Remove & Install
R&I feeder house drive chain
Removed shields
Separated and replaced drive chain
Replaced chain idlers as needed
Adjusted chain and reinstalled shields

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE80366	Link Chain #60H with 189 Links	1.00	141.69	141.69	\$141.69	N
SW60HCOUS	CHAIN LINK	1.00	5.35	5.35	\$5.35	N
Labor: \$78.47						
Parts: \$147.04						
OL&M: \$0.00						
Misc: \$0.00						
					Sub-Total: \$225.51	

9770STS/1357/UFH/10P Retail

CORRECTION:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

				Invoice Number:	1000361107
				Invoice Date:	9/20/2022
				Location:	46
				Work Order Number:	2185440
				Payment Type:	Finance
Bus:	Prv:	Bus:	Prv:	Tech: Corey Borders	Page: 6 of 11
Mob:(620)229-3194		Mob:(620)229-3194			

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3284	1H09770SJA0741150	168841PLP	

9770STS/1357/JFH/10P Retail
12 BELT UPPER FEEDER HOUSE - Remove & Install
R&I UPPER FEEDER HOUSE BELT-
Loosened tensioner for upper belt
Removed strap on electric clutch module
Removed bolt on reel pump brace arm and twisted arm up to get belt out
Loosened reverser bracket
Removed belt for reverser
Installed new belt
Reinstalled all parts in reverse order

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
14M7299	FLANGE NUT	1.00	2.06	2.06	\$2.06	N
19M7789	SCREW	1.00	2.15	2.15	\$2.15	N
HXE95935	V-Belt	1.00	337.42	337.42	\$337.42	N
Labor: \$406.98		Parts: \$341.63		OL&M: \$0.00		Misc: \$0.00
						Sub-Total: \$748.61

9770STS/6936/CP/10P Retail
CORRECTION:
13 KNIFE BANK CHOPPER - Remove & install
R&I chopper knife bank
Raised chopper all the way up and lowered bottom plate
Supported knife bank and removed nut and bolt at each end
Lowered away from housing
Installed in reverse order

Ended up having to order all new clips for the knife bank they were all broke holding the rod in place. Also replaced a couple knives.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
H206215	PIN FASTEN	1.00	61.40	61.40	\$61.40	N
H211231	Clip	8.00	18.60	18.60	\$148.80	N
H215004	BLADE	1.00	9.24	9.24	\$9.24	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: _____ Prv: _____ Mob:(620)229-3194		Bus: _____ Prv: _____ Mob:(620)229-3194		Invoice Number: 1000361107
				Invoice Date: 9/20/2022
				Location: 46
				Work Order Number: 2185440
				Payment Type: Finance
				Tech: Corey Borders
				Page: 7 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3284	1H09770SJA0741150	168841PLP	

9770STS/6936/CP/10P Retail							
P37501	FREIGHT		1.00	38.69	38.69	\$38.69	N
Labor: \$78.47	Parts: \$219.44	OL&M: \$0.00	Misc: \$38.69	Sub-Total: \$336.60			

9770STS/1357/RSJ/10P Retail
CORRECTION:
14 BELT ROTARY SCREEN JACKSHAFT DRIVE - Remove
R&I ROTARY SCREEN JACKSHAFT DRIVE BELT-
Opened engine compartment and got into rear doors
Removed belt tension
Replaced belt and reset tension
Test ran

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H213353	V-Belt	1.00	33.54	33.54	\$33.54	N
Labor: \$156.94	Parts: \$33.54	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$190.48		

9770STS/1357/ALT/10P Retail
CORRECTION:
15 Alternator belt - Remove & Install
Removed & Installed alternator belt.
Opened access door to engine.
Relieved belt tension and removed old belt.
Installed new belt and set tensioner.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H206426	Pulley	1.00	225.18	225.18	\$225.18	N
HXE32806	V-Belt	1.00	68.72	68.72	\$68.72	N
RE548027	Belt Tensioner	1.00	147.38	147.38	\$147.38	N
Labor: \$102.41	Parts: \$441.28	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$543.69		

9770STS/4006/10P Retail
CORRECTION:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 1000361107
				Invoice Date: 9/20/2022
				Location: 46
				Work Order Number: 2185440
				Payment Type: Finance
				Tech: Corey Borders
				Page: 8 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3284	1H09770SJA0741150	168841PLP	

9770STS/4006/10P Retail

16 Engine coupling (includes engine R&I) - Remove & Install
 Drained coolant.
 Drained engine oil.
 Removed engine shields as necessary.
 Removed hoses, wiring, and belts as necessary.
 Removed muffler, air cooler tubes, alternator.
 Removed A/C compressor, fan shroud, cooling fan.
 Removed engine to gear case cap screws.
 Removed all mounting hardware.
 Attached appropriate lifting device and removed engine.
 Removed the bolts.
 Removed and installed the splined coupling.
 Reassembled and torqued to specifications.
 Installed engine and all parts in reverse order.
 Installed engine and all parts in reverse order.
 Torqued all hardware to specification.
 Refilled fluids to proper level.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7805	SCREW	2.00	2.79	2.79	\$5.58	N
19M7868	SCREW	6.00	1.39	1.39	\$8.34	N
AH168456	Splined Coupling	1.00	586.02	586.02	\$586.02	N
H168359	Hose	2.00	30.36	30.36	\$60.72	N
JD7147	Ball Bearing	1.00	12.79	12.79	\$12.79	N
R42729	Washer	6.00	0.95	0.95	\$5.70	N
R519654	Screw	6.00	5.15	5.15	\$30.90	N
RE52702	CLAMP	2.00	17.44	17.44	\$34.88	N

Labor: \$3,092.25	Parts: \$744.93	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$3,837.18
-------------------	-----------------	--------------	--------------	-----------------------

9770STS/1357/R/10P Retail
CORRECTION:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 1000361107
				Invoice Date: 9/20/2022
				Location: 46
				Work Order Number: 2185440
				Payment Type: Finance
				Tech: Corey Borders
				Page: 9 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3284	1H09770SJA0741150	168841PLP	

9770STS/1357/R/10P Retail

17 BELT ROTOR - Remove & Install
R&I ROTOR BELT

w/ separator engaged and running, set separator drive in low speed position so driven sheaves on gear case were closed
Shifted STS rotor drive gear case to the neutral position
Loosened cap screws, draw bolt and fully rotated gear case to LH side of machine using draw bolt
Removed drive belt
Installed new drive belt
Tightened draw bolt until specified sheave gap was achieved
Tightened bolts to spec and put drive in gear
Ran separator & adjusted drive up & down for a few minutes
Verified sheave gap and operation

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE147321	V-BELT	1.00	953.33	953.33	\$953.33	N
Labor: \$391.02						
Parts: \$953.33						
OL&M: \$0.00						
Misc: \$0.00						
Sub-Total: \$1,344.35						

9770STS/6043/146P Retail

CORRECTION:
18 Rotor drive cams - Grease

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AN102562	Corn Head grease	1.00	6.47	6.47	\$6.47	N
Labor: \$110.39						
Parts: \$6.47						
OL&M: \$0.00						
Misc: \$0.00						
Sub-Total: \$116.86						

9770STS/1909/TRS/10P Retail

CORRECTION:
19 SENSOR TURBO SPEED - Remove & Install

Removed covers and step as needed to access turbo Removed speed sensor
Installed in reverse order

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

[Redacted]		Invoice Number: 1000361107	
		Invoice Date: 9/20/2022	
Bus: Prv:		Location: 46	
Mob:(620)229-3194		Work Order Number: 2185440	
Bus: Prv:		Payment Type: Finance	
Mob:(620)229-3194		Tech: Corey Borders	
		Page 10 of 11	

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3284	1H09770SJA0741150	168841PLP	

9770STS/1909/TRS/10P Retail						
RE523319	Sensor	1.00	397.84	397.84	\$397.84	N
Labor: \$156.94	Parts: \$397.84	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$554.78		

9770STS/1161/SO/51P Retail

CORRECTION:

20 Rear crankshaft seal (w/Engine removed) - Replace

Replaced rear crankshaft seal.
Engine already removed.
Removed flywheel if not previously removed.
Removed eight screws securing rear seal to housing.
Separated seal from housing and removed seal.
Cleaned ID of rear seal housing and flange.
Positioned crankshaft rear oil seal & drive tool on flange.
Applied LOCTITE® thread sealant to button head screws.
Installed eight screws, securing seal to housing.
Torqued to specification.
Installed flywheel if it was previously removed.
Verified operation.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
R522768	Gasket	1.00	8.16	8.16	\$8.16	N
R531312	HOUSING	1.00	118.38	118.38	\$118.38	N
RE520035	SEAL	1.00	63.00	63.00	\$63.00	N
Labor: \$312.55	Parts: \$189.54	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$502.09		

9770STS/1498/TEN/10P Retail

CORRECTION:

PRAIRIELAND


PARTNERS

WWW.PRAIRIELANDPARTNERS.COM

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225



WWW.AGRIVISIONEQUIPMENT.COM



Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

[Redacted]		Invoice Number: 1000361107	
		Invoice Date: 9/20/2022	Location: 46
Bus: Prv:		Work Order Number: 2185440	Payment Type: Finance
Mob:(620)229-3194		Tech: Corey Borders	
Bus: Prv:		Page: 11 of 11	
Mob:(620)229-3194			

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3284	1H09770SJA0741150	168841PLP	

9770STS/1498/TEN/10P Retail
21 Engine drive belt tensioner - Remove & Install

Opened access door to engine.
Relieved belt tension.
Removed the bolt and removed tensioner.
Installed tensioner and reassembled.

This time needs to be added to the engine removal segment

Labor: \$66.46	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$66.46
----------------	---------------	--------------	--------------	--------------------

INVOICE CONTAINS \$1.29 DISCOUNT

Customer PO No:		Finance Information		Labor: \$10,039.07
Tax Exempt No: 2019	Type: Multi-use Acct US	Auth. No: 993685	Parts: \$6,171.03	
Advisor: Mark McCaslin	Merchant No: 37000456	Card No: xxxxxxxxxxxx2788	OL&M: \$0.00	
	Bill Code: 784 - COMBINE INSPECTION	Credit Plan: 12012 - DEERE AG NO PAYMENTS/NO INTEREST WAIVER UNTIL JULY 1,	Misc: (\$264.76)	
			Sales Tax: \$0.00	
			Grand Total: \$15,945.34	

*** DOCUMENT COPY ***

TERMS AND CONDITIONS

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by: Date:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

[Redacted]		Invoice Number: 1001066191	
		Invoice Date: 2/29/2024	
Bus: Prv:		Location: 46	
Mob:(620)229-3194		Work Order Number: 2307390	
Bus: Prv:		Payment Type: Finance	
Mob:(620)229-3194		Tech: Corey Borders	
		Page: 1 of 10	

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3453	1H09770SJA0741150	168841PLP	

PWR/9002S/590 Retail

CORRECTION:

01 STS STANDARD COMBINE INSPECTION

Performed combine inspection
Went over findings with customer
Received approvals for repairs

**Legacy Series Combine Inspection Promotion

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
P5340142	SERVICE PROMOTIONAL DISCOUNT	-1.00	1,703.18	1,703.18	(\$1,703.18)	N
Labor: \$2,202.18	Parts: \$0.00		OL&M: \$0.00	Misc: (\$1,703.18)	Sub-Total: \$499.00	

9770STS/7052/LLT/10 Retail

CORRECTION:

03 FEEDER HOUSE LATERAL TILT FRAME - Remove & Install

Removed tube and seal from top of feeder house
Removed pin from tilt cylinder
Removed bolts from lower corners of frame
Used lifting device and removed tilt frame
Installed in reverse order
Torqued bolts to specification

Labor: \$338.53	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$338.53
------------------------	----------------------	-------------------------	---------------------	----------------------------

9770STS/6072/LLT/10 Retail

CORRECTION:

04 FEEDER HOUSE LATERAL TILT FRAME WEAR PADS - Remove & Install

Replaced the wear pads on the upper corners of the tilt frame due to wear of the pads and the frame
Added 2 spacers on each side to take up some play
Once the wear pads were installed, we went back and reinstalled the tilt frame

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H149461	Wear Plate	2.00	48.74	48.74	\$97.48	N

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: _____ Prv: _____ Mob:(620)229-3194		Bus: _____ Prv: _____ Mob:(620)229-3194		Invoice Number: 1001066191	
				Invoice Date: 2/29/2024	
				Location: 46	
				Work Order Number: 2307390	
				Payment Type: Finance	
				Tech: Corey Borders	
				Page: 2 of 10	

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3453	1H09770SJA0741150	168841PLP	

9770STS/6072/LLT/10 Retail							
HXE104720	PLATE	4.00	24.32	24.32	\$97.28	N	
R495R	O-RING	2.00	3.34	3.34	\$6.68	N	
Labor: \$360.98		Parts: \$201.44		OL&M: \$0.00		Misc: \$0.00	
						Sub-Total: \$562.42	

9770STS/5102/20 Retail
CORRECTION:
05 FEEDER HOUSE LIFT CYLINDER - Recondition X2

Put cylinder in vise
Removed end cap from cylinder
Removed ram out of cylinder housing
Installed new seal kit

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind	
AHC11572	HYDRAULIC	2.00	96.74	96.74	\$193.48	N	
AHC22107	HYDRAULIC	2.00	78.85	78.85	\$157.70	N	
Labor: \$407.62		Parts: \$351.18		OL&M: \$0.00		Misc: \$0.00	
						Sub-Total: \$758.80	

9770STS/5102/10 Retail
CORRECTION:
06 FEEDER HOUSE LIFT CYLINDER - Remove & Install X2

Lowered feeder house so that it is setting on the ground
Removed and capped hoses that connect to the cylinders
Removed cotter pins on each side
Removed pins from cylinders
Removed cylinders
Prepared for rebuild
Installed in reverse order

Labor: \$528.52		Parts: \$0.00		OL&M: \$0.00		Misc: \$0.00	
						Sub-Total: \$528.52	

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: _____ Prv: _____ Mob:(620)229-3194		Bus: _____ Prv: _____ Mob:(620)229-3194		Invoice Number: 1001066191	Invoice Date: 2/29/2024
				Location: 46	Work Order Number: 2307390
Make/Model: JOHN DEERE 9770 STS				Payment Type: Finance	Tech: Corey Borders
Meter: 3453		Serial Number: 1H09770SJA0741150		Eq ID: 168841PLP	Page: 3 of 10
Fleet No:					

9770STS/6404/CV/10 Retail

CORRECTION:

07 FEEDER HOUSE CONVEYOR CHAIN - Remove & Install

Loosened feeder house chain tension
 Removed drive chain
 Turned feeder house chain around so the master links are facing the front
 Cut out a 1/2 link from each section of chain
 Retightened the feeder house chain to spec
 Reinstalled the drive chain
 Ran and tested operation

Labor: \$528.52	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$528.52
------------------------	----------------------	-------------------------	---------------------	----------------------------

9770STS/4177/CVP/10 Retail

CORRECTION:

08 PLASTIC CONVEYOR GUIDES - Remove & Install

Removed top doors from feeder house
 Removed 3 bolts from plastic strips
 Installed new strips with new bolts

Labor: \$222.81	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$222.81
------------------------	----------------------	-------------------------	---------------------	----------------------------

9770STS/3351/CSL/10 Retail

CORRECTION:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 1001066191
				Invoice Date: 2/29/2024
				Location: 46
				Work Order Number: 2307390
				Payment Type: Finance
				Tech: Corey Borders
				Page: 4 of 10

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3453	1H09770SJA0741150	168841PLP	

9770STS/3351/CSL/10 Retail
09 CLEANING SHOE PITMAN ARM BEARING (LH) - Remove & Install

Loosened belt idler and removed belt from sheave
 Removed cap screws, and sheave
 Removed cap screw and hub
 Removed nuts and bolts, and flanged housing
 Removed snap ring
 Removed eccentric
 Eccentric is a press fit
 Removed nuts and bolts to separate flanged housing halves
 Removed bearing
 Assembled bearing in flanged housing halves
 Installed bolts and nuts

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H234550	CAM	1.00	95.52	95.52	\$95.52	N
Labor: \$405.89						
Parts: \$95.52						
OL&M: \$0.00						
Misc: \$0.00						
Sub-Total: \$501.41						

9770STS/3105/GTVA/10 Retail
CORRECTION:
10 GRAIN TANK VERTICAL AUGER GEAR CASE - Remove & Install

Loosened and removed drive chain
 Removed chain guard and drive sprocket
 Attached stand to gear case
 Loosened and removed all hardware and lower gear case
 Installed in reverse order

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H64376	SHAFT KEY	1.00	13.01	13.01	\$13.01	N
Labor: \$552.70						
Parts: \$13.01						
OL&M: \$0.00						
Misc: \$0.00						
Sub-Total: \$565.71						

9770STS/3105/GTVA/20 Retail
CORRECTION:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

[Redacted]		[Redacted]		Invoice Number:	1001066191
[Redacted]		[Redacted]		Invoice Date:	2/29/2024
[Redacted]		[Redacted]		Location:	46
[Redacted]		[Redacted]		Work Order Number:	2307390
[Redacted]		[Redacted]		Payment Type:	Finance
[Redacted]		[Redacted]		Tech: Corey Borders	Page: 5 of 10

Bus: [Redacted]	Prv: [Redacted]	Bus: [Redacted]	Prv: [Redacted]	Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
Mob:(620)229-3194		Mob:(620)229-3194		JOHN DEERE 9770 STS	3463	1H09770SJA0741150	168841PLP	

9770STS/3105/GTVA/20 Retail
11 GRAIN TANK VERTICAL AUGER GEAR CASE- Recondition

Disassembled gear case
Replaced all required bearings
Replaced shafts
Replaced gears
Replaced shims, etc
Reassembled in reverse order
Set up per TM manual

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7843	SCREW	4.00	4.47	4.47	\$17.88	N
24H1533	Shim	2.00	5.26	5.26	\$10.52	N
AH90963	SEAL	1.00	28.37	28.37	\$28.37	N
H149361	LOCK NUT	1.00	4.02	4.02	\$4.02	N
H215085	Shaft	1.00	152.84	152.84	\$152.84	N
JD8524	Bearing	4.00	26.58	22.59	\$90.36	N
Labor: \$569.98		Parts: \$303.99		OL&M: \$0.00		Misc: \$0.00
						Sub-Total: \$873.97

9770STS/1357/FED/10 Retail
CORRECTION:
12 FEED ACCELERATOR DRIVE BELT - Remove & Install

Released tension on accelerator and jackshaft belt
Released tension on shoe supply auger belt
Removed all belts from jackshaft
Installed new accelerator belt
Reset tension on jackshaft, accelerator and shoe auger belt
Test ran

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE95511	V-Belt	1.00	176.76	176.76	\$176.76	N
Labor: \$162.36		Parts: \$176.76		OL&M: \$0.00		Misc: \$0.00
						Sub-Total: \$339.12

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 1001066191
				Invoice Date: 2/29/2024
				Location: 46
				Work Order Number: 2307390
				Payment Type: Finance
				Tech: Corey Borders
				Page: 6 of 10

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3453	1H09770SJA0741150	168841PLP	

9770STS/3351/CSR/10 Retail

CORRECTION:

13 CLEANING SHOE PITMAN ARM BEARING (RH) - Remove & Install

Loosened belt idlers and removed belts
 Removed sheave to access pitman arm
 Removed pitman arm and disassembled
 Removed bearing
 Installed bearing
 Reassembled in reverse order
 Tested

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH125975	Ball Bearing	4.00	98.90	98.90	\$395.60	N
Labor: \$711.61		Parts: \$395.60		OL&M: \$0.00		Misc: \$0.00
Sub-Total: \$1,107.21						

9770STS/7555/RFD/10 Retail

CORRECTION:

14 RIGHT FINAL DRIVE INPUT SEAL - Remove & Install

Removed the drive shaft couplers
 Removed the driveshaft
 Removed the seal from the housing
 Installed new seal
 Installed the driveshaft and couplers

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH128391	SEAL	1.00	23.07	17.31	\$17.31	N
Labor: \$305.71		Parts: \$17.31		OL&M: \$0.00		Misc: \$0.00
Sub-Total: \$323.02						

9770STS/1056/10P Retail

CORRECTION:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 1001066191
				Invoice Date: 2/29/2024
				Location: 46
				Work Order Number: 2307390
				Payment Type: Finance
				Tech: Corey Borders
				Page: 7 of 10

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3453	1H09770SJA0741150	168841PLP	

9770STS/1056/10P Retail
15 TURBO ACTUATOR - Remove & Install

Turned key to off position and disconnected battery power
Gained access to engine compartment turbo area
Removed electrical connection to actuator
Drained engine coolant to remove coolant lines to actuator
Removed actuator mounting hardware per TM
Reinstalled in reverse order
Calibrated and tested for proper operation

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE535990	LINKAGE	1.00	351.89	351.89	\$351.89	N
Labor: \$609.70						
Parts: \$351.89						
OL&M: \$0.00						
Misc: \$0.00						
Sub-Total: \$961.59						

9770STS/5959/10 Retail
CORRECTION:
16 IMPACT PLATE MASS FLOW SENSOR - Remove & Install

Removed top cover on mass flow sensor
Removed assembly and replaced impact plate
Reinstalled and tested

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH164349	BRACKET	1.00	236.35	236.35	\$236.35	N
Labor: \$203.81						
Parts: \$236.35						
OL&M: \$0.00						
Misc: \$0.00						
Sub-Total: \$440.16						

ALL/9010/3/38 Retail
CORRECTION:

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

[Redacted]		[Redacted]		Invoice Number: 1001066191 Invoice Date: 2/29/2024 Location: 46 Work Order Number: 2307390 Payment Type: Finance Tech: Corey Borders	Page: 8 of 10
Bus: Prv:	Bus: Prv:	Meter:	Serial Number:	Eq ID:	Fleet No:
Mob:(620)229-3194	Mob:(620)229-3194	3453	1H09770SJA0741150	168841PLP	
Make/Model:	JOHN DEERE 9770 STS				

ALL/9010/3/38 Retail
17 SWING CYLINDER UNLOADING AUGER - Check Solenoids & Possibly Replace

Customer said that the unloading auger would move out of the cradle going down the road and while he was unloading the machine it would creep back from fully extended

Started by looking at service advisor at hydraulic system of the unloading cylinder oil flow
Pulled 3 different valves and found that 1 of them had a broken o-ring
Replaced the valve with the broken o-ring because parts does not offer a breakdown of the valve to replace just the o-ring
Ran and tested operation

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE38513	Solenoid Valve	1.00	468.06	468.06	\$468.06	N
Labor: \$129.54						
Parts: \$468.06						
OL&M: \$0.00						
Misc: \$0.00						
				Sub-Total:	\$597.60	

9770STS/7286/HUA/10 Retail
CORRECTION:
18 HORIZONTAL UNLOADING AUGER BOOT - Remove & Install

Removed and installed the unloading auger boot because there was a chunk of poly plastic wrapped up in the auger that needed to be removed
Once removed, we reinstalled the boot

Labor: \$179.63	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$179.63
------------------------	----------------------	-------------------------	---------------------	----------------------------

9770STS/1909/CP/10 Retail
CORRECTION:
19 CONCAVE POSITION SENSOR - Remove & Install

Removed concave position sensor
Installed new sensor

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

2300 W 9th
Winfield KS 67156
Phone: (620) 221-1770
Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number:	1001066191
				Invoice Date:	2/29/2024
				Location:	46
				Work Order Number:	2307390
				Payment Type:	Finance
				Tech: Corey Borders	Page: 9 of 10

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3453	1H09770SJA0741150	168841PLP	

9770STS/1909/CP/10 Retail	AXE58085	Sensor	1.00	166.50	166.50	\$166.50	N
Labor: \$101.90	Parts: \$166.50	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$268.40			

9770STS/1909/CP/57 Retail
CORRECTION:
20 CONCAVE POSITION SENSOR - Calibrate

Removed hardware holding sensor on
Removed sensor
Installed sensor and hardware
Calibrated

Labor: \$50.09	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$50.09			
-----------------------	----------------------	-------------------------	---------------------	---------------------------	--	--	--


ALL/9010/2/38 Retail
CORRECTION:
21 ARMREST HEIGHT BOLT IS LOOSE OR MISSING PIN - Diagnose & Repair

Customer said left side arm rest came apart on the seat in the cab, he tried to fix it but it will not stay up
I looked at it and it was missing a pin that holds it in place
Ordered a new arm rest
Replaced it with the new arm rest
Reinstalled the side covers

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind	
AL117354	ARMREST	1.00	380.81	380.81	\$380.81	N	
Labor: \$146.81	Parts: \$380.81	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$527.62			

DISCOUNTSAPPLIED Retail
CORRECTION:
22 DISCOUNTS APPLIED

**Customer Transportation Discount
**10% Parts & 20% Labor Discount With Legacy Series Combine Inspection



2300 W 9th
 Winfield KS 67156
 Phone: (620) 221-1770
 Fax: (620) 221-0225

Invoice To Account No: 123592

Deliver To:

SERVICE INVOICE

Bus: Prv: Mob:(620)229-3194		Bus: Prv: Mob:(620)229-3194		Invoice Number: 1001066191 Invoice Date: 2/29/2024 Location: 46 Work Order Number: 2307390 Payment Type: Finance
				Tech: Corey Borders Page 0 of 10

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9770 STS	3453	1H09770SJA0741150	168841PLP	

DISCOUNTS APPLIED Retail

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
P5340132	PARTS PROMOTIONAL DISCOUNT	-1.00	315.84	315.84	(\$315.84)	N
P5340141	CUSTOMER TRANSPORTATION DISCOUNT	-1.00	100.00	100.00	(\$100.00)	N
P5340142	SERVICE PROMOTIONAL DISCOUNT	-1.00	1,303.34	1,303.34	(\$1,303.34)	N

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: (\$1,719.18)	Sub-Total: (\$1,719.18)
----------------------	----------------------	-------------------------	---------------------------	--------------------------------

INVOICE CONTAINS \$21.72 DISCOUNT

Customer Information		Finance Information		Totals	
Customer PO No:		Type: Multi-use Acct US	Auth. No: 886159	Labor:	\$8,718.89
Tax Exempt No: 2019		Merchant No: 37000456		Parts:	\$3,158.42
Advisor: Geoffery Dafforn		Card No: xxxxxxxxxxxx2788		OL&M:	\$0.00
		Bill Code: 784 - COMBINE INSPECTION		Misc:	(\$3,422.36)
		Credit Plan: 12041 - DEERE AG NO PAYMENTS/NO INTEREST WAIVER UNTIL		Sales Tax:	\$0.00
				Grand Total:	\$8,454.95

*** DOCUMENT COPY ***

TERMS AND CONDITIONS

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by: Date: