



2361 State Hwy 91
 Albion, NE 68620
 Phone: 402-395-2173
 Fax: 402-395-6749
 Email: Albion@AKRS.com
 www.akrs.com



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 130037

Deliver To:

AMERICA'S HOME ENVIRONMENT
 BOB BITTNER
 PO BOX 444
 ALBION NE 68620

 Bus Phone: (402)395-5000
 Prv Phone:

AMERICA'S HOME ENVIRONMENT
 PO BOX 444
 ALBION NE 68620

 Bus Phone: (402)395-5000
 Prv Phone:

Invoice Number: **3861774**
 Invoice Date: 05/31/2024
 Location: 27
 Work Order Number: 1056710
 Payment Type: Credit Card
 Authorization Number: 02162P
 Page: 4 of 4

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 2555		L02555T728781	LL02555T728781	

Labor: \$41.25 Parts: \$0.00 OL&M: \$0.00 Svc Acc/Env: \$44.96 Svc Call: \$0.00 Sub-Total: \$86.21

Technicians: T27410

GL Account:	Credit Card Information	
Customer PO No:	Type: Credit Card	Labor: \$899.25
Tax Exempt No:	Auth No: 02162P	Parts: \$291.45
	Amount: \$1,303.59	OL&M: \$0.00
		Svc Acc/Enviro: \$44.96
		Svc Call/Hauling: \$0.00
		Sales Tax: \$67.93
		Total: \$1,303.59

TERMS AND CONDITIONS

Approved charges are due the 15th of the month following invoice date. Accounts 30 days past due will be charged a FINANCE CHARGE of 1.5% per month which equals an 18% ANNUAL RATE of interest per year. \$35 returned check fee. Purchaser agrees to pay reasonable attorney fees if collection efforts are required. The invoice must accompany all returned goods. No returns accepted after 30 days. Returned goods subject to restocking charges. Electrical parts are non-refundable.

Received by:

Date:

JEFF'S FARM TIRE SERVICE

2834 240TH ST.
ALBION, NE 68620
(402) 741-0784

CUSTOMER'S ORDER NO. _____ PHONE _____ DATE 1-22-16

NAME Bob Bittner
ADDRESS _____

SOLD BY _____ CASH C.O.D. _____ CHARGE _____ ON ACCT. _____ MDSE. RET'D. _____ PAID OUT _____

QTY.	DESCRIPTION	PRICE	AMOUNT
	<u>ReR 184-30</u>		<u>71 83</u>
<u>1</u>	<u>16.9/18.4R30 michelin tube</u>		<u>107 95</u>
	<u>Pump fluid</u>		<u>40 00</u>
	<u>50 gal fluid</u>		<u>150 00</u>
	<u>Service call</u>		<u>60 00</u>
	<u>michelin</u>		<u>20 00</u>
	<u>pc # 2690</u>		
	<u>Thanky</u>		

RECEIVED BY _____ TAX 5 94
TOTAL 453 72

5210

All claims and returned goods MUST be accompanied by this bill.

THANK YOU





2361 State Hwy 91
 Albion, NE 68620
 Phone: 402-395-2173
 Fax: 402-395-6749
 Email: Albion@AKRS.com
 www.akrs.com



JOHN DEERE

Invoice To Account No: 130037

Deliver To:

SERVICE INVOICE

AMERICA'S HOME ENVIRONMENT
 BOB BITTNER
 PO BOX 444
 ALBION NE 68620

Bus Phone: (402)395-5000
 Prv Phone:

AMERICA'S HOME ENVIRONMENT
 PO BOX 444
 ALBION NE 68620

Bus Phone: (402)395-5000
 Prv Phone:

Invoice Number: **3861774**
 Invoice Date: 05/31/2024
 Location: 27
 Work Order Number: 1056710
 Payment Type: Credit Card
 Authorization Number: 02162P
 Page: 2 of 4

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 2555		L02555T728781	LL02555T728781	

Labor: \$660.00 Parts: \$93.20 OL&M: \$0.00 Svc Acc/Env: \$0.00 Svc Call: \$0.00 Sub-Total: \$753.20

Technicians: T27410

GEN-2 Retail

COMPLAINT:

03 - Speedometer/tach not working

CAUSE:

CORRECTION:

Removed hood and interior cowl to trace and test wires to the tachometer.
 All wires tested good.
 Tested engine speed sensor and found that sensor was not ready correctly.
 When tractor engine speed is increased volts do not increase.
 Replaced the sensor with a new sensor.
 Volts are now increasing with rpm
 Hooked wire up to the sensor and engine speed is now working in the tachometer.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
14H631	NUT	2.00	\$0.21	\$0.42	Y
19H1948	CAP SCREW	2.00	\$0.65	\$1.30	Y
24M7027	WASHER	2.00	\$0.14	\$0.28	Y
AL32267	Wiring Lead	1.00	\$30.73	\$30.73	Y
AL64856	Shield	1.00	\$65.92	\$65.92	Y
AR96480	Sensor	1.00	\$69.88	\$69.88	Y
R67230	Cover	1.00	\$28.08	\$28.08	Y
R79915	O-RING	1.00	\$1.64	\$1.64	Y

Labor: \$99.00 Parts: \$198.25 OL&M: \$0.00 Svc Acc/Env: \$0.00 Svc Call: \$0.00 Sub-Total: \$297.25

Technicians: T27410

GEN-3 Retail

COMPLAINT:

04 - Oil leak out of clutch cavity

CAUSE:

CONTINUED ON NEXT PAGE->



2361 State Hwy 91
 Albion, NE 68620
 Phone: 402-395-2173
 Fax: 402-395-6749
 Email: Albion@AKRS.com
 www.akrs.com



JOHN DEERE

Invoice To Account No: 130037

Deliver To:

SERVICE INVOICE

AMERICA'S HOME ENVIRONMENT
 BOB BITTNER
 PO BOX 444
 ALBION NE 68620

 Bus Phone: (402)395-5000
 Prv Phone:

AMERICA'S HOME ENVIRONMENT
 PO BOX 444
 ALBION NE 68620

 Bus Phone: (402)395-5000
 Prv Phone:

Invoice Number: **3861774**
 Invoice Date: 05/31/2024
 Location: 27
 Work Order Number: 1056710
 Payment Type: Credit Card
 Authorization Number: 02162P
 Page: 1 of 4

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 2555		L02555T728781	LL02555T728781	

GEN-1 Retail

COMPLAINT:

02 - Leaking SCV's

CAUSE:

Gasket bad and SCV drains plumbed wrong

CORRECTION:

SCV #2 was found to be leaking in the gasket on the back part.
 Removed SCV.
 Disassembled and Found the gasket to have a tear where it was leaking.
 Replaced gasket.
 Reassembled the SCV
 Reinstalled SCV and investigated the drain plumbing
 Plumbing schematic showed that the plumbing was not correct and oil from the receptacle side was being drained back to the transmission when it should drain out to the ground.
 Plumbing was rerouted to match the proper schematic.
 Tractor was run and no leaks were detected.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
19H2020	Cap Screw	1.00	\$0.68	\$0.68	Y
24H1822	WASHER	1.00	\$0.59	\$0.59	Y
L65383	HOSE	31.00	\$0.47	\$14.57	Y
R100230	GASKET	1.00	\$5.19	\$5.19	Y
R100333	GASKET	1.00	\$3.19	\$3.19	Y
R26484	BACK-UP RING	1.00	\$2.17	\$2.17	Y
R27564	O-RING	1.00	\$1.24	\$1.24	Y
R45925	BACK-UP RING	1.00	\$3.16	\$3.16	Y
R69891	SEAL	4.00	\$6.97	\$27.88	Y
T30785	Clamp	1.00	\$3.56	\$3.56	Y
TY22462	CLAMP	1.00	\$1.73	\$1.73	Y
TY22551	BULK HOSE	46.00	\$0.26	\$11.96	Y
TY22561	BULK HOSE	36.00	\$0.48	\$17.28	Y

CONTINUED ON NEXT PAGE->



PF Repair, LLC

Roy & Judy Pribnow
1015 Old Mill Road
Albion, NE 68620

Invoice

Date	Invoice #
2/16/2024	5170

Bill To
P.O. Box 444 <i>Bob Billner</i> Albion, NE 68620 Boone

Job Description

Description	Qty	Rate	Amount
parts-unit-R68485U	1	438.08	438.08
parts-flywheel-R18678	1	450.56	450.56
parts-release bearing-510 0020 10	1	360.11	360.11
parts-pilot bearing-836202	1	14.18	14.18
parts- rear main seal kit-R44574	1	31.05	31.05
Freight		91.28	91.28
Labor-Removed loader mounts disassembled tractor to split for clutch. Replaced rear seal and flywheel and clutch assembly with trough bearing and sleeve cylinder. Reassembled and bled clutch cylinder.	15	105.00	1,575.00
NE & City Sales Tax		7.00%	0.00

Phone #	Fax #
402-395-2111	402-395-2114

TOTAL	\$2,960.26
Payments/Credits	\$0.00
Balance Due	\$2,960.26



2361 State Hwy 91
 Albion, NE 68620
 Phone: 402-395-2173
 Fax: 402-395-6749
 Email: Albion@AKRS.com
 www.akrs.com



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 130037

AMERICA'S HOME ENVIRONMENT
 BOB BITTNER
 PO BOX 444
 ALBION NE 68620

Bus Phone: (402)395-5000
 Prv Phone:

Make/Model:

JOHN DEERE 2555

Deliver To:

AMERICA'S HOME ENVIRONMENT
 PO BOX 444
 ALBION NE 68620

Bus Phone: (402)395-5000
 Prv Phone:

Invoice Number: **3861774**
 Invoice Date: 05/31/2024
 Location: 27
 Work Order Number: 1056710
 Payment Type: Credit Card
 Authorization Number: 02162P
 Page: 3 of 4

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 2555		L02555T728781	LL02555T728781	

CORRECTION:

No leaking was observed anywhere the tractor was parked. No work was done.

Labor: \$16.50 Parts: \$0.00 OL&M: \$0.00 Svc Acc/Env: \$0.00 Svc Call: \$0.00 Sub-Total: \$16.50

Technicians: T27410

GEN-4 Retail

COMPLAINT:

05 - Oil leak in front axle area

CAUSE:

CORRECTION:

Investigated oil leak in front area of tractor and found leak to be in the front pump. It is a small drip and when customer was advised he opted to wait to repair unless it gets worse.

Labor: \$82.50 Parts: \$0.00 OL&M: \$0.00 Svc Acc/Env: \$0.00 Svc Call: \$0.00 Sub-Total: \$82.50

Technicians: T27410

GEN-5 Retail

COMPLAINT:

07 - Clutch adjustment

CAUSE:

CORRECTION:

No work was done. When driving tractor clutch adjustment and free play was correct.

Miscellaneous Charges:

Service Accessories

\$44.96

CONTINUED ON NEXT PAGE->

