



322 SOUTH BELTLINE HWY EAST  
 SCOTTSBLUFF, NE 69361  
 P: (800) 658-4052  
 F: (308) 632-5634  
 308-632-2911



BILL TO  
 TYLER KULAS - 18026  
 1227 TOLUCA  
 ALLIANCE NE 69301  
 P: (308) 760-4998  
 F:

DELIVER TO  
 TYLER KULAS - 18026  
 1227 Toluca  
 ALLIANCE NE 69301  
 P: (308) 760-4998  
 F:

**SERVICE INVOICE: R101036246:03**


| DATE ARRIVED         | DATE INVOICE | SALES TYPE   | ADVISOR           | TERMS           | CUSTOMER REFERENCE |            |                    |          |
|----------------------|--------------|--------------|-------------------|-----------------|--------------------|------------|--------------------|----------|
| 11/22/2023 3:27:34PM | 2/27/2024    | SRET         | TROYG             | CASH            |                    |            |                    |          |
| YEAR                 | MAKE         | MODEL        | VIN               | CUSTOMER UNIT # | ENGINE HOURS       | IN SERVICE | Component Serial # | ODOMETER |
| 1987                 | KENWORTH     | CONSTRUCTION | 1XKWDB9X1HS340983 |                 | 0                  |            | 7FB71206           | 946792   |

**Sold Operations**

**JOB #56 05**

**MENU ITEMS**

COMPLAINT CAUSE CORRECTION CROSS OVER LINE BOTTOM OF FUEL TANKS--ALSO REPLACE BOTH FUEL SHUT OFF VALVES-  
 - Crossover line/tube on both fuel tanks, both fuel shut off valves, sending unit, filler neck, & equalizer valve.  
 - Technician pulled the truck into the service bay and began by draining the fuel from the drivers side fuel tank. He was then able to unhook the crossover line, tube & brackets. Once lines, tubes & brackets were removed we were able to unbolt and remove the drivers side fuel tank straps which ultimately allowed us to lower the drivers side fuel tank and replace the fuel tank "Shut Off" valve. Before reinstalling the drivers fuel tank we were able to remove the damaged rubber that goes on the straps and replace the rubber on both fuel tank straps for the drivers side. He then reinstalled the drivers side fuel tank.  
 - Once driver side tank repairs were completed and the tank reinstalled, technician was able to transfer the fuel from the passenger side fuel tank into the drivers side fuel tank. While transferring the fuel we discovered that the filler neck is damaged and a portion of the filler neck is located in the bottom of the passenger side fuel tank. He was also able to locate (2) separate fuel level floats that were damaged and at the bottom of the tank. Technician was able to fish out both of the fuel level floats but in order to remove the fuel filler neck and replace with new the tank will need to go to a welding/fabrication shop to cut the damaged filler neck from the tank which will also allow us to remove the other portion of the filler neck. - Technician then continued with the crossover tube replacement but encountered the crossover line is seized in the tube. At this time tech will inquire about a crossover line & tube assembly. Once new crossover line/tube assembly arrived we were able to modify the support straps and reinstall the new line/tube. Once Tube was replaced we then removed all of the mounting hardware and fuel tank straps in order to drop the fuel tank from the truck & send it to the welding/fabrication shop to make the circular shaped cut in the top of the fuel tank. Once cut is made the welding/Fabrication shop then removed the broken filler neck, installed the new filler neck & rewelded the fuel tank shut. After the fuel tank arrived back to the dealerhsip we were able to reinstall the drivers side fuel tank with a new sending unit, fuel tank rubber for the straps, & an equalizer valve that was located on the bottom side of the drivers fuel tank. Once both tanks were properly installed we verified proper operation with no fuel leaks detected at this time.



**Sold Operations (Cont.)**

| QTY | ITEM                  | DESCRIPTION                        | UNIT PRICE | EXTD PRICE |
|-----|-----------------------|------------------------------------|------------|------------|
|     | LABOR 05-10           | Fuel tank removal and installation |            | 600.00     |
|     | LABOR 05-10           | FUEL TANKS                         |            | 1,200.00   |
| 4   | 101X/RFK161-793-22    | TANK STRAP LINING                  | 70.96      | 283.84     |
| 4   | 101X/RFK161-934-11    | LINING                             | 68.88      | 275.52     |
| 1   | FRT                   | 703003 FREIGHT                     | 120.00     | 120.00     |
| 2   | 101D/PH V590P 8       | VALVE                              | 61.93      | 123.86     |
| 2   | 101D/PH VS48F 10 8    | COUPLING                           | 4.65       | 9.30       |
| 2   | 101D/PH 16826 10 10   | CRIMP                              | 30.50      | 61.00      |
| 9   | 101D/PH 213 10 RL 250 | HOSE-250FT HOSE                    | 17.31      | 155.79     |
| 2   | 101D/PHM 5 46271      | CLAMP RBR CUSH 3 *D                | 1.52       | 3.04       |
| 6   | 101B/D39005           | GR. 8 HX HD CAP SCR 1/4-20X        | 0.28       | 1.68       |
| 6   | 101B/KP66127          | GR. C LOCK NUT 1/4-20              | 0.36       | 2.16       |
| 12  | 101B/36701            | HARDENED FLAT WASHER- 1/4 SAE,     | 0.20       | 2.40       |
| 6   | 101B/BT4L-C0          | BARB TY CABLE TIE, 14.3"L X        | 0.52       | 3.12       |
| 1   | 101X/391PL-P          | FUEL SENDING UNIT                  | 84.15      | 84.15      |
| 1   | F12150                | [WELDING]                          | 218.13     | 218.13     |


Prepay: \$0 Parts: \$1,005.86 Labor: \$1,800.00 Misc: \$120.00 Sublet: \$218.13 \$3,143.99

**JOB #57 05 MENU ITEMS**

**COMPLAINT** 5TH WHEEL ASSY--  
**CAUSE** - 5th Wheel Assembly Replacement.  
**CORRECTION** - Technician began removing the air lines that were connected to the 5th wheel plate, as well as both rear fenders to gain access to the 5th wheel assembly. Technician was required to cut the tail light wires in order to remove the fenders (Will reinstall and splice wires once the fenders get reinstalled - COMPLETED). 5th wheel removal required the technician to cut the current welds that were holding it in place. Once 5th wheel assembly was free from any welds we were able to use the fork lift to raise the old 5th wheel off the back of the truck. He then thoroughly cleaned the mounting surface of any Rust and Debris. Once work area was cleaned and prepped we were able to measure, install, and weld the new support bracket onto the "Cat Walk" of the truck. He then marked all of his mounting points and verified the mounting points were correct and centered properly. Once he verified mounting points were accurate and centered he drilled the holes in order to mount the rails that the 5th wheel sit on. Once rails were mounted and tightened down he was able to raise the new 5th wheel assembly onto the truck. Once 5th wheel was aligned with the rails properly he made "tac" welds in order to hold the 5th wheel into place. Technician then verified the proper fitment before welding the rest of the 5th wheel assembly to the mounting on the frame rail. Once 5th wheel assembly was properly secured he reinstalled the air lines and tested 5th wheel operation. Final step was him cleaning the surface area where weldng and cutting was required before painting both 5th wheel rails & both sides of the frame. After 5th wheel installation was complete he reinstalled the fenders and completed the required tail light wiring repair.

| QTY | ITEM                  | DESCRIPTION                       | UNIT PRICE | EXTD PRICE |
|-----|-----------------------|-----------------------------------|------------|------------|
|     | LABOR 05-10           | INSTALL NEW FIFTH WHEEL ASSEMBLY. |            | 1,500.00   |
|     | LABOR 05-10           | REMOVE FIFTH WHEEL ASSEMBLY       |            | 600.00     |
| 1   | 101D/HLD FW35H024XL00 | FIFTH WHEEL ASSEMBLY *D           | 4,237.83   | 4,237.83   |
| 1   | 101X/AN4414           | 4"x4"x1/4" ANGLE IRON             | 120.71     | 120.71     |
| 2   | 101X/22021            | CUT OFF WHEEL                     | 5.30       | 10.60      |
| 21  | 101B/C39046           | GR. 8 HX FLANGE CS 5/8-11X1-      | 3.56       | 74.76      |
| 13  | 101B/C39070           | GR. G 5/8 FLANGE METAL LOCK       | 1.91       | 24.83      |
| 8   | 101D/23-13861-110     | NUT-HEX,W FLANGE,5/8-11,ZN AL     | 2.61       | 20.88      |
| 2   | 101B/C39049           | GR. 8 HX FLANGE CS 5/8-11X2-      | 4.18       | 8.36       |
| 1   | 101B/MP34274          | NE STYLE NYL INS LOCK NUT 3/      | 0.54       | 0.54       |
| 5   | 101B/23846            | TERM- BOWMA SEAL 16-14 GA. B      | 1.05       | 5.25       |
| 3   | 101B/23847            | 12-10GA BUTT CONNECTOR            | 2.63       | 7.89       |

Prepay: \$0 Parts: \$4,511.65 Labor: \$2,100.00 Misc: \$0 Sublet: \$0 \$6,611.65



Factory Warranty. We do not guarantee that any repairs you request will be covered by your manufacturer warranty. We do not issue your warranty; we are merely a factory-authorized warranty repair facility. We will do our best to determine your warranty coverage prior to the repair, and we will submit to the manufacturer repairs that we believe qualify for manufacturer warranty coverage. But the manufacturer may deny your claim. In the event the manufacturer denies your claim, you are fully responsible for all charges incurred.

Workmanship Warranty Disclaimer. We warranty labor and/or workmanship for 30 days following the completion of repair. No claim will be honored past the stated 30-day period. We expressly disclaim all other warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose. We do not assume nor authorize any other person to assume for it any liability in connection with the sale of the parts or repair. In no event are we liable to you or any third-party for any indirect, special, punitive, incidental, or consequential damage connected to, or arising out of, our work on your vehicle whether the damage arises from breach of contract or tort or whether we have been previously advised of the possibility of such damage. If we are found liable to you for any damage, our damages are limited to the replacement of parts and/or the labor cost of repeating the service.

Acts of God. We are not responsible for damage to your vehicle due to acts of God that occur while your vehicle is in our possession. Acts of God include but are not limited to wind, hail, fire, and flood.

Payment. All charges for repairs, including labor and materials, are due at or before the time we tender the vehicle to you. We may tender the vehicle to you through a phone call, mail, email, or any other means of communication that shows, upon payment, we are returning the vehicle to your custody. If any charges remain unpaid for 30 days past due, we may hire attorneys to help with collection, and you are responsible for paying those attorney's fees. Further, we will charge you interest monthly on all past due amounts at a rate of 16% per annum.

Storage Charge. If you do not take custody of the vehicle within three days after we tender the vehicle to you, we will charge you a storage fee of \$25.00 per day.

Credit Card Surcharge: Our credit card processor will impose a surcharge on credit cards that will not be greater than our cost of acceptance. This surcharge will not reflect on this invoice but will reflect on credit card receipt.


|                 |                    |
|-----------------|--------------------|
| LABOR           | \$3,900.00         |
| PARTS           | \$5,517.51         |
| MISC            | \$120.00           |
| SUBLET          | \$218.13           |
| PREPAY          | \$0.00             |
| <b>SUBTOTAL</b> | <b>\$9,755.64</b>  |
| SHOP SUPPLIES   | \$250.00           |
| MISC SUPPLIES   | \$0.00             |
| TAX             | \$0                |
| <b>TOTAL</b>    | <b>\$10,005.64</b> |

Please Remit Payment to:  
FLOYD'S TRUCK CENTER, INC.  
PO BOX 490  
SCOTTSBLUFF NE 69363-0490  
308-632-2911

Scan to leave a Google Review



AUTHORIZED BY \_\_\_\_\_ DATE \_\_\_\_\_



322 SOUTH BELTLINE HWY EAST  
 SCOTTSBLUFF, NE 69361  
 P: (800) 658-4052  
 F: (308) 632-5634  
 308-632-2911



**BILL TO**  
 TYLER KULAS - 18026  
 1227 TOLUCA  
 ALLIANCE NE 69301  
 P: (308) 760-4998  
 F:

**DELIVER TO**  
 TYLER KULAS - 18026  
 1227 Toluca  
 ALLIANCE NE 69301  
 P: (308) 760-4998  
 F:

**SERVICE INVOICE: R101036246:01**

| DATE ARRIVED         | DATE INVOICE | SALES TYPE | ADVISOR | TERMS | CUSTOMER REFERENCE |
|----------------------|--------------|------------|---------|-------|--------------------|
| 11/22/2023 3:27:34PM | 12/27/2023   | SRET       | TROYG   | CASH  |                    |

| YEAR | MAKE     | MODEL        | VIN               | CUSTOMER UNIT # | ENGINE HOURS | IN SERVICE | Component Serial # | ODOMETER |
|------|----------|--------------|-------------------|-----------------|--------------|------------|--------------------|----------|
| 1987 | KENWORTH | CONSTRUCTION | 1XKWDB9X1HS340983 |                 | 0            |            | 7FB71206           | 946792   |

**Sold Operations**

**JOB #1 02 EXPRESS ASSESSMENT:**

COMPLAINT EXPRESS ASSESSMENT:fan shroud bad shape  
 CAUSE  
 CORRECTION

| QTY  | ITEM        | DESCRIPTION                         | UNIT PRICE | EXTD PRICE |
|--|-------------|-------------------------------------|------------|------------|
|  | LABOR 02-10 | CHECK & ADVISE - EXPRESS ASSESSMENT |            | 105.00     |
| Prepay: \$0 Parts: \$0 Labor: \$105.00 Misc: \$0 Sublet: \$0 |             |                                     |            | \$105.00   |


**JOB #2 05 MENU ITEMS**

COMPLAINT INSPECT PUSHER AXLE--ADVISE  
 CAUSE  
 CORRECTION

| QTY   | ITEM                 | DESCRIPTION                  | UNIT PRICE | EXTD PRICE |
|---|----------------------|------------------------------|------------|------------|
|   | LABOR 05-10          | PUSHER                       |            | 3,390.00   |
| 1   | 101D/ABP N46 R201307 | KING PIN KIT                 | 197.11     | 197.11     |
| 2   | 101D/NA 380001A      | OIL BATH SEAL                | 41.03      | 82.06      |
| 1   | 101D/SBN SET412TRB   | BEARING *D                   | 56.74      | 56.74      |
| 1   | 101D/SBN SET406TRB   | BEARING *D                   | 37.54      | 37.54      |
| 2   | 101D/STM 300 4024    | BULK 340 4024 HUB CAPS *D    | 22.11      | 44.22      |
| 2   | 101D/NA 380001A      | OIL BATH SEAL                | 41.03      | 82.06      |
| 1   | 101B/BD3267          | FLAP WHEEL AO 2X1X1/4 SHANK  | 10.87      | 10.87      |
| 2   | 101B/MP7588          | GREASE FITTING 1/8 PIPE THRD | 1.59       | 3.18       |
| 2   | 101B/MP7604-58       | GREASE FITTING               | 1.92       | 3.84       |
| 2   | 101X/75-210          | 80W-90 QT                    | 14.57      | 29.14      |
| 1   | 101X/MC1308WMF       | RELINE BRAKE SHOES           | 151.93     | 151.93     |
| Prepay: \$0 Parts: \$698.69 Labor: \$3,390.00 Misc: \$0 Sublet: \$0 |                      |                              |            | \$4,088.69 |

**JOB #3 05 MENU ITEMS**

COMPLAINT SERVICE DIFF'S  
 CAUSE  
 CORRECTION



**Sold Operations (Cont.)**

| QTY   | ITEM            | DESCRIPTION             | UNIT PRICE | EXTD PRICE |
|-------|-----------------|-------------------------|------------|------------|
|       | LABOR 05-10     | DIFF'S                  |            | 405.00     |
| 39.58 | 101D/MBL 122046 | BULK/PINT DELVAC 75W-90 | 5.53       | 218.88     |
| 40.12 | 101D/MBL 122046 | BULK/PINT DELVAC 75W-90 | 5.53       | 221.86     |

Prepay: \$0 Parts: \$440.74 Labor: \$405.00 Misc: \$0 Sublet: \$0 \$845.74

**JOB #4 05 MENU ITEMS**

COMPLAINT SERVICE TRANS  
 CAUSE  
 CORRECTION

| QTY   | ITEM            | DESCRIPTION                   | UNIT PRICE | EXTD PRICE |
|-------|-----------------|-------------------------------|------------|------------|
|       | LABOR 05-10     | TRANS                         |            | 120.00     |
| 28.64 | 101D/MBL 122951 | BULK/PINT DELVAC 1 SYN TF 40W | 8.01       | 229.41     |

Prepay: \$0 Parts: \$229.41 Labor: \$120.00 Misc: \$0 Sublet: \$0 \$349.41

**JOB #5 PM SERVICE - PM LABOR RATE ONLY (parts a la carte)**

COMPLAINT SERVICE - PM LABOR RATE ONLY (parts a la carte)  
 CAUSE  
 CORRECTION

| QTY   | ITEM               | DESCRIPTION                   | UNIT PRICE | EXTD PRICE |
|-------|--------------------|-------------------------------|------------|------------|
|       | LABOR PM           | SERVICE - PM LABOR RATE ONLY  |            | 225.00     |
| 1     | 101X/7216          | STARTING FLUID                | 9.36       | 9.36       |
| 35.99 | 101D/SLO 500010048 | OIL, ROT T4 15W-40, CK-4-BULK | 5.05       | 181.75     |

Prepay: \$0 Parts: \$191.11 Labor: \$225.00 Misc: \$0 Sublet: \$0 \$416.11

**JOB #6 95 ADDITIONAL PARTS AND LABOR**

COMPLAINT CHANGE ALL FILTERS  
 CAUSE  
 CORRECTION

| QTY | ITEM               | DESCRIPTION                    | UNIT PRICE | EXTD PRICE |
|-----|--------------------|--------------------------------|------------|------------|
|     | LABOR 01-30        | ALL FILTERS                    |            | 225.00     |
| 1   | 101D/FG FF105      | FILTER *D                      | 12.68      | 12.68      |
| 1   | 101X/3374          | FILTER, FUEL                   | 25.53      | 25.53      |
| 1   | 101D/FG LF691A     | PACKAGE, LUBRICATION FILTER *D | 29.65      | 29.65      |
| 1   | 101D/SLO 550026854 | GADUS GREASE S3-50KG KEG       | 14.48      | 14.48      |
| 2   | 101X/2966          | AIR FILTER                     | 100.52     | 201.04     |

Prepay: \$0 Parts: \$283.38 Labor: \$225.00 Misc: \$0 Sublet: \$0 \$508.38

**JOB #7 05 MENU ITEMS**

COMPLAINT SERVICE AIR DRIER  
 CAUSE  
 CORRECTION



**Sold Operations (Cont.)**

| QTY | ITEM                 | DESCRIPTION                    | UNIT PRICE | EXTD PRICE |
|-----|----------------------|--------------------------------|------------|------------|
|     | LABOR 05-10          | AIR DRIER                      |            | 360.00     |
| 1   | 101D/BW R109685      | AIR DRYER ASM *D               | 223.87     | 223.87     |
| 1   | 101D/BW R109685-CORE | AIR DRYER ASM *D               | 180.00     | 180.00     |
| 1   | 101X/G352100404      | #4 FITTING                     | 15.25      | 15.25      |
| 6   | 101D/PH 213 4 RL 250 | HOSE-REELED,BULK J1402 A1, 4,A | 10.70      | 64.20      |
| 2   | 101D/PH 16826 4 4    | CRIMP FTG WIRE BRAID           | 12.68      | 25.36      |
| 6   | 101B/BT4I-C0         | BARB TY CABLE TIE, 14.3"L X    | 0.52       | 3.12       |
| -1  | 101D/BW R109685-CORE | AIR DRYER ASM *D               | 180.00     | -180.00    |

Prepay: \$0 Parts: \$331.80 Labor: \$360.00 Misc: \$0 Sublet: \$0 \$691.80

**JOB #8 05 MENU ITEMS**

COMPLAINT CHANGE ALL BELTS IF NEEDED  
 CAUSE  
 CORRECTION

| QTY | ITEM           | DESCRIPTION                    | UNIT PRICE | EXTD PRICE |
|-----|----------------|--------------------------------|------------|------------|
|     | LABOR 05-10    | BELTS                          |            | 240.00     |
| 2   | 101D/GT 22572E | V BELT-EXTENDED LIFE,22/32IN X | 26.47      | 52.94      |
| 2   | 101X/259660    | BELT                           | 42.16      | 84.32      |

Prepay: \$0 Parts: \$137.26 Labor: \$240.00 Misc: \$0 Sublet: \$0 \$377.26

**JOB #9 05 MENU ITEMS**

COMPLAINT CHANGE AIR LINES FROM TRUCK TO TRAILER-SMOOTH STYLE  
 CAUSE  
 CORRECTION

| QTY | ITEM                | DESCRIPTION                    | UNIT PRICE | EXTD PRICE |
|-----|---------------------|--------------------------------|------------|------------|
|     | LABOR 05-10         | AIR LINES                      |            | 660.00     |
| 1   | 101D/ABP N42APGCH   | POGO STICK - 40IN -CHROME/W 3- | 45.74      | 45.74      |
| 1   | 101D/ABP N42AAPL12T | 3IN1 AIRPOWER LN-12FT W/RD&BLU | 181.21     | 181.21     |
| 2   | 101D/PHM 12 012 100 | RUBBER GLADHAND SEAL, BLACK    | 0.51       | 1.02       |

Prepay: \$0 Parts: \$227.97 Labor: \$660.00 Misc: \$0 Sublet: \$0 \$887.97

**JOB #10 05 MENU ITEMS**

COMPLAINT TAG AXLE WONT BUILD AIR PRESSURE TO TRAILER WHEN TAG DOWN  
 CAUSE  
 CORRECTION

| QTY | ITEM        | DESCRIPTION | UNIT PRICE | EXTD PRICE |
|-----|-------------|-------------|------------|------------|
|     | LABOR 05-10 | TAG         |            | 30.00      |
| 1   | F15791      | POMP'S TIRE | 998.97     | 998.97     |

Prepay: \$0 Parts: \$0 Labor: \$30.00 Misc: \$0 Sublet: \$998.97 \$1,028.97

**JOB #11 05 MENU ITEMS**

COMPLAINT CHECK ALL LIGHTS-REPLACE MISC MILGHTS MISSING  
 CAUSE  
 CORRECTION



**Sold Operations (Cont.)**

| QTY | ITEM               | DESCRIPTION                    | UNIT PRICE | EXTD PRICE |
|-----|--------------------|--------------------------------|------------|------------|
|     | LABOR 05-10        | LIGHTS                         |            | 1,800.00   |
| 1   | 101D/PLC H4651C1   | HALOGEN SEALED HIGH BEAM       | 11.08      | 11.08      |
| 1   | 101D/GRO 44530     | FLASHER-12 LAMP MAX,2 TERMI *D | 11.29      | 11.29      |
| 1   | 101D/A06-47956-001 | LAMP-MARKER,LED,SQUARE         | 132.83     | 132.83     |
| 2   | 101B/71417M        | SNAP PLUG 16-14GA .180MALE     | 1.24       | 2.48       |
| 2   | 101B/71417F        | SEAL PLG RECP 16-14GA .180FEM  | 1.67       | 3.34       |
| 2   | 101X/FUSE          | FUSE                           | 1.76       | 3.52       |
| 1   | 101X/577.59003     | TURN SIGNAL KW                 | 125.84     | 125.84     |
| 1   | FRT                | 703003 FREIGHT                 | 30.00      | 30.00      |
| 3   | 101B/14GA          | 14 GA WIRE ALL COLORS          | 0.58       | 1.74       |

Prepay: \$0 Parts: \$292.12 Labor: \$1,800.00 Misc: \$30.00 Sublet: \$0 \$2,122.12

**JOB #15 ASR ADDITIONAL SERVICE REQUEST**

COMPLAINT 1st drive axle driver side brake chamber had a hole  
 CAUSE  
 CORRECTION

| QTY | ITEM                | DESCRIPTION                   | UNIT PRICE | EXTD PRICE |
|-----|---------------------|-------------------------------|------------|------------|
|     | LABOR 05-21         | BRAKE CHAMBER                 |            | 375.00     |
| 2   | 101D/HDX 16632      | HOSE AIR 3/8 I.D. *D          | 10.18      | 20.36      |
| 1   | 101D/PH VS2214P 6 6 | COUPLING                      | 3.92       | 3.92       |
| 1   | 101D/HDX SC30       | CHAMBER-T30,2.50 STR,10.34 *D | 42.27      | 42.27      |
| 1   | 101X/59235          | HI-TEMP THREAD SEALANT        | 24.78      | 24.78      |

Prepay: \$0 Parts: \$91.33 Labor: \$375.00 Misc: \$0 Sublet: \$0 \$466.33

**JOB #16 ASR ADDITIONAL SERVICE REQUEST**

COMPLAINT wiper sprayer hanging off on driver side  
 CAUSE  
 CORRECTION

| QTY | ITEM              | DESCRIPTION               | UNIT PRICE | EXTD PRICE |
|-----|-------------------|---------------------------|------------|------------|
|     | LABOR 54-10       | WASHER SPRAYER            |            | 615.00     |
| 1   | 101X/575.1041     | KW WASHER RESIV(K114-20)  | 107.92     | 107.92     |
| 1   | FRT               | 703003 FREIGHT            | 35.00      | 35.00      |
| 1   | 101D/SPR GW 138 L | NOZZLE                    | 5.80       | 5.80       |
| 1   | 101X/WASHERFLUID  | WASHER FLUID WITH DEICER  | 5.67       | 5.67       |
| 1   | 101X/H450         | 3/32 HOSE                 | 8.45       | 8.45       |
| 2   | 101D/ABP N82 WN13 | NARROW WINTER WIPER BLADE | 10.09      | 20.18      |

Prepay: \$0 Parts: \$148.02 Labor: \$615.00 Misc: \$35.00 Sublet: \$0 \$798.02


**JOB #18 05 MENU ITEMS**

COMPLAINT ADJUST CLUTCH  
 CAUSE  
 CORRECTION

| QTY | ITEM        | DESCRIPTION | UNIT PRICE | EXTD PRICE |
|-----|-------------|-------------|------------|------------|
|     | LABOR 05-10 | CLUTCH      |            | 90.00      |

Prepay: \$0 Parts: \$0 Labor: \$90.00 Misc: \$0 Sublet: \$0 \$90.00

**JOB #19 05 MENU ITEMS**



**Sold Operations (Cont.)**

COMPLAINT INSPECT FRONT END WANDERS  
 CAUSE  
 CORRECTION

| QTY  | ITEM        | DESCRIPTION | UNIT PRICE | EXTD PRICE |
|--|-------------|-------------|------------|------------|
|  | LABOR 05-10 | FRONT END   |            | 150.00     |
| Prepay: \$0 Parts: \$0 Labor: \$150.00 Misc: \$0 Sublet: \$0 |             |             |            | \$150.00   |

**JOB #23 ASR ADDITIONAL SERVICE REQUEST**

COMPLAINT drag link is bad  
 CAUSE  
 CORRECTION

| QTY   | ITEM           | DESCRIPTION       | UNIT PRICE | EXTD PRICE |
|---|----------------|-------------------|------------|------------|
|   | LABOR 05-11    | drag link         |            | 135.00     |
|   | LABOR 05-11    | DRAG LINK INSTALL |            | 150.00     |
| 1   | 101X/463.DS994 | DRAG LINK         | 271.62     | 271.62     |
| 1   | FRT            | 703003 FREIGHT    | 45.00      | 45.00      |
| Prepay: \$0 Parts: \$271.62 Labor: \$285.00 Misc: \$45.00 Sublet: \$0 |                |                   |            | \$601.62   |

**JOB #24 ASR ADDITIONAL SERVICE REQUEST**

COMPLAINT both king pins are bad  
 CAUSE  
 CORRECTION

| QTY   | ITEM          | DESCRIPTION                  | UNIT PRICE | EXTD PRICE |
|---|---------------|------------------------------|------------|------------|
|   | LABOR ALIGN/2 | KING PINS                    |            | 1,710.00   |
| 1   | 101X/K931L    | QWIK PIN KIT                 | 518.26     | 518.26     |
| 1   | ft            | 703003 FREIGHT               | 65.00      | 65.00      |
| 4   | 101B/MP7577   | GREASE FITTING 1/8 PIPE THRD | 1.42       | 5.68       |
| 1   | 101B/MP39614  | GR. 8 HEX NUT 7/16-20        | 0.68       | 0.68       |
| Prepay: \$0 Parts: \$524.62 Labor: \$1,710.00 Misc: \$65.00 Sublet: \$0 |               |                              |            | \$2,299.62 |

**JOB #25 ASR ADDITIONAL SERVICE REQUEST**

COMPLAINT the left bump stop is bent and needs adjusted  
 CAUSE  
 CORRECTION

| QTY  | ITEM        | DESCRIPTION | UNIT PRICE | EXTD PRICE |
|--|-------------|-------------|------------|------------|
|  | LABOR 05-09 | BUMPER STOP |            | 110.00     |
| Prepay: \$0 Parts: \$0 Labor: \$110.00 Misc: \$0 Sublet: \$0 |             |             |            | \$110.00   |

**JOB #32 ASR ADDITIONAL SERVICE REQUEST**

COMPLAINT #1 and #2 u joints are bad  
 CAUSE  
 CORRECTION

| QTY   | ITEM           | DESCRIPTION                 | UNIT PRICE | EXTD PRICE |
|---|----------------|-----------------------------|------------|------------|
|   | LABOR 41-30    | bad u joints #1 and #2      |            | 690.00     |
| 2   | 101D/SP 5 280X | U - JOINT *D                | 63.43      | 126.86     |
| 1   | 101B/BD3267    | FLAP WHEEL AO 2X1X1/4 SHANK | 10.87      | 10.87      |
| Prepay: \$0 Parts: \$137.73 Labor: \$690.00 Misc: \$0 Sublet: \$0 |                |                             |            | \$827.73   |





**Sold Operations (Cont.)**

**JOB #33 ASR ADDITIONAL SERVICE REQUEST**

CLAIM NUMBER#

COMPLAINT pusher axle needs brake shoes

CAUSE

CORRECTION

| QTY | ITEM | DESCRIPTION | UNIT PRICE | EXTD PRICE |
|-----|------|-------------|------------|------------|
|     |      |             |            |            |

Prepay: Parts: Labor: Misc: Sublet:

**JOB #34 ASR ADDITIONAL SERVICE REQUEST**

COMPLAINT right hub cap needs replaced on tag axle

CAUSE

CORRECTION

| QTY | ITEM | DESCRIPTION | UNIT PRICE | EXTD PRICE |
|-----|------|-------------|------------|------------|
|     |      |             |            |            |

Prepay: Parts: Labor: Misc: Sublet:

**JOB #37 ASR ADDITIONAL SERVICE REQUEST**

COMPLAINT passenger side #2 axle brake pod line is cracked real bad also

CAUSE

CORRECTION

| QTY | ITEM        | DESCRIPTION     | UNIT PRICE | EXTD PRICE |
|-----|-------------|-----------------|------------|------------|
|     | LABOR 42-30 | REPAIR - BRAKES |            | 120.00     |

Prepay: \$0 Parts: \$0 Labor: \$120.00 Misc: \$0 Sublet: \$0 \$120.00

**JOB #38 05 MENU ITEMS**

COMPLAINT CHECK JAKES--CAT--3406B--

CAUSE

CORRECTION

| QTY | ITEM        | DESCRIPTION | UNIT PRICE | EXTD PRICE |
|-----|-------------|-------------|------------|------------|
|     | LABOR 05-10 | JAKES       |            | 195.00     |

Prepay: \$0 Parts: \$0 Labor: \$195.00 Misc: \$0 Sublet: \$0 \$195.00

**JOB #39 05 MENU ITEMS**

COMPLAINT TEST BLOCK HEATER

CAUSE

CORRECTION


| QTY | ITEM        | DESCRIPTION  | UNIT PRICE | EXTD PRICE |
|-----|-------------|--------------|------------|------------|
|     | LABOR 05-10 | BLOCK HEATER |            | 30.00      |

Prepay: \$0 Parts: \$0 Labor: \$30.00 Misc: \$0 Sublet: \$0 \$30.00

**JOB #40 05-10 ALIGNMENT/ 3 AXLE**

COMPLAINT ALIGNMENT/ 3 AXLE

CAUSE



**Sold Operations (Cont.)**

**CORRECTION**

| QTY  | ITEM          | DESCRIPTION                  | UNIT PRICE | EXTD PRICE |
|--|---------------|------------------------------|------------|------------|
|  | LABOR 05-10   | ALIGNMENT/ 3 AXLE            |            | 800.00     |
| 4  | 101B/C39070   | GR. G 5/8 FLANGE METAL LOCK  | 1.91       | 7.64       |
| 4  | 101X/EM821291 | +5/8-11X6 J429 GR. 8 HX BOLT | 4.73       | 18.92      |
| Prepay: \$0 Parts: \$26.56 Labor: \$800.00 Misc: \$0 Sublet: \$0 |               |                              |            | \$826.56   |

**JOB #41 05-09 ALIGNMENT/ STEER AXLE**

COMPLAINT ALIGNMENT/ TAG AXLE  
 CAUSE  
 CORRECTION

| QTY  | ITEM        | DESCRIPTION           | UNIT PRICE | EXTD PRICE |
|--|-------------|-----------------------|------------|------------|
|  | LABOR 05-09 | ALIGNMENT/ STEER AXLE |            | 200.00     |
| Prepay: \$0 Parts: \$0 Labor: \$200.00 Misc: \$0 Sublet: \$0 |             |                       |            | \$200.00   |

**JOB #42 05-36 MISC REPAIR (BELTS, HOSE, BOLTS ECT.)**

COMPLAINT GLADHANDS AND ELECTRICAL PLUG DAMAGED ON TEST DRIVE.  
 CAUSE  
 CORRECTION

| QTY   | ITEM        | DESCRIPTION                   | UNIT PRICE | EXTD PRICE |
|---|-------------|-------------------------------|------------|------------|
|   | LABOR 05-36 | REPAIR MISC(BELTS,HOSES,ECT.) |            | 52.00      |
| Prepay: \$0 Parts: \$0 Labor: \$52.00 Misc: \$0 Sublet: \$0 |             |                               |            | \$52.00    |

**JOB #45 ASR ADDITIONAL SERVICE REQUEST**

COMPLAINT air leaks in dash  
 CAUSE  
 CORRECTION

| QTY  | ITEM               | DESCRIPTION                    | UNIT PRICE | EXTD PRICE |
|--|--------------------|--------------------------------|------------|------------|
|  | LABOR 54-10        | AIR LEAKS IN DASH              |            | 375.00     |
| 1  | 101D/PH 209P4 2    | BUSHING 1/2 PIPE               | 1.52       | 1.52       |
| 1  | 101D/FSC 2749 2108 | SWITCH-PRESSURE,NC,73+/-7PSI,2 | 9.22       | 9.22       |
| 1  | FRT                | 703003 FREIGHT                 | 18.00      | 18.00      |
| Prepay: \$0 Parts: \$10.74 Labor: \$375.00 Misc: \$18.00 Sublet: \$0 |                    |                                |            | \$403.74   |

**JOB #47 05 MENU ITEMS**

COMPLAINT ABS LIGHT--CHASED WIRE TO FIREWALL. WILL LOOK INTO WHILE FIXING AIR LEAK IN DASH--cut cable back and there is power thru the factory breaker. removed added wiring and taped back. extended wire to plug. check operation at 7 way and its still all good. pulled unit out and parked. turned in key to desk  
 CAUSE  
 CORRECTION

| QTY   | ITEM        | DESCRIPTION | UNIT PRICE | EXTD PRICE |
|---|-------------|-------------|------------|------------|
|   | LABOR 05-10 | ABS         |            | 143.00     |
| 1   | 101X/12GA   | WIRE        | 0.39       | 0.39       |
| Prepay: \$0 Parts: \$0.39 Labor: \$143.00 Misc: \$0 Sublet: \$0 |             |             |            | \$143.39   |



SERVICE INVOICE: R101036246:01

ESTIMATE: E101022592

Factory Warranty. We do not guarantee that any repairs you request will be covered by your manufacturer warranty. We do not issue your warranty; we are merely a factory-authorized warranty repair facility. We will do our best to determine your warranty coverage prior to the repair, and we will submit to the manufacturer repairs that we believe qualify for manufacturer warranty coverage. But the manufacturer may deny your claim. In the event the manufacturer denies your claim, you are fully responsible for all charges incurred.

Workmanship Warranty Disclaimer. We warranty labor and/or workmanship for 30 days following the completion of repair. No claim will be honored past the stated 30-day period. We expressly disclaim all other warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose. We do not assume nor authorize any other person to assume for it any liability in connection with the sale of the parts or repair. In no event are we liable to you or any third-party for any indirect, special, punitive, incidental, or consequential damage connected to, or arising out of, our work on your vehicle whether the damage arises from breach of contract or tort or whether we have been previously advised of the possibility of such damage. If we are found liable to you for any damage, our damages are limited to the replacement of parts and/or the labor cost of repeating the service.

Acts of God. We are not responsible for damage to your vehicle due to acts of God that occur while your vehicle is in our possession. Acts of God include but are not limited to wind, hail, fire, and flood.

Payment. All charges for repairs, including labor and materials, are due at or before the time we tender the vehicle to you. We may tender the vehicle to you through a phone call, mail, email, or any other means of communication that shows, upon payment, we are returning the vehicle to your custody. If any charges remain unpaid for 30 days past due, we may hire attorneys to help with collection, and you are responsible for paying those attorney's fees. Further, we will charge you interest monthly on all past due amounts at a rate of 18% per annum.

Storage Charge. If you do not take custody of the vehicle within three days after we tender the vehicle to you, we will charge you a storage fee of \$25.00 per day.

Credit Card Surcharge: Our credit card processor will impose a surcharge on credit cards that will not be greater than our cost of acceptance. This surcharge will not reflect on this invoice but will reflect on credit card receipt.


|                 |                    |
|-----------------|--------------------|
| LABOR           | \$13,500.00        |
| PARTS           | \$4,043.49         |
| MISC            | \$193.00           |
| SUBLET          | \$998.97           |
| PREPAY          | \$0.00             |
| <b>SUBTOTAL</b> | <b>\$18,735.46</b> |
| SHOP SUPPLIES   | \$500.00           |
| MISC SUPPLIES   | \$0.00             |
| TAX             | \$0                |
| <b>TOTAL</b>    | <b>\$19,235.46</b> |

Please Remit Payment to:  
FLOYD'S TRUCK CENTER, INC.  
PO BOX 490  
SCOTTSBLUFF NE 69363-0490  
308-632-2911

Scan to leave a Google Review



AUTHORIZED BY \_\_\_\_\_ DATE \_\_\_\_\_



322 SOUTH BELTLINE HWY EAST  
 SCOTTSBLUFF, NE 69361  
 P: (800) 658-4052  
 F: (308) 632-5634  
 308-632-2911



BILL TO  
 TYLER KULAS - 18026  
 1227 TOLUCA  
 ALLIANCE NE 69301  
 P: (308) 760-4998  
 F:

DELIVER TO  
 TYLER KULAS - 18026  
 1227 Toluca  
 ALLIANCE NE 69301  
 P: (308) 760-4998  
 F:

**SERVICE INVOICE: R101036246:02**

| DATE ARRIVED         | DATE INVOICE | SALES TYPE   | ADVISOR           | TERMS           | CUSTOMER REFERENCE |            |                    |          |
|----------------------|--------------|--------------|-------------------|-----------------|--------------------|------------|--------------------|----------|
| 11/22/2023 3:27:34PM | 1/30/2024    | SRET         | TROYG             | CASH            |                    |            |                    |          |
| YEAR                 | MAKE         | MODEL        | VIN               | CUSTOMER UNIT # | ENGINE HOURS       | IN SERVICE | Component Serial # | ODOMETER |
| 1987                 | KENWORTH     | CONSTRUCTION | 1XKWDB9X1HS340983 |                 | 0                  |            | 7FB71206           | 946792   |

**Sold Operations**

**JOB #46 ASR ADDITIONAL SERVICE REQUEST**

COMPLAINT air leak at pass wiper motor suspected cracked motor housing-unhooked the air lines to the passenger side wiper motor. unbolted wiper arm, unbolted wiper motor mounting bracket and removed motor from the bracket. installed new fittings into the new wiper motor. bolted motor up to the mounting bracket. hooked up the wiper arm to the wiper motor and bolted up the bracket. hooked up the air lines. made sure the wiper motor worked and no air was coming from the air lines or fittings

CAUSE  
 CORRECTION

| QTY | ITEM               | DESCRIPTION                  | UNIT PRICE | EXTD PRICE |
|-----|--------------------|------------------------------|------------|------------|
|     | LABOR 54-10        | PASS WIPER AIR LEAK          |            | 315.00     |
| 1   | FRT                | 703003 FREIGHT               | 89.00      | 89.00      |
| 1   | 101X/GS18536R      | WIPER MOTOR RH               | 918.96     | 918.96     |
| 2   | 101D/PH VS68NTA4 2 | COUPLING-NON-SOLDERED JOINTS | 1.76       | 3.52       |

Prepay: \$0 Parts: \$922.48 Labor: \$315.00 Misc: \$89.00 Sublet: \$0 \$1,326.48

**JOB #47 05 MENU ITEMS**

COMPLAINT LIFT AXLE WONT GO ALL THE WAY DOWN-found both f the lower air bags leaking between the lower mounting bracket and the air bag lower bracket. need to replace both air bag assemblies.

CAUSE  
 CORRECTION

| QTY | ITEM                 | DESCRIPTION                    | UNIT PRICE | EXTD PRICE |
|-----|----------------------|--------------------------------|------------|------------|
|     | LABOR 05-10          | LIFT AXLE                      |            | 105.00     |
| 1   | 101D/23-09446-300    | SCREW-CAP,HEX3/4-10X3          | 6.69       | 6.69       |
| 4   | 101D/23-09446-400    | SCREW-CAP,HEX,3/4-10,4 IN,GR8, | 6.89       | 27.56      |
| 8   | 101B/36708           | HARDENED FLAT WASHER           | 1.24       | 9.92       |
| 4   | 101B/KP66134         | GR. C LOCK NUT 3/4-10          | 2.65       | 10.60      |
| 4   | 101B/D39054          | GR.8HXCAPSCREW3/8-16X1         | 0.54       | 2.16       |
| 4   | 101B/39729           | BOWMALLOY LOCK WASHER 1/2      | 0.38       | 1.52       |
| 2   | 101D/FI W01 358 8033 | AIR SPRING                     | 222.02     | 444.04     |

Prepay: \$0 Parts: \$502.49 Labor: \$105.00 Misc: \$0 Sublet: \$0 \$607.49

**JOB #48 05 MENU ITEMS**



**Sold Operations (Cont.)**

**COMPLAINT** LIFT AXLE SHOCKS--installed new air bags. hooked up the air lines to the bags and checked for air leaks. bolted up the outer shock mounting brackets. found the shock bracket on the tie rod not aligned correctly. aligned the mounting bracket on the tie rod. installed tag axle re-centering shocks

**CAUSE**  
**CORRECTION**

| QTY | ITEM           | DESCRIPTION                | UNIT PRICE | EXTD PRICE |
|-----|----------------|----------------------------|------------|------------|
|     | LABOR 05-10    | LIFT AXLE SHOCKS           |            | 675.00     |
| 2   | 101D/MAE 66502 | SHOCK ABSORBER, STABILIZER | 81.93      | 163.86     |
| 2   | 101B/39618     | GR. 8 HEX NUT 3/4-16       | 1.90       | 3.80       |

Prepay: \$0 Parts: \$167.66 Labor: \$675.00 Misc: \$0 Sublet: \$0 \$842.66

**JOB #50 05 MENU ITEMS**

**COMPLAINT** DASH LIGHTS DONT WORK--found the connector going to the tach light broke. spliced wire and the light worked. found one of the bulb assemblies missing for the psi gauge. made sure it had power and ground. installed new light bulb assembly and the light worked. the other air psi gauge just needed the connections cleaned and the lights worked.checked for power to the lights in the dash and there was no power. put power to one of the lights to make sure it worked. found the dimmer switch and found that it has some bad spots in it. have parts looking into a new dash light dimmer switch. checked to see if all dash lights were working and found the tach lights not working and a couple of the air psi gauges lights not working.

**CAUSE**  
**CORRECTION**

| QTY | ITEM               | DESCRIPTION                  | UNIT PRICE | EXTD PRICE |
|-----|--------------------|------------------------------|------------|------------|
|     | LABOR 05-10        | DASH LIGHTS                  |            | 480.00     |
| 1   | 101D/WWS 7821-3440 | TERMINAL                     | 0.53       | 0.53       |
| 3   | 101B/23846         | TERM- BOWMA SEAL 16-14 GA. B | 1.05       | 3.15       |
| 1   | 101X/FUSE          | FUSE                         | 1.76       | 1.76       |
| 1   | 101D/AMA Y101506   | SOCKETBULB                   | 3.94       | 3.94       |

Prepay: \$0 Parts: \$9.38 Labor: \$480.00 Misc: \$0 Sublet: \$0 \$489.38

**JOB #51 05 MENU ITEMS**

**COMPLAINT** BRAKE LIGHTS AND REVERSE LIGHT DONT WORK.removed plug for the brake light. jumped the wires for the brake lights to se if they would come on and the brake lights did not come on.installed the low air psi sensor and hooked the wires up to it. hooked up the wire to the brake light switch. made sure the low air psi light shut off and the brake lights worked.

**CAUSE**  
**CORRECTION**

| QTY | ITEM        | DESCRIPTION  | UNIT PRICE | EXTD PRICE |
|-----|-------------|--------------|------------|------------|
|     | LABOR 05-10 | BRAKE LIGHTS |            | 375.00     |


Prepay: \$0 Parts: \$0 Labor: \$375.00 Misc: \$0 Sublet: \$0 \$375.00

**JOB #52 05 MENU ITEMS**

**COMPLAINT** SHFITER BOOT--unhooked the air lines from the shifter knob. removed knob and the old boot. installed the new boot. secured the knob and hooked up the air lines.

**CAUSE**  
**CORRECTION**

| QTY | ITEM              | DESCRIPTION                 | UNIT PRICE | EXTD PRICE |
|-----|-------------------|-----------------------------|------------|------------|
|     | LABOR 05-10       | SHIFTER BOOT                |            | 315.00     |
| 1   | 101X/RFK042-70-2  | BOOT SHIFTER                | 164.87     | 164.87     |
| 1   | FRT               | 703003 FREIGHT              | 30.00      | 30.00      |
| 6   | 101D/23-13445-707 | SCREW-SEMS 1/2 DOG PT 10-16 | 0.53       | 3.18       |



**Sold Operations (Cont.)**

Prepay: \$0 Parts: \$168.05 Labor: \$315.00 Misc: \$30.00 Sublet: \$0 \$513.05

**JOB #53 05 MENU ITEMS**

**COMPLAINT**

CHANGE CABIN FILTER-POOR AIR FLOW--secured the vent tubes in the dash to the heater housing. ran blower motor and found it only runs at high speed. removed the blower motor resistor and found the resistor bad. removed the air intake tubes from the air filter housings to the turbo. removed the blower motor cover/ housing. found the evaporator partially plugged. tried blowing it out. blew buildup off the blower motor blade. the blower motor turns harder than it should. set blower motor back in place and checked the air flow. still has poor air flow. would recommend replacing the blower motor and blower motor resistor and see how the air flow is after that. if the air flow is still not very good. will need to remove the evaporator to see if the heater core is plugged externally.

**CAUSE**

**CORRECTION**

| QTY | ITEM                | DESCRIPTION                    | UNIT PRICE | EXTD PRICE |
|-----|---------------------|--------------------------------|------------|------------|
|     | LABOR 05-10         | CABIN FILTER-AIR FLOW PROBLEMS |            | 1,590.00   |
| 1   | 101D/ABP N83 321310 | RESISTOR *D                    | 10.18      | 10.18      |
| 1   | 101D/ABP N83 301072 | MOTOR KW 12 VOLT WS *D         | 195.08     | 195.08     |
| 1   | FRT                 | 703003 FREIGHT                 | 30.00      | 30.00      |
| 6   | 101B/-23849-1       | .250 TAB SIZE-16-14 GA FEMAL   | 1.75       | 10.50      |

Prepay: \$0 Parts: \$215.76 Labor: \$1,590.00 Misc: \$30.00 Sublet: \$0 \$1,835.76

**JOB #54 05 MENU ITEMS**

**COMPLAINT**

CHANGE 5TH WHEEL AIR LINE--had to heat the pins of the 5th wheel to get the roll pin out of them. the pins were seized in place. had to heat them up and press them out. removed the 5th wheel and found the bushing bad, the saddles worn out and the plate surfaces worn out. found the fitting had broken off in the 5th wheel lock cylinder. tried to get the fitting out and it is stuck in the air cylinder. noticed a bunch of stuff in the inlet of the air cylinder. blew as much of the junk out of it. put air to the cylinder and found air leaking out the drivers side of the cylinder.

**CAUSE**

**CORRECTION**

| QTY | ITEM                 | DESCRIPTION                    | UNIT PRICE | EXTD PRICE |
|-----|----------------------|--------------------------------|------------|------------|
|     | LABOR 05-10          | 5TH WHEEL                      |            | 705.00     |
| 1   | 101D/HLA XA 11699 B  | AIR CYLINDER IN A BOX *D       | 192.15     | 192.15     |
| 1   | 101D/HLA RK 2500 10  | AIR LINE KIT *D                | 49.94      | 49.94      |
| 1   | 101D/PH VS279NTA 4 4 | AIR BRAKE - NTA 45 ELBOW       | 3.59       | 3.59       |
| 1   | 101D/23-14392-001    | CONN-STR,PTC,.25 MPT TO .25 NT | 3.44       | 3.44       |

Prepay: \$0 Parts: \$249.12 Labor: \$705.00 Misc: \$0 Sublet: \$0 \$954.12

**JOB #55 05 MENU ITEMS**

**COMPLAINT**


ADJUST CLUTCH

**CAUSE**

**CORRECTION**

| QTY | ITEM        | DESCRIPTION   | UNIT PRICE | EXTD PRICE |
|-----|-------------|---------------|------------|------------|
|     | LABOR 05-10 | ADJUST CLUTCH |            | 150.00     |

Prepay: \$0 Parts: \$0 Labor: \$150.00 Misc: \$0 Sublet: \$0 \$150.00



Factory Warranty. We do not guarantee that any repairs you request will be covered by your manufacturer warranty. We do not issue your warranty; we are merely a factory-authorized warranty repair facility. We will do our best to determine your warranty coverage prior to the repair, and we will submit to the manufacturer repairs that we believe qualify for manufacturer warranty coverage. But the manufacturer may deny your claim. In the event the manufacturer denies your claim, you are fully responsible for all charges incurred.

Workmanship Warranty: Disclaimer. We warranty labor and/or workmanship for 30 days following the completion of repair. No claim will be honored past the stated 30-day period. We expressly disclaim all other warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose. We do not assume nor authorize any other person to assume for it any liability in connection with the sale of the parts or repair. In no event are we liable to you or any third-party for any indirect, special, punitive, incidental, or consequential damage connected to, or arising out of, our work on your vehicle whether the damage arises from breach of contract or tort or whether we have been previously advised of the possibility of such damage. If we are found liable to you for any damage, our damages are limited to the replacement of parts and/or the labor cost of repeating the service.

Acts of God. We are not responsible for damage to your vehicle due to acts of God that occur while your vehicle is in our possession. Acts of God include but are not limited to wind, hail, fire, and flood.

Payment. All charges for repairs, including labor and materials, are due at or before the time we tender the vehicle to you. We may tender the vehicle to you through a phone call, mail, email, or any other means of communication that shows, upon payment, we are returning the vehicle to your custody. If any charges remain unpaid for 30 days past due, we may hire attorneys to help with collection, and you are responsible for paying those attorney's fees. Further, we will charge you interest monthly on all past due amounts at a rate of 16% per annum.

Storage Charge. If you do not take custody of the vehicle within three days after we tender the vehicle to you, we will charge you a storage fee of \$25.00 per day.

Credit Card Surcharge: Our credit card processor will impose a surcharge on credit cards that will not be greater than our cost of acceptance. This surcharge will not reflect on this invoice but will reflect on credit card receipt.

|                 |                   |
|-----------------|-------------------|
| LABOR           | \$4,710.00        |
| PARTS           | \$2,234.94        |
| MISC            | \$149.00          |
| SUBLET          | \$0.00            |
| PREPAY          | \$0.00            |
| <b>SUBTOTAL</b> | <b>\$7,093.94</b> |
| SHOP SUPPLIES   | \$500.00          |
| MISC SUPPLIES   | \$0.00            |
| TAX             | \$0               |
| <b>TOTAL</b>    | <b>\$7,593.94</b> |

Please Remit Payment to:  
FLOYD'S TRUCK CENTER, INC.  
PO BOX 490  
SCOTTSBLUFF NE 69363-0490  
308-632-2911

Scan to leave a Google Review



AUTHORIZED BY \_\_\_\_\_ DATE \_\_\_\_\_