Thomgaars

604 S Hwy 385 Chadron, NE 69337 308-432-3242

Manager D REGULAR SALE

INV NO 50484240

BATTERY, W/EXCHANGE 104.99 tx Reg Prc 124.99 Sale Prc 104.99 656489359025 CORE EXCHANGE FEE vetured 9/20 26.00 nt -047771 BATTERY, W/EXCHANGE 104.99 tx Reg Prc 124.99 Sale Prc 104.99 656489359025 CORE EXCHANGE FEE 26.00 nt -047771-SUBTOTAL 261.98 7.5% SALES TAX 7.5% 15.75 TOTAL 277.73 M/C xxxxxxxxxxxx7220

035736 CTROUTD: 23432 Result: APPROVED

Card entry mode: Chip Read

AID: A0000000042203

Debit ARC: 00

TVR: 8000088000

TSI: 6800

Mode: ISSUER CVM: NONE

You Saved \$40.00

THANK YOU FOR SHOPPING BOMGAARS! MON - FRT 7:30 AM - 8 PM

SATURDAY SUNDAY

7:30 AM - 8 PM

277.73

9 AM - 6 PM RETAIN RECEIPT FOR RETURN OR EXCHANGE. COMPLETE POLICY POSTED AT STORE.

0005000102994030620

0050 001

50 2994 03/06/20 17:02:20

Exempt X

Chuck's Repair Service

4233 600th RD

Hay Springs, NE 69347

Phone: Shop (308)638-7635

Home (308)638-4587

nessary material and grant permission to operate equipment

mechanic's lien is acknowledged to secure the amount of repairs.

for the purposes of testing and inspection. An express

X

Date Paid: 3/24/20

Check #

Date: 4/24/20

Marilyn Kutschara

4234 600th RD

Hay Springs

NE 69347

Phone # 308-638-7534

luan	Part#	Description	Price Each	Price	Year		
9	1-01-4161	Starter 9130	382.27	382.27	Model	9130	
					Hours, Odometer		
					ser#		
		k			Mechanic	Chuck	
					Job Discription		
					9130 - Replace starter		
- 1							
- 1		(8)			B 2		
- 1		199					
- 1		4.					
- 1							
1							
- 1					18		
- 1				-			
							201
		'					
		- "			Labor cost		\$60.0
		1 2	1		Outside Labor		
-					Guisius Bubs.		
l		1.77					
					The state of the s		
			1				40.
							04
					Ou	tside Labor	Cost
					J To	otal Labor	\$60.00
			Total Parts	\$382.27		otal Parts	\$382.27
			iotai i aits	700			•
	1	i the chave read	air work to he	done with	the	Freight	
he	reby auth	norize the above repa	scion to one	S GOILE WILL	uic.	Milage	

Scanned with CamScanner

Sales Tax

Total | \$442.27

Misc

Exempt X

Chuck's Repair Service

4233 600th RD

Hay Springs, NE 69347

Phone: Shop (308)638-7635

Home (308)638-4587

Date Paid: 8/30/18

0/18 Check #

Date: 8/29/18

Hyle Kutschara

4234 600th RD

Hay Springs

NE 69347

Phone # 308-638-7534

Qua	n Part#	Description	Price Each	Price	Year
4	2-3792T1	Seal Kit	28.00	112.00	Model 9130 Case
3	50-2388T1	Seal Kit	61.00	183.00	Hours, Odometer 9447
3	A48959	Spring	8.70	26.10	ser#
3	A48960	Spring	21.00	63.00	Mechanic Chuck
3	86511345	O-Ring	0.67	2.01	Job Discription
3	D71056	Ring	12.00	36.00	Rebuild all 3 remote hydraulic valves and
3	167269	O-Ring	0.71	2.13	test system.
3	138-1816	Pin	3.80	11.40	
3	19711R1	Pin	2.00	6.00	Replace 1 small hydraulic hose.
1	50-2582T1	Seal Kit	48.43	48.43	
1	Hyd. Hose	Made Up	26.45	26.45	
1	1/2" PT	Breather Vent	15.66	15.66	
					Labor cost \$540.00 Outside Labor Outside Labor Cost

Total Parts \$532.18

I hereby authorize the above repair work to be done with the nessary material and grant permission to operate equipment for the purposes of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.

>	(

Total Labor \$540.00

Total Parts \$532.18

Freight \$35.29

Milage

Misc Sales Tax Total \$1107.47

Date: 7/30/12

Aug12

Taxed Exempt

Chuck's Repair Service

4233 600th RD

Hay Springs, NE 69347

Phone: Shop (308)638-7635

Home (308)638-4587

Date Paid: 8/1/12

Check #

Hyle Kutschara

4234 600th RD

Hay Springs

NE 69347

Phone # 308-638-7534

Qua	n Part#	Description	Price Each	Price	Year
1	6-1451	Belt	25.05	25.05	Model 9130 Case
1	60-5818T4	Drier	72.33	72.33	Hours, Odometer 8215
1	87033212	Valve	66.43	66.43	ser#
1	60-2921T94	Compressor	444.00	444.00	Mechanic Chuck
3	Lb	R134a	16.00	48.00	Job Discription
1	A/C	Oil	16.00	16.00	Replaced A/C compressor, expansion
1	A/C	Flush	86.00	86.00	valve and drier. Flushed system.
				1	
			1		Charged System.
		87			
1					
1					
				i	
				1	
				1	Labor cost \$162.00
			197	1	Labor cost \$162.00
					Outside Labor
			-		1 1 2
		1	15	1	
					Outside Labor Cost
			W.L.		Total Labor \$162.00

Total Parts \$757.81

I hereby authorize the above repair work to be done with the nessary material and grant permission to operate equipment for the purposes of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.

Χ	
^	
`	

	Total Labor	\$162.00
	Total Parts	\$757.81
	Freight	
	Milage	
Misc		
	Sales Tax	
	Total	\$919.81

Exempt

Chuck's Repair Service

4233 600th RD

Hay Springs, NE 69347

Phone: Shop (308)638-7635

Home (308)638-4587

Date Paid: 3/31/09

Check #

Date: 3/11/09

Hyle Kutschara

4234 600th RD

Hay Springs

NE 69347

Phone # 308-638-7534

Quan	Part#	Description	Price Each	Price	Year
1	A78013	Engine Kit	2572.64	2572.64	Model 9130 Case IH
1	A77719	Gask. Kit	147.96	147.96	Hours, Odometer 6962
1	A77808	Seal Kit	83.57	83.57	ser# JCB0001954
1	A77810	Seal Kit	102.35	102.35	Mechanic Chuck
12	J928870	Bolt	10.11	121.32	Job Discription
12	J934864	Nut	3.81	45.72	Rebuild engine - New pistons, sleeves,
14	J907233	Bolt	9.55	133.70	brgs, cam and brgs, head and brg bolts, oil
12	J907234	Bolt	8.62	103.44	pump, injectors and rebuilt inj. pump.
14	J906655	Bolt	25.99	363.86	Replaced starter.
1	87339552	PaintKit	53.60	53.60	i i i i i i i i i i i i i i i i i i i
1	J923478	Camshaft	644.80	644.80	Replaced hanger brg. for rear drive shaft.
12	J931623	Tappet	15.72	188.64	
1	JR948071	Oil Pump	135.99	135.99	
2	J928639	Therm.	20.75	41.50	
1	196804A1	Heater	67.79	67.79	
1	31-2483	Hose	42.07	42.07	
1	31-2482	Hose	57.49	57.49	
1	J920762	Elbow	14.55	14.55	
1	J286499	Hose	10.49	10.49	
1	86637927	Plug	6.77	6.77	
1	Inj. Pump	Parts	169.04	169.04	
6	Rebuilt	Injectors	58.93	353.58	Labor cost \$2484.00
12	140-8122	Valve Guide	5.06	60.72	, T. 10 1.00
	72-65045	Starter	323.52	323.52	Outside Labor
	J945329	Cam Brg.	8.86	62.02	Inj. Pump Labor - 741.00 Radiator Repair - 339.00
6	J913990	Bushings	25.57	153.42	Machine Shop - 1243.00
	J906694	O-Ring	1.19	1.19	
27	J906695	O-Ring	0.72	0.72	
	14457880	O-Ring	1.52	3.04	
	86357	filter	10.38	10.38	Outside Labor Cost \$2323.00
1	86358	Filter	8.53	8.53	

Total Parts \$6131.91

I hereby authorize the above repair work to be done with the nessary material and grant permission to operate equipment for the purposes of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.

X		
<u></u>	 	 _

	Total Labor	\$4807.00
	Total Parts	\$6131.91
	Freight	\$139.00
	Milage	
Misc	Ţ.	
	Sales Tax	
	Total	\$11077.91

Exempt

Chuck's Repair Service

4233 600th RD

Hay Springs, NE 69347

Phone: Shop (308)638-7635 Home (308)638-4587 Date Paid: 9/10/08

Check #

Date: 8/26/08

Hyle Kutschara

4234 600th RD

Hay Springs

NE 69347

Phone # 308-638-7534

Quan	Part#	Description	Price Each	Price	Year
1	103807A1R	Alt.	160.00	160.00	Model 9130 Case
10	Gal.	80-90 Gear Lube	12.00	120.00	Hours, Odometer 6813
1	hyd. Hoses	Made Up	51.60	51.60	ser#
1	16-1568	Nut	88.23	88.23	Mechanic Chuck
2	33-1267T1	shim	5.99	11.98	Job Discription
	22-1279T1	shim	4.12	8.24	Rebuild rear differential. Pinion Brgs. were
	24903750	Brg.	240.09	240.09	bad. Replaced pinion brgs and side carrier
1	16-1523	Brg.	116.42	116.42	brgs.
1	33-1178T1	Seal	90.39	90.39	
1	33-1179T1	Brg.	235.11	235.11	
1	33-1216T1	Brg.	217.66	217.66	
1	91082R91	Brg.	89.55	89.55	
1	33-1005T1	U-Joint	214.34	214.34	
2	ZPX51550	Gask. Maker	13.44	26.88	
				,	Labor cost \$648.00
			1		Outside Labor
				~ '	
		3			Outside Labor Cost
					Total Labor \$648.00

Total Parts \$1670.49

I hereby authorize the above repair work to be done with the nessary material and grant permission to operate equipment for the purposes of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.

~	
X	

Total Labor \$648.00

Total Parts \$1670.49

Freight \$78.25

Milage

Misc

Sales Tax

Total \$2396.74

Exempt

Chuck's Repair Service

4233 600th RD Hay Springs, NE 69347

Phone: Shop (308)638-7635

Home (308)638-4587

Date Paid: 4/27/07

Check #

Apr7

Hyle Kutschara

HC 70 Box 44

Hay Springs

NE

69347

Date: 4/26/07

Phone # 308-638-7534

					nie# 000 000 1004
Qua		escription	Price Each	Price	Year
18 1 3 1	38571 663557R91 145769C91 518842R1	Diesel Aditive Brg. Seal Cap	14.50 10.84 5.95 6.91	261.00 10.84 17.85 6.91	Model 9130 Case, Misc Hours, Odometer ser#
1 1 2 1 1 1 1 1	T54253 T54252 70-4621T2 70-4662T3 435499A1 2-10T1 A139458 E3NN15330A	Hub spindle Bushing Pin Brg. Retainer Lamp Bulb	84.16 86.76 28.47 108.96 158.74 18.81 12.30 10.54	84.16 86.76 56.94 108.96 158.74 18.81 12.30 10.54	Mechanic Chuck Job Discription Replaced center pivet pin bushings.
					Labor cost \$48.00 Outside Labor Outside Labor Cost Total Labor \$48.00

Total Parts \$833.81

I hereby authorize the above repair work to be done with the nessary material and grant permission to operate equipment for the purposes of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.

Χ	
^	

\$833.81 **Total Parts** \$64.61 Freight Milage Misc Sales Tax Total | \$946.42