



I changed the
~~the~~ Flat Tire yesterday
so its ready to go
That Quinstar
is a 49ft.

7 Section
model
3649

800-888-1380
www.midwestmessenger.com
e-mail: support@midwestmessenger.com

Complete Engine Overhaul
& New Clutch

Sleeves + Piston Set From
Don Diesel Lawrence, ks

New Clutch Plate +
Pressure Plate

New ~~Trarbo~~
Turbo

New Radiator

AC will work but
~~the~~ Bearing in Compressor
Clutch locked up
Needs New Compressor or clutch

CHARGE TO

37101006 3711906708

RUNDUS, JAMES W

James Rundus

441-9742822
Kehlman Implement and
Hardware
Linn, KS No. 271255

For value received the undersigned promises to pay the total amount shown (together with any other charges due there upon) in accordance with the agreement or regulations governing Farm Plan and, if qualifies, hereby certifies that all items, except as indicated hereon, are purchased for use or consumption in connection with the production of horticultural agricultural products as a business enterprise, and agrees to reimburse the seller the sales tax if used or consumed otherwise.

I am authorized to execute this exemption.

W05440

Nov. 2019

RECEIVED BY

1105

QUAN.	DESCRIPTION	UNIT PRICE	AMOUNT
	Owner Furnished Sleeve Set		
	Engine Overhaul		
	Less Piston + Sleeve		
	Set Owner Furnished		
	Parts		310742
			16550
SW	Labor		240950
9914		FED TAX	
1.6474		STATE TAX	568242
<input type="checkbox"/> CD <input type="checkbox"/> FP <input type="checkbox"/> CASH	DATE	AUTHORIZATION NO.	TOTAL
	11-21-19	VH	568242

TC 25

3

Quan.	Part No. or Description	Amount
1	521669 M91 crankshaft	712 67
1	834064 M1 seal	53 95
2	70923645 O-ring .69	1 38
2	520380 M1 gasket 17 ³²	35 26
1	514434 M2 "	25 60
1	19467X exp. plug	7 55
1	70917808 sleeve	2 16
1	516069 M94 hyd filter	66 95
2	528385 M1 ring 15 ³²	30 64
	oden + frt chgs	22 74
3	bolts 3.30	9 90
4	" .35	1 40
2	gal 921 hyd fluid 22 ⁹⁵	45 90
1	SN3306 U-bolt (he took)	8 65
		<hr/>
		1024 75

Kuhlman Implement & Hardware Inc.

N^o. 6638

(785) 348-5547 301 N. Main • Linn, KS 66953

Name James Rundus Date 9-9-24

Address _____ Phone No. _____

MAKE and MODEL MF 1105 tractor SPEEDOMETER READING _____

R+R + rebuild steering
Replace hyd filter

807 50

Steering Sector

overhaul Sept 9, 2024

~~\$~~1832.25

Now Shaft & Seals

Total Labor	807 50
Total Parts	1024 75
Subtotal	
State Tax	
Total Amount	1832 25

Total Parts