



WEST-EQUIP.COM

Now with 21 LOCATIONS TO SERVE YOU!

South Highway 207
Spearman, TX 79081
Phone: (806) 659-2568
Fax: (806) 659-2860

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 256376
Bus Phone:
Prv Phone:

Internal Used Stock No. 256376
Bus Phone:
Prv Phone:

Invoice Number: 4061359
Invoice Date: 11/01/2023
Location: 19
Work Order Number: 693826
Payment Type: Account
Page: 1 of 3

Table with 5 columns: Make/Model, Meter, Serial Number, EQ Id, Fleet No. Row 1: 2018 LANDOLL 1770-40 BLADE PLOW, 17D1800022, 44674GCE

LABOR 2 Internal

COMPLAINT:

03 LABOR - Coultter assembly \$1,219.66 Labor \$145.00 (we can rebuild but labor will have to be adjusted)

CAUSE:

CORRECTION:

Removed coultter
old coultter arm assembly was bent and wouldnt swivel
installed new with new hardware and tightened it
installed disk

Table with 7 columns: PartNumber, Description, Quantity, Net Price, Extended Price, Taxed Ind. Rows include COULTER ASSY 22 STRAIGHT BLADE, Bulk Hardware, and FREIGHT.

LABOR 3 Internal

COMPLAINT:

04 LABOR - Bearings \$60.75 each Labor x 2

CAUSE:

bearings were out on 5 of the pickers sets removed picker assembly's from blade plow and brought them into the shop tried heating them up to see if i could get them broke loose couldn't get them to budge ended having to cut pickers out and bearings they were seized onto the shafts had to cut out pickers on all assembly's

CORRECTION:

removed bolt hardware had to cut them out nuts on bearing brackets were wore and rounded off so couldnt reuse them had to get new hardware for them after cuttin hardware then removed bracket s and cut out bearing from the shaft after cutting them out had to clean up the shaft to get the new bearing installed and bearing bracket and installed new hardware then installed them back onto picker assemblies

Table with 7 columns: PartNumber, Description, Quantity, Net Price, Extended Price, Taxed Ind. Row 1: CONTINUED ON NEXT PAGE->



WEST-EQUIP.COM

Now with 21 LOCATIONS TO SERVE YOU!

South Highway 207
Spearman, TX 79081
Phone: (806) 659-2568
Fax: (806) 659-2860

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 256376
Bus Phone:
Prv Phone:

Internal Used Stock No. 256376
Bus Phone:
Prv Phone:

Invoice Number: 4061359
Invoice Date: 11/01/2023
Location: 19
Work Order Number: 693826
Payment Type: Account
Page: 2 of 3

Table with 4 columns: Make/Model, Meter, Serial Number, EQ Id, Fleet No.
2018 LANDOLL 1770-40 BLADE PLOW, 17D1800022, 44674GCE

Main parts list table with columns: Part Number, Description, Quantity, Net Price, Extended Price, Taxed Ind. Includes items like 1-065-010011, 1-512-010005-09, etc.

Labor: \$2,506.94 Parts: \$1,452.44 OL&M: \$0.00 Misc: \$223.91 Sub-Total: \$4,183.29

LABOR 4 Internal

COMPLAINT:

05 LABOR - RH Picker \$208.14 each x 6

CAUSE:

CORRECTION:

had to clean up threads on shafts and cut pickers out to replace the ones that needed replaced
cleaned up shafts to get all the burrs out from where pickers had to be removed
installed pickers and installed new nuts and roll pins
installed all picker assemblies back into the blade plow
installed hardware and tightened them down

Table with 6 columns: PartNumber, Description, Quantity, Net Price, Extended Price, Taxed Ind. Includes items like 1-647-010004255, 1-647-010004257, etc.

Labor: \$997.08 Parts: \$953.65 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$1,950.73

CONTINUED ON NEXT PAGE->



WEST-EQUIP.COM

Now with 21 LOCATIONS TO SERVE YOU!

South Highway 207 Spearman, TX 79081 Phone: (806) 659-2568 Fax: (806) 659-2860

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 256376
Bus Phone:
Prv Phone:

Internal Used Stock No. 256376
Bus Phone:
Prv Phone:

Invoice Number: 4061359
Invoice Date: 11/01/2023
Location: 19
Work Order Number: 693826
Payment Type: Account
Page: 3 of 3

Table with 4 columns: Make/Model, Meter, Serial Number, EQ Id, Fleet No. Row 1: 2018 LANDOLL 1770-40 BLADE PLOW, 17D1800022, 44674GCE

LABOR 5 Internal

COMPLAINT:

06 LABOR - Grease machine \$194.87 w/ labor

CAUSE:

CORRECTION:

greased machine at all grease points implement looked like it hadn't been greased in a while. Remove grease zerks and soaked them to get them to take grease

Table with 7 columns: PartNumber, Description, Quantity, Net Price, Extended Price, Taxed Ind, Labor, Parts, OL&M, Misc, Sub-Total. Row 1: TY6341, SD PLYUREA GREASE, 5.00, \$6.81, \$34.05, N. Summary row: Labor: \$612.49, Parts: \$34.05, OL&M: \$0.00, Misc: \$0.00, Sub-Total: \$646.54

Customer PO No:
Tax Exempt No:
Advisor: [Redacted]

Summary table: Labor: \$4,273.19, Parts: \$3,668.77, OL&M: \$0.00, Misc: \$399.91, Sales Tax: \$0.00, Total: \$8,341.87

TERMS AND CONDITIONS

Received by: .....

Date: .....