



BTI Bucklin
 94 SE 30 Road
 Great Bend, KS 67530
 (800) 817-9921
 (620) 793-3500

BTI Bucklin (800) 334-4823 (620) 826-3271
 BTI Greensburg (888) 723-3331 (620) 723-3331
 BTI Ness City (800) 572-2251 (785) 798-2410
 BTI Pratt (800) 573-5606 (620) 672-5606
 BTI Hoxie (844) 688-4362 (785) 675-8207
 BTI Great Bend (800) 817-9921 (620) 793-3500



SERVICE INVOICE

Invoice To Account No: 16803

Deliver To:

| | | |
|---|---|-------------------------------|
| VINCENT FREES 430 8TH RD BUSHTON KS 67427 | VINCENT FREES 430 8TH RD BUSHTON KS 67427 | Invoice Number: 548988 |
| Bus Phone: 620-562-3236 | Bus Phone: (620)562-3236 | Invoice Date: 12/23/2020 |
| Prv Phone: | Prv Phone: | Location: 7 |
| | | Work Order Number: 90372 |
| | | Payment Type: Finance |
| | | Page: 1 of 6 |

| | | | | |
|------------------|--------|-------------------|----------|-----------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 6175R | 2106 | 1RW6175RCGA025372 | GA025372 | |

ALL/9001/CAB/590 Retail

CORRECTION:

TECH NAME: MIKE F.

TRACTOR CAB - JOHN DEERE INSPECTION

| Miscellaneous | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|------------------------|---------------------------------|-------------------------|-------------------------|--------------------------|----------------|-----------|
| ROLLBACK7 | SVC ROLLBACK INSPECTION DISC/GB | 1.00 | 0.00 | -625.00 | (\$625.00) | N |
| Labor: \$625.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: (\$625.00) | Sub-Total: \$0.00 | | |

GEN-02 Retail

CORRECTION:

REMOVED THE OLD WHEEL ANGLE SENSOR AND TRIED TO STRAIGHTEN IT. COULD NOT GET IT STRAIGHT SO I INSTALLED A NEW ONE OVER THE WIRING HARNESS.

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-----------------------|----------------------|-------------------------|---------------------|---------------------------|----------------|-----------|
| L215329 | Guard | 1.00 | 9.94 | 9.94 | \$9.94 | N |
| Labor: \$12.50 | Parts: \$9.94 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$22.44 | | |

GEN-03 Retail

CORRECTION:

REMOVED THE SHIELDS AROUND THE BATTERIES AND THE LOADER VALVE. REMOVED THE LEAKING LOADER PRESSURE HOSE, AND REPLACED WITH A NEW HOSE. INSTALLED THE SHIELDS AND THE STEPS. WASHED-OFF OIL MESS AND RUN TO MAKE-SURE NOTHING ELSE WAS LEAKING.

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|------------------------|------------------------|-------------------------|---------------------|----------------------------|----------------|-----------|
| 19M7784 | SCREW | 1.00 | 1.27 | 1.27 | \$1.27 | N |
| 19M7865 | SCREW | 1.00 | 0.99 | 0.99 | \$0.99 | N |
| AL212706 | Hydraulic Hose | 1.00 | 131.37 | 131.37 | \$131.37 | N |
| T77858 | O-RING | 2.00 | 1.87 | 1.87 | \$3.74 | N |
| Labor: \$187.50 | Parts: \$137.37 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$324.87 | | |



BTI Bucklin
 94 SE 30 Road
 Great Bend, KS 67530
 (800) 817-9921
 (620) 793-3500

BTI Bucklin (800) 334-4823 (620) 826-3271
 BTI Greensburg (888) 723-3331 (620) 723-3331
 BTI Ness City (800) 572-2251 (785) 798-2410
 BTI Pratt (800) 573-5606 (620) 672-5606
 BTI Hoxie (844) 688-4362 (785) 675-8207
 BTI Great Bend (800) 817-9921 (620) 793-3500



Invoice To Account No: 16803

Deliver To:

SERVICE INVOICE

| | | |
|---|---|-------------------------------|
| VINCENT FREES 430 8TH RD BUSHTON KS 67427 | VINCENT FREES 430 8TH RD BUSHTON KS 67427 | Invoice Number: 548988 |
| Bus Phone: 620-562-3236 | Bus Phone: (620)562-3236 | Invoice Date: 12/23/2020 |
| Prv Phone: | Prv Phone: | Location: 7 |
| | | Work Order Number: 90372 |
| | | Payment Type: Finance |
| | | Page: 2 of 6 |

| | | | | |
|------------------|--------|-------------------|----------|-----------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 6175R | 2106 | 1RW6175RCGA025372 | GA025372 | |

GEN-04 Retail

CORRECTION:

REMOVED THE LEFT HAND TAIL LIGHT ASSEMBLY AND FOUND THE HOUSING WAS FULL OF WATER AND HAD THE BULB CONNECTIONS SHORTED OUT, ORDERED A NEW TAIL LIGHT ASSEMBLY AND INSTALLED, AND THE TAIL, BRAKE AND TURN SIGNAL WORKED. REMOVED THE LEFT FRONT HEADLIGHT AND FOUND THE RUBBER SEAL THAT HELD THE DIRT OUT WAS TORN. SO I ORDERED A NEW LIGHT ASSEMBLY AND INSTALLED IN THE HOOD AND FRONT GRILL AND MADE SURE IT WORKED.

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|------------------------|----------------|------------------------|------------|-------------------------|----------------------|----------------------------|
| 37M7181 | Screw | 1.00 | 0.59 | 0.59 | \$0.59 | N |
| AL206154 | Headlight | 1.00 | 230.15 | 230.15 | \$230.15 | N |
| AL215076 | Tail Lamp | 1.00 | 49.34 | 49.34 | \$49.34 | N |
| L223037 | Filter Housing | 1.00 | 48.35 | 48.35 | \$48.35 | N |
| Miscellaneous 37501 | FREIGHT | 1.00 | 12.12 | 12.12 | \$12.12 | N |
| Labor: \$551.25 | | Parts: \$328.43 | | OL&M: \$0.00 | Misc: \$12.12 | Sub-Total: \$891.80 |

GEN-05 Retail

CORRECTION:

REMOVED AND REPLACED #1 AND #3 RIGHT HAND COUPLERS AND REPLACED ALL OF THE HOSE TIP O-RINGS.

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|------------------------|----------------------------|------------------------|------------|-------------------------|---------------------|----------------------------|
| AL205022 | Seal Kit | 1.00 | 26.35 | 26.35 | \$26.35 | N |
| AL213391 | Hydr. Quick Coupler Socket | 2.00 | 98.66 | 98.66 | \$197.32 | N |
| Labor: \$131.25 | | Parts: \$223.67 | | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$354.92 |

GEN-06 Retail

CORRECTION:

TRACED DOWN THE RPT 2818.31 OPERATOR PRESENT SYSTEM CODE. FOUND THAT THE WIRES TO THE SEAT SWITCH WERE CUT UNDER THE SEAT. ORDERED A NEW HARNESS AND INSTALLED AND INSTALLED THE SEAT CUSHION, AND CHECKED TO MAKE SURE IT CODE DID NOT COME BACK.

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-------------|-------------|----------|------------|-----------|----------------|-----------|
|-------------|-------------|----------|------------|-----------|----------------|-----------|



BTI Bucklin
 94 SE 30 Road
 Great Bend, KS 67530
 (800) 817-9921
 (620) 793-3500

BTI Bucklin (800) 334-4823 (620) 826-3271
 BTI Greensburg (888) 723-3331 (620) 723-3331
 BTI Ness City (800) 572-2251 (785) 798-2410
 BTI Pratt (800) 573-5606 (620) 672-5606
 BTI Hoxie (844) 688-4362 (785) 675-8207
 BTI Great Bend (800) 817-9921 (620) 793-3500



SERVICE INVOICE

Invoice To Account No: 16803

Deliver To:

| | | |
|--|---|---|
| VINCENT FREES 430 8TH RD BUSHTON KS 67427 Bus Phone: 620-562-3236 Prv Phone: | VINCENT FREES 430 8TH RD BUSHTON KS 67427 Bus Phone: (620)562-3236 Prv Phone: | Invoice Number: 548988 Invoice Date: 12/23/2020 Location: 7 Work Order Number: 90372 Payment Type: Finance Page: 3 of 6 |
|--|---|---|

| | | | | |
|------------------|--------|-------------------|----------|-----------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 6175R | 2106 | 1RW6175RCGA025372 | GA025372 | |

GEN-06 Retail
RE310923

Wiring Harness

1.00 189.45 189.45 \$189.45 N

Miscellaneous
37501

Description
FREIGHT

Quantity List Price Net Price Extended Price Taxed Ind
1.00 20.85 20.85 \$20.85 N

Comments: Freight for part RE310923

Labor: \$137.50 Parts: \$189.45 OL&M: \$0.00 Misc: \$20.85 Sub-Total: \$347.80

GEN-07 Retail

CORRECTION:
CHANGED THE ENGINE OIL AND FILTER.

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-------------|---------------------------------|----------|------------|-----------|----------------|-----------|
| RE529554 | FILLER CAP | 1.00 | 17.09 | 17.09 | \$17.09 | N |
| RE539279 | OIL FILTER | 1.00 | 19.79 | 19.79 | \$19.79 | N |
| TY26682 | 15W-40 PLUS 50 SHOP BULK QUARTS | 26.00 | 3.99 | 3.99 | \$103.74 | N |

Labor: \$137.50 Parts: \$140.62 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$278.12

6175R/1261/FLTR/10 Retail

CORRECTION:
REMOVE & INSTALL FUEL FILTERS

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-------------|-------------|----------|------------|-----------|----------------|-----------|
| RE556406 | FILTER KIT | 1.00 | 97.87 | 97.87 | \$97.87 | N |

Labor: \$121.88 Parts: \$97.87 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$219.75

GEN-09 Retail

CORRECTION:
CHANGED THE HYDRAULIC AND THE TRANSMISSION OILS AND FILTERS.

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-------------|----------------|----------|------------|-----------|----------------|-----------|
| AL203341 | Filter Element | 1.00 | 84.80 | 84.80 | \$84.80 | N |



BTI Bucklin
 94 SE 30 Road
 Great Bend, KS 67530
 (800) 817-9921
 (620) 793-3500

BTI Bucklin (800) 334-4823 (620) 826-3271
 BTI Greensburg (888) 723-3331 (620) 723-3331
 BTI Ness City (800) 572-2251 (785) 798-2410
 BTI Pratt (800) 573-5606 (620) 672-5606
 BTI Hoxie (844) 688-4362 (785) 675-8207
 BTI Great Bend (800) 817-9921 (620) 793-3500



SERVICE INVOICE

Invoice To Account No: 16803

Deliver To:

| | | |
|--|---|---|
| VINCENT FREES 430 8TH RD BUSHTON KS 67427 Bus Phone: 620-562-3236 Prv Phone: | VINCENT FREES 430 8TH RD BUSHTON KS 67427 Bus Phone: (620)562-3236 Prv Phone: | Invoice Number: 548988 Invoice Date: 12/23/2020 Location: 7 Work Order Number: 90372 Payment Type: Finance Page: 4 of 6 |
|--|---|---|

| | | | | |
|------------------|--------|-------------------|----------|-----------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 6175R | 2106 | 1RW6175RCGA025372 | GA025372 | |

GEN-09 Retail

| | | | | | | |
|------------------------|---------------------------|------------------------|-------|-------------------------|---------------------|----------------------------|
| AL221066 | OIL FILTER | 1.00 | 41.11 | 41.11 | \$41.11 | N |
| TY22028 | SHOP HY-GARD BY THE QUART | 92.00 | 3.24 | 3.24 | \$298.08 | N |
| Labor: \$312.50 | | Parts: \$423.99 | | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$736.49 |

GEN-10 Retail
 CORRECTION:
 REPLACED BOTH OF THE ENGINE AIR FILTERS AND CLEANED THE DIRT OUT OF THE FILTER HOUSING.

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-----------------------|-------------|------------------------|------------|-------------------------|---------------------|----------------------------|
| AL215053 | AIR FILTER | 1.00 | 107.80 | 107.80 | \$107.80 | N |
| AL215054 | AIR CLEANER | 1.00 | 47.92 | 47.92 | \$47.92 | N |
| Labor: \$68.75 | | Parts: \$155.72 | | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$224.47 |

GEN-11 Retail
 CORRECTION:
 REPLACED THE CAB AIR FILTERS.

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-----------------------|-------------|-----------------------|------------|-------------------------|---------------------|----------------------------|
| AL220527 | Air Filter | 1.00 | 42.64 | 42.64 | \$42.64 | N |
| L214634 | FILTER | 2.00 | 20.05 | 20.05 | \$40.10 | N |
| Labor: \$68.75 | | Parts: \$82.74 | | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$151.49 |

GEN-12 Retail
 CORRECTION:
 THE HYDRAULIC PUMP SUCTION HOSE WAS SEEPING SO I INSTALLED ANOTHER HOSE CLAMP AND TIGHTENED ALL OF THE CLAMPS DOWN.

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-------------|-------------|----------|------------|-----------|----------------|-----------|
|-------------|-------------|----------|------------|-----------|----------------|-----------|



BTI Bucklin
 94 SE 30 Road
 Great Bend, KS 67530
 (800) 817-9921
 (620) 793-3500

BTI Bucklin (800) 334-4823 (620) 826-3271
 BTI Greensburg (888) 723-3331 (620) 723-3331
 BTI Ness City (800) 572-2251 (785) 798-2410
 BTI Pratt (800) 573-5606 (620) 672-5606
 BTI Hoxie (844) 688-4362 (785) 675-8207
 BTI Great Bend (800) 817-9921 (620) 793-3500



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 16803

Deliver To:

| | | |
|--|---|---|
| VINCENT FREES 430 8TH RD BUSHTON KS 67427 Bus Phone: 620-562-3236 Prv Phone: | VINCENT FREES 430 8TH RD BUSHTON KS 67427 Bus Phone: (620)562-3236 Prv Phone: | Invoice Number: 548988 Invoice Date: 12/23/2020 Location: 7 Work Order Number: 90372 Payment Type: Finance Page: 5 of 6 |
|--|---|---|

| | | | | |
|------------------|--------|-------------------|----------|-----------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 6175R | 2106 | 1RW6175RCGA025372 | GA025372 | |

| | | | | | | |
|----------------------------------|------------|-----------------------|-------------------------|---------------------|---------------------------|---|
| GEN-12 Retail AN209299 | Hose Clamp | 1.00 | 10.78 | 10.78 | \$10.78 | N |
| Labor: \$38.75 | | Parts: \$10.78 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$49.53 | |

GEN-13 Retail
 CORRECTION:
 DRAINED THE MFWD HUB OILS AND THE FRONT AXLE OIL. INSTALLED ALL NEW OIL IN THEM.

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|------------------------|---------------------------|-----------------------|-------------------------|---------------------|----------------------------|-----------|
| TY22028 | SHOP HY-GARD BY THE QUART | 16.00 | 3.24 | 3.24 | \$51.84 | N |
| Labor: \$187.50 | | Parts: \$51.84 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$239.34 | |

GEN-14 Retail
 CORRECTION:
 DIAGNOSE & REPAIR AIR RESTRICTION LIGHT
 LOOKED ON D-TAC TO SEE IF I COULD FIND OUT WHY THE ENGINE AIR FILTERS WERE PLUGGING SO FAST. DID NOT SEE ANYTHING ON D-TAC TO HELP BUT AFTER STUDYING THE PARTS PICTURES I FOUND A SEAL MISSING THAT THE HOOD SETS ON IN FRONT ON THE RADIATOR. ORDERED AND INSTALLED AND FOUND THE SEAL ON THE AIR FILTER HOUSING WAS BAD. INSTALLED A NEW DOOR AND TOLD THE CUSTOMER TO TRY THAT AND LET US KNOW.

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|---------------|-------------|----------|------------|-----------|----------------|-----------|
| L218062 | Isolator | 1.00 | 45.68 | 45.68 | \$45.68 | N |
| Miscellaneous | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |



BTI Bucklin
 94 SE 30 Road
 Great Bend, KS 67530
 (800) 817-9921
 (620) 793-3500

BTI Bucklin (800) 334-4823 (620) 826-3271
 BTI Greensburg (888) 723-3331 (620) 723-3331
 BTI Ness City (800) 572-2251 (785) 798-2410
 BTI Pratt (800) 573-5606 (620) 672-5606
 BTI Hoxie (844) 688-4362 (785) 675-8207
 BTI Great Bend (800) 817-9921 (620) 793-3500



JOHN DEERE

Invoice To Account No: 16803

Deliver To:

SERVICE INVOICE

| | | |
|---|---|-------------------------------|
| VINCENT FREES 430 8TH RD BUSHTON KS 67427 | VINCENT FREES 430 8TH RD BUSHTON KS 67427 | Invoice Number: 548988 |
| Bus Phone: 620-562-3236 | Bus Phone: (620)562-3236 | Invoice Date: 12/23/2020 |
| Prv Phone: | Prv Phone: | Location: 7 |
| | | Work Order Number: 90372 |
| | | Payment Type: Finance |
| | | Page: 6 of 6 |

| | | | | |
|------------------|--------|-------------------|----------|-----------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 6175R | 2106 | 1RW6175RCGA025372 | GA025372 | |

| | | | | | | |
|------------------------|---------|------|-------|-------|---------|---|
| GEN-14 Retail 37501 | FREIGHT | 1.00 | 19.40 | 19.40 | \$19.40 | N |
|------------------------|---------|------|-------|-------|---------|---|

Labor: \$363.75 Parts: \$45.68 OL&M: \$0.00 Misc: \$19.40 Sub-Total: \$428.83

Finance Information

| | | | |
|-----------------------------|--|------------------|--------------------------------|
| Customer PO No: | Type: Multi-use Acct US | Auth. No: 256696 | Labor: \$2,944.38 |
| Tax Exempt No: REC'D/PORTAL | Merchant No: 37000371 | | Parts: \$1,898.10 |
| Advisor: TYLER SCHWINDT | Card No: xxxxxxxxxxxx6644 | | OL&M: \$0.00 |
| | Bill Code: 783 - PERFORMAX INSPECTION - TRACTOR | | Misc: (\$572.63) |
| | Credit Plan: 11469 - DEERE AG NO PAYMENTS/NO INTEREST WAIVER UNTIL JULY 1, | | Sales Tax: \$0.00 |
| | | | Grand Total: \$4,269.85 |

*** DOCUMENT COPY ***



TERMS AND CONDITIONS

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

This purchase(s) is subject to the terms of the multi-use account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by: Date: