

# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.SchunemanEquipment.com



JOHN DEERE

SAME AS BELOW

Ship to:

Invoice to:

SCHUT FARMS  
5224 EAST 60TH ST N  
SIOUX FALLS SD 57104

Branch GARRETSON, SD		
Date 12/06/16	Time 16:51:31 (O)	Page 02
Account No. SCHUT011	Phone No. 6052701600	Invoice No. S17098
Ship Via	Purchase Order	
Sales Tax License No.	Federal Exemption No. SDDL 00210214	
Farmplan Number	Salesperson 2BS	

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	COMBINE 9600	3081 1748	H09600X661844		
			SRV ACCESSORIES		17.06
			SUB TOTAL==>		953.30
			4.5 % SD STATE		.77
929442	8649		JDF MULTI-USE		954.07

REMIT TO: JOHN DEERE FINANCIAL  
PO BOX 4450  
CAROL STREAM, IL 60197-4450

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.



# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.SchunemanEquipment.com



JOHN DEERE

SAME AS BELOW

Ship to:

Invoice to:

SCHUT FARMS  
5224 EAST 60TH ST N  
SIOUX FALLS SD 57104

Branch		
GARRETSON, SD		
Date	Time	Page
12/06/16	16:51:31 (O)	01
Account No.	Phone No.	Invoice No.
SCHUT011	6052701600	S17098
Ship Via	Purchase Order	
Sales Tax License No.	Federal Exemption No.	
	SDDL 00210214	
Farmplan Number	Salesperson	
	2BS	

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	COMBINE	3081	H09600X661844		
	9600	1748			

REPAIR# 1 C 42416 N/A 11/15/16 11/16/16

ENGINE FAN BELT BROKE

COMPLAINT:

REPLACE BELTS AND BEARING ON DRIVE SHAFT

ADDITIONAL DESCRIPTION:

Service call to the combine out in the field.  
Customer had taken some of the shaft apart.  
Cut a bearing off a shaft and installed a new one.  
Took some brackets and panels off to get the shaft back in.  
Installed all new belts on it.  
Put everything back together.  
Adjusted the throttle linkage on the tractor quick.

AH118443	DISK	1	81.88	81.88
AH156244	BALL BEARING	1	40.69	40.69
AH96292	IDLER	1	86.49	86.49
HANDLING	HANDLING	1	18.00	18.00
H101813	BELT	1	17.42	17.42
H123918	SPACER	1	6.52	6.52
H146636	BELT	1	13.57	13.57
H80896	BELT	1	11.67	11.67
	PARTS			276.24
	LABOR			525.00
10925	REPAIR TOTAL==>			801.24

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

PARTS	276.24
LABOR	525.00
SERVICE CALL	135.00

CONTINUED ON PAGE 02

# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.SchunemanEquipment.com



JOHN DEERE

SAME AS BELOW

Ship to:

Invoice to:

SCHUT FARMS  
5224 EAST 60TH ST N  
SIOUX FALLS SD 57104

Branch GARRETSON, SD		
Date 06/27/16	Time 17:23:55 (O)	Page 01
Account No. SCHUT011	Phone No. 605 2701600	Invoice No. S15002
Ship Via	Purchase Order	
Sales Tax License No.	Federal Exemption No. SDDL 00210214	
Farmplan Number	Salesperson 2BS	

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	COMBINE 9600	3019 1747	H09600X661844		

REPAIR# 1 C 42409 SACOMBINE 11/27/15 05/19/16

SERVICE ADVANTAGE COMBINE INSPECTION

COMPLAINT:

X

ADDITIONAL DESCRIPTION:

\*\*COMPLETE JOHN DEERE COMBINE INSPECTION\*\*

- CONTROL SYSTEM
- FEEDER HOUSE AREA
- FEED ACCELERATOR (FAST)
- LEFT HAND SIDE
- RIGHT HAND SIDE
- ENGINE COMPARTMENT
- GRAIN TANK SECTION
- CAB SECTION
- AMS

\*\*CLEANING AND DELIVERY HAVE BEEN DISCOUNTED FOR YOU!\*\*

HANDLING	HANDLING	1	10.00	10.00
PROMO-PARTS	PROMO DISCOUNT	1-	58.59	58.59CR
PROMO-SERVICE	PROMO DISCOUNT	1-	301.00	301.00CR
TY26860	SCAN TEST KIT	1	48.59	48.59
	PARTS			301.00CR
	LABOR			800.00
10925	REPAIR TOTAL==>			499.00

REPAIR# 2 C 42409 NA 11/27/15 05/20/16

REPAIRS MADE

Remove conveyor, auger drive belt, shield, and slip clutch.  
Remove cross drive shaft, Replace bearings and lock collars on shaft. Replace both sets of wood block bearings.

CONTINUED ON PAGE 02

# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.SchunemanEquipment.com



JOHN DEERE

Ship to: SAME AS BELOW

Invoice to: SCHUT FARMS  
5224 EAST 60TH ST N  
SIOUX FALLS SD 57104

Branch			
GARRETSON, SD			
Date	Time	Page	
06/27/16	17:23:55 (O)	02	
Account No.	Phone No.	Invoice No.	
SCHUT011	605 2701600	S15002	
Ship Via		Purchase Order	
Sales Tax License No.		Federal Exemption No.	
		SDDL 00210214	
Farmplan Number			Salesperson
			2BS

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	COMBINE	3019	H09600X661844		
	9600	1747			

Replace keys in gears. Replace seven bearings and lock collars on lower conveyor augers. Reassemble and adjust belt tensioner.

Remove cross augers from tank. Cut a liner in half. Cut out liners to fit around clean grain elevator and tack weld in liners.

Weld up crack in right front grain tank support. Cut a patch plate and weld on front of tank where rusted through. Reinstall augers.

Replace bearings and lock collars on left ends of augers. Install sprockets and chain. Adjust chain tensioner.

Replace bulb in grain tank lamp. Replace two bulbs in right amber lamp.

Replace seals on unloading auger tube inspection doors.

Disassemble upper feeder house drive sheaves and inspect. Fill with grease and assemble. Replace dust boot over cylinder.

Replace engine oil and filter. Replace engine air cleaners. Remove rotary screen jackshaft and replace bearings and lock collars.

Replace bearings and lock collars on tailings rotary paddle. Replace upper tailings return auger drive chain and adjust tensioner.

Tighten clean grain elevator paddle chain tighten lower tailings elevator drive chain.

Lube all chains with fluid film.

Drain hyd. res. Remove lower return hose. It was bent over. Check to see if flow was restricted. ok. Reinstall and tighten so is straight.

CHECK ON WHY HYDRO GETS HOT

CONTINUED ON PAGE 03

# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.SchunemanEquipment.com



JOHN DEERE

Ship to: SAME AS BELOW

Invoice to: SCHUT FARMS  
5224 EAST 60TH ST N  
SIOUX FALLS SD 57104

Branch GARRETSON, SD		
Date 06/27/16	Time 17:23:55 (O)	Page 03
Account No. SCHUT011	Phone No. 605 2701600	Invoice No. S15002
Ship Via	Purchase Order	
Sales Tax License No.	Federal Exemption No. SDDL 00210214	
Farmplan Number	Salesperson 2BS	

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	COMBINE 9600	3019 1747	H09600X661844		

Remove reel control valve and disassemble to make sure relief valve isn't stuck.  
Remove filter bypass valve to make sure it isn't stuck.  
Remove inline return check valve and make sure it is not stuck open.  
Refill res. and test drive to see if hyd. oil gets hot. It did. Check hyd. pump stall pressure-good.  
Check to make sure all hyd. functions are shut off-ok.  
Check hydro charge pump pressure-good  
Check hydro pump forward and reverse pressures-good.  
Remove forward and reverse reliefs valves in hydro motor.  
Retest drive to see if hydro oil gets hot. Checked oil temp with heat gun and is good. Check all fluid levels.  
Drain oil in primary countershaft gear case. Had water in it. Install new oil.  
Add antifreeze to radiator.  
Add oil to dual speed cylinder gear case.  
Add oil to transmission.  
Completely grease combine.  
Tighten air conditioning compressor drive belt.

AD2062R	BULB	1	3.19		3.19
AH126007	124L50 CHAIN	1	55.45		55.45
AH129451	BALL BEARING	1	53.10		53.10
AH129452	ECCENTRIC Eccentric Locking Collar	1	10.06		10.06
AH133191	ECCENTRIC Eccentric Locking Collar	2	11.57		23.14
AH140495	BALL BEARING	1	29.55		29.55
AH168093	LINER KIT	1	231.66		231.66

CONTINUED ON PAGE 04

# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.SchunemanEquipment.com



JOHN DEERE

SAME AS BELOW

Ship to:

Invoice to:

SCHUT FARMS  
5224 EAST 60TH ST N  
SIOUX FALLS SD 57104

Branch GARRETSON, SD		
Date 06/27/16	Time 17:23:55 (O)	Page 04
Account No. SCHUT011	Phone No. 605 2701600	Invoice No. S15002
Ship Via	Purchase Order	
Sales Tax License No.	Federal Exemption No. SDDL 00210214	
Farmplan Number	Salesperson 2BS	

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	COMBINE 9600	3019 1747	H09600X661844		
AH214862	BALL BEARING	7	16.96		118.72
AR62407	BULB	1	2.58		2.58
AR70106	ENG AIR FILTER	1	92.24		92.24
AR70107	ENG AIR FILTER	1	45.55		45.55
AZ10044	ECCENTRIC Eccentric Locking Collar	2	7.33		14.66
AZ10045	ECCENTRIC Eccentric Locking Collar	2	8.64		17.28
DZ101880	Filter Kit	1	16.97		16.97
E10018	PRESSED FL Pressed Flanged Housing	1	4.84		4.84
H133384	BULB	1	3.19		3.19
H135475	BEARING	4	4.72		18.88
H161529	PRESSED FL Pressed Flanged Housing	1	4.74		4.74
H167587	KEY	7	2.33		16.31
H203610	BOOT	1	17.48		17.48
H63289	O-RING	1 N	1.45		1.45
H77698	TIE BAND	1	.31		.31
H81330	ISOLATOR	1	13.39		13.39
JD39102	BALL BEARING	2	19.30		38.60
JD39103	BALL BEARING	2	20.57		41.14
JD39104	BALL BEARING	2	35.91		71.82
JD8554	LOCK COLLAR Eccentric Locking Collar	8	2.72		21.76
JD8665	BEARING	1	11.81		11.81
TY22032	FLUID FILM	1	10.69		10.69
TY26625Q	HY-GARD QT	1	2.66		2.66
TY26686Q	15W40+50 II QT	27	3.11		83.97
TY26816Q	80W90 QT	2	7.77		15.54

CONTINUED ON PAGE 05

# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.SchunemanEquipment.com



JOHN DEERE

SAME AS BELOW

Ship to:

Invoice to:

SCHUT FARMS  
5224 EAST 60TH ST N  
SIOUX FALLS SD 57104

Branch GARRETSON, SD		
Date 06/27/16	Time 17:23:55 (O)	Page 05
Account No. SCHUT011	Phone No. 605 2701600	Invoice No. S15002
Ship Via	Purchase Order	
Sales Tax License No.	Federal Exemption No. SDDL 00210214	
Farmplan Number	Salesperson 2BS	

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	COMBINE 9600	3019 1747	H09600X661844		
03M7183	M8 X 16	1	.60		.60
03M7189	M8X45 CAR BOLT	1	1.17		1.17
03M7191	M10X25 CAR BOLT	3	.74		2.22
14M7298	M8 FLA NUT	1	.82		.82
14M7396	M8 LOCK NUT	4	.98		3.92
34H333	ROLL PIN	7	.87		6.09
			PARTS		1107.55
			LABOR		3936.00
10925			REPAIR TOTAL==>		5043.55

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

PARTS	806.55
LABOR	4736.00
SRV ACCESSORIES	70.00
SUB TOTAL==>	5612.55
2% CITY SALES TAX	1.40
4.5 % SD STATE	5.83
JDF MULTI-USE	5619.78

922278 8649

REMIT TO: JOHN DEERE FINANCIAL  
PO BOX 4450  
CAROL STREAM, IL 60197-4450

Customer Disclosure - This form must be signed by the customer to process the Multi-Use Account transaction. The following special terms, as described in the Multi-Use Account credit agreement, apply to the attached invoice. Up to 120 Days No Payments / No Interest Financing followed by the ANNUAL PERCENTAGE RATE (APR) applicable to your Account. This purchase(s) is subject to the terms of the Multi-Use Account, a

CONTINUED ON PAGE 06

# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.SchunemanEquipment.com



JOHN DEERE

SAME AS BELOW

Ship to:

Invoice to:

SCHUT FARMS  
5224 EAST 60TH ST N  
SIOUX FALLS SD 57104

Branch		GARRETSON, SD	
Date	Time	Page	
06/27/16	17:23:55 (O)	06	
Account No.	Phone No.	Invoice No.	
SCHUT011	605 2701600	S15002	
Ship Via		Purchase Order	
Sales Tax License No.		Federal Exemption No.	
		SDDL 00210214	
Farmplan Number		Salesperson	
		2BS	

## SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	COMBINE	3019	H09600X661844	
	9600	1747		

service of John Deere Financial, f.s.b. I grant the issuer the purchase money security interest, except as limited in that agreement, in the goods described.





# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.SchunemanEquipment.com



JOHN DEERE

SAME AS BELOW

Ship to:

Invoice to:

SCHUT FARMS  
5224 EAST 60TH ST N  
SIOUX FALLS, SD 57104

Branch GARRETSON, SD		
Date 02/10/15	Time 11:24:01 (O)	Page 01
Account No. SCHUT011	Phone No. 605 2701600	Invoice No. S13040
Ship Via	Purchase Order	
Sales Tax License No.	Federal Exemption No.	
Farmplan Number	Salesperson PAB	

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	COMBINE 9600	2947 1710	H09600S661844		

REPAIR# 1 C G409 NA 12/18/14 12/18/14

\$499 COMBINE INSPECTION

INSPECTED COMBINE AND MADE LIST OF FINDINGS TO GO OVER WITH CUSTOMER

1. FRONT FEEDER HOUSE FLOOR
2. OIL LEAK ON LEFT HAND SIDE OF FEEDER HOUSE
3. ONE LOWER SHOE GRAIN AUGER BEARING
4. ENGINE OIL PAN LEAKS
5. TOP PIECE OF POLY FLIGHTING ON TANK LOADING AUGER
6. HYDRAULIC PUMP DIRTY - LEAK
7. HYDRAULIC RESERVOIR DIRTY - LEAK
8. HYDRAULIC STACK VALVE LEAK
9. REAR AXLE SPINDLE BUSHINGS
10. ANY FLUIDS OR FILTERS
11. UNLOADING AUGER LIGHT
12. OIL COOLER PUMP GEAR CHAIN - CHECK IF HYDRAULICS STILL OVERHEAT
13. FEEDER HOUSE LATCHING PINS
14. CHOPPER TAILBOARD AND FIN
15. CHAFF SPREADER HOSE LEAKS
16. WASHED AND WAXED COMBINE
17. CLEANED AND DETAILED CAB

10925	LABOR	499.00
	REPAIR TOTAL==>	499.00

REPAIR# 2 C G409 NA 12/18/14 01/10/15

REPAIRS MADE

1. REPLACED ONE LOWER SHOE GRAIN AUGER BEARING AND LOCK COLLAR
2. HEATED UP HANDLE PINS IN FEEDER HOUSE TO HEADER LOCKING

CONTINUED ON PAGE 02

# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.SchunemanEquipment.com



JOHN DEERE

Ship to: SAME AS BELOW

Invoice to: SCHUT FARMS  
5224 EAST 60TH ST N  
SIOUX FALLS, SD 57104

Branch		GARRETSON, SD	
Date	Time	Page	
02/10/15	11:24:01 (O)	02	
Account No.	Phone No.	Invoice No.	
SCHUT011	605 2701600	S13040	
Ship Via		Purchase Order	
Sales Tax License No.		Federal Exemption No.	
Farmplan Number		Salesperson	
		PAB	

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	COMBINE	2947	H09600S661844		
	9600	1710			

- PIN TO GET LOOSE - REMOVED HANDLES, SLIDING LOCKING PINS, AND BROKEN SPRINGS - CLEANED UP PINS AND BLEW OUT HOLES - INSTALLED NEW SPRINGS AND REINSTALLED PINS
3. WELDED UP CRACKS IN CHOPPER TAILBOARD AND INSTALLED MISSING HARDWARE FOR FIN - PAINTED TAILBOARD
  4. REMOVED HYDRAULIC HOSE FROM CHAFF SPREADER FLOW CONTROL VALVE DOWN TO SPREADER MOTOR - HAD NEW HOSE MADE UP AND INSTALLED HOSE AND TIE STRAPPED UP
  5. CHECKED LAMP ON UNLOADING AUGER AND FOUND BULB WAS GOOD - CHECKED WIRING HARNESS AND FOUND A SHORT AT THE TUBE ELBOW - CUT OUT BAD SPOT IN BOTH WIRES AND SODERED THEM BACK TOGETHER AND TESTED LAMP - OK
  6. REMOVED REAR WHEELS, SPINDLES, CROSS TUBE, AND STEERING CYLINDER - REPLACED SPINDLE BUSHINGS IN REAR AXLE AND REASSEMBLED - REPLACED BOOT SEALS ON OUTER CYLINDER TIE ROD ENDS
  7. CHANGED ENGINE OIL AND FILTER
  8. REPLACED ENGINE AIR CLEANERS
  9. REPLACED ENGINE FUEL FILTER - REPLACED WATER/FUEL SEPERATOR FILTER AND BLED OUT FILTERS
  10. REPLACED FRONT FLOOR PLATE IN FEEDER HOUSE
  11. ORDERED PARTS AND MODIFIED TO MAKE A CHAIN RAIL FOR FEEDER HOUSE REVERSER OIL COOLER PUMP CHAIN TO RIDE AGAINST TO KEEP CLOSE TO PUMP DRIVE SPROCKET
  12. DRAINED HYDRAULIC RESERVOIR - REPLACED MAIN AND STEERING HYDRAULIC PUMPS
  13. INSTALLED SOLENOID AND PUPPET SEAL KIT IN HEADER LIFT VALVE
  14. REPLACED THREE HYDRAULIC FILTERS AND INSTALLED NEW OIL IN HYDRAULIC RESERVOIR
  15. REMOVED TANK LOADING AUGER - REPLACED POLY FLIGHTING

CONTINUED ON PAGE 03



25285 485th Ave  
 Garretson, SD 57030  
 Phone: 605-594-3476  
 www.SchunemanEquipment.com



JOHN DEERE

SAME AS BELOW

Ship to:

Invoice to:

SCHUT FARMS  
 5224 EAST 60TH ST N  
 SIOUX FALLS, SD 57104

Branch GARRETSON, SD		
Date 02/10/15	Time 11:24:01 (O)	Page 03
Account No. SCHUT011	Phone No. 605 2701600	Invoice No. S13040
Ship Via	Purchase Order	
Sales Tax License No.	Federal Exemption No.	
Farmplan Number	Salesperson PAB	

**SERVICE INVOICE**

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	COMBINE	2947	H09600S661844		
	9600	1710			

AND REINSTALLED AUGER

16. REPLACED CAB AIR CLEANER AND VACUUMED OUT CANISTER - REMOVED AIR INTAKE DIFFUSER AND CLEANED OUT SINCE IT WAS PLUGGED

17. CHECKED ALL FLUID LEVELS AND ADDED OIL TO CYLINDER GEARCASE

18. REPLACED UNLOADING AUGER DRIVE CHAIN AND ADJUSTED TENSIONER

19. TIGHTENED TAILINGS ELEVATOR PADDLE CHAIN

20. TIGHTENED UPPER TAILINGS RETURN AUGER DRIVE CHAIN

21. TIGHTENED STRAW CHOPPER DRIVE BELT TENSIONER

22. COMPLETELY GREASED COMBINE - GREASED INTERMEDIATE SHEAVE CAM CAVITY - GREASED DRIVESHAFT IN GRAIN TANK U-JOINTS

23. TEST RAN COMBINE AND ALL FUNCTIONS - TRIED TO SEE IF HYDRAULICS WOULD HEAT UP - CUSTOMER SAID TEMPERATURE LIGHT CAME ON DURING HARVEST - UNLOADING AUGER SWING IN AND OUT ALWAYS SHUT OFF HERE - WASHED OUT OIL COOLER AND RADIATOR WHICH WAS DIRTY

24. CHECKED HYDRAULIC STACK VALVE FOR LEAK AFTER TEST RUNNING - OK

AH115833	CAB AIR FILTER	1	62.73	62.73
AH126837	198L60H CHAIN	1	138.64	138.64
AH128449	HYD FILTER	3	56.61	169.83
AH151400	SEAL KIT	1	175.46	175.46
AH214333	HARDWARE KIT	1	5.63	5.63
AH214862	BALL BEARING	1	16.96	16.96
AH227027	HYDRAULIC PUMP	1 N	732.08	732.08
AH227028	HYDRAULIC PUMP	1 N	705.74	705.74
AR70106	ENG AIR FILTER	1	89.12	89.12
AR70107	ENG AIR FILTER	1	44.00	44.00

CONTINUED ON PAGE 04

# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.SchunemanEquipment.com



JOHN DEERE

SAME AS BELOW

Ship to:

Invoice to:

SCHUT FARMS  
5224 EAST 60TH ST N  
SIOUX FALLS, SD 57104

Branch GARRETSON, SD		
Date 02/10/15	Time 11:24:01 (O)	Page 04
Account No. SCHUT011	Phone No. 605 2701600	Invoice No. S13040
Ship Via	Purchase Order	
Sales Tax License No.	Federal Exemption No.	
Farmplan Number	Salesperson PAB	

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	COMBINE	2947	H09600S661844		
	9600	1710			
AR86745	FUEL FILTER	1	22.29		22.29
AT81478	FUEL FILTER	1	29.24		29.24
A4655R	NUT	1	.54		.54
HANDLING	HANDLING	2	11.63		23.25
H144051	WEAR PLATE	1 N	135.00		135.00
H158884	BUSHING	4	15.13		60.52
H172472	SUPPORT	1 N	41.58		41.58
H172475	GUIDE	1 N	15.64		15.64
JD8554	LOCK COLLAR	1	2.72		2.72
M86436	TIE BAND	7	.53		3.71
RE57394	OIL FILTER	1	17.36		17.36
R26375	O-RING	1	2.18		2.18
R26906	O-RING	1	2.56		2.56
R29936	O-RING	1	3.66		3.66
R78027	COVER	2	7.41		14.82
TY22000	1G LOW-VIS HYG	3	19.37		58.11
TY26686Q	15w40 +50II QT	23	3.26		74.98
TY26860	SCAN TEST KIT	1	48.59		48.59
TY6342	5G LV HY-GARD	1	90.12		90.12
TY6344Q	LOW VIS HY	4	5.18		20.72
T76938	O-RING	1	2.13		2.13
T77857	O-RING	1	1.58		1.58
T77858	O-RING	1	1.84		1.84
T77932	O-RING	1	1.72		1.72
U12547	O-RING	1	1.84		1.84
X11343-8-8	FITTING	2	15.15		30.30
X351TC-8-RL	1/2 HOSE-4000PS	140	.40		56.00
03M7184	M8X20 CAR BOLT	7	.54		3.78
124424	SPRING	2	4.22		8.44
14M7396	M8 LOCK NUT	2	.97		1.94
19M7802	M8 X 65	2	2.11		4.22

CONTINUED ON PAGE 05

# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.SchunemanEquipment.com



JOHN DEERE

SAME AS BELOW

Ship to:

Invoice to:

SCHUT FARMS  
5224 EAST 60TH ST N  
SIOUX FALLS, SD 57104

Branch GARRETSON, SD		
Date 02/10/15	Time 11:24:01 (O)	Page 05
Account No. SCHUT011	Phone No. 605 2701600	Invoice No. S13040
Ship Via	Purchase Order	
Sales Tax License No.	Federal Exemption No.	
Farmplan Number	Salesperson PAB	

## SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	2947	H09600S661844		
	1710			
41464		1	44.50	44.50
			PARTS	2966.07
			LABOR	3335.00
10925			REPAIR TOTAL==>	6301.07
***** WORK ORDER TOTALS *****				
			PARTS	2966.07
			LABOR	3834.00
			EPA CHARGE	5.00
			OIL SCAN PROMO	48.59CR
			SERVICE ACCESS	50.00
			SUB TOTAL==>	6806.48
695834	8649	4 % SOUTH DAKOTA ST		4.41
		JDF MULTI-USE		6810.89

Customer Disclosure - This form must be signed by the customer to process the multi-use account transaction. The following special terms, as described in the multi-use account credit agreement, apply to the attached invoice. Up to 150 Days No Payments / No Interest Financing followed by the ANNUAL PERCENTAGE RATE (APR) applicable to your Account. This purchase(s) is subject to the terms of the multi-use account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.schunemanequipment.com



JOHN DEERE

SAME AS BELOW

Ship to:

Invoice to:

SCHUT FARMS  
5224 EAST 60TH N  
SIOUX FALLS, SD 57104

Branch GARRETSON, SD		
Date 02/20/14	Time 14:38:33 (O)	Page 01
Account No. SCHUT011	Phone No. 605 4892109	Invoice No. S11212
Ship Via	Purchase Order	
Sales Tax License No.	Federal Exemption No.	
Farmplan Number	Salesperson 3DP	

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	COMBINE	2883	H09600S661844		
		1672			

REPAIR# 1 C G409 NA 01/23/14 01/24/14

COMBINE INSPECTION \$499

Repairs needed:

Feederhouse shield bracket broke

FH reverser oil pump sprocket does not run close enough to chain

Intermediate drive bushings wore

Concave adjusting problems

Cob stuck in tailings elevator pulley

Servive unit

Rotary screen idler pullies wore

Engine gearcase dipstick broke off

Top panel over radiator cracked

Straw chopper door cracked

Relays in engine compartment

Straw chopper vane bent

Rear axle spindle bushings wore

Hydraulic valve block leaks oil

Raditor door seals

Coolant system needs to be flushed and new coolant

Wash combine

Wax combine

Clean cab windows and cab interior

10925	LABOR	499.00
	REPAIR TOTAL==>	499.00

REPAIR# 2 C G409 NA 01/23/14 01/23/14

REPAIRS MADE

1. Removed lower bracket on front feeder house shield - bracket was broken - welded back together - bent to fit

Dedication. Experience. Trust.

CONTINUED ON PAGE 02

Visit us at [www.schunemanequipment.com](http://www.schunemanequipment.com) for all of your Parts, Service or Sales needs!

# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.schunemanequipment.com



JOHN DEERE

SAME AS BELOW

Ship to:

Invoice to:

SCHUT FARMS  
5224 EAST 60TH N  
SIOUX FALLS, SD 57104

Branch GARRETSON, SD		
Date 02/20/14	Time 14:38:33 (O)	Page 02
Account No. SCHUT011	Phone No. 605 4892109	Invoice No. S11212
Ship Via	Purchase Order	
Sales Tax License No.	Federal Exemption No.	
Farmplan Number	Salesperson 3DP	

## SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	2883	H09600S661844		
COMBINE 9600	1672			

- shield and floor - reinstalled
2. Removed right hand side feeder house drive chain - replaced upper chain guide board and removed reverser oil pump to modify support bracket so pump drive sprocket would run closer to chain - adjusted chain tensioner and reinstalled shields
3. Removed right hand side drive wheels, removed intermediate drive sheave assembly - disassembled and cleaned - replaced inner hub bushings and seals - replaced both cams - assembled and reinstalled on combine - filled cam cavity with grease - installed drive belts and adjusted tensioner - reinstalled both drive wheels and torqued wheel bolts
4. Checked out concave adjusting problem - concave adjusting works but link for concave indicator was broke off - installed new link and retested - ok
5. Removed stuck cob from tailings drive belt pulley
6. Replaced fuel/water separator filter - replaced engine fuel filter and bled filters
7. Replaced engine oil filter
8. Replaced 2 idler pulleys for rotary screen drive belt
9. Replaced engine gear case dipstick - old one was broken
10. Welded up top panel on engine radiator housing - painted over where welded
11. Welded up crack in upper straw chopper door
12. Replaced 2 relays up in engine compartment - replaced 1 circuit breaker - cleaned and tightened all connections
13. Remove right hand side chopper vane - straightened and reinstalled - installed missing hardware
14. Removed rear wheels and spindles - replaced spindle bushings in rear axle - greased spindles and wheel bearings

CONTINUED ON PAGE 03

Visit us at [www.schunemanequipment.com](http://www.schunemanequipment.com) for all of your Parts, Service or Sales needs!

# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.schunemanequipment.com



JOHN DEERE

SAME AS BELOW

Ship to:

Invoice to:

SCHUT FARMS  
5224 EAST 60TH N  
SIOUX FALLS, SD 57104

Branch GARRETSON, SD		
Date 02/20/14	Time 14:38:33 (O)	Page 03
Account No. SCHUT011	Phone No. 605 4892109	Invoice No. S11212
Ship Via	Purchase Order	
Sales Tax License No.	Federal Exemption No.	
Farmplan Number	Salesperson 3DP	

## SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	2883	H09600S661844		
COMBINE	9600			1672

15. Replaced engine air cleaner
16. Replaced O-rings on solenoid valves in all hydraulic blocks on hydraulic stack valve - cleaned up harness connector with contact cleaner
17. Removed old seals from radiator door housing - cleaned up housing - installed new 1 piece seal on housing
18. Tightened clean grain elevator paddle chain
19. Tightened tailings elevator paddle chain
20. Tightened lower tailings elevator drive chain
21. Tightened upper tailings return auger drive chain
22. Tightened unloading auger drive chain
23. Checked all fluid levels - added oil to transmission, added oil to dual speed rasp bar cylinder gear case, added oil to hydraulic reservoir
24. Test ran combine and checked all functions
25. Completely greased combine - greased drive shaft u-joints in tank - greased variable drive sheave cam cavity - worked on combine 2 hours to get started and into shop
26. Drained engine and radiator coolant - flushed with water hose in radiator - ran combine to help flush out dirty coolant - did this in wash bay and again in shop - installed new antifreeze

AH106110	SEAL	2	11.87	23.74
AH112189	CIRCUIT BR	1	18.28	18.28
AH136497	SEAL	1	19.93	19.93
AH140967	ACOUSTICAL	1 S	105.68	105.68
AH145029	219L60 CHAIN	1	128.90	128.90
AH150498	BALL JOINT	1 N	26.85	26.85
AH170157	KIT	1 N	400.70	400.70
AH173464	DIPSTICK	1	75.43	75.43
AN277319	IDLER	1	59.98	59.98

CONTINUED ON PAGE 04

Visit us at [www.schunemanequipment.com](http://www.schunemanequipment.com) for all of your Parts, Service or Sales needs!



# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.schunemanequipment.com



JOHN DEERE

SAME AS BELOW

Ship to:

Invoice to:

SCHUT FARMS  
5224 EAST 60TH N  
SIOUX FALLS, SD 57104

Branch GARRETSON, SD		
Date 02/20/14	Time 14:38:33 (O)	Page 04
Account No. SCHUT011	Phone No. 605 4892109	Invoice No. S11212
Ship Via	Purchase Order	
Sales Tax License No.	Federal Exemption No.	
Farmplan Number	Salesperson 3DP	

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	COMBINE	2883	H09600S661844		
	9600	1672			
AN277320	IDLER	1	39.00		39.00
AR70106	ENG AIR FILTER	1	86.52		86.52
AR73144	RELAY	2	31.06		62.12
AR86745	FUEL FILTER	1	21.64		21.64
AT81478	FUEL FILTER	1	28.39		28.39
HANDLING	HANDLING	1	13.00		13.00
H125528	BUSHING	2	24.03		48.06
H130530	GUIDE	1	48.60		48.60
H158884	BUSHING	4	14.99		59.96
RE57394	OIL FILTER	1	16.85		16.85
SW600LUS	60 1/2 LINK	1	4.87		4.87
TY26577Q	PD ANTI-FREEZE	42	3.81		160.02
TY26686Q	15w40 +50II QT	24	3.26		78.24
TY26860	SCAN TEST KIT	1	48.59		48.59
TY6341	GREASE	4	3.99		15.96
TY6344Q	LOW VIS HY	7	5.18		36.26
T75984	O-RING	9	.99		8.91
U40962	O-RING	9 S	.63		5.67
03M7184	M8X20 CAR BOLT	1	.54		.54
14M7396	M8 LOCK NUT	1	.97		.97
24H1657	WASHER	1	1.20		1.20
80W90GL5	GL5 LUBE	2	5.50		11.00
	PARTS				1655.86
	LABOR				2740.75
10925	REPAIR TOTAL==>				4396.61

Dedication. Experience. Trust. \*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

PARTS 1655.86  
LABOR 2740.75  
EPA CHARGE 5.00

CONTINUED ON PAGE 05

Visit us at [www.schunemanequipment.com](http://www.schunemanequipment.com) for all of your Parts, Service or Sales needs!

# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.schunemanequipment.com



JOHN DEERE

Ship to: SAME AS BELOW

Invoice to: SCHUT FARMS  
5224 EAST 60TH N  
SIOUX FALLS, SD 57104


Branch GARRETSON, SD		
Date 02/20/14	Time 14:38:33 (O)	Page 05
Account No. SCHUT011	Phone No. 605 4892109	Invoice No. S11212
Ship Via	Purchase Order	
Sales Tax License No.	Federal Exemption No.	
Farmplan Number	Salesperson 3DP	

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	COMBINE	2883	H09600S661844		
	9600	1672			
			OIL SCAN PROMO		48.59CR
			SERVICE ACCESS		50.00
668168	8649		JDF MULTI-USE		4902.02

Customer Disclosure - This form must be signed by the customer to process the multi-use account transaction. The following special terms, as described in the multi-use account credit agreement, apply to the attached invoice. 150 Days No Payments and No Interest. Following the deferral period, the ANNUAL PERCENTAGE RATE (APR) applicable to your Account will apply to this purchase.

This purchase(s) is subject to the terms of the multi-use account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.



Dedication. Experience. Trust.

Visit us at [www.schunemanequipment.com](http://www.schunemanequipment.com) for all of your Parts, Service or Sales needs!

# SCHUNEMAN

## EQUIPMENT CO.

25285 485th Ave  
 Garretson, SD 57030  
 Phone: 605-594-3476  
 www.schunemanequipment.com



JOHN DEERE

Ship to: SAME AS BELOW

Invoice to: DALE I SCHUT  
 5224 EAST 60TH N  
 SIOUX FALLS, SD 57104

Branch GARRETSON, SD		
Date 11/11/13	Time 10:58:59 (O)	Page 01
Account No. SCHUT004	Phone No. 605 4892109	Invoice No. S10874
Ship Via		Purchase Order
Sales Tax License No.		Federal Exemption No.
Farmplan Number		Salesperson 3DP

### SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	COMBINE	2854 H09600S661844		
	9600	1618		

REPAIR# 1 C 42415 NA 10/29/13 10/29/13

**REVERSER PULLIES SLIP**

Ran combine and listened for noise  
 Belt was squeaking on variable speed  
 Removed feeder house belt

Variable speed sheaves rotated opposite direction of each other which they should not  
 Replaced variable speed outside sheave and inside hub, replaced bearings and seal, greased variable speed  
 Replaced feeder house belt  
 Readjusted variable speed pulleys and tensioner

Ran combine

Greased variable speed again

Removed wheels on left hand side of combine and removed broken bolts and one bolt broke

Had a hard time removing bolts

Welded nuts on two of them, heated and took out

Had to drill through and heat one other to get out

AH136497	SEAL	1	19.93	19.93
H160869	HALF SHEAV	1 M	561.02	561.02
H97378	HUB	1	198.60	198.60
JD10018	BEARING	2	77.60	155.20
	PARTS			934.75
	LABOR			1091.55
10925	REPAIR TOTAL==>			2026.30

**THIS IS NOT A BILL**  
 This is a copy for your records  
 This invoice has been sent to your  
 JD Financial Multi-Use Account.  
 Please pay JD Financial when you receive  
 your statement from them

Dedication. Experience. Trust.

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

PARTS	934.75
LABOR	1091.55

CONTINUED ON PAGE 02

Visit us at [www.schunemanequipment.com](http://www.schunemanequipment.com) for all of your Parts, Service or Sales needs!

# SCHUNEMAN EQUIPMENT CO.

25285 485th Ave  
Garretson, SD 57030  
Phone: 605-594-3476  
www.schunemanequipment.com



JOHN DEERE

SAME AS BELOW

Ship to:

Invoice to:


DALE I SCHUT  
5224 EAST 60TH N  
SIOUX FALLS, SD 57104

Branch GARRETSON, SD		
Date 11/11/13	Time 10:58:59 (O)	Page 02
Account No. SCHUT004	Phone No. 605 4892109	Invoice No. S10874
Ship Via	Purchase Order	
Sales Tax License No.	Federal Exemption No.	
Farmplan Number	Salesperson 3DP	

## SERVICE INVOICE

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS
B9004825	9600	2854	H09600S661844		
		1618			
			EPA CHARGE		5.00
			SERVICE ACCESS		32.74
			DISCOUNT		405.26CR
309128	8649		JDF MULTI-USE		1658.78

This purchase(s) is subject to the terms of the multi-use account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.



*Dedication. Experience. Trust.*

Visit us at [www.schunemanequipment.com](http://www.schunemanequipment.com) for all of your Parts, Service or Sales needs!