

INTEGRITY * FINANCIAL STRENGTH * QUALITY * TEAMWORK

P O Box 1508, 2701 West Jones Avenue

Garden City, KS 67846 BUS: (620) 276-3275 FAX: (620) 276-2516

Email: kanequip@kanequip.com Website: www.kanequip.com

ELDON ALEXANDER 13990 S SANDHILL RD GARDEN CITY, KS 67846							SANI N CIT	ANDER DHILL RD Y, KS 67846					
Account No. Starting Date		Er	nding Date	P.O. Nur	. Number		Service Tag		Tax ID		Salesperson		
115777	10/9/	2023 12:00 A	M 12	/29/2023 12:00 AM								Mike S	tapleton
Make Mode		Model		Year	Serial	Num	ber		Stock	Number			
NEW HOLLAND BE		BB340		2014	58408	584087009 009217							
Promised	1	Deliver?		Usage Type 1	Usage 1		Usag	e Type 2	Usage 2		Invoice Typ	0	Store
The second second	(Herself)	No		Hours	0.0000				0.0000		Final		GC

Ship To:

SANDHILL RANCH

10/09/2023 WMS

Packer slip clutch

10/9/2023 MO

Sold To:

SANDHILL RANCH

*locate and unhook baler from tractor.

10/23/2023 MO

*get slip clutch information.

*get service truck, go to back lot.

*open shields.

*inspect pick up clutch area.

*pick up clutch hub loose on packer crank/pick up drive shaft.

loosen chain, remove pick up drive sprocket bearing shaft housing.

*remove clutch, splines on packer crank shaft. damaged and sharp where the clutch hub rides. inspected pick up slip clutch hub, splines are stripped out of hub.

*packer crank shaft needs replacement also new hub will be needed for slip clutch.

*reported findings to service manager.

*checked on parts needed.

11/2/2023 MO

*make room in shop.

*download information for removal of the packer crank.

*took extra time to get unit into shop wheels would not lock out making it difficult to steer with forklift. .50 hr

*start removal of pick up.

11/3/2023 MO

*remove chain and sprocket from pick up drive. Un hook sensor.

*remove old slip clutch.

*removed pickup limiting chain.

*removing hardware for pickup. took extra time to remove pin from floatation cylinder, pin was under pressure from weight of pickup and spring pressure and hyd. pressure from floatation cylinder. Drained pressure from cylinder 1.5hr

took extra time to get dollys from south shop, .50 hr.

*used floor jacks to raise pick onto dollys.

*used forklift to raise baler high enough to roll out pick up.

11/4/2023 MO

*had to remove hay material in pre charge chamber to access hardware for guide removal. .50 hr.

began removing pre compression chamber guides rear hardware, and guide alignment rod, some guides were bent making difficult to remove the rod, took extra time .50 hr.

11/13/2023 MO

*remove hardware on front pre charge chamber.

**THANK YOU FOR YOUR BUSINESS **

Parts being returned must be in new, saleable condition and accompanied with this invoice

A restocking fee may apply. View our return policy for complete details.

*Designates Tax Applied to This item

INVOICE: 18W121904-01



5/28/2024 5:04:01 PM



INTEGRITY * FINANCIAL STRENGTH * QUALITY * TEAMWORK

P O Box 1508, 2701 West Jones Avenue

Garden City, KS 67846 BUS: (620) 276-3275 FAX: (620) 276-2516

Email: kanequip@kanequip.com Website: www.kanequip.com

remove front guide bracket, took extra time to remove packed debris from hardware inside baler frame. .50hr.

11/15/2023 MO

*remove rhs crank shaft bearing.

11/16/2023 MO

*remove crank bearing left hand side.

*took extra time to rig straps to support and to lower crank. .75hr

*trimmed bad crank to get out of chamber.

11/17/2023 MO

*un crate packer crank shaft.

*rig straps to install packer crank per service manual.

*clocked new crank in different position to insert will not clear.

11/21/2023 MO

*drill out rivet for harness in order to move frame for clearance.

*un bolt frame for pre charge chamber on left hand side, took extra time to unbolt frame, bolts were rusty and had to remove debris to access, 2.0 hr *install rigging to crank.

*move frame on left side to clear crank and install crank.

*install mounting bearings on crank.

11/22/2023 MO

*remove packer forks from damaged crank, clean up forks.

*shim forks for proper clearance.

11/24/2023 MO

*Shim packer forks. Torque forks.

11/27/2023 MO

*install packer connecting rod links.

11/28/2023 MO

*install guides on rear half of chamber.

*install chamber front frame work. replace broken bolt on frame mount.

*install guide rod.

12/1/2023 MO

*attach font half of pre charge chamber, took extra time to lineup guides because of warpage.

*replaced some damaged hardware.

12/2/2023 MO

*re attach frame hardware and tighten.

*center crank in chamber and guides. lock collars.

*set pickup back on dollys.

*get forklift and lift baler to clear pickup.

*move pick up under frame of baler and line up.

12/4/2023 MO

*install floatation spring/cylinder, took extra time to line up and make connection because of spring tension, 1.5 hr

*connect floatation cylinder hyd line.

*install mounting bearings on pick up, bolt up to baler frame.

*set bearings pre load for pick up pivot bearings.

12/5/2023 MO

*install slip clutch.

*install pick up drive sprocket.

*install speed sensor and adjust sensor.

*install lube lines to packer forks and zip tie them to links.

*install pickup drive chain and adjust.

*install oil lube line for pickup chain.

*move unit out for tractor hookup.

12/20/2023 MO

*finish up.

** THANK YOU FOR YOUR BUSINESS **

Parts being returned must be in new, saleable condition and accompanied with this invoice.

A restacking fee may apply. View our return policy for complete details.

*Designates Tax Applied to This Item

INVOICE: 18W121904-01

5/28/2024 5:04:01 PM



INTEGRITY * FINANCIAL STRENGTH * QUALITY * TEAMWORK

P O Box 1508, 2701 West Jones Avenue Garden City, KS 67846

BUS: (620) 276-3275 FAX: (620) 276-2516

Email: kanequip@kanequip.com Website: www.kanequip.com

2ty	0/0	Taxable	Description	Price	Amount
			47690661 - CLUTCH	\$1115.00	\$1115.00
			84800483 - SHAFT	\$8415.00	\$8415.00
			385424 - BEARING - Bin: F905	\$129.32	\$129.32
			9839342 - SET	\$70.20	\$70.2
			47577177 - BEARING	\$407.88	\$407.8
			853175 - FLANGE	\$26.44	\$52.8
			86620027 - FLANGE - Bin: 4 E 1	\$6.58	\$13.10
			84240146 - BEARING - Bin: F804	\$140.98	\$140.98
!			P2007970 - M12N - Bin: BB2 D 1	\$0.46	\$0.92
			140046 - M12 WSHR - Bin: 3 E26	\$1.43	\$2.8
!			P2007971 - M16N - Bin: BB2 F 1	\$0.72	\$1.4
3			394631 - WASHER - Bin: 3 E42	\$5.31	\$42.4
2			P2008227 - M16X40 - Bin: BB2 4 F	\$3.58	\$7.1
6			140045 - M10 WSHR - Bin: 3 E20	\$0.96	\$5.7
6			9804278 - M10 NUT - Bin: 3 B29	\$3.81	\$22.80
2			444-21 - N.R. MCH	\$1.32	\$2.6
2			444-22 - N.R. MCH	\$2.07	\$4.1
12			923-T50L - NYLON CA	\$0.22	\$2.6
			73344349 - MP GREAS - Bin: LOCKER	\$4.95	\$4.9
		•	Total Labor		\$9338.8
ı			Consumables & Gov Compliance	\$110.00	\$110.00

* * THANK YOU FOR YOUR BUSINESS * *

Parts being returned must be in new, saleable condition and accompanied with this invoice.

A restacking fee may apply. View our return pelicy for complete details.

*Designates Tax Applied to This frem

Invoice: 18W121904-01





P O Box 1508, 2701 West Jones Avenue

Garden City, KS 67846 BUS: (620) 276-3275 FAX: (620) 276-2516

Email: kanequip@kanequip.com Website: www.kanequip.com

Equipment	\$0.00
Labor	\$9338.88
Parts	\$10442.27
Freight	\$0.00
Mileage	\$0.00
Other	\$0.00
Shop Supplies	\$110.00
Total Charges	\$19891.15
Total Tax	\$0.00
Total	\$19891.15
Total Payments	\$0.00
Balance	\$19891.15

SIGNATURE

INVOICE 18W121904



• • THANK YOU FOR YOUR BUSINESS • •

arts being returned must be in new, saleable condition and accompanied with this invoice

A restocking fee may apply. View our return policy for complete details.

*Designates Tax Applied to This Item

Invoice: 18W121904-01



BUS: (620) 276-3275 FAX: (620) 276-2516

Email: kanequip@kanequip.com Website: www.kanequip.com

Sold To: Ship To: SANDHILL RANCH SANDHILL RANCH **ELDON ALEXANDER ELDON ALEXANDER** 13990 S SANDHILL RD 13990 S SANDHILL RD **GARDEN CITY, KS 67846 GARDEN CITY, KS 67846** 620-275-1378

Salesperson Account No. Starting Date P.O. Number Service Tag Tax ID **Ending Date** Timothy 115777 11/24/2023 12:00 AM 1/31/2024 12:00 AM Wideman Stock Number Make Model Serial Number Year 584087009 009217 NEW HOLLAND 2014 Invoice Type Store Promised Deliver? Usage Type 2 Usage 2 Usage Type 1 Usage 1 28811.0000 0.0000 Final GC No Rales

11/24/23 T3

complete approved repairs

12/22/2023 MO

*Got forklift to jack up baler.

*Got service truck to use compressor to air up tire.

"Was not able to seat tire, tire had come off of bead.

*Customer had brought tractor that is used for the baler.

*Had to jump start tractor. Noticed that while tractor as running the tractor had a hyd leak.

1/2/2024 MO

*cleared area in the shop for the baler.

*Went out with jack and blocks removed wheel and had tire repaired at tire shop.

*Reinstalled tire.

*Hook up to tractor. Connected hydraulic hoses and electrical harness.

*Took extra time to connect PTO shaft, because the cv joint all and socket came out of place had to get truck and tools to get it back into place to connect PTO shaft to tractor. .75hr.

Started PTO and ran unit. Stuffer crank had been replaced and has not been run yet. Let unit run at different RPMs and checked bearings and clutch for

Tripped knotters. No misties.

1/11/2024 MO

*Inspect knotters and knotter components.

*Inspect needle area per check list.

*Check VT functions, knotter operation. Check lights.

1/24/2024 MO

*Replaced roller for knotter clutch. Took extra time to get new roller on shaft, had to dress shaft because new roller was catching and not rolling freely.

*Also had to dress new roller so that snap ring would go into place and seat completely. extra time .50hr

*Assemble knotter shield lock components.

"Had to free up stuck latch. extra time .50hr

*Installed rod and adjusted.

Ran unit for QC.

01/30/2024 WMS

NH BB340 #584087009 28811 bales

*Verified repairs

5/28/2024 5:05:24 PM

*Test ran unit with tech. Unit ran smoothly with no issues found. Inspected unit for loose or missing hardware. No Issues found.

0000070

* THANK YOU FOR YOUR BUSINESS * *

Invoice: 18W122021-01

estacking fee may apply. Yiew our return policy for complete details.



BUS: (620) 276-3275 FAX: (620) 276-2516

Email: kanequip@kanequip.com Website: www.kanequip.com

INTEGRITY * FINANCIAL STRENGTH * QUALITY * TEAMWORK

Qty O/O Ta	axable Description	Price	Amount
	8030370 - NULLEN	\$07.5U	UC.10¢
ĺ	47447317 - SHAFT	\$195.04	\$195.04
	84439533 - BALL JOI	\$42.66	\$42.66
	84520548 - BALL JOI	\$32.67	\$32.67
ſ	14496621 - WASHER - Bin: 3 E14	\$0.24	\$0.96
!	325829 - M10X45 - Bin: 2 J31	\$5.68	\$11.36
į.	86588501 - WASHER	\$5.50	\$22.00
1	86512554 - M10 NUT - Bin: 3 C23	\$2.44	\$4.88
200	P2007969 - M10NUT - Bin: BB2 C 1	\$0.28	\$0.28
2	86529981 - NUT	\$2.06	\$4.12
	47447293 - SHAFT	\$228.96	\$228.96
	Total Labor		\$3295.36
1	Consumables & Gov Compliance	\$110.00	\$110.00
1	KANSAS LAND TIRE. TIRE REPAIR.INV#39483	\$90.00	\$90.00
ĺ	Freight IN	\$45.69	\$45.69
1	Freight IN	\$30.83	\$30.83
ı	SERVICE ADVANTAGE 5% LABOR ADJ	-\$164.77	-\$164.77
Payment Type	Deposit Check No. Date Amount	1975	

**THANK YOU FOR YOUR BUSINESS **

Parts being returned must be in new, esteable condition and accempanied with this invoice

A restocking fee may apply. Yiew our return policy for complete details.

*Designater Tax Applied to This Rem

Invoice: 18W122021-01





P O Box 1508, 2701 West Jones Avenue

Garden City, KS 67846 BUS: (620) 276-3275 FAX: (620) 276-2516

Email: kanequip@kanequip.com Website: www.kanequip.com

Equipment	\$0.00			
Labor	\$3295.36			
Parts	\$610.43			
Freight	\$76.52			
Mileage	\$0.00			
Other	-\$74.77			
Shop Supplies	\$110.00			
Total Charges	\$4017.54			
Total Tax	\$0.00			
Total	\$4017.54			
Total Payments	\$0.00			
Balance	\$4017.54			

SIGNATURE

INVOICE 18W122021



* * THANK YOU FOR YOUR BUSINESS * *
Parts being returned must be in new, saleable condition and accempanied with this invoice
A restocking fee may apply. View our return policy for complete details.

*Designates Tax Applied to This Item
INVOICE: 18W122021-01





BUS: (620) 276-3275 FAX: (620) 276-2516

Email: kanequip@kanequip.com Website: www.kanequip.com

Ship To: Sold To: SANDHILL RANCH SANDHILL RANCH **ELDON ALEXANDER ELDON ALEXANDER** 13990 S SANDHILL RD 13990 S SANDHILL RD **GARDEN CITY, KS 67846 GARDEN CITY, KS 67846** 620-275-1378 Salesperson Tax ID Service Tag P.O. Number **Ending Date** Account No. Starting Date Timothy 11/24/2023 12:00 AM 1/31/2024 12:00 AM 115777 Wideman Stock Number Serial Number Year Model Make 009217 2014 584087009 BB340 **NEW HOLLAND** Invoice Type Store Usage 2 Usage Type 2 Deliver? Usage Type 1 Usage 1 **Promised** GC Final 0.0000 28811.0000 Bales 11/24/23 T3 complete inspection flat rate 2.9 hours 12/18/2023 MO *Begin inspection. *Safety equipment and Pick up area. Inspect Stuffer area. 12/21/2023 MO *Inspect gearboxes. *Check timing. *plunger rollers and rails. 1/8/2024 MO *Inspect PTO and Flywheel brake. *Check sensors and harness routing Per inspection sheet. 1/10/2024 MO *remove partial bale. *Check hay dogs and springs. *Check needles and holding fingers and linkage. 1/30/2024 MO *Finish up.

Qty	0/0	Taxable	Description	Price	Amount
		311011111111111111111111111111111111111	Total Labor		\$456.00
1	Consumables & Gov Compliance			\$22.80	\$22.80
1	1 SERVICE ADVANTAGE ADJ			-\$23.80	-\$23.80
Payme	ent Type	A Park	Deposit Check No. Date Amount		

**THANK YOU FOR YOUR BUSINESS **

Parts being returned must be in new, calcable condition and accompanied with this invoice.

A restocking fee may apply. View our return policy for complete details.

*Designates Tax Applied to This Item

[NVOICE: 18W122021-02



5/28/2024 5:05:24 PM



BUS: (620) 276-3275 FAX: (620) 276-2516

Email: kanequip@kanequip.com Website: www.kanequip.com

Equipment	\$0.00
Labor	\$456.00
Parts	\$0.00
Freight	\$0.00
Mileage	\$0.00
Other	\$0.00
Shop Supplies	-\$1.00
Total Charges	\$455.00
Total Tax	\$0.00
Total	\$455.00
Total Payments	\$0.00
Balance	\$455.00

SIGNATURE

INVOICE 18W122021



**THANK YOU FOR YOUR BUSINESS **

arts being returned must be in new, saleable condition and accompanied with this invoice
A restocking fee may apply. View our return policy for complete details.

*Designates Tax Applied to This Item
Invoice: 18W122021-02

