GRAND ISLAND TITAN MACHINERY-GRAND ISLAND 3721 W HWY 2 **GRAND ISLAND NE 68803-1211**



Questions?

Phone: 308-384-0310

Phone: 800-967-1928

Email: AR.GrandIsland@titanmachinery.com

Customer Number:BP0097843

WAYNE STOLTENBERG 4699 W ABBOTT RD GRAND ISLAND NE 68803-9455 WORK SITE: **TITAN MACHINERY-GRAND ISLAND** 3721 W HWY 2 **GRAND ISLAND NE 68803-1211**

Invoice #: SO0038559-1	Service Order #:SO0038559	Invoice Date: 10/26/2023	Due Date: 11/25/2023	
Cust PO: MONITOR		Make: CASE IH	Model: 7088	
Sold By:		Unit: E00123921	Serial #: YBG006872	
Cust Fleet #:		Hours: 2,825.00		
Service Order Summary				

Segment# **Segment Description Segment Total** AGL YIELD MONITORING NOT WORKING \$196.09

> **Payment Information** \$196.09

OPEN A/R

Subtotal \$196.09 Tax \$0.00 Invoice Total \$196.09 Credits Applied \$0.00 Payment Received \$0.00

Balance Amount \$196.09

CUSTOMER ACCEPTANCE

Phone: Cell:

By signing I certify that I am authorized to use this Account, to sign this receipt, and that I agree that the total amount of this invoice is repayable in accordance with the Account Agreement applicable to this Account.

GRAND ISLAND TITAN MACHINERY-GRAND ISLAND 3721 W HWY 2 GRAND ISLAND NE 68803-1211



GRAND ISLAND

SOLD TO: STOLTENBERG, WAYNE

SERVICE ORDER: SO0038559

Segment#: 1 AGL YIELD MONITORING NOT WORKING

Work Site: 3721 W HWY 2 GRAND ISLAND, NE 68803-1211

Concern:

Complaint:

Yield monitor not working.

CORRECTION:

I got in the combine with Wayne.

I went through his display to see why his yield monitoring wasn't working.

Found that the yield plus moisture sensor was turned to none instead of yield.

After moisture sensor was turned on the yield started to work.

Auto header height - I did a ground calibration and then we engaged the header.

I set his one and two set points and then we test ran.

Running through the field auto header height was working as it should .

We got to the other end and it raised

When the machine was turned around it lowered back to where it should.

When we were coming back to the truck so that I could leave.

He shut the header off and it came up with the Auto header height disabled code again.

When we engage the header everything was still working properly so he didn't want me to look at any further at this time.

Labor:

Description	Amount
LABOR	\$145.20
	Total Labor: \$145.20

Others:

Description	Amount
SHOP SUPPLIES	\$10.89
service call	\$40.00
	Total Others: \$50.89

Tax : \$0.00 Total Segment : \$196.09