



KP 8770

Website: www.ParallelAg.com
Store #: (580) 540-3581
After Hours #: (800) 659-1639

PLEASE REMIT TO:
Livingston Machinery Company
P.O. Box 666
Chickasha, OK 73023

Ship To: FARMER CO-OP EXCHANGE
800 WASHINGTON
PO BOX 158
BESSIE, OK 73622-0158

Invoice To: FARMERS COOPERATIVE EXCHANGE
PO BOX 158
800 WASHINGTON
BESSIE OK 73622

Branch Fairview			*REPRINT*		
Date 04/22/24	Time 14:11:59 (B)	Page 01			
Account No FARME031	Phone No 5803376342	Inv No W17624			
Ship Via	Purchase Order				
Tax ID No STS-10039836-05	06/30/2024				
	Salesperson 413				

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
031523	SPRAYER	4235E A1300HCNSL1268		
	1300			

SEGMENT# 1 C 00976 NA 04/17/24 04/18/24

CUST - HYDRAULIC LEAK

CONCERN:

Hydraulic leak.

CAUSE:

Bad o ring.

CORRECTION:

Cleaned up area and found leak coming from pressure test port. I removed and found that the oring had a piece missing. Replaced O ring and put it back in. Leak stopped. Let run for awhile and it didn't leak.

BERRYMAN B-12	16.25OZB-1	2	9.00	18.00
V837073357	CONTROL UNIT	1 M	2722.44	2722.44
			PARTS	2740.44
			LABOR	835.91
10300000			SEGMENT TOTAL==>	3576.35

SEGMENT# 2 C 00976 NA 04/17/24 04/19/24

CUST - DERATED

CONCERN:

CODE D134 - TMS NOT WORKING

CAUSE:

Controller failure.

CORRECTION:

While hooked up to machine with edt and doing diagnostic checking for possibilities of what would cause the derated state of machine the EEM4 engine controller went offline and would not come back. After doing testing on the wiring I took the controller back to the shop and plugged into

CONTINUED ON PAGE 02

Customer hereby authorizes dealer to perform the work described above and agrees to pay all amounts due in accordance with the terms and conditions on the back side of this Invoice.

X

Received By

CHICKASHA, OK	DALHART, TX	FAIRVIEW, OK	LIBERAL, KS	MARSHALL, MO	MULESHOE, TX
CONCORDIA, MO	EMMETSBURG, IA	FORT DODGE, IA	LUBBOCK, TX	MONTGOMERY CITY, MO	REDWOOD FALLS, MN

WE KEEP YOU RUNNING, 24/7

