

KEARNEY
 TITAN MACHINERY-KEARNEY
 PO BOX 548
 KEARNEY NE 68847-0548

TITAN MACHINERY

Questions?
Phone: 308-237-3128
Phone: 800-245-6026
Email: AR.Kearney@titanmachinery.com

Customer Number:BP0100083

ALLAN DIETZ
 1219 V RD
 KEARNEY NE 68847-8045

WORK SITE :
 TITAN MACHINERY-KEARNEY
 PO BOX 548
 KEARNEY NE 68847-0548

Invoice #: SO0147286-1	Service Order #:SO0147286	Invoice Date: 12/03/2024	Due Date: 12/03/2024
Cust PO:		Make: NEW HOLLAND	Model: LS185B
Sold By:		Unit: E00153373	Serial #: N5M410425
Cust Fleet #:		Hours: 1,096.00	

Service Order Summary

Segment#	Segment Description	Segment Total
1	CEL REPAIR LEAK	\$3,316.91

Payment Information

CHECK#02523685 \$3,316.91

Subtotal	\$3,316.91
Tax	\$0.00
Invoice Total	\$3,316.91
Credits Applied	\$0.00
Payment Received	\$3,316.91
Balance Amount	\$0.00

CUSTOMER ACCEPTANCE

Phone:
 Cell :

By signing I certify that I am authorized to use this Account, to sign this receipt, and that I agree that the total amount of this invoice is repayable in accordance with the Account Agreement applicable to this Account.

KEARNEY
 TITAN MACHINERY-KEARNEY
 PO BOX 548
 KEARNEY NE 68847-0548

TITAN MACHINERY

KEARNEY

SOLD TO : DIETZ, ALLAN
 SERVICE ORDER : SO0147286

Work Site : PO BOX 548 KEARNEY, NE 68847-0548

Segment#: 1 CEL REPAIR LEAK

Concern:

Complaint :
 Repair hydraulic leak.

CORRECTION:
 Put oil in the unit and pulled it into the shop. Removed the cover at the pedal valve and inspected. Discovered one of the lines going to the valve was only finger tight. Tightened the line up and rechecked for leaks. Found a leak coming back from the engine. Raised up the rear of the unit and supported with jackstands. Removed the left rear wheel and the access panel underneath the unit. Inspected for the leak and found a hose came off the hydraulic pump. Had to remove the hydraulic filter and a steel line going to the tank to gain access to the hose that came off. Inspected the hose and found it had two plastic caps in the hose. Removed the caps and reinstalled the hose with new hose clamps and tightened them down. Installed a new hydraulic filter and reinstalled the steel line that had been removed. Filled the unit with oil and ran it. Rechecked for leaks, none found. Reinstalled the bottom cover and the left rear wheel. Replaced a couple studs in the both the left and right rear wheels. Put the bucket back on the unit and a hydraulic pressure light came on. Inspected and found its the pressure switch. Unplug the switch and the light goes out. A new switch is \$290.

Also replaced the seat in the unit.

Parts :

QTY	Vendor	Part Number	Description	Original Price	Sell Price	Core	Amount
1	CASE	73344211	NO.1 10W30 2.5 GAL	\$60.00	\$60.00	\$0.00	\$60.00
1	CASE	73344211	NO.1 10W30 2.5 GAL	\$60.00	\$60.00	\$0.00	\$60.00
1	CASE	SK5	1/2# GRADE 5	\$2.92	\$2.92	\$0.00	\$2.92
3	NEWHOL	86979742	NUT	\$4.35	\$4.35	\$0.00	\$13.05
3	NEWHOL	175617	BOLT, WHEEL	\$7.40	\$7.40	\$0.00	\$22.20
3	NEWHOL	86979742	NUT	\$4.35	\$4.35	\$0.00	\$13.05
2	NEWHOL	175617	BOLT, WHEEL	\$7.40	\$7.40	\$0.00	\$14.80
1	NEWHOL	9842392	FILTER, HYDRAULIC OI	\$79.40	\$79.40	\$0.00	\$79.40
4	MISC	SMALL-TIE	TIESTRAP	\$0.54	\$0.54	\$0.00	\$2.16
1	CASE	73344210	NO.1 10W30 1 GAL	\$25.50	\$25.50	\$0.00	\$25.50
1	MISC	5216	CLAMP	\$2.65	\$2.65	\$0.00	\$2.65
1	CASE	73344210	NO.1 10W30 1 GAL	\$25.50	\$25.50	\$0.00	\$25.50
1	NAPA	7051503	HOSE CLAMP	\$10.78	\$10.78	\$0.00	\$10.78
1	K&M	8643	KM 128 BUCKET SEAT-BLK VIN-NEW	\$215.00	\$215.00	\$0.00	\$215.00
2	CASE	F1119905	BOLT, FLANGE	\$0.29	\$0.29	\$0.00	\$0.58
1	NEWHOL	9847458	SWITCH	\$60.50	\$60.50	\$0.00	\$60.50
						Total Parts :	\$608.09

Labor :

Description	Amount
LABOR	\$2,502.50
Total Labor : \$2,502.50	

Others :

Description	Amount
SHOP SUPPLIES	\$178.50
FREIGHT & HANDLING	\$27.82

KEARNEY
TITAN MACHINERY-KEARNEY
PO BOX 548
KEARNEY NE 68847-0548

TITAN **MACHINERY**

KEARNEY

SOLD TO : DIETZ, ALLAN
SERVICE ORDER : SO0147286

Total Others : \$206.32

Tax : \$0.00
Total Segment : \$3,316.91