

**Gill Diesel**

5076 W ABBOTT RD  
 GRAND ISLAND, NE 68803-9426  
 gilldiesel4@gmail.com  
 308-390-2652

**GILL DIESEL**

308-390-2652

Invoice: 1298

Date: 1/27/2021

Bill To  
 Country Side Transfer

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
1785	COD	1/27/2021	Brock Baxter		1629

Item Description	Quantity	Rate	Amount
<b>Complaint:</b> EATING STARTERS.			
<b>Cause:</b> Voltage issue			
Labor <b>Correction:</b> Engine / Starting & Charging / Replaced starter with customer supplied starter. Load tested batteries and the batteries failed the load test so we replaced all 4.	3.04000	\$100.00	\$304.00
Parts Battery - BAT1131MF	4.00000	\$143.096	\$572.38
		<b>Subtotal</b>	<b>\$876.38</b>

**Complaint:** overhaul  
**Cause:** Customer request (Inspection)

Labor <b>Correction:</b> Engine / Lubrication / Pulled truck in for head gasket job originally, took all head accessory's off took head bolts out and proceeded to remove head itself. Checked liner protrusion and all heights were in spec. Customer decided to overhaul. Took oil pan and block girdle off along with oil pump. Then proceeded to take all 6 rods and pistons out. Pulled all 6 liners out. Cleaned inside of block well, took crank bearings out and rolled in all new bearings and torqued main caps to spec. Then installed 6 new liners, assembled new pistons to rods. Installed new rod bearings and installed rod and pistons two at a time and torqued rod bolts to spec, cleaned and reinstalled block griddle. Installed new o rings for oil sump and pump and installed new oil pump. Cleaned pan and installed with new gasket. Got new head out of box and swapped over all brackets, plugs and sensors to new head. Put down new head gasket and installed head. Put 6 new injectors in along with 6 new injector lines from rail to head. Cleaned rocker arms thoroughly. installed all 6 rocker arm sets and ran overhead valve adjustment. Cleaned valve cover and installed new gasket. filled with oil and changed all filters, filled coolant. Primed fuel system and started truck up let run for 10 min and took on a test drive everything worked as it should no check engine light.	45.00000	\$100.00	\$4,500.00
Parts Temp Sensor - 115P/1893478PE	1.00000	\$191.719	\$191.72
Parts Cylinder Liner - 115P/1935136PE	6.00000	\$240.056	\$1,440.34
Parts V-Clamp - 115P/1976451PE	1.00000	\$57.6085	\$57.61
Parts Exhaust Gasket - 115P/2035973PE	1.00000	\$34.71	\$34.71
Parts Air Inlet Gasket - 115P/1786103PE	1.00000	\$21.45	\$21.45
Parts V-Clamp - 115P/1976452PE	1.00000	\$58.1015	\$58.10
Parts Cylinder Head - 115P/2184938PEX	1.00000	\$6,177.778	\$6,177.78
Parts Injectors - 115P/1972591PEX	6.00000	\$1,171.832	\$7,030.99
Parts Overhaul kit - 115P/2163238PE	1.00000	\$5,872.848	\$5,872.85
Parts Fuel Pipe Injection - 2047594PE	2.00000	\$219.366	\$438.73

Parts Fuel Pipe Injection - 115P/2047593PE	4.00000	\$219.366	\$877.46
Parts Dirty Core for Cylinder Head - 115P/2184938PEXC	-1.00000	\$2,520.00	-\$2,520.00
Parts Inherent Core for Cylinder Head - 115P/2184938PEXC	1.00000	\$2,520.00	\$2,520.00
Parts Dirty Core for Injectors - 115P/1972591PEXC	-6.00000	\$399.00	-\$2,394.00
Parts Inherent Core for Injectors - 115P/1972591PEXC	6.00000	\$399.00	\$2,394.00
Parts Oil Pump - 115P/1973051PE	1.00000	\$791.95	\$791.95
Parts Ring Seal - 115P/1608394PE	2.00000	\$15.68	\$31.36
Parts Ring Seal - 115P/1608393PE	2.00000	\$14.07	\$28.14
Parts Copper Washer - 115P/0119132PE	1.00000	\$0.94	\$0.94
Parts Oil Pan Seal - 115P/1925946PE	1.00000	\$216.5865	\$216.59
Parts T Bolt Clamp - BRZ-B9224-0411FRU	1.00000	\$8.155	\$8.16
Parts Cenex Coolant - 283140	12.00000	\$14.95	\$179.40
		<b>Subtotal</b>	<b>\$27,958.28</b>

Unit: 1629 VIN: 1XKWPP9X7GJ485129

Chassis: 668,316 Miles

Labor	\$4,804.00
Parts	\$24,030.66
Shop Supplies	\$50.00
<b>Pre Tax Total</b>	<b>\$28,884.66</b>
Exempt (0.0000% of \$24,080.66)	\$0
<b>Total</b>	<b>\$28,884.66</b>
Payments & Credits	\$28,884.66
<b>Balance Due</b>	<b>\$0.00</b>

### Payment Information

Date Created	Date Applied	Payment #	Method	Reference #	Amount
1/29/2021	1/29/2021	[REDACTED]	[REDACTED]		\$28,884.66

Thank you for your business.

All customer invoices must be paid in full prior to the vehicle leaving the premises. All returned checks will have a \$35 non sufficient funds fee. Please send payment within 30 days of the invoice date. We will assess a service charge of 1.33% on all amounts per month or 16% per year. If vehicles are not picked up and the invoice paid in full within 30 days of the invoice date, a \$10 per day service/storage fee will be assessed until invoice is paid in full and the vehicle picked up.

Gill Diesel will not be liable for towing charges, rental car, travel/lodging expenses, lost time/wages, or any other claims for special, indirect, or consequential damages that may arise under the provisions of this warranty. Purchaser hereby agrees that no express or implied warranties are provided by Gill Diesel relative to labor or parts listed on this invoice except where indicated. Gill Diesel hereby agrees to provide reasonable assistance to purchaser as to any applicable manufacturer warranties should the need arise. All warranty work must be done by Gill Diesel. Warranty does not cover damage due to overheating, low fluid levels, customer abuse or neglect, customer modification. Purchaser assumes all responsibility regarding adherence to local, state, and federal regulations relating to these parts and their usage and further acknowledges that these products may void existing manufacturer warranties within the vehicle. Purchaser waives all consequential and incidental damages related to the use of aftermarket tuning and/or other race products. Any old parts not taken when vehicle is picked up will be discarded. The customer assumes all responsibility for damaged or stolen items that take place outside the building at Gill Diesel.

**Name:**