Brown Equipment

3036 Cumming Ave. Cumming, IA, 50061 515-981-4393



				rarts, sales & se	VICE
	an Mal	REPAIR WC	RK ORDER		
CLIENT NAME	Brown Equipme	nt Trade-in Unit		Ford 6610 Series ii Hrs: Unreadable	
CLIENT PHONE	515-981-4393				
LOCATION	Cumming, IA				
ORDER DATE	05/01/2024	EXPECTED START DATE	05/03/2024	EXPECTED END DATE	05/10/2024
WORK AUTHORIZED BY	Brad Brown				
REQUESTED WORK DESCRIPTION	Fix fuel leak at tank. Charging system doesn't work.				
ADDITIONAL COMMENTS					
WORK PERFORMED BY	Kyle Brown				
DESCRIPTION OF WORK COMPLETED AND MATERIALS USED	Found hole in fuel tank, replaced tank. Parts used: QTY 1: D5NN9002AE. Alternator failed. Replaced with 1 wire alternator. Parts used: QTY1 3000-0502.				
CLIENT APPROVAL	Brad Brown			COST OF LABOR	-
APPROVING PARTY SIGNATURE	Bra, Ph	v		COST OF MATERIALS	-
DATE OF APPROVAL	05/14/2024			TOTAL	
			CHARGEABLE TO	Trade In R	Repair

CHARGEABLE TO

Trade In Repair