

Hultman Services Inc

6552 N. Broadway
Wichita, KS 67219

3162049084

Invoice

Web Site
WWW.hultmanservices.COM

Date 3/23/2023

Bill To
Rohloff Trucking 1030 N Washington Wichita, KS. 67214

Vehicle Info:
2007 Freightliner VIN: 1FUJA6CGX7LX62671 Mileage: 541245

Invoice # 032323-2671

Qua...	Item Code	Description	Price ...	Amount
20	Labor On-Site	Turbo and Exhaust Manifold caused a melt down of Air Cleaner and Duct work. Customer provided these parts with used. Difficult to remove Turbo, exhaust Manifold, EGR--excessive rusted components and Bolts. Exhaust bolt broken off in head--drilled and Heli-coiled. S-Pipe from Turbo rusted out--replaced, replacement was not correct angle--cut to fit and welded. Fittings to water pump rusted completely and about to leak, could not remove--replaced water pump. Difficulty finding fittings needed. Reassembled and tested.	175.00	3,500.00T
	DISCOUNT 1...	15% DISCOUNT	-15.00%	-525.00
1	04-17094-014	Exhaust S Pipe	227.25	227.25T
1	23532122	Exhaust Manifold	344.61	344.61T
1	23511222	Exhaust Manifold	126.00	126.00T
1	23511221	Exhaust Manifold	126.00	126.00T
12	08929357	Exhaust Manifold Bolts	13.28	159.36T
3	23539193	Exhaust Manifold Gaskets	14.25	42.75T
2	23506325	Hose	42.72	85.44T
4	CT 300 L SS	CT Hose Clamp	10.11	40.44T
1	171702N	Turbo	1,176.14	1,176.14T
1	23505899	Tube	186.44	186.44T
1	23515354	Oil Tube	107.75	107.75T
1	23539290	Oil Tube	61.28	61.28T
5	CT350LT	Clamp	17.96	89.80T
1	R23535017	Water Pump	646.62	646.62T
1	23539103	Rocker Cover Gasket	67.14	67.14T
1	Shop Supplies	Fittings, O-Rings, Gaskets, Clamps, Pipe	71.09	71.09T
Subtotal				\$6,533.11

Fax #	316-831-1223	hultmanservices@gmail.com
--------------	--------------	---------------------------

Sales Tax (7.5%)	\$489.98
Total	\$7,023.09

07 Freightliner

Hultman Services Inc

6552 N. Broadway
Wichita, KS 67219

3162049084

Web Site
WWW.hultmanservices.COM

Date 2/13/2023

Invoice

Bill To
Rohloff Trucking 1030 N Washington Wichita, KS. 67214

Vehical Info:
2007 Freightliner VIN: 1FUJA6CGX7LX62671 Mileage: 538653

Invoice # 021323-007

Qua...	Item Code	Description	Price ...	Amount
47	Labor On-Site	Set Truck up with Hydraulics to operate End-Dump. Customer provided Fuel/Hydraulic Combo Tank with hangers. Customize an air tank mount while using hangers that came with new tank which did not accommodate air tank. Fit PTO Gear to Transmission. Fit Hydraulic Pump to PTO Gear. Plumb all components. Fitted Hoses. Made supports for supply line and support for Discharge side. Capped off lines not used on fuel tank. Installed pedestal for Driver Operation of PTO.	175.00	8,225.00T
	DISCOUNT 1...	15% DISCOUNT	-15.00%	-1,233.75
1	1163520	489GQAHX-A5RK PTO	2,009.06	2,009.06T
1	1031266	314-9325-227 Pump Assembly	1,170.53	1,170.53T
1	1055213	Dump Control Assembly	503.91	503.91T
1	1082895	Relief Valve	146.28	146.28T
3.5	50W	50 Weight Synthedic Transmission Fluid	67.77	237.20T
1	FREIGHT		150.00	150.00T
1	QC16MQW-I...	Brass Male Nipple for Coupling	78.03	78.03T
1	16MJ-16MP	Bulkhead Fitting	39.00	39.00T
1	32MP-24FP	Fitting	51.44	51.44T
1	20MP-24FPL	Fitting	58.11	58.11T
2	16G-16MP	16 Hose-16 MP	59.18	118.36T
2	16G-16FJX	16 Hose-16 FJIC	65.40	130.80T
11	16M2T	2500 PSI Hose	29.21	321.31T
1	Shop Supplies	steel, bolts, nuts, Brass fittings, and such	85.00	85.00T
2	Steel	Misc Steel for Fabrication	85.00	170.00T
1	12-15476-000	Air Supply Tank	635.84	635.84T
20	Hydraulic Oil	Hydraulic Oil Per Gallon	18.50	370.00T
Subtotal				\$13,266.12

Fax #	316-831-1223	hultmanservices@gmail.com
-------	--------------	---------------------------

Sales Tax (7.5%) \$994.96

Total \$14,261.08

07 Freight

Pd 4,261.08 2/27
10,000.00

HULTMAN SERVICES INC
 6552 N. Broadway
 Wichita, KS 67219 US
 +1 3162049084
 hultmanservices@gmail.com
 WWW.hultmanservices.COM

Invoice

BILL TO
 Dick Rohloff Construction
 Rohloff Trucking
 1030 N Washington
 KS.
 Wichita, KS 67214

SHIP TO
 2007 Freightliner #2671
 VIN: 1FUJA6CGX7LX62671
 Mileage: 556700
 Jay

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
081524-2671	08/15/2024	\$3,097.02	08/30/2024	Net 15	

SALES REP
 Jay

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
Labor On-Site	DIAGNOSIS AC INOP. Hooked up to system, no freon, pulled vacuum, system failed to hold. Charged system with half pound and found leaks with leak detector at the dryer on right side frame rail. Was unable to remove lines from dryer, bolt was stripped out and seized up. Removed dryer and hoses from condenser to expansion valve.. Replaced dryer and both hoses. (customer supplied hose from condenser to dryer) . All new P-clamps and bolts to secure lines to frame and new clamps to secure dryer to frame. Installed two new ac switches, pulled vacuum on system, leak test passed, charged system with proper amount. secured wiring and other hoses with zip ties	4	175.00	700.00T
ABP N83 319745	824 Dryer Filter	1	43.88	43.88T
23-13202-000	824 Seal	2	6.84	13.68T
A22-45194-001	824 Med Press AC Switch	1	123.96	123.96T
22-51296-000	824 Binary AC Switch	1	60.70	60.70T
A22-59999-003	824 AC Hose Assembly	1	425.48	425.48T
134A	134A PER LB	3.50	35.25	123.38T
Labor On-Site	LEFT WINDOW INOP. Found window crank stripped out and could physically move window up and down in track indicating window was detached from regulator. Disassembled door panel/ regulator assembly. Found metal channel on bottom of window rusted away and broken free from regulator. Replaced window and channel, regulator and window crank	5	175.00	875.00T
331200	824 Window	1	70.54	70.54T
A18-35310-002	824 Window Channel	1	34.44	34.44T
A18-52065-000	824 Window Regulator	1	256.32	256.32T
A18-18557-002	824 Window Crank Handle	1	27.02	27.02T
Shop Supplies	P-clamps, nuts, bolt, washer, zip ties, o'rings, horse shoe clamps Nylon Retainers. Glass tape	1	100.00	100.00T

Freight

Thank you for your return Business.

Hultman Services Inc

6552 N. Broadway
Wichita, KS 67219

3162049084

Web Site
WWW.hultmanservices.COM

Invoice

Date 6/23/2023

Bill To
* Rohloff Trucking 1030 N Washington Wichita, KS. 67214

Vehicle Info:
* 2007 Freightliner # R9 VIN: 1FUJA6CGX7LX62671 Mileage: 542791

Invoice # 062223-R9

Qua...	Item Code	Description	Price ...	Amount
24	Labor On-Site	Replaced King Pins--Pins were severely grooved and difficult to press out. Pin Keeper wedges were rusted and nearly impossible to remove. Tie Rod Ends were difficult to remove. Replaced Right Tie Rod End. Replaced Brake Shoes--Shoes were cracked. Replaced both Brake Chambers--chambers badly rusted.	175.00	4,200.00T
	DISCOUNT 1...	15% DISCOUNT	-15.00%	-630.00
1	K961L	King Pin Kit	1,135.42	1,135.42T
2	35066	623 Wheel Seal	87.50	175.00T
1	R230069	623 RH Tie Rod End	82.04	82.04T
2	4702Q STD	Q+ Brake Shoes	135.54	271.08T
2	SBT20	Brake Chamber	66.74	133.48T
1	Shop Supplies		45.00	45.00T
Subtotal				\$5,412.02

Fax #	316-831-1223	hultmanservices@gmail.com
-------	--------------	---------------------------

Sales Tax (7.5%)	\$405.90
Total	\$5,817.92

Freight