

**Christianson Farm Machinery Inc.**



2686 East Hwy 14  
 P.O. Box D  
 Tyler, MN 56178  
 Phone: (507) 247-5526



|  |  |
|--|--|
| <b>Sold To:</b><br>JUSTIN GRIMMIUS<br>655 50TH AVE<br>CHANDLER, MN 56122 | <b>Ship To:</b><br>JUSTIN GRIMMIUS<br>655 50TH AVE<br>CHANDLER, MN 56122<br>507-227-2835 |
|--|--|

| Account No. | Starting Date    | Ending Date       | P.O. Number | Service Tag | Tax ID | Salesperson        |
|-------------|------------------|-------------------|-------------|-------------|--------|--------------------|
| 1339        | 8/3/2023 1:42 PM | 8/30/2023 2:31 PM |             |             |        | AARON CHRISTIANSON |

| Make        | Model     | Year         | Serial Number | Stock Number |         |              |       |
|-------------|-----------|--------------|---------------|--------------|---------|--------------|-------|
| NEW HOLLAND | TJ450 4WD | 0            | RVSO001999    | TJ450-02     |         |              |       |
| Promised    | Deliver?  | Usage Type 1 | Usage 1       | Usage Type 2 | Usage 2 | Invoice Type | Store |
|             | No        | ENGINE HOURS | 7179.0000     |              | 0.0000  | Final        |       |

| Qty             | B/O | Taxable | Description | Serial Number | Price | Amount                             |
|-----------------|-----|---------|-------------|---------------|-------|------------------------------------|
| <b>Customer</b> |     |         |             |               |       | <b>Segment 1 Total: \$12356.23</b> |

SEND IN ARM REST CONTROLLER, AND RIGHT HAND A-POST INSTRUMENT CLUSTER FOR REPAIR/INSPECTION: Multiple error codes and units go offline.  
 We removed both instrument clusters and arm rest controller for inspection and repair. We inspected wiring, and can terminals.  
 We installed and not fault codes are present. All worked as it should.

CUSTOMER WANTS NEW INJECTORS INSTALLED AND TOP RACK GONE THROUGH.  
 We installed new Cummins Reman injectors and adjusted top rack of engine.

|   |    |  |   |           |           |        |           |
|---|----|--|---|-----------|-----------|--------|-----------|
| 1 |    |  | MANHMO00427 - PERFROMANCE MONITOR REPAIR, TJ275-500 |           | \$586.50  | \$0.00 | \$586.50  |
| 1 |    |  | MANHMO00428 - ARM REST CONTROL PANEL REPAIR         |           | \$586.50  | \$0.00 | \$586.50  |
| 1 |    |  | MACAMO00276 - MONITOR, LOWER                        |           | \$586.50  | \$0.00 | \$586.50  |
| 1 |    |  | 4026507 - CUMMINS GASKET                            |           | \$229.50  | \$0.00 | \$229.50  |
| 1 |    |  | 4062569PX - CUMMINS INJECTOR                        | 1T8393377 | \$1326.00 | \$0.00 | \$1326.00 |
| 1 |    |  | 4062569PX - CUMMINS INJECTOR                        | 1T8393368 | \$1326.00 | \$0.00 | \$1326.00 |
| 1 |    |  | 4062569PX - CUMMINS INJECTOR                        | 1T8393409 | \$1326.00 | \$0.00 | \$1326.00 |
| 1 |    |  | 4062569PX - CUMMINS INJECTOR                        | 1T8393383 | \$1326.00 | \$0.00 | \$1326.00 |
| 1 | 76 |  | 4062569PX - CUMMINS INJECTOR                        | 1T8393391 | \$1326.00 | \$0.00 | \$1326.00 |
| 1 |    |  | 4062569PX - CUMMINS INJECTOR                        | 1T8393379 | \$1326.00 | \$0.00 | \$1326.00 |
| 1 |    |  | 84557717 - FILTER FUEL - Bin: FILTRCK5              |           | \$63.75   | \$0.00 | \$63.75   |
| 8 |    |  | 4LOLA - 1/4 COOLANT HOSE - Bin: SOP                 |           | \$5.21    | \$0.00 | \$41.68   |
| 5 |    |  | PREMIX - COOLANT BULK 50/50 - Bin: SHOP             |           | \$12.24   | \$0.00 | \$61.20   |