

**Labor:**

Description	Amount
Labor	\$8,622.68
Shop Supplies	\$104.42
<b>Total Labor</b>	<b>\$8,727.10</b>

**Parts:**

QTY	Vendor	Part Number	Description	Bin	Price	Ext. Price
2.00	CAS	47509176	BEARING, BAL	J004G	\$134.00	\$268.00
1.00	CAS	87299946	KIT	USW-S03+	\$495.00	\$495.00
2.00	CAS	B95352	SIEVE HANGER ARM KIT	F004K	\$152.00	\$304.00
1.00	CAS	87710709	SIEVE UPPER 1 5/8 CLOSED	WH-O3	\$1,750.00	\$1,750.00
4.00	CAS	87584225	PACKAGE, GRAIN PAN DIVIDERS	USW-U03	\$204.00	\$816.00
1.00	CAS	1994858C1	COVER	USW-W01	\$45.25	\$45.25
1.00	CAS	87330903	CHOPPER DRIVE BELT NA	USBH033	\$99.00	\$99.00
1.00	CAS	47931962	LOWER, CLOSZ SLAT, 1 5/8	WH-O3	\$1,450.00	\$1,450.00
1.00	CAS	841699374	RAIL/A-LH		\$705.00	\$705.00
10.00	CAS	87745690	PAN ASSM GRAIN NAO PAINTED	USW-X03	\$187.00	\$1,870.00
1.00	CAS	1312476C1	FINGER	K002F	\$5.45	\$5.45
1.00	CAS	87379127	SUPPORT		\$137.00	\$137.00
1.00	CAS	1322616C2	SHAFT	S2-RACK4	\$527.00	\$527.00
1.00	CAS	1322573C1	CAMLH	K001D	\$160.00	\$160.00
1.00	CAS	1322573C1	CAMLH	K001D	\$160.00	\$160.00
1.00	CAS	FREIGHT	FREIGHT		\$141.16	\$141.16
12.00	CAS	445395	RIVET	V905A	\$0.30	\$3.60
1.00	CAS	1312476C1	FINGER	K002F	\$5.45	\$5.45
1.00	CAS	86619060	BOLT CARRIAGE SSQ MBX16	BB-A40	\$0.77	\$0.77
1.00	CAS	145456	PKG-NUT, SER	V902A	\$0.17	\$0.17
3.00	CAS	87491115	BEARING, BAL	J002F	\$45.25	\$135.75
1.00	CAS	FREIGHT	FREIGHT		\$21.25	\$21.25
1.00	CAS	P4752-035	5/8NUTNCGR8	BOLTBIN7	\$0.74	\$0.74
1.00	CAS	47924947	SHOE SIEVE	USW-S02	\$24.00	\$24.00
2.00	CAS	86511978	SCREW, MACH	V501C	\$1.35	\$2.70
1.00	CAS	645342C1	SPACER	V611E	\$6.75	\$6.75
4.00	CAS	326-644	CSSH G8 PHC .375-16 X 2.75	BB-C09	\$2.20	\$8.80
1.00	CAS	BOLT-P	BOLT BY #	BOLT BIN	\$5.25	\$5.25
1.00	CAS	9706693	BOLT, M12X60 8.8 ZND	BB-E37	\$2.25	\$2.25
1.00	CAS	86512497	NUT, FLANGE	BB-D51	\$0.70	\$0.70
<b>Total Parts</b>						<b>\$7,517.09</b>
<b>Tax</b>						<b>\$610.90</b>
<b>Total WO</b>						<b>\$16,855.09</b>



# MACHINERY

Questions?

Phone: 712 - 435 - 4237  
 Phone: 800 - 782 - 9978  
 Email: AR.Avooca@titanmachinery.com

SHIP TO:  
 TITAN MACHINERY  
 502 W HIGH ST  
 PO BOX 218  
 AVOCA IA 51521-0218

Customer Number: 115182  
 185081 AB 0.461 E0123X 10207 D8429330808 S2P8716330 0001:0003  
  
 DUANE HURSEY  
 520 550TH ST  
 SHELBY IA 51570-5102



Invoice #: 16418475 - GS	Service Order #: 1345825 CL	
Sold By: CHAD WICKS		
Cust PO:		
Cust Fleet #:		
Job Desc: RETURN TO CUT NOT WORKING		
Closed Date: 12/03/2021		
Make: CASE IH		
Model: 5088		
Serial #: YBG06082		
Tag: 2771230		
Hours: .00		
<b>Service Order Summary</b>		
WO #	WO Description	WO Total
2337200 SV	RETURN TO CUT NOT WORKING	\$424.45
2342927 SV	RETURN TO CUT NOT WORKING	\$665.64
2342928 SV	SIEVE ISSUE	\$16,855.09

This is a **COPY** of an invoice from a recent visit to our store.  
 If you would like to stop receiving this copy of your invoice, please call us at the number above or if you would like to receive this copy via email, please email us at the email address listed above.

**Thank you for your business!**

### Payment Information

DUANE HURSEY

TOTAL INVOICE	\$17,945.18
TOTAL DUE	\$0.00

CHECK #1254

Trans ID: 01Z6LL7HV00P7AKJRU09FCV8KSP2G  
 Client ID: 321B739003

Store ID: 1414576004

TO PAYVIEW DETAILS ONLINE GO TO:  
<https://titanmachinery.billtrust.com>

CUSTOMER NUMBER ENROLLMENT TOKEN

115182 MFS HSS HGB

8238  
 English  
 ver 2010  
 7479345

# BigIron

Invoice is to be paid in full. Titan may be entitled to a lien on the repaired equipment for any unpaid balance, as permitted by law.  
 Terms and Conditions: All invoices are due net 30 days from the date of invoice or per existing terms agreement with Titan machinery, A  
 lesser of 1.5% per month of the maximum rate permitted by law on all delinquent accounts until paid in full.

Boundary  
 ence

Radon Wi.  
 Roger  
 Roger  
 Roger  
 Roger

8238  
 2478153  
 01d

TITAN MACHINERY - AVOCA  
 802 W. HIGH ST.  
 PO BOX 218  
 AVOCA IA 5021-0218

# TITAN MACHINERY

Sold To: DUANE HURSEY AVOCA  
 SERVICE ORDER: 1345625

**Labor:**

Description	Amount
Labor	\$9,522.00
Shop Supplies	\$106.47
<b>Total Labor</b>	<b>\$9,628.47</b>

**Parts:**

QTY	Vendor	Part Number	Description	Bin	Price	Ext. Price
2.00	CAS	47509178	SCARING BAL	J0040	\$104.00	\$208.00
1.00	CAS	87299940	KIT	USW-503*	\$495.00	\$495.00
2.00	CAS	096352	SEIVE HANGER ARM KIT	FOOK	\$152.00	\$304.00
1.00	CAS	87710709	SEIVE UPPER 1 5/8 CLOSED	WH-03	\$1,750.00	\$1,750.00
4.00	CAS	87584225	PACKAGE GRAIN PAN DIVIDERS	USW-003	\$204.00	\$816.00
1.00	CAS	1984558C1	COVER	USW-W01	\$45.25	\$45.25
1.00	CAS	87530903	CHOPPER DRIVE BELT NA	USW-033	\$99.00	\$99.00
1.00	CAS	47831982	LOWER CLOSZ SLAT, 1 5/8	WH-02	\$1,450.00	\$1,450.00
1.00	CAS	84169374	RALUUM		\$708.00	\$708.00
1.00	CAS	87745890	FAN ASSM GRAIN NAC PAINTED	USW-X03	\$187.00	\$187.00
10.00	CAS	1312478C1	FINGER	K002F	\$3.45	\$34.50
1.00	CAS	87570127	SUPPORT		\$137.00	\$137.00
1.00	CAS	1322818C2	SHAFT	82-RACKA	\$527.00	\$527.00
1.00	CAS	1322573C1	CAMLN	K001D	\$190.00	\$190.00
1.00	CAS	1322573C1	CAMLN	K001D	\$190.00	\$190.00
1.00		FREIGHT	FREIGHT		\$141.16	\$141.16
12.00	CAS	445385	ROVET	V605A	\$0.30	\$3.60
1.00	CAS	1312478C1	FINGER	K002F	\$0.45	\$0.45
1.00	CAS	86619080	BOLT CARRIAGE SSQ MSX 18	BB-A40	\$0.77	\$0.77
1.00	CAS	148430	FRS-NUT, SER	V603A	\$0.17	\$0.17
2.00	CAS	87491115	BEARNG, BAL	J002F	\$45.25	\$90.50
1.00		FREIGHT	FREIGHT		\$21.25	\$21.25
1.00	CAS	14752-035	5/8X7/16X3/8	BOLTBW7	\$0.74	\$0.74
1.00	CAS	47624947	SHOE SEIVE	USW-502	\$24.00	\$24.00
2.00	CAS	86511978	SCREW, MACH	V601C	\$1.38	\$2.76
1.00	CAS	845342C1	SPACER	V611E	\$5.75	\$5.75
4.00	CAS	325-644	CSHM 68 PNC .375-16 X 2.75	BB-C09	\$2.20	\$8.80
1.00	CAS	BOLT-P	BOLT BY #	BOLT BIN	\$0.25	\$0.25
1.00	CAS	8706893	BOLT, M12X80 8.8 ZND	BB-E31	\$2.25	\$2.25
1.00	CAS	86912497	NUT, FLANGE	BB-D51	\$0.70	\$0.70

<b>Total Parts</b>	<b>\$7,577.06</b>
Tax	\$910.90
<b>Total WO</b>	<b>\$16,855.09</b>

**BigIron**

TITAN MACHINERY - AVOCA  
 822 W HIGH ST  
 PO BOX 218  
 AVOCA IA 51521-0218

# TITAN MACHINERY

AVOCA

Sold To: DUANE HURSEY  
 SERVICE ORDER: 1345825

WOF: 2337200 3V RETURN TO CUT NOT WORKING

Comments: RETURN TO CUT NOT WORKING ( DUANE, 712-240-4544 ) WAIVED SERVICE CALL FEE ( Drive to customer location, fault 46.4 active ) ( Removed bucket from body seat to access CXCM, checked for power out of CXCM, no 5 volt out ) ( Followed diagnostic trouble shooting for fault code ) ( Back probed into connector on back of A-post for 5 volt reference, 7 volts coming out ) ( Diagnostic instructions to check for continuity to ground, with key on 0.0 ohms to ground with key off gave 974 K ohms to ground ) ( Unplugged harness coming out of cab on right side, no change ) ( Filed an asset case for certification on diagnostic procedure )

**Labor:**

Description	Amount
Labor	\$399.00
Shop Supplies	\$27.68
<b>Total Labor</b>	<b>\$426.68</b>

**Parts:**

QTY	Vendor	Part Number	Description	Bin	Price	Ext. Price
					<b>Total Parts</b>	
					Tax	\$27.77
					<b>Total WO</b>	<b>\$454.45</b>

WOF: 2342927 3V RETURN TO CUT SHOP

Comments: RETURN TO CUT IN SHOP REPAIRS ( Straight combine into shop, tried more diagnostics for error 46.4, error now inactive )

**Labor:**

Description	Amount
Labor	\$100.00
Shop Supplies	\$42.75
<b>Total Labor</b>	<b>\$142.75</b>

**Parts:**

QTY	Vendor	Part Number	Description	Bin	Price	Ext. Price
1.00	CAS	8729412	BOLT RH M16X130 CL 10.9 2HD	86-042	\$10.00	\$10.00
					<b>Total Parts</b>	<b>\$10.00</b>
					Tax	\$42.89
					<b>Total WO</b>	<b>\$155.54</b>

WOF: 2342925 3V SIEVE REPAIR

Comments: ( DIRT FIELD ) ( 3V ) ( Removed straw spreaders, removed chula to spreaders ) ( Found that the back left bolt of the upper sieve and the front right bolt broken ) ( Unplugged power distributor harness and removed covers from around harness ) ( Removed bolts holding lower sieve seat, and lower sieve, unclipped lower sieve rollers ) ( Used a catched slip to hold up upper sieve, and another to get lower sieve to come free ) ( Removed lower and upper sieve ) ( Found that the rear spreader bar, front grain pan, sieves, steel frame were all broke ) ( Loosened hardware for shaker bushings, removed hardware and shaker arms from the combine ) ( Found that the eccentric arm on the left was very sloppy, oily coming from both the cam and the shaft ) ( Contacted customer for customer approval on parts ) ( Ordered needed parts, measured bushing ) ( Looked up parts and got a rough view of parts of parts ) ( Called customer for customer approval on parts ) ( Ordered needed parts, measured bushing ) ( Removed cross shaft and spreader bar bushings ) ( Removed wheelbones and installed new bearing bits ) ( Pressed in new bushings, bearings and caps ) ( Removed cross shaft and disassembled, replaced the 3 bearings, installed front gear onto new shaft and installed cross shaft slowly ) ( Removed seals, lateral rollers, and rollers from the sieves ) ( Installed new roller dividers on sieve, one was able to be salvaged ) ( Disassembled front grain pan and removed broken fingers, rollers from the sieves ) ( Installed the bar for the fingers onto the new part and installed assembly with new lateral dividers into sieve side frame ) ( Installed new bearing on grain pan ) ( Installed the bar for the fingers onto the new part and installed assembly with new lateral dividers into sieve side frame ) ( Installed new bearing on sieve frame and new spreader bar ) ( Installed shaker arms socket, installed ball-noon keys and eccentric arms ) ( Installed alignment bolt ) ( Installed angle nut on sieve frame and new spreader bar ) ( Installed shaker arms socket, installed ball-noon keys and eccentric arms ) ( Installed alignment bolt ) ( Installed new shaft yoke/pusher to combine lightened bearing flanges ) ( Tightened eccentric arms, installed drive pulley, slip clutch and spring on cross shaft ) ( Set back teeth on upper and lower sieves and lightened clamps ) ( Tightened clamp and flanges for center bearing ) ( Installed templates for getting shaker apart ) ( Set back teeth on upper and lower sieves and lightened clamps ) ( Tightened clamp and flanges for center bearing ) ( Installed templates for getting shaker apart ) ( Installed upper sieve with new hardware, installed lower sieve, trash chula and straw spreaders ) ( Installed new chopper belt, tensioned other bearing parts ) ( Reinstalled alignment templates and marked combine and equipped operator ) ( Checked operation, operating as it should ) ( Hooked up sieve rollers and calibrated upper and lower sieves ) ( Called customer and parked outside for customer to pick up )

BigIron

TITAN MACHINERY - AVCOA  
 302 W HIGH ST  
 PO BOX 218  
 AVCOA IA 51521-0218

Work Done on 5087  
 Nov - 2021  
 Oct 2021

Lower 1/2

**TITAN MACHINERY**

Questions?

Phone: 712 - 435 - 4227  
 Phone: 800 - 782 - 9978  
 Email: AR.Avoac@titanmachinery.com

Customer Number: 115152  
 1806 1 48 2457 181032 4257 1842033008 82 PR1030 0001 0001



DUANE HURSEY  
 520 550TH ST  
 SHELBY IA 51570-5102

SHIP TO:  
 TITAN MACHINERY  
 302 W HIGH ST  
 PO BOX 218  
 AVCOA IA 51521-0218

Invoice #: 15418475 - GS	Service Order #: 134525 - CL	Closed Date: 12/03/2021
Sold By: CHAD WICKS		Make: CASE IH
Customer PO:		Model: 5055
Customer Fleet #:		Serial #: Y3900082
Job Desc: RETURN TO CUT NOT WORKING		Tag: 2771230
		Hours: 00

WO #	WO Description	WO Total
2337200 - SV	RETURN TO CUT NOT WORKING	\$424.45
2342027 - SV	RETURN TO CUT SHOP	\$665.64
2342028 - SV	SIEVE ISSUE	\$16,855.09

This is a **COPY** of an invoice from a recent visit to our store.  
 If you would like to stop receiving this copy of your invoice, please call us at the number above or if you would like to receive this copy via email, please email us at the email address listed above.

Thank you for your business!

<b>Payment Information</b>	<b>TOTAL INVOICE:</b>	\$17,845.18
DUANE HURSEY	<b>TOTAL DUE:</b>	\$0.00

DUANE HURSEY  
 520 550TH ST  
 SHELBY IA 51570-5102

**TO PAY/VIEW DETAILS ONLINE GO TO:**  
<https://titanmachinery.com/invt>  
**CUSTOMER NUMBER ENROLLMENT TOKEN:**  
 115152 MFS-HSS-HCB

Invoice is to be paid in full. Titan may be entitled to a lien on the repaired equipment for any unpaid balance, as permitted by law.  
 Terms and Conditions: All invoices are due net 30 days from the date of invoice or per applicable terms agreed upon with Titan machinery. A service charge will be assessed equal to the amount of 1.5% per month of the maximum rate permitted by law on all delinquent accounts, until paid in full.

