SAME AS BELOW

FIELD SERVICE

REPRINT

03/29/24

09:15:39 (B)

01

ESTES015

4056401930

W0053105

ESTES FARMS 5725 RENO W

EL RENO OK 73036

06/30/2023

EXM-13595018-03

JS2

STK#/FLEET#

BALER

PIN/EIN HRS FHB04278 25111

WARRANTY DATE

HRS

A023263

SEGMENT# 1 C MA5

2270

AM

03/07/24 03/11/24 03/31/24

preaseason repairs

COMPLAINT:

Preseason inspection and repairs

CAUSE:

Normal wear

CORRECTION:

Drove to the unit and inspected and repaired

Aux clutch disc worn out from slippage and aux drive chain

was out of

adjustment 4 discs and chain replaced.

Replaced the hydraulic tank vent and filter.

The bill hook tongue cam roller is rough and oddly worn.

Replaced the bill hook tongue on all knotters.

Replaced lower slacker arm roller on #6.

Performed knitter adjustments and checked over well.

Customer is to replace pickup teeth and have knitter drive

hub built up.

ADDITIONAL DESCRIPTION:

Preseason inspection and repairs

M700718710	KNIFE/TWINE	6	30.18	181.08
700108820	FRICTION DISC-6	4	155.45	621.80
700144059	SPACER	1	29.10	29.10
700724615	ROLLER CHAIN #1	1	541.24	541.24
700734488	KNOTTER BILLHOO	6	31.99	191.94
700738686	FILTER ELEMENT	1	44.53	44.53
70922598	GROOVE PIN 3/16	6	1.37	8.22
71154718	BREATHER VENT	1	45.85	45.85
863738	SPLIT PIN 3/16	6	1.37	8.22
		CONTINUED ON PAGE 02		

CS CamScanner

SAME AS BELOW

FIELD SERVICE

03/29/24

09:15:39 (B)

02

ESTES015

4056401930

W0053105

ESTES FARMS 5725 RENO W

EL RENO OK 73036

06/30/2023

EXM-13595018-03

JS2

STK#/FLEET#

A023263

BALER

PIN/EIN HRS 25111 FHB04278 WARRANTY DATE

HRS

2270

PARTS LABOR

1671.98

SEGMENT TOTAL ==>

1719.90 3391.88

11000000

***** WORK ORDER TOTALS *****

PARTS	1671.98
LABOR	1719.90
SHOP SUPPLIES	137.59
SUB TOTAL ==>	3529.47
GOLDSBY City	123.54
MCCLAIN County	17.66
OK STATE TAX	158.83
ON ACCOUNT	3829.50

CHARGE ACCT

CS CamScanner