



Ken's Westside Service & Towing

3111 Venture Blvd.
Bloomington, IN 47404
812-336-9050

8/16/2024 1:54:05 PM UEDT

Invoice #50103

Page:2

Kens Westside Service And Towing

Vehicle: 2007 Mack CL733 15.0 L 912 CID L6 Cummins

Code	Reference	Description	Condition	Unit Price	Price
---	4952629	THERMOSTAT	New	\$96.18	\$96.18
---	3681906	ISOLATOR	New	\$10.07	\$10.07
---	4973532	OIL GASKET	New	\$8.29	\$49.74
---	4356366	VALVE SEAL	New	\$4.60	\$110.40
---	US6344	WATER PUMP	New	\$449.99	\$449.99
---	141402	OIL COOLER	New	\$321.75	\$643.50
---	P021385	INJECTOR SLEEVE	New	\$19.99	\$119.94
---	P021563	INJECTOR SLEEVE SEAL RING	New	\$4.30	\$25.80
---	CU3413137	BRAKE PLUNGER		\$29.55	\$177.30
---	12B50015158	5" EXHAUST ELBOW	New	\$80.99	\$80.99
-	HARD	MISC. HARDWARE		\$2.02	\$44.44
-	4318947	THERMOSTAT		\$63.34	\$63.34
FIL	3711	Fuel Filter - NAPA Gold		\$32.87	\$32.87
FIL	7746XD	Oil Filter - NAPA Gold		\$66.97	\$66.97
---	3681221	bolt		\$5.60	\$5.60
---	3412351	spacer	New	\$9.60	\$9.60
---	3679427	clamp	New	\$12.96	\$12.96
-	3588	FUEL FILTER		\$30.15	\$30.15
---	6882	AIR FILTER	New	\$73.47	\$73.47
---	4112	COOLANT FILTER		\$48.51	\$48.51
---	4024759	SOLENOID	New	\$165.50	\$331.00
	Note: PLMR				
---	25163462	MUFFLER BRACKET CLAMP	New	\$52.17	\$52.17
	Note: VOMACK				
---	25168579	MUFFLER BRACKET CLAMP	New	\$47.55	\$47.55
---	25167699	BRACKET, MUFFLER	New	\$26.73	\$26.73
	Note: VOMACK				
---	NONSTOCK	STAINLESS HARDWARE	New	\$0.37	\$6.66
---	5120910	12 RIB BELT 91"		\$184.30	\$184.30
---	5466997	BELT		\$121.72	\$121.72
---	7333225	5" EXHAUST CLAMP		\$12.99	\$25.98
---	7333224	4" EXHAUST CLAMP		\$13.32	\$13.32
---	15W40	15W40 DURON HP HEAVY DUTY ENGINE OIL		\$2.99	\$131.56
---	GREASE	PRECISION XL EP2 CHASSIS GREASE(TUBE)		\$2.99	\$2.99
---	25194985	PANEL, ELECTRIC	New	\$332.11	\$332.11
	Note: VOMAC, #177308				
---	8235CB2106611XSA	CENTER SUPPORT BEARING		\$72.26	\$72.26
	Note: VOMAC, #177308S				

Sublet/Misc.

Code/Tech*	Reference	Description	Condition	Unit Price	Price
-	SMH	CYLINDER HEAD SERVICE		\$0.00	\$0.00

Note: SUB-LET SERVICE TO PRESSURE TEST CYLINDER HEAD(S), PERFORM VALVE JOB AND MILL CYLINDER HEAD SURFACE.

Labor	\$88.93
Parts	\$22,858.77





Ken's Westside Service & Towing

3111 Venture Blvd.
Bloomington, IN 47404
812-336-9050

8/16/2024 1:54:05 PM UEDT

Invoice #50103

Page:3

Kens Westside Service And Towing

Vehicle: 2007 Mack CL733 15.0 L 912 CID L6 Cummins

Cash: \$681.00

Total \$22,947.70

PAYMENT \$0.00

BALANCE DUE \$22,947.70

Approvals

Date & Time

Total Amount

Authorized By

Method

Employee

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount or repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repairs.

Customer Signature _____



Ken's Westside Service & Towing

3111 Venture Blvd.
Bloomington, IN 47404
812-336-9050

8/16/2024 1:54:05 PM UEDT

Invoice #50103

Page:1

Kens Westside Service And Towing

3111 W Venture Blvd.
Bloomington, IN 47404

Phone: 812-336-9050

Vehicle : 2007 Mack CL733 15.0 L 912 CID L6 Cummins ISX Diesel
VIN : 1M1AD64YX7M002899
Fleet #/Driver : 15 / many
Created : 1/7/2022 12:19:24 PM UEST
Invoiced : 4/5/2022 9:39:54 AM UEDT

Service Writer : 16
Tag/State : 2441321/IN
Color : WHITE
Odometer In : 6471790
Odometer Out : 6471798

Labor/Notes

Qty	Technician	Reference	Description	Unit Price	Price
1		FREIGHT	freight charge	\$20.00	\$20.00
1		FREIGHT	freight charge	\$68.93	\$68.93
44.4	61	Guide	ENGINE OVERHAUL	\$0.00	\$0.00
Includes draining and filling of required Engine Fluids, Piston and Liner replacement, Main, Thrust and Rod Bearing replacement, and all required engine adjustments after re-assembly.					
5	62	LABOR	REPAIR STROBE LIGHTS AND ADD FRONT STROBE LIGHTS TO HOOD	\$0.00	\$0.00
3	42	LABOR	REPAIR AND INSTALL EXHAUST	\$0.00	\$0.00
1	62	DOT	D.O.T INSPECTION	\$0.00	\$0.00
1	62	ADJUST	BRAKE ADJUSTMENT	\$0.00	\$0.00
2	42	HEAVYDUTYSVC	HEAVY DUTY SERVICE	\$0.00	\$0.00
Change Oil, Oil Filter, Fuel Filter(s). Lubricate and Check Chassis.					
3.5	42	Guide	CENTER BEARING R&I	\$0.00	\$0.00
Includes R&I of driveshaft.					

Parts

Code	Reference	Description	Condition	Unit Price	Price
---	ISX106081	ENGINE INFRAME KIT	New	\$3,429.99	\$3,429.99
---	131640	GASKET KIT	New	\$469.99	\$469.99
---	9111535100X	AIR COMPRESSR	Rebuilt	\$599.99	\$599.99
---	4088665R	INJECTOR	Rebuilt	\$366.99	\$2,201.94
---	PI191938E	INJECTOR CAM SHAFT		\$2,369.99	\$2,369.99
---	PI191937	CAM SHAFT		\$1,149.99	\$1,149.99
---	cu5484228	rocker		\$177.39	\$532.17
---	CU484231	rocker		\$177.39	\$532.17
---	CU5484230	rocker		\$170.59	\$511.77
---	CU4311990	rocker		\$269.49	\$1,616.94
---	CU5484229	rocker		\$177.39	\$532.17
---	cu4965689	GASKET	New	\$61.88	\$61.88
Note: TRUCKPRO					
---	CU4059329	VALVE CROSSOVER		\$45.82	\$274.92
---	CU3413098	ENGINE BRAKE VALVE		\$628.59	\$3,771.54
---	CU4059342	VALVE SHIELD		\$47.15	\$282.90
---	CU3413137	BRAKE PLUNGER		\$45.42	\$45.42
---	4319031	CAM BEARINGS	New	\$22.09	\$88.36
---	4319032	CAM BEARINGS	New	\$35.70	\$107.10
---	3685690CUM	CAMSHAFT BUSHINGS/BEARINGS		\$16.98	\$118.86
---	5599284RX	OIL PUMP	New	\$649.42	\$649.42
---	3089025	O'RING SEAL	New	\$11.09	\$11.09

