

MODEL  
18 Ram 2500

VIN  
JG211745

MILES  
82661

DESCRIPTION

SERVICE REQUEST - Check engine light

SERVICE LABOR - Scan codes and found several codes for turbocharger performance and various emissions codes normally present with a turbocharger failure. Attempted to sweep vanes in turbo and they will move but get stuck. Advised customer of findings and given the go ahead to make repairs. Removed and replaced turbocharger. Changed air filter, engine oil and filter, and fuel filters. Cleared codes. Test drove truck to verify turbo operation. Performed service regeneration to be sure truck passes Nox efficiency tests. Had to add fuel to truck to finish regeneration as it was too low.

5326058 Turbocharger  
- 1yr Warranty

Shipping Charges w/ Core Return

MO-285 Oil Filter

15W40 Rotella T Diesel Oil (QT)

68157291AA Fuel Filter (Engine Mounted)

68197867AB Fuel Filter (Frame Mounted)

46930 Air Filter

Shop Supplies/Waste Disposal Fee - 1.5%

Diesel Fuel

QTY RATE

1

7.50 135.00

1 3,117.43

1 60.00

1 26.94

12 6.25

1 137.00

1 81.70

1 48.03

1 68.38

1 20.02

AMOUNT

0.00

1,012.50

3,117.43

60.00

26.94

75.00

137.00

81.70

48.03

68.38

20.02

Subtotal: 4,647.00

SUBTOTAL

4,647.00

TAX

0.00

TOTAL

4,647.00

TOTAL DUE

\$4,647.00

THANK YOU.

Purchaser hereby agrees that no express or implied warranties are

voice

ing

ality

to

products

laser

of

on