USA

Account Number 0268030	Invoice Number	Customer PO	Division	
	NOT AN INVOICE		CM	
SC700151	- Sincin reims	Service Call Date	Service Writer	
Make Model	COD - PAYMENT ON DELIVERY	11/20/2024	Richard R Aguilar	
AA 277B	Carial NI	Customer Equipment Number	Equipment Number	Last Meter
			EQN013571	2,401.00

Workscope

Troubleshoot - Piston Motor

Customer complaint:

troubleshoot low power when steering

Resultant damage:

to low rpm for hydraulic function

Cause of failure:

throttle not working

Repair process comments:

operated the machine and got all fluids to operating temp and noticed that the hand throttle did not work and the foot throttle was stuck. upon further trouble shooting the throttle was adjusted and pre set to around 1900 RPM. there is a small delay in the stick but is withing the CAT spec of 1.5 seconds. repair process is in segment four.

a coat frame and were in poor condition.

Labor

Flat Rate Labor

318.00
0.00
318.00
0.00
318.00

Extended Price

Repair - Seat Cushions

Customer complaint: replace seat

Resultant damage:

na

Cause of failure:

na

Bigiron