

**S&S Truck Repair Inc**  
P.O. Box 783 1503 7TH ST SE  
Pipestone, MN. 56164  
Phone: 507-825-3477

**INVOICE**

**244076**

**Invoice from History**

Printed Date: 10/14/2024

Work Completed: 08/21/2024

**PATER, ARVIN**

1986 INTERNATIONAL -

Lic # : TLA2984

Odometer In : 258992

Home 507-215-3646

VIN # : 1HSZEGFR3 **GHA34513**

Part Description	Qty	Sale	Ext	Labor Description	Hours	Ext
1" HOSE	1.00	39.95	39.95	CHECK OVER TRUCK	0.25	30.00
SILICON HOSE CLAMP - SS	2.00	2.94	5.88	CHECKED OVER. FOUND WHEEL SEAL LEAKING, SUSPENSION LEAF SPRING BROKEN, AND YOKES LOOSE.		
NAPA 10W40	2.00	10.18	20.36	POWER STEERING HOSE LEAKING	1.25	150.00
15" BLACK CABLE TIE	6.00	0.84	5.04	STEAMED CLEANED EVERYTHING BY PUMP AND RESERVOIR AND REMOVED OLD HOSE AND INSTALLED NEW HOSE AND CLAMPS AND TIED HOSE UP.		
SKF WHEEL SEAL	1.00	59.87	59.87	LEFT FRONT DRIVE AXLE WHEEL LEAKING	1.00	120.00
AXLE GASKET	1.00	1.87	1.87	JACKED AXLE UP AND REMOVED AXLE AND AXLE NUTS REMOVED HUB DRUM WHEEL ASSEMBLY AND REMOVED BEARINGS AND SEAL AND INSTALLED NEW SEAL AND REINSTALLED ASSEMBLY AND TIGHTENED AXLE NUTS AND REINSTALLED AXLE AND FILLED WITH OIL.		
SYN. GEAR OIL / 1 LB OR 1 PINT	1.00	5.66	5.66	TIGHTEN NUTS ON TRANNY OUTPUT AND FRONT DIFF INPUT	2.00	240.00
SPICER U-JOINT KIT	1.00	99.51	99.51	REMOVED DRIVE LINE AND TIGHTENED NUTS ON YOKES AND REAR U-JOINT BROKE AND REMOVED AND REPLACED. AND REINSTALLED DRIVE LINE GREASED ALL GOOD.		
				SPEEDOMETER NOT WORKING	0.25	30.00
				CABLE GOING INTO BACK OF TRANNY IS BROKEN SO NEED TO ORDER NEW ONE TO MAKE SPEEDOMETER WORK. TRIED TO ORDER THROUGH INTERNATIONAL AND OBSOLETE. COULDN'T LOCATE A NEW ONE.		
				Environmental Charge		28.50

[ Payments - Check (#PCHECK4957) - \$853.01 ]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

<b>Labor:</b>	<b>570.00</b>
<b>Parts:</b>	<b>238.14</b>
<b>HazMat:</b>	<b>28.50</b>
<b>Sub:</b>	<b>836.64</b>
<b>Tax:</b>	<b>16.37</b>
<b>Total:</b>	<b>\$853.01</b>
<b>Bal Due:</b>	<b>\$0.00</b>

Vehicle Received: 8/19/2024

Customer Number : 2729

Email Address: [greg@sstruckrepair.com](mailto:greg@sstruckrepair.com)