

# Busser Repair

24647 458 Ave  
Colton, SD 57018

# Invoice

DATE	INVOICE #
6/16/2023	71449

BILL TO
Tim Schut 8 Dale Schut 5224 E 60th N Sioux Falls SD 57104

Serial/ VIN number	Milage/ Hours	TERMS	PROJECT
29296XTD	3213		AC 190XT
QUANTITY	DESCRIPTION	RATE	AMOUNT
	Oil seal, 70256909	8.15	8.15
	Speedi Sleeve, 99134	33.74	33.74
	Grind flywheel	115.50	115.50
	Clutch disc, D261029	157.23	157.23
	Pilot bearing, 836205	14.06	14.06
	Releases bearing, 832065	24.44	24.44
	Pressure plate, D255689	144.25	144.25
	Rear engine seal, HC474024562	66.76	66.76
2	Hydraulic oil	18.40	36.80
9.25	Labor, Replace leaking front transmission seal, replace clutch and rear engine seal.	50.00	462.50
<b>Total</b>			\$1,063.43