

9 Mile

330721 County Road E
Minatare, NE 69356
Michael@schiffarms.com
3082208568

Estimate 1064

Date: 9/13/2022

Bill To
Schiff of Nebraska

Remit Payment To
Primary
330721 County Road E
Minatare, NE 69356

Service Order

Purchase Order

Service Writer

Authorizer

1064

Henwick, Michael

Item	Description	Quantity	Rate	Amount
Complaint: LEAF SPRING SHACKLE FAILED, RUBBED THROUGH ON HANGER BRACKET				
Cause: Customer request				
Labor	Correction: Rear Axle/Final Drives / Springs / LEAF SPRING SHACKLE FAILED, RUBBED THROUGH ON HANGER BRACKET	6.00000	\$20.00	\$120.00
Parts	BRACKET - B11-1034-7 - A	1	\$427.09	\$427.09
Parts	SHACKLE - B20-6017 - A	2	\$46.41	\$92.82
Subtotal				\$639.91
Shop Supplies				\$0.00

Unit: 207 **VIN:** 2NKHHJ7XXGM493654
2016 Kenworth T3 Series
Engine: 14,700 Hours

Labor	\$120.00
Parts	\$519.91
Subtotal	\$639.91
Exempt (0% of \$519.91)	\$0.00
Total	\$639.91

*: Core charges not included in total. You will be charged for any core that is not in returnable condition. This charge may be applied on a separate invoice.
The details and the estimate for the repairs provided above are based on our first inspection and do not constitute a guarantee that no further work or parts will be required. The estimate is not a guarantee of the final price of the repairs. The total bill of work and final price will be as per the details available on completion of the repairs. Other terms and conditions as applicable. If you authorize us to perform the above repairs, either verbally or in writing, you agree to pay in full for the work performed and parts required.

Customer Signature: _____

Printed Name: _____ **Date:** _____

9 Mile

330721 County Road E
Minatare, NE 69356
Michael@schiffarms.com
3082208568

Estimate

1112

Date:

10/15/2022

Bill To
Schiff of Nebraska

Remit Payment To
Primary
330721 County Road E
Minatare, NE 69356

Service Order

Purchase Order

Service Writer

Authorizer

1112

Henwick, Michael

Item	Description	Quantity	Rate	Amount
Complaint: REPLACE ALL 3 BATTERIES				
Cause: Customer request				
Labor	Correction: Electrical System / Battery / REPLACE ALL 3 BATTERIES	1.00000	\$20.00	\$20.00
Parts	18MO WTY BAT - 7236 - A	3	\$139.99	\$419.97
			Subtotal	\$439.97

Complaint: REPLACE LH SIDE HOOD SUPPORT BRACKET

Cause: Customer request (Inspection)

Labor	Correction: Chassis / Hood / REPLACE LH SIDE HOOD SUPPORT BRACKET	1.00000	\$20.00	\$20.00
Parts	HOOD SUPPORT LH - L85-1105 - A	1	\$117.81	\$117.81
Parts	CAB ANGLE FOR HOOD SUPPORT - K078-236 - A	1	\$87.27	\$87.27
			Subtotal	\$225.08

Shop Supplies

\$0.00

Unit: 207 **VIN:** 2NKHHJ7XXGM493654
2016 Kenworth T3 Series
Engine: 14,700 Hours

Labor	\$40.00
Parts	\$625.05
Subtotal	\$665.05
Exempt (0% of \$625.05)	\$0.00
Total	\$665.05

*: Core charges not included in total. You will be charged for any core that is not in returnable condition. This charge may be applied on a separate invoice.

The details and the estimate for the repairs provided above are based on our first inspection and do not constitute a guarantee that no further work or parts will be required. The estimate is not a guarantee of the final price of the repairs. The total bill of work and final price will be as per the details available on completion of the repairs. Other terms and conditions as applicable. If you authorize us to perform the above repairs, either verbally or in writing, you agree to pay in full for the work performed and parts required.

Customer Signature: _____

Printed Name: _____ **Date:** _____