



Tomorrow's Solutions Today
AHW LLC - Monticello
 600 W. Bridge St
 Monticello, IL 61856
 Main Office: (217) 762-2534
 Fax : (217) 762-8032

AHW LLC

www.ahwllc.com

Ashmore, IL	(217) 349-8338	Monticello, IL	(217) 762-2534
Clinton, IL	(217) 935-8558	Mount Pulaski, IL	(217) 792-5086
Crawfordsville, IN	(765) 361-3300	New Holland, IL	(217) 445-2212
Dwight, IL	(815) 584-2074	Rockville, IN	(765) 569-3195
Elburn, IL	(630) 365-6020	Somonauk, IL	(815) 498-2371
Hoopeston, IL	(217) 283-5511	Urbana, IL	(217) 328-2820
Manteno, IL	(815) 468-1745	Watseka, IL	(815) 432-5441
Melvir, IL	(217) *** PROFORMA INVOICE *** 85		762-3653



JOHN DEERE

Invoice To Account No: 72733

Deliver To:

SERVICE INVOICE

CLINT GOODMAN 538 COUNTY ROAD 00 N PESOTUM IL 61863-9769	CLINT GOODMAN 538 COUNTY ROAD 00 N PESOTUM IL 61863-9769 Bus: 217-253-6546 Prv: 217-253-6546 Mob: 217-841-0447 Email: cgoodmann02@aol.com	Invoice Number: Invoice Date: 07/29/2019 Location: 20 Work Order Number: 797790 Payment Type: Account Page: 1 of 2
--	--	---

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9410R	2440	1RW9410RHCH004117	W122024	

Service Reminders:

+9R Service Work 2 Retail

COMPLAINT:

ANTIFREEZE IN THE OIL

CORRECTION:

9R Service Work6/7

SERVICE CALL.

HELP GET STARTED AND ON SEMI TO HAUL TO SHOP.

LEA CLAYTON BACK TO SHOP.

UNLOAD TRACTOR AND PUT IN SHOP..

Found Coolant low but no oil in cooling system. Checked coolant level in radiator and engine at about water pump shaft level (checked with clear hose on drains). Removed water pump and found weep hole damp and plugged with debris. Replaced water pump then tried to pressurize again. Air was coming out of engine ventilator hose. Removed hood, right front tires, water hoses, air pipes, air hoses, fan drive, fan, fan driven sheave, alternator, engine harness connectors, engine mount bolts, drive shaft bolts, fuel lines and moved air conditioner compressor out of the way. Removed engine from tractor then mounted on engine stand. Plugged cooling system hoses to pressurize system. Removed oil pan ten pressurized system and found bottom of cylinder liner leaking. Tore down engine far enough to remove cylinder head and pistons. After removing liner found o rings had been damaged when assembled. Ordered re manufactured engine then installed. Filled with break in oil and new anti freeze. Filed DTAC case to get software for re manufactured released. Installed software and reset after treatment part numbers, serial numbers and calibration data. Ran and checked for leaks. Finished assembling tractor (hood, tires, shields). Reassembled old engine and prepared for return to Deere.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
DRC4222-P	Shop Towels Bucket Refill	2.00	\$12.25	\$24.50	Y
DZ100375	GASKET	1.00	\$5.22	\$5.22	N
DZ106318	WATER PUMP	1.00	\$1,212.24	\$1,212.24	N
DZ106318-CR	CORE for:Water Pump	-1.00	\$50.00	-\$50.00	N
MPR13068	Product Improvement Kit	1.00	\$97.49	\$97.49	N
R116911	CAP SCREW	12.00	\$3.43	\$41.16	N
R117080	RADIATOR H	1.00	\$19.42	\$19.42	N
R253764	SCREW	4.00	\$1.16	\$4.64	N
R300399	V-Belt	1.00	\$84.04	\$84.04	N
R320565	GASKET	3.00	\$8.27	\$24.81	N
R522023	GASKET	1.00	\$5.58	\$5.58	N
R528498	SEAL	1.00	\$6.70	\$6.70	N
R528512	SEAL	1.00	\$27.63	\$27.63	N
R528625	GASKET	1.00	\$34.85	\$34.85	N
R529640	GASKET	1.00	\$22.18	\$22.18	N



Tomorrow's Solutions Today

AHW LLC - Monticello
600 W. Bridge St
Monticello, IL 61856
Main Office: (217) 762-2534
Fax : (217) 762-8032

AHW LLC

www.ahwllc.com

Ashmore, IL (217) 349-8338
Clinton, IL (217) 935-8558
Crawfordsville, IN (765) 361-3300
Dwight, IL (815) 584-2074
Elburn, IL (630) 365-8020
Hoopston, IL (217) 283-5511
Manteno, IL (815) 466-1745
Melvin, IL (217) *** PROFORMA INVOICE *** 85) 762-3650
Monticello, IL (217) 762-2534
Mount Pulaski, IL (217) 792-5086
New Holland, IL (217) 445-2212
Rockville, IN (765) 569-3195
Somonauk, IL (815) 498-2371
Urbana, IL (217) 328-2820
Watseka, IL (815) 432-5441



JOHN DEERE

Invoice To Account No: 72733

Deliver To:

SERVICE INVOICE

CLINT GOODMAN
538 COUNTY ROAD 00 N
PESOTUM IL 61863-9769

CLINT GOODMAN
538 COUNTY ROAD 00 N
PESOTUM IL 61863-9769
Bus: 217-253-6546 Prv: 217-253-6546
Mob: 217-841-0447
Email: cgoodmann02@aol.com

Invoice Number:
Invoice Date: 07/29/2019
Location: 20
Work Order Number: 797790
Payment Type: Account
Page: 2 of 2

Table with 5 columns: Make/Model, Meter, Serial Number, EQ Id, Fleet No. Row 1: 2013 JOHN DEERE 9410R, 2440, 1RW9410RHCH004117, W122024

Service Reminders:

Table with 6 columns: Part Number, Description, Quantity, Net Price, Extended Price, Taxed Ind. Includes items like O-Ring, CLAMP, PRESSURE S, OIL FILTER, etc.

Miscellaneous Charges:

Service Accessories \$51.95

Labor: \$10,410.72 Parts: \$61,427.01 OL&M: \$0.00 Misc: \$155.20 Sub-Total: \$71,992.93

Customer PO No:
Tax Exempt No: Get Card
Advisor: SCOT WESTRAY

Labor: \$10,410.72
Parts: \$61,427.01
OL&M: \$0.00
Misc: \$155.20
Sales Tax: \$22.17
Total: \$72,015.10

TERMS AND CONDITIONS

Charge Tickets: All accounts are due and payable 30 DAYS FROM THE DATE OF PURCHASE. A finance charge of 2% per month (24% ANNUAL PERCENTAGE RATE) will be charged on all past due accounts. All collections costs (i.e. collection agency, attorney's fees, etc.) will be charged to the customer. Normally stocked parts are returnable within 10 days. A 15% restocking fee applies after 10 days. Special ordered parts are non-returnable. All electrical parts are non-returnable.

* Farm Plan Tickets: This purchase is subject to the terms and conditions of the Farm Plan credit agreement. Normally stocked parts are returnable within 10 days. A 15% restocking fee applies after 10 days. Special ordered parts are non-returnable. All electrical parts are non-returnable.

Received by Credit Card Tickets: Normally stocked parts are returnable within 10 days. A 15% restocking fee applies after 10 days. Special ordered parts are non-returnable. All electrical parts are non-returnable.

Work Order Preview

AHW LLC

8/21/2019 9:44

MONTICELLO
600 W. Bridge Street
Monticello, IL 61856
Location Phone:

Location:20

Invoice To: 72733 GOODMAN, CLINT 538 COUNTY ROAD 00 N PESOTUM, IL 61863-9769	GOODMAN, CLINT 538 COUNTY ROAD 00 N PESOTUM, IL 61863-9769 Phone: 217-253-6546	Customer Order: Advisor: WESTRAY, SCOT	Eq IDW122024 1N DEERE 9410R 4WD TRACTOR 1RW9410RHCH004117 Meter: 2440
---	---	--	---

Work Order: **Job Code:** Retail - +9R Service Work 2
797790

Created: 6/6/2019
Vehicle Picked up

Parts		<u>Requested</u>	<u>Delivered</u>	<u>Price</u>	<u>Extended</u>
SE502701-CR	CORE for:Diesel Engine Reman	-1.00	-1.00	\$9,800.00	(\$9,800.00)
		Total Parts			\$56,530.26
Job Code +9R Service Work 2 Total					\$66,940.98
Repair Order # 797790 Total					\$66,940.98

SALES TAX IS NOT CALCULATED NOR INCLUDED.
INVOICED WORK ORDERS DO NOT INCLUDE MISCELLANEOUS ITEMS

Work Order Preview

AHW LLC

8/21/2019 9:44

MONTICELLO
600 W. Bridge Street
Monticello, IL 61856
Location Phone:

Location:20

Invoice To: 72733 GOODMAN, CLINT 538 COUNTY ROAD 00 N PESOTUM, IL 61863-9769	GOODMAN, CLINT 538 COUNTY ROAD 00 N PESOTUM, IL 61863-9769 Phone: 217-253-6546	Customer Order: Advisor: WESTRAY, SCOT	Eq IDW122024 IN DEERE 9410R 4WD TRACTOR 1RW9410RHCH004117 Meter: 2440
---	---	--	---

Work Order: 797790 **Job Code:** Retail - +9R Service Work 2

Created: 6/6/2019
Vehicle Picked up

	Requested	Delivered	Price	Extended
--	-----------	-----------	-------	----------

Details

CORRECTION:

9R Service Work6/7

DTAC-647928

SERVICE CALL.

HELP GET STARTED AND ON SEMI TO HAUL TO SHOP.

LEAd CLAYTON BACK TO SHOP.

UNLOAD TRACTOR AND PUT IN SHOP..

Found Coolant low but no oil in cooling system. Checked coolant level in radiator and engine at about water pump shaft level (checked with clear hose on drains). Removed water pump and found weep hole damp and plugged with debris. Replaced water pump then tried to pressurize again. Air was coming out of engine ventilator hose. Removed hood, right front tires, water hoses, air pipes, air hoses, fan drive, fan, fan driven sheave, alternator, engine harness connectors, engine mount bolts, drive shaft bolts, fuel lines and moved air conditioner compressor out of the way. Removed engine from tractor then mounted on engine stand. Plugged cooling system hoses to pressurize system. Removed oil pan ten pressurized system and found bottom of cylinder liner leaking. Tore down engine far enough to remove cylinder head and pistons. After removing liner found o rings had been damaged when assembled. Ordered re manufactured engine then installed. Filled with break in oil and new anti freeze. Filed DTAC case to get software for re manufactured released. Installed software and reset after treatment part numbers, serial numbers and calibration data. Ran and checked for leaks. Finished assembling tractor (hood, tires, shields). Reassembled old engine and prepared for return to Deere.

Service Accessories

Standard Rate SHOP LABOR

06/07/2019 from 09:52 to 12:00	TIM WALKER	2.14	\$149.57
06/17/2019 from 07:13 to 12:03	MARTY STOERGER	4.84	\$556.40
06/17/2019 from 12:38 to 15:56	MARTY STOERGER	3.30	\$379.86
06/18/2019 from 07:24 to 11:51	MARTY STOERGER	4.44	\$510.51
06/20/2019 from 12:41 to 17:00	MARTY STOERGER	4.33	\$497.92
06/21/2019 from 06:45 to 12:14	MARTY STOERGER	5.48	\$383.66
06/21/2019 from 12:45 to 17:11	MARTY STOERGER	4.44	\$310.74
06/24/2019 from 06:40 to 13:15	MARTY STOERGER	6.59	\$757.69
06/24/2019 from 13:49 to 17:15	MARTY STOERGER	3.43	\$394.45
06/25/2019 from 06:40 to 12:34	MARTY STOERGER	5.90	\$678.50
06/25/2019 from 13:32 to 17:24	MARTY STOERGER	3.86	\$444.22
06/26/2019 from 06:41 to 07:24	MARTY STOERGER	0.73	\$84.02
06/26/2019 from 12:50 to 17:14	MARTY STOERGER	4.39	\$505.05
06/27/2019 from 06:42 to 12:06	MARTY STOERGER	5.39	\$620.10
06/27/2019 from 12:41 to 13:20	MARTY STOERGER	0.65	\$74.59
06/28/2019 from 12:46 to 13:11	MARTY STOERGER	0.41	\$47.60
07/01/2019 from 06:34 to 12:05	MARTY STOERGER	5.51	\$633.87
07/01/2019 from 12:37 to 17:10	MARTY STOERGER	4.56	\$523.89
07/02/2019 from 06:37 to 12:08	MARTY STOERGER	5.52	\$634.44
07/02/2019 from 12:43 to 17:11	MARTY STOERGER	4.46	\$513.41
07/03/2019 from 06:33 to 12:50	MARTY STOERGER	6.28	\$722.07

Work Order Preview

AHW LLC
8/21/2019 9:44

MONTICELLO
600 W. Bridge Street
Monticello, IL 61856
Location Phone:

Location:20

Invoice To: 72733 GOODMAN, CLINT 538 COUNTY ROAD 00 N PESOTUM, IL 61863-9769	GOODMAN, CLINT 538 COUNTY ROAD 00 N PESOTUM, IL 61863-9769 Phone: 217-253-6546	Customer Order: Advisor: WESTRAY, SCOT	Eq IDW122024 IN DEERE 9410R 4WD TRACTOR 1RW9410RHCH004117 Meter: 2440
---	---	--	---

Work Order: 797790 **Job Code: Retail - +9R Service Work 2**

Created: 6/6/2019
Vehicle Picked up

	<u>Requested</u>	<u>Delivered</u>	<u>Price</u>	<u>Extended</u>
<u>Ag Rate SHOP LABOR</u>				
07/03/2019 from 13:07 to 13:42 MARTY STOERGER		0.58		\$66.34
07/08/2019 from 06:37 to 07:23 MARTY STOERGER		0.77		\$88.30
07/08/2019 from 10:54 to 12:45 MARTY STOERGER		1.87		\$214.51
07/08/2019 from 13:00 to 17:10 MARTY STOERGER		4.17		\$479.48
07/09/2019 from 06:33 to 07:45 MARTY STOERGER		1.19		\$137.30
07/11/2019 from 06:37 to 06:39 MARTY STOERGER		0.02		\$2.23
Total SHOP LABOR		95.25		\$10,410.72

<u>Parts</u>				
DRC4222-P	Shop Towels Bucket Refill	2.00	2.00	\$12.25 \$24.50
TY22487	Hose Clamp	1.00	1.00	\$2.25 \$2.25
TY26101	Brake Cleaner	4.00	4.00	\$4.92 \$19.68
TY26661	12D Break-In Plus Oil 1 gal	12.00	12.00	\$21.61 \$259.32
FREIGHT	FREIGHT	1.00	1.00	\$93.00 \$93.00
FREIGHT	FREIGHT	1.00	1.00	\$10.25 \$10.25
POLICYSRV	CREDIT TO ADJUST SERVICE BILL	1.00	1.00	(\$2,500.00) (\$2,500.00)
SPECIALLOW	CREDIT FOR SPECIAL ALLOWANCE	1.00	1.00	(\$2,500.00) (\$2,500.00)
DZ100375	GASKET	1.00	1.00	\$5.22 \$5.22
DZ106318	WATER PUMP	1.00	1.00	\$1,212.24 \$1,212.24
DZ106318-CR	CORE for:Water Pump	-1.00	-1.00	\$50.00 (\$50.00)
MPR13068	Product Improvement Kit	1.00	1.00	\$97.49 \$97.49
R116911	CAP SCREW	12.00	12.00	\$3.43 \$41.16
R117080	RADIATOR H	1.00	1.00	\$19.42 \$19.42
R253764	SCREW	4.00	4.00	\$1.16 \$4.64
R300399	V-Belt	1.00	1.00	\$84.04 \$84.04
R309746	Shield	-1.00	-1.00	\$88.04 (\$88.04)
R309746	Shield	1.00	1.00	\$88.04 \$88.04
R320565	GASKET	3.00	3.00	\$8.27 \$24.81
R522023	GASKET	1.00	1.00	\$5.58 \$5.58
R528498	SEAL	1.00	1.00	\$6.70 \$6.70
R528512	SEAL	1.00	1.00	\$27.63 \$27.63
R528625	GASKET	1.00	1.00	\$34.85 \$34.85
R529640	GASKET	1.00	1.00	\$22.18 \$22.18
R530142	O-Ring	2.00	2.00	\$1.60 \$3.20
RE52702	CLAMP	1.00	1.00	\$13.13 \$13.13
RE539840	PRESSURE S	1.00	1.00	\$81.49 \$81.49
RE546669	Wiring Harness	-1.00	-1.00	\$225.81 (\$225.81)
RE546669	Wiring Harness	1.00	1.00	\$225.81 \$225.81
RE572785	OIL FILTER	1.00	1.00	\$49.67 \$49.67
RE62981	Pressure Relief Valve	1.00	1.00	\$3.49 \$3.49
SE502701	DIESEL ENG	1.00	1.00	\$69,234.32 \$69,234.32



Reports

Search For?

Machine

Customer

- Claim Information

Engine Option

Expiration Report

[Feedback](#)

PIN /Serial

: 1RW9410RHCH004117

Customer Number	:	336133952
Purchase Type	:	FARM
End Use Code	:	ROW CROP / SMALL GRAIN
Delivery Date	:	25 Oct 2012
Settlement Date	:	25 Oct 2012
Invoice Date	:	03 Aug 2012
Registration Date	:	25 Oct 2012
Selling Dealer	:	066281-SLOAN IMPLEMENT COMPANY, Assumption, IL
Responsible Dealer	:	069839-AHW LLC, Urbana, IL

Model	:	9410R	Description	:	9410R TR IT4 24/6 MANUAL SHIFT	Model Year	:	2012
Latest Delivery Date	:	25 Oct 2012	Last Reported Registration Measurement	:	5			
Machine Build Date	:	02 Aug 2012	Last Reported Claim Measurement	:	2440			
Approximate Cumulative Rental Days*	:	0	JDLink Expiration Date	:	31 Dec 2021			
Machine status 1	:	Used Machine						

*See John Deere Warranty System for accumulated rental days/detailed rental history

Warranty Coverage

[Show/Hide](#)

Warranty type <input type="checkbox"/>	Coverage term <input type="checkbox"/>	Expiration Date <input type="checkbox"/>	Days Remaining (may be estimate)	Hours Limit	Deductible Amount
Default Warranty	120m/0h	24 Oct 2012	0		N/A
Basic Warranty	24m/2000h	26 Oct 2014	0	2000	N/A
Extended Warranty (Powertrain)	60m/2000h	25 Oct 2017	0	2000	USD-750.0
Emissions Warranty	60m/3000h	26 Oct 2017	0	3000	N/A

Component Serial Numbers

[Show/Hide](#)

Component <input type="checkbox"/>	Serial Number <input type="checkbox"/>
VALVE,RC SELECTIVE CONTROL VALVE	092611176906A
FILTER EXHAUST DPF	REXF180007230
ENGINE (DEERE MANUFACTURED)	RG6135R006485
MACHINE INFORMATION GATEWAY	PCMAMGA826018
PUMP, HYD. VARIABLE DISPLACEMENT	A122807156
MODULE, DISPLAY	210439-312697
REPLACEMENT ENGINE	SE6135R010253
MODULE, DISPLAY	AL210439-3126
SOUND-GARD BODY	RWCG045003234
VALVE,RC SELECTIVE CONTROL VALVE	RE30926111769
FILTER OXIDATION DOC	REXD180007629
TRANSMISSION	R0TSMST040133
BELT, FAN	RE335495F1342
POSITION RECEIVER	PCGT3TA396184

BELT, FAN
C FRAME

E335495F13424
ROCF607049008

Order BASE / Option Codes

[Show/Hide](#)

Code	Component	Base Machine Code
03BORW0202	U.S.A. DEST. COUNTRY	03BORW
03BORW0409	ENGLISH OP MANUAL & LABELS	03BORW
03BORW0500	0500 NO PACKAGE	03BORW
03BORW1400	24/6 MANUAL SHIFT TRANS	03BORW
03BORW1823	7IN COLOR TOUCH DISPLAY	03BORW
03BORW1838	SF2 RECEIVER	03BORW
03BORW1847	SF2 AT ACTIVATION	03BORW
03BORW1887	JDLINK ULT. PROMOTION	03BORW
03BORW2059	CAB DELUXE COMMANDVIEW II	03BORW
03BORW2660	DLX RADIO PKG	03BORW
03BORW3241	STD HYDR SYSTEM	03BORW
03BORW3341	FOUR REMOTE CYLINDER CONTROL	03BORW
03BORW3800	NO REAR PTO	03BORW
03BORW4000	NO RS-HITCH/ADJ.DRAWBAR	03BORW
03BORW4321	REG DRAWBAR CAT 4	03BORW
03BORW5055	REAR AXLE (110MM) 120 IN	03BORW
03BORW5510	DUAL 710/70R38 166A8 R1W	03BORW
03BORW5903	MICHELIN TIRES	03BORW
03BORW7202	PRM HID LIGHT PKG	03BORW
03BORW8242	DUAL BEAM RADAR SENSOR	03BORW
03BORW8340	ENGINE 13.5L IT COMPLIANT	03BORW
03BORW8760	PIN, HEAVY GREASEABLE STEER	03BORW
03BORW8970	(2)165LB & (4)450LB OUT	03BORW

Customer History

[Show/Hide](#)

Customer 1 of 1	
<u>JOHN GOODMAN</u> 317 COUNTY ROAD 700 E PESOTUM IL US 618639761	Customer Number : 336133952 Purchase Type : FARM End Use Code : ROW CROP / SMALL GRAIN
Home : US2178672385 Cell : US2172536546 Business : US2178672385	Delivery Date : 25 Oct 2012
Selling Dealer : 066281-SLOAN IMPLEMENT COMPANY, Assumption, IL Responsible Dealer : 069839-AHW LLC, Urbana, IL	

Claim History

[Show/Hide](#)

Dealer	Claim #	Type	Fail Date	Repair Date	Process Date	Ref # 1	Ref # 2	Measurement
060534	104697456	NORMAL	21 Oct 2013	21 Nov 2013	27 Nov 2013	W10142-1	W10142	354
060534	104698167	NORMAL	23 Oct 2013	21 Nov 2013	25 Nov 2013	W10191-1	W10191	354
060534	104698113	NORMAL	23 Oct 2013	21 Nov 2013	25 Nov 2013	W10190-1	W10190	354
060534	106424101	NORMAL	25 Sep 2014	15 Oct 2014	17 Oct 2014	W13484-1	W13484	714
066210	107744057	PIP	18 Jun 2015	22 Jun 2015	26 Jun 2015	57020-1	57020	1105
063949	109084708	PIP	09 Mar 2016	14 Mar 2016	21 Mar 2016	654207-1	654207	1390
066210	112913595	PIP	24 Feb 2018	04 Apr 2018	05 Apr 2018	208027-02		2040

066210	112913579	PIP	24 Feb 2018	04 Apr 2018	05 Apr 2018	208027-01	2040
069839	115493435	PIP	26 Jun 2019	18 Jul 2019	24 Jul 2019	800856	2440

PIP History					Show/Hide
PIP Number	PIP Type	PIP Participation Type	PIP Title	PIP Status	
14RW605	Fix-as-Fail	Dealer	14RW605 - TOUCH COMMANDCENTER™ DISPLAY IMPROVEMENT	TERMINATED	
15RW622B	Safety Mandatory	Dealer	15RW622B-9000,9020,9030,9R WHEEL TRACTOR DRIVE SHAFT RETAINE	COMPLETE	
15RW622I	Fix-as-Fail	Dealer	15RW622I-9000,9020,9030,9R WHEEL TRACTOR DRIVE SHAFT RETAINE	NOT_FAILED	
15RW646A	Safety Mandatory	Dealer	15RW646A - 9000,9020,9030 MY12-14 9R DRIVE SHAFT INSPECTION	COMPLETE	
15RW646C	Fix-as-Fail	Dealer	15RW646C - 9000,9020,9030 MY12-14 9R DRIVE SHAFT INSPECTION	NOT_FAILED	
16RW700C	Mandatory	Dealer	16RW700C - 9R/RT MODEL YEAR 12-14 WITH 6135 IT4 ENGINE ECU H	COMPLETE	
16RW726J	Safety Mandatory	Dealer	16RW726J - 9000, 9020, 9030, 9R MY12-14 FRONT DRIVESHAFT IMP	COMPLETE	
17RW740	Product Enhancement Programs	Dealer	17RW740 - 9000, 9020, 9030, & 9R MY12-14 FRONT DRIVESHAFT U-	TERMINATED	
17RW765A	Fix-as-Fail	Dealer	17RW765A - 9R AND 9RT AG TRACTORS 13.5L TORSIONAL DAMPER IMP	COMPLETE	
18RW788A	Fix-as-Fail	Dealer	18RW788A - 9R, 9RT, AND 9RX IT4/STAGE IIIB AND FT4/STAGE IV	NOT_FAILED	

| EXPORT TO EXCEL | PRINT |

Copyright © 2009 Deere & Company. All rights reserved