ps fltr 7191

UNIT 144
INTERNATIONAL TRUCK (2006)
MODEL NO. 7400 SFA (4X2)
VIN NO. 1HTWDAZR56J226371
INTERNATIONAL ENGINE DTS70
SERIAL NO. 570HM2U2062241
CU. IN. 570 (310HP @ 2200RPM
ALLISON 6 SPEED AUTOMATIC
MODEL NO. 3000 RDS6 SP W/PTO
SERIAL NO. 6510566357
CLASS 106
License Plate Number 68822

			Hours or			Oil	Fuel	Power	Check		Differentia	a				Air		Trans	
Date		Mechanic	Mileage	Oil	Grease	Filter	Filter	Steering	Trans	Lights	ı	Battery	Radiator	Tires	Brakes	Filter	Hyd.	Filter	Air Dryer
6/16/05	DELIVERED	TRUCKS IN																	
	CHECKED SPECS-CLASSIFY & INSURE	1230																	
	DELIVERED TOO MTE TO INSTALL BODY	1230																	
	DIFFERENTIAL STILL HAS A VIBRATION & NOISE AROUND 50 TO 55	1230																	
	MPH - TOLD TRUCKS INC. ABOUT IT (ED AND STEVE)																		
8/9/05	PICK UP TRUCKS FROM MTE W/EQUIPMENT INSTALLED	1230																	
8/9/05	INSTALL NEW SIDE BOARDS	1934	*1043*																
8/10/05	CLASSIFY & INSURE & ENTER INTO COMPUTOR INSTALLED	1230																	
0/10/03	EQUIPMENT	1200																	
	TOOK BACK TOO TRUCKS INC TO HAVE DIFFERENTIAL CHECKED	1230																	
	OUT																		
8/11/05	BRING BACK FROM TRUCKS INC TO INSTALL RADIO	1230	*1934*																
8/17/05	TOOK BACK TOO TRUCKS INC. TO HAVE DIFFERENTIAL CHECKED	1230																	
0/1//05	OUT																		
8/22/05	PICK UP FROM TRUCKS INCTAKE TOO MTE FOR WARRANTY	1230	*1934*																
	WORK ON WING																		
8/23/05	PICK UP FROM MTE-TAKE TOO TRUCKS INC.	1230																	
8/30/05	TALKED TO NAVISTAR REP ABOUT NOISE IN REAR END HE WILL	1230																	
0,00,00	GET IN TOUCH WITH ROCKWELL REP																		
	ROAD READY	2354																	
8/31/05	DELIVERED TRUCK TO CHERI	1230																	
9/1/05	ADJUST AIR RIDE	1934																	
9/8/05	REPOSITION CIRUS CONTROLS ON SEAT SO SEAT WILL	MTE																	
	OSCILLATE (WARRANTY)																		
	MAKE UP AND WELD ON FORK HOLDER-INSTALL LICENSE PLATE	0054																	
10/24/05	AND MOUNTING BRACKET - TAKE TO TRUCKS INC. FOR	2354																	
	WARRANTY WORK	TRUCKO IN																	
10/25/05		TRUCKS IN																	
11/15/05	HYD VALVE FOR WING TOE WAS STUCK OPEN-HYD GOT HOT AND	MTE																	
444000	WOULD NOT OPERATE HYD VALVE FOR SPINNER WAS STUCK OPEN	MTE																	
11/16/05			2400		X				X										
11/23/05	GREASE TRUCK SYNE - CHECK FOR VIBRATION W/BOX UP (AUGER RUNNING TOO	1934	3489		^				^										
11/28/05	FAST)	2354	*MTE*																
	TRUCKS INC FOUND RIGHT FRT TIRE WAS OUT OF ROUND																		
40/4/05	(WARRANTY) WE INSTALLED 2 NEW MICHELIN XZY-3 20 PLY FRT	TRUCKS INC	4186																
12/1/05	TIRES	1934	4100																
	TOOK TOO TRUCKS INC. SO IHC REPRESENTATIVE COULD DRIVE																		
12/7/05	AND CHECK OUT FRONT WHEEL WOBBLE OR VIBRATION - LOAD	1230-1934																	
12///05	WITH SALT FOR TEST	1230-1934																	
	REPAIR BROKEN OFF JOY STICK-SLOW DOWN SPINNER-SPEED																		
12/13/05		MTE																	
12/13/03	(WARRANTY)	WITE																	
	CHECK OUT AIR LEAK IN SEAT (COULDN'T FIND ANY)	TRUCKS IN																	
12/14/05	MOUNT UP 2 NEW MICHELIN 315/80R22.5 XZU-S FRT TIRES	1934																	
12/20/05	FULL SERVICE-CHANGE MAIN TRANS FILTER	1934	6871	32	Х	Х	X		X									X	
12/28/05	NEEDS A NEW SENSOR (TRUCKS INC WILL CALL WHEN IT IS IN)	1230	0071	02	^	^,													
	INSTALL NEW TURBO BOOST SENSOR-CHECK TOE IN ON FRONT																		
1/13/06	END (WARRANTY)	TRUCKS IN																	
1/26/06	INSTALL NEW TURBOCHARGER (WARRANTY)	TRUCKS IN																	
2/1/06	CHECK OUT FRONT END WOBBLE WIHC REP AT NEW GLARUS	1230																	
	REMOVE WING-TAKE TOO TRUCKS INC SO THEY CAN TAKE TO																		
2/2/06	POMPS FOR FRT END ALIGNMENT	1230	*2354*																
	INSTALL WING-HAD POMPS ADJUST THE CASTER ON FRT END -	4000	*100 11																
2/3/06	REAR AXLE OUT OF ALIGNMENT - TOE IN WAS OFF	1230	*1934*																
2/6/06	TAKE TOO MTE FOR COMPUTOR CONTROL REMOUNT	1230																	
	MOUNT COMPUTOR CONTROLS ON A PEDISTAL & SCREENS ON	MTE																	
2/8/06	DASH TO PREVENT VIBRATION	IVI I E																	

ps fltr 7191

UNIT 144
INTERNATIONAL TRUCK (2006)
MODEL NO. 7400 SFA (4X2)
VIN NO. 1HTWDAZR56J226371
INTERNATIONAL ENGINE DT570
SERIAL NO. 570HM2U2062241
CU. IN. 570 (310HP @ 2200RPM
ALLISON 6 SPEED AUTOMATIC
MODEL NO. 3000 RD56 SP W/PTO
SERIAL NO. 6510566357
CLASS 106
License Plate Number 68822

	Date		Mechanic	Hours or Mileage	Oil	Grease	Oil Filter	Fuel Filter	Power Steering	Check Trans	Lights	Differentia I Battery	Radiator	Tires	Deal	Air Filter	U	Trans	A :- E
	,	TOOK TOO MTE TO HAVE BOX ROCKING CHECKED OUT-THEY		3-		- Judo			Steering	114113	Ligitio	Dattery	Nauidior	riies	Brakes	riiler	Hyd.	Filter	Air Dryer
2/1	13/06	SAID THAT ROCKING IS IN THE ROLLERS ON TOP OF THE BOX LIFT CYLINDER - NORMAL ROCKING. PINTLE HITCH WAS INSTALLED	MTE																
2/1	14/06	WORNG THAT WHY IT HITS SANDER BOTTOM CHECKED WHEEL HOP (DETERMINED WE HAD A TOUCHY FOOT																	
	14/00	FEED) CHANGE PINTLE HITCH BUSHINGS FROM FRT TO BACK	1230 392	392															
	21/06 23/06	GROUND OFF LATCHES TO MAKE TOOL BOX DOORS CLOSE DISMOUNT BAD TIRE OFF RIM TO SEND IN	MTE 1230																
	24/06	REPLACE AIR RELEASE VALVE FOR AIR RIDE (WARRANTY) ADJUST FOOTFEED TO NO.3 SETTING (WARRANTY)	TRUCKS IN TRUCKS IN																
	27/06 2/06	ADJUST FOOTFEED TO MANUAL TRANS SETTING (NO GOOD) GREASE TRUCK	IHC-REPS	44500		v													
3/2	2/00	INSTALL NEW DOUBLE SHOCK SEAT BOTTOM-BLOW OUT W/S	1934 1934	11562		Х				X									
	3/06	WASHER NOZZLE PASSENGER SIDE SPITTING BLACK SMOKE (WARRANTY) FOUND NOTHING	LAKESIDE																
	5/06 0/06	INSTALL DIFFERENT FOOTFEED (IHC REP GREG MCKEON) FULL SERVICE (238.2HRS) INSTALL NEW FRT SHOCKS	IHC-REPS 1934	13306	32	Х	х	х		x									
	7/06	PICK UP FROM NEW GLARUS SHOP & TAKE TOO LAKESIDE GO OVER TO LAKESIDE IHC-DRIVE TRUCK-MAKE IT SMOKE	1230 1934																
4/5	5/06	TAKE TOO AND FROM LAKESIDE IHC (INSTALL COVER OVER CPS) TAKE TRUCK TO NEW GLARUS SHOP	1230							45									
4/12	2/06	BRING BACK FROM LAKESIDE IHC. (REMOVED MAGNETS FROM FAN CLUTCH) (WARRANTY)	1230																
5/3	3/06	TAKE TOO LAKESIDE IHC TO HAVE NEW VARIABLE FRONT SPRINGS INSTALLED	1230																
5/8	3/06	PICK UP FROM TRUCKS INC. (VARIABLE FRONT SPRINGS INSTALLED)	1230																
0/4		TAKE TOO LAKESIDE IHC TO HAVE (JAKE BRAKE CHECKED BELT																	
-	1/06	TENSIONER CHECKED - AM/FM RADIO RECEPTION BAD FOOD FEED PUHES HARD	1230																
6/5 6/6	5/06	INSTALLED NEW TURBO HOSE (WARRANTY) MAKE A NEW STEP ON TANK HALF WAY BETWEEN TOP AND	LAKESIDE																
	9/06	BOTTOM STEP INSTALL NEW TURBO CHARGER 2ND TIME (WARRANTY)	2354 LAKESIDE																
	3/06	TAKE TOO LAKESIDE (WARRANTY) STARTING & SMOKING PROBLEM (COULDN'T FIND ANYTHING)	1230																
7/24	4/06	PICKED UP FROM LAKESIDE (REPLACED KEY SWITCH AND INSTALLED REBUILT STARTER) WARRANTY	1230																
7/27	7/06	REPAIR W/S WASHER HOSE	1934																
8/3		REPLACED CRANKSHAFT SENOR & CAM SHAFT POSITION SENSOR (WARRANTY)	LAKESIDE																
8/7/		GREASE TRUCK INSTALL NEW SERPENTINE BELT	1934 1230	16524 *1934*		Х				X									
9/14		PICK UP FROM ALPHORN (RIGHT DOOR REPAIR) CHECK SERPENTINE BELT	1230 2354	*1934*															
9/19		CHECK ANTI FREEZE -30 PICK UP FROM LAKESIDE TAKE TOO ALPHORN TO HAVE DECALS	2354																
9/26	5/06	INSTALLED AND TAKE BACK TO LAKESIDE INSTALL FRT SHOCK ABSORBERS	1230 LAKESIDE																
	3/06	PICK UP FROM LAKESIDE AND TEST DRIVE INSTALL NEW FRT SHOCKS-NEW TENSIONER PULLEY FOR	1230																
12/24	4/06	INSTALL NEW FRESHOCKS-NEW TENSIONER PULLEY FOR SEPENTINE BELT - INSTALL NEW GASKETS FOR THE EGR COOLER (WARRANTY)	LAKESIDE																
		CHANGE TRANS FILTERS-CHANGE AIR DRYER ELEMENT W WINTER CHECK	1934	17710														X	X
11/2	2/06	DID RECALL (G-06910) REMOVE PRESSURE PROTECTION VALVE ON 1200 AIR DRYERS	LAKESIDE																
		DID RECALL (05513-R1) REPLACE BRAKE PUSH ROD IN DRIVERS CONTROL MODULE	LAKESIDE																
11/7		REPLACED WIRING HARNESS TOO ECM	LAKESIDE																

ps fltr 7191

UNIT 144
INTERNATIONAL TRUCK (2006)
MODEL NO. 7400 SFA (4X2)
VIN NO. 1HTWDAZRS6J226371
INTERNATIONAL ENGINE DT570
SERIAL NO. 570HM2U2062241
CU. IN . 570 (310HP @ 2200RPM
ALLISON 6 SPEED AUTOMATIC
MODEL NO. 3000 RDS6 SP WIPTO
SERIAL NO. 6510566357
CLASS 106
License Plate Number 68822

			Hours or	0.1		Oil	Fuel	Power	Check	Limbia	Differentia Battery	Dadiston	T:	Destres	Air Filter	T. Frank	Trans Filter	Air Dover
Date	The second secon	Mechanic	Mileage	Oil	Grease	Filter	Filter	Steering	Trans	Lights	1 ballery	Radiator	Tires	Brakes	Filler	Hyd.	riitei	Air Dryer
11/30/06	AIM RIGHT PLOW LIGHT-INSTALL NEW MARKER POLE ON PLOW	2354	10550			V.			V									
12/5/06	FULL SERVICE (2607HRS)	1934	19556	32	Х	X	X		X									
12/14/06	DIAGNOSE COMPUTOR PROBLEM AND SHORTED OUT PRINTED	1230	*2354*															
12/14/00	CIRCUIT FOR AUGER SENSOR - TAKE TO MTE																	
	ADD 2 QTS OF TRANSYND TO TRANS	2354																
10/15/06	REPLACE RED BOX COMPUTOR COMPONENT-REPLACE CIRCUIT	MTE																
12/15/06	BOARD FOR AUGER SENSOR	MILE																
1/4/07	INSTALL REBUILT RED BOX COMPUTOR COMPONENT IN PLACE OF	MTE																
1/4/07	NEW ONE THAT WAS INSTALLED PREVIOUSLY	WIIL																
	TAKE TOO 92 & SANDYHOOK RD	1230																
1/17/07	INSTALL 2 NEW W/S WIPERS-INSTALL NEW (LH) FOG LIGHT	1230																
1/18/07	REPLACE BROKEN MIRROR ON RIGHT SIDE	1230																
	REPAIR BROKEN WIRE TO RIGHT TOP STROBE LIGHT-INSTALL A	1934																
	HOT WIRE TO CENTER OF 7 PRONG TRUCK PLUG	1934																
1110107	BRING TOO SHOP MAIN STROBE LIGHTS DONT SHUT OFF HAD TO	1230	*2354*															
1/19/07	ORDER NEW CIRCUIT BOARD FOR SWITCH	1230	2334															
	TAKE TOO AND FROM LAKESIDE FOR BACKUP ALARM-FUSE WAS																	
	BLOWN (LOCATED ON FIREWALL IN ENGINE COMPARTMENT IN	1230																
	BLACK BOX ON LEFT SIDE)																	
1/23/07	INSTALL NEW STROBE LIGHT SWITCH CIRCUIT BOARD	2354							,	9								
1/24/07	GREASE TRUCK-CLEAN BATTERY CONNECTIONS	1934	22898		X				X									
2/7/07	INSTALL NEW SEAL BEAM IN SPREADER LIGHT	1230																
2/14/07	CHECK RADIO OUT-REMOVE SUPPRESSOR	2354																
2/15/07	CHECK OUT WHY SANDER TURNS ON WHEN RADIO MIC IS KEYED	MTE																
	CHANGE OUT BLUE MAKO BOX FOR SANDER CONTROL-THIS WILL																	
2/20/73	STOP SANDER FROM COMING ON WHEN RADIO MIC IS KEYED	MTE																
2/21/07	FULL SERVICE (2976HRS)	1934	26350	32	X	X	X		Х									
	REMOVE LFT FRT WHEEL CLEAN WATER OUT OF BEARINGS &	4005																
3/6/07	PUT IN NEW OIL - INSTALL NEW RUBBER CAP IN STEMCO CAP	1935																
0.0.07	INSTALL REBUILT MAKO BOX W/MAGNETS SO SANDER DOESN'T	MTE																
3/9/07	START WHEN RADIO IS ENGAGED	IVIIL																
2112127	KNOCKED WIRE FOR SPEEDOMETER SENSOR OFF WHEN	MTE																
3/12/07	REPLACING MAKE BOX (SANDER WOULDN'T WORK)	IVI I																
3/16/07	GET LOANER CIRCUIT BOARD FOR TOP STROBES INSTALLED	MTE																
3/23/07	GET LOANER COMPUTOR BOX INSTALLED FOR TOP STROBES	MTE																
3/26/07	MAKE UP NEW HITCH TO PULL 383 GRADER	1230																
3/27/07	WELD PLATE ON TRUCK FOR PINTLE HITCH FOR GRADER	2354																
4/9/07	GREASE TRUCK (3186HRS)	1934	30585		X				X									
5/22/07	FULL SERVICE	1934	33952	32	X	X	X		X									
	PICK UP FROM MTE (HAD REBUILT COMPUTER SWITCHED OUT -																	
	SET BLAST BUTTON SO IT STAYS ON AS LONG AS YOU HOLD	1230																
5/22/07	BUTTON DOWN - MANUAL CAN NOT BE CHANGED. Put computer in	1230																
	test mode and set the percentage up to 50 to spray																	
6/19/07	INSTALL NEW ANTENNA BASE FOR AM-FM RADIO	2354																
0/07/07	INSTALL LONGER ANTENNA ON TRUCK FOR AM-FM RADIO (DIDN'T	2354																
6/27/07	HELP)	2554																
8/7/07	GREASE TRUCK	1934	38016		×				X									
8/27/07	MOUNT UP 4 NEW 12R22.5 GOODYEAR G124 DRIVE TIRES	1934																
8/28/07	FUEL PUMP IN 55 GAL BARREL WAS STUCK	392																
9/24/07	PAVEMENT SENSOR WAS UNPLUGGED FROM BEHIND SCREEN	MTE																
	INSTALL 4-NEW 12R22.5 GOODYEAR G124 DRIVE TIRES AND ONE	1934	39892															
	315/80R22.5 MICHELIN XZU-S LEFT FRONT TIRE	1004	55052															
	FULL SERVICE-CHANGE HYD FILTER AND TRANS FILTERS	1934	39892	32	Х	×	Х		X							X	X	X
	CHANGE AIR DRYER FILTER - CHECK ANTIFREEZE - 45		55552	02	^ ,	/ \	^		^									
9/25/07	DISMOUNT 4-12R22.5 TIRES FOR CASING CREDIT	1934																
10/22/07	PICKUP 2-315/80R22.5 MICHELIN XZU-S FRT TIRES AT POMPS	1230																
10/23/07	MOUNT UP 2 NEW 315/80R22.5 MICHELIN XZU-S FRT TIRES	1230																
11/13/07	INSTALL NEW AM-FM RADIO ANTENNA ON RIGHT SIDE OF ROOF	2354																
44/44/07	CLEAN BATTERY TERMINALS-WINTER CHECK-REPLACE BULBS IN	2354																
11/14/07	BACK UP LIGHTS	2004																*

ps fltr 7191

UNIT 144
INTERNATIONAL TRUCK (2006)
MODEL NO. 7400 SFA (4X2)
VIN NO. 1HTWDAZR55J226371
INTERNATIONAL ENGINE DTS70
SERIAL NO. 570HM2U2062241
CU. IN. 570 (310HP @ 2200RPM
ALLISON 6 SPEED AUTOMATIC
MODEL NO. 3000 RDS6 SP W/PTO
SERIAL NO. 6510566357
CLASS 106
License Plate Number 68822

Date		Mechanic	Hours or Mileage	Oil	Grease	Oil Filter	Fuel Filter	Power Steering	Check Trans	Lights	Differentia I	Battery	Radiator	Tires	Brakes	Air Filter	Hvd.	Trans Filter	Air Dryer
12/14/07	CRANKSHAFT - INSTALL SHORTER SERPENTINE BELT	LAKESIDE						<u> </u>									,		7 2.90.
	(WARRANTY) BRING BACK FROM LAKESIDE-INSTALL PLOW BACK ON	1230																	
12/18/07	FULL SERVICE	1934	45246	32	X	X	X		X										
	TARP ROD PULLED APART-SLID BACK TOGETHER AND TIGHTENED SET SCREWS	1934																	
1/16/08	TAKE TOO LAKESIDE SATELITE SHOP TO HAVE CRANKSHAFT PULLEY DRIVE HUB INSTALLED (WARRANTY)	LAKESIDE																	
	INSTALL NEW RESETABLE CIRCUIT BREAKER FOR BACK UP ALARM - FILL W/S WASHER FLUID - DRILL HOLES IN TARP RODS																		
1/25/08	TO LET WATER OUT AND POUND DOWN ON PEGS - CHECK ANITFREEZE OIL AND LIGHTS	2354																	
1/29/08	GREASE TRUCK (4132HRS)	1934	49616		Х				X										
	PUT SPARE ON RIGHT FRT TIRE	1934	10010		**				^										
	FIX RIGHT FRT TIRE	1934																	
1/30/08	PINCH PIN HOLE SHUT IN RADIATOR TUBE AND ADD STOP LEAK AND ANTIFREEZE	1935	*2354*																
2/11/08	FULL SERVICE (4322HRS) INSTALL NEW AIR CLEANER REST- RICKER GAUGE	1934	51805	32	Х	Х			Х										
	PUT DIFFERENT TOW CHAIN IN TOOL BOX-ALSO PUT 1 REAR TIRE CHAIN IN TOOL BOX	1230								8									
2/14/08	INSTALL RIGHT FRT REPAIRED TIRE	1934																	
2/15/08	ADD 2 QTS OF ANTI FREEZE	2354																	
3/4/08	CHECK OUT STROBES-TAKE TOO & FROM MTE-REPLACED GREEN COUMPUTER BOX	1230	*2354*																
	CHECK OUT PLOW LIGHTS & TARP REWIND-TAKE TO MTE																		
3/6/08	REPLACE GREEN COMPUTER GOX AGAIN - SEND OTHER COMPUTER IN TO HAVE 40 AMP DIODES INSTALLED TO FIX	1230	*392*																
3/17/08	PROBLEM WITH CIRCUIT BREAKERS KICKING OUT INSTALL NEW BAND CLAMP ON RIGHT TOP STROBE LIGHT	1935																	
0,11700	TAKE TO AND FROM MTE (PAVEMENT TEMP SENSOR WAS	1000																	
3/26/08	UNPLUGGED) (CHANGED OUT GREEN COMPUTER BOX) DID NOT WORK RIGHT (INSTALLED OLD ONE AGAIN AND SENT BACK TO	1230	*1934*																
3/27/08	REPAIR) WARRANTY INSTALL NEW ENGINE OIL PAN - FULL SERVICE (4322HRS)	1934	55847	32	×	Х	Х		X										
4/14/08	INSTALL STEPS BACK ON FUEL TANK AFTER PAINTING	1934	00011	o_	^				^										
4/15/08	TAKE TO AND FROM MTE (HAD REBUILT GREEN COMPUTER BOX INSTALLED)	1230-2354																	
4/24/08	REPLACE RIGHT FRT HEADLIGHT-UNHOOK POWER TO GREEN BOX	2354																	
4/30/08	TAKE TOO MTE (STROBE LIGHTS STAY ON-ALL OTHER AUXILLARY	1934																	
5/5/08	LIGHTS DON'T WORK) TAKE TOO AND FROM MTE (REMOVE ASPHALT PAN)	1230	*1934*																
5/1/08	BRING BACK FROM MTE-CIRUS LEFT SOME PIECES OUT OF COMPUTER WHEN THEY REBUILT IT	408																	
5/20/08	LUBE AND LOOSEN UP TAILGATE LATCHES	1934																	
5/29/08	START UNIT	392																	
6/5/08	REPAIR REAR LIGHTS	2354																	
7/10/08 7/22/08	START UNIT AND CHG BATTERY GREASE TRUCK & REPAIR LIGHTS (4716HRS)	392 1934	59086																
7/31/08	START UNIT	392	59086																
10/6/08	FULL SERVICE-CHANGE TRANS FILTER-CHANGE HYD FILTER CHANGE AIR DRYER ELEMENT	1934	61901	32	×	X	X		Х								X	X	×
10/6/08	INSTALL NEW RIGHT FRT TIRE 315/80R22.5 MICHELIN 20PLY WINTER CHECK	1934 1934	61901 61901																
10/7/08	LOOSEN UP AND LUBE ALL 3 PINTLE HITCHES	1934	5 150 1																
	CHECK BATTERIES (OK)-INSTALL NEW 150 AMP CIRCUIT BREAKER - INSTALL NEW ENDS ON WIRE TO CIRCUIT BREAKER - CHARGE BATTERIES - CHECK ANTIFREEZE - 20	2354																	
10/9/08	INSTALL 3 NEW BATTERIES	392																	
	CHECK ANTI FREEZE -45	2354																	

ps fltr 7191

UNIT 144
INTERNATIONAL TRUCK (2006)
MODEL NO. 7400 SFA (4X2)
VIN NO. 1HTWDAZR56J226371
INTERNATIONAL ENGINE DTS70
SERIAL NO. 570HM2U2062241
CU. IN. 570 (310HP @ 2200RPM
ALLISON 6 SPEED AUTOMATIC
MODEL NO. 3000 RDS6 SP W/PTO
SERIAL NO. 6510566357
CLASS 106
License Plate Number 68822

			Hours or			Oil	Fuel	Power	Check		Differentia				Air		Trans	
Date		Mechanic	Mileage	Oil	Grease	Filter	Filter	Steering	Trans	Lights	I Battery	Radiator	Tires	Brakes	Filter	Hyd.	Filter	Air Dryer
10/22/08	STRAIGHTEN OUT RIGHT SPILL PLATE ON TAIL GATE	2354																
12/5/08	NEW W/S WIPERS-REPAIR TOW CHAIN-CHECK LIGHT IN RADIO	392																
12/18/08	FULL SERVICE (5113HRS) GREASE WING POST-REPAIR MARKER	1934																
	LIGHT ON CAB																	
12/24/08	REPAIR STROBES	392																
12/30/08	INSTALL NEW BAND ON STROBE LIGHT	2354																
	INSTALL NEW SEAL BEAM IN LEFT AMBER	2354																
1/5/09	REPLACE LOAD SENSE HYD HOSE	392																
1/6/09	REPLACE RIGHT PLOW LIGHT SEAL BEAM-REPAIR MARKER &	392																
	BACK UP LIGHT																	
1/8/09	INSTALL NEW TEFLON LINER IN BOX	BADGER	PLASTIC															
	INSTALL TAIL GATE AND SPILL PLATES BACK ON	1645																
1/15/09	INSTALL 2 NEW HYD LINES FROM PLOW LIFT RAM TOO SELECT	2354																
17 10/00	ON VALVE																	
1/16/09	GREASE TRUCK (5276HRS) REPLACE FRT WHEEL GREASE SEAL	1934	69890		X				X									
17 10/03	(LEFT SIDE) CHECK OUT ELECTRICAL ON TARP REWIND																	
	LUBE TARP SPRINGS AND BRG ON ROLL UP BAR	381																
2/10/09	INSTALL NEW HEADLIGHT & FOG LIGHT SEAL BEAM	2354																
2/18/09	INSTALL NEW ELECTRICAL CABLE THROUGH TUBE ON	2354																
	HEADBOARD FOR STROBES								v ,									
2/20/09	FULL SERVICE	1934	72843	32	X	Х	X		X									
2/25/09	INSTALL NEW AIR HORN ASSY	2354																
3/10/09	REPAIR WIRES INSIDE TUBE BETWEEN STROBES	392																
4/6/09	GREASE TRUCK-CLEAN BATTERY CONNECTIONS	1934	75635		X				X									
5/12/09	GET READY FOR SPRAYING	392																
7/6/09	Service	1934	78475	32	X	X	X		X									
7/6/09	painted fuel tank	farmer																
10/20/09	grease poly floor repaired by floor company	1934	82143		X													
1/15/10	Service	1934	87763	32	X	x	x		X									
1/18/10	Right front wheelseal new plow blades	2354																
2/8/10	Replace tarp motor	2478																
2/12/10	Tied up hosed, welded plow and straightened sander plate	2478-392																
2/16/10	New lift hose	2478																
3/1/10	Grease, cleared codes off for engine	1934	91287															
3/16/10	Replaced EGR fuse	392																
3/19/10	Strobes not working, spliced wires by left top strobe	392																
3/24/10	Installed new water pump	392																
5/5/10	Full Service, took off sander, replaced tarp bar	392	94000	32														
	shut off while driving check electrical system lite was on it was a20 amp	202																
6/21/10	fuse in under hood fuse box	392																
7/27/10	New dipstick for trans, rewired auger sensor wires, Installed new tarp	2478																
	Drilled out leaking bolt and patched. Free up trubo waste gate accuator,																	
	change dash assembly, install new am/fm radio, install new wiper blades,																	
	install repaired auxillary light switch panel, loosen tailgate latch, pop dent	2354-2478																
8/2/2010	out of passenger door, repaired tarp and box liner, new tarp																	
8/31/2010	Grease, replaced filter for AC	1934	97733															
11/15/2010	and the second s	1934	100100	32											X	X		X
12/6/2010	Replaced air governor	392																
1/5/2011	Grease, installed four new heavy rims on rear axle	1934																
1/24/2011	Full service, repair broken marker light wire	1934	106078	32														
2/10/2011	Replaced swing cylinder, new wing blades and fixed auger button	2478																
2/10/2011	Replaced swing ram	2478																
2/28/2011	no start problem repaired by lakeside repair order in filing cabinet	LAKESIDE																
3/4/2011	Tied up plastic cover that was rubbing on driveshaft	2478																
4/1/2011	Grease	1934	109865															
4/ 1/2011	Full service, replaced right side cub mount bushing, weld on shovel	,5554	.00000															
7/12/2011	holder, loosen hitches, AC repaired at Triangle	1934	112931															
7/12/2011		1934	115709															
11/14/2011		1934	113703															
11/21/2011		392																
	Made auto chains 6" longer	1934	119365	32														
	Full service, replaced sander light																	

ps fltr 7191

UNIT 144
INTERNATIONAL TRUCK (2006)
MODEL NO. 7400 SFA (4X2)
VIN NO. 1HTWDAZR56J226371
INTERNATIONAL ENGINE DT570
SERIAL NO. 570HM2U2062241
CU. IN . 570 (310HP @ 2200RPM
ALLISON 6 SPEED AUTOMATIC
MODEL NO. 3000 RDS6 SP WIPTO
SERIAL NO. 6510566357
CLASS 106
License Plate Number 68822

Date		Mechanic	Hours or Mileage	Oil	Grease	Oil Filter	Fuel Filter	Power Steering	Check Trans	Lights	Differentia I Batter	n Dedieter	Ti	D	Air		Trans	
Date	40 amp fuse holder in battery box was corroded. Cleaned up connection	Wechanic	Willeage	Oil	Glease	1 liter	Tillel	Steering	IIalis	Ligitis	I Daller	y Radiator	Tires	Brakes	Filter	Hyd.	Filter	Air Dryer
2/27/2012		392																
4/3/2012		1934	122430															
	Replaced connection for fuse holder in battery box, repaired bad wires in		122 100															
4/23/2012	front harness for headlights	2478																
	New wipers, installed weed spray tank	2478																
	Full service, changed trans oil and filters transynd synthetic oil	1934	125528	32														
	Found bad connector on firewall, replaced connector and ends on wires	1934	.20020	-														
	Grease, installed 2 XZYS Michelin 315-80 R22.5 tires on front, installed 4																	
10/28/2012	G622RSD Goodyear 12R22.5 tires on rear	1934																
	Full service, installed new stainless steel oil pan, repaired heater plug,	1001																
1/14/2013	calibrated brine. fixed radio	1934-2478	132817	35														
	Replaced EGR cooler on engine, it was using a lot of antifreeze	2478	102017	00														
	Grease, changed air dryer and hydraulic filter, fixed air leak	1934	135723															
	Replaced mouldboard spring	MTE	155725															
	Full service, repalced right front spring, installed summer tires and rims	1934-2478																
	Repaired air leak, installed new seal in hyd pump	2354																
	replace seal in hydrolic pump	2354	141396															
	Installed new blet and idler pulley	392	141330															
10/21/2013		2354																
11/26/2013		2478								es .								
1/4/2014	repaired left rear tire	1934																
1/5/2014	rebuilt wing slide	3006																
	replaced electric turbo accuator	2478																
			4.40000	00														
	full service could find nothing wrong	1934	146803	36			x											
		3006/2478																
2/17/2014	repaired rt hand spill plate	2478/3005	149275															
6/4/2014	grease	1934																
	repaired wiring for backup lights/alarm	3005																
	Replaced prewet hyd motor and pump																	
		3006																
11/10/2014		2478																
	Full service	1934	152841	46	4lb													
	New plow blades																	
2/9/2015	new o-rings on lift ram, Replaced left swing cyl and cushion value	1934																
	New fan clutch installed Horton 99a4701 Lakeside	2354																
6/25/2015	remove joy stick and install togel switches because hvdm is no longer avaible	2478																
0/10/2015	cam shaft sensor	2254																
	grease job and service air dryer worked on left slack adj. fixed exhaust	2354	450570															
		1934	156576		4lbs													
	replacedWING CHECK VALVE, new radiator cap	1934																
	repair auto chains	3006																
	Full service	1934	158807		4lbs							1 gal						
	New tarp motor	3006																
2/6/2016	Replaced belt tensioner	3005																
		3204																
	replace rear brake shoes and drums	3204	161439															
	oil feed tube replaced	3204																
	replaced sander hose	2478																
	New batteries, new air dryer, new hyd filter, and changed gps box	3006	162577															
11/15/2016		1934	162578		4lbs													
	Plow left/right switch replaced	3204																
	Full service, put used tire on right rear inside, fixed ldft door panel	1934	164733		4lbs							2qts						
2/6/2017	repaired box liner/ changed sander light	3204																
	new tranny cooler	1934																
	replaced steering gear and new fuel tank strap	3204																
	replaced right front rim	1934																
	Grease job	1934	168503		4lbs							2 qts						
	Winter check/replaced exhaust pipe/ block heater installed	3204	168569									- 4-						
	air leak, replaced front brake valves	1934	168579															
1/8/2018	replaced faulty switches for box/hoist and wing post controls	3204																

ps fltr 7191

UNIT 144
INTERNATIONAL TRUCK (2006)
MODEL NO. 7400 SFA (4X2)
VIN NO. 1HTWDAZR56J226371
INTERNATIONAL ENGINE DT570
SERIAL NO. 570HM2U2062241
CU. IN. 570 (310HP @ 2200RPM
ALLISON 6 SPEED AUTOMATIC
MODEL NO. 3000 RDS6 SP W/PTO
SERIAL NO. 6510566357
CLASS 106
License Plate Number 68822

			Hours or			Oil	Fuel	Power	Check		Differentia				Air		Trans	
Date		Mechanic	Mileage	Oil	Grease	Filter	Filter	Steering	Trans	Lights	I Batter	/ Radiator	Tires	Brakes	Filter	Hyd.	Filter	Air Dryer
2/15/2018	P/S hose clamp/refill	2354																
5/2/2018	Full service/replace right rear brake chambers	1934	170725	36	4 lbs													
5/3/2018	removed brine tank flushed tank	3329 3329/3204																
6/25/2018	check blower motor connections, reseal water pump and coolant housing new front right tire	1934	171751															
6/27/2018 11/9/2018		1934	171751															
	check fuel leak/ needs tank,replaced fuel tank with repair tank from 143	3204	172943															
11/12/2010	Winter check, replaced air drier, hyd filter, cab air filter, installed led fog																	
11/19/2018	lights, free up brine pump, tarp repair,	3329	172943															
	replaced crank sensor and repaired wiring, installed new turbo	2354																
12/13/2018	4 new rear tires	1934	173108															
	Installed ABS senor left rear wheel	3034																
	replaced cam sensor	2354																
1/31/2019		3430																
2/26/2019		3204 1934	176226	36	2lbs													
	Full service	1934	170220	30	2105													
	winter check replaced ICP sensor and valve cover gasket	2354																
	replaced air tank	10/8/1908																
2/7/2020	GREASE JOB	2354	179724		5LB													
2/25/2020	replaced right side strobe light	3204								s.								
5/5/2020	repaired wiring for plow light on right side	3204																
	Winter check list and repairs replace right plow head light bul, replaces																	
	both left and lower right heated mirrors, replace EGR valve, cleaned																	
	engine air breather used new oring and hose, free up pintall hitch, install											40				CO+ TC	V	~
10/26/2020	-	2354	182332		Х				Х			-40				6Qt T6	X	X
11/18/2020		1934	100050	36	4lb										Cleaned			
11/19/2020		1934 3430	182352	36	4ID										Cleaned			
12/30/2020 12/31/2020		3430																
12/3 1/2020	Remove right steering gear box and replace steering filter and o-ring	5450																
1/4/2021	check and repair lights	2354																
1/7/2021	Install steering gear box run and top off oil	2354																
1/8/2021	Take out and hook up to plow and put away	2354																
1/18/2021	Fix sander lite fix tail lite	1934																
4/8/2021	Straight box arm	3430																
4/19/2021	Weld up cracks in hoist frame	3204																
6/9/2021	A/C 1oz PAG100 added and 2lb .25 oz. HFC134A added	3430			011					~	x x	×	Х	х	X			
7/13/2021	Air tank loose grease and head lites	1934	185735 185950		3lb			Х		Х	x x	^	^	^	^			
7/20/2021	52 OZ Freon added A/C problems fix leaks and charge up 2lbs25oz reseal condensor seals	1934 3430	185950															
7/20/2021	Check over and repairs	2354																
9/7/2021 11/12/2021	Install right tail light	2354																
11/19/2021		4015																
11/22/2021		4015																
11/23/2021		4015																
11/24/2021	Replace rear brakes	1934																
1/3/2022	Fix right rear tail lite replace plow bolt	1934																
1/5/2022	Replace Pto covers on trans, service and seal leak on rear end in put	1934																
1/24/2022	Snow valve actuator bad, placed in snow mode and unplugged	4015																
1/28/2022	Work on rear end	1934																
1/28/2022	Help pull off rear end cone	3430 1934																
1/31/2022 2/1/2022	Work on rear end Pull off lift, push in other	3430																
2/2/2022	Clean and paint	1934																
2/9/2022	Put rear end together	1934																
2/10/2022	Put rear end together and in truck	1934																
2/10/2022	Help Todd put on lift and help install diff	3430																
2/11/2022	Clean and hook plow, road test	1934																
2/24/2022	Replace GPS with 5G unit	4239																
3/21/2022	Remove wing and spreader, attach 9930 auger	4239																

ps fltr 7191

UNIT 144
INTERNATIONAL TRUCK (2006)
MODEL NO. 7400 SFA (4X2)
VIN NO. 1HTWDAZR56J226371
INTERNATIONAL ENGINE DT570
SERIAL NO. 570HM2U2062241
CU. IN. 570 (310HP @ 2200RPM
ALLISON 6 SPEED AUTOMATIC
MODEL NO. 3000 RDS6 SP W/PTO
SERIAL NO. 6510566357
CLASS 106
License Plate Number 68822

		Manufacture	Hours or	0.1	0	Oil	Fuel	Power	Check		Differentia		Dadistas	Tiese	Danker	Air Filter H	Trans vd. Filter	
Date	souloss sight moves arm rejectall mirrors and adjust	Mechanic 4239	Mileage	Oil	Grease	Filter	Filter	Steering	Trans	Lights		Battery	Radiator	Tires	Brakes	Filter H	yd. Filter	Air Dryer
3/22/2022	replace right morror arm, reinstall mirrors and adjust Service and replace grease zerks	1934																
3/25/2022	Service/loosen tailgate latch needs front brakes and front right wheel seal	1934																
3/25/2022	leaking bolt broken on hoist cylinder	4239	189231	36	4lb	X	Х	X	X	X	X	X	×	X	X	Cleaned		
3/28/2022	Full service, replace service due tag. Check tailgate for open/close	1934	103231	30	410	^	^	^	^	^	^	^		^	^	Olculica		
3/29/2022	Replace bottom hoist cylinder bolt	144																
4/4/2022	Replace female hyd end on blade hose	4239																
4/18/2022	Replace rear tires	1934																
6/15/2022	Diagnose A/C blower fan issues	2354																
6/16/2022	Recharge A/C recovered 1.9 charged 5oz, install new fan regulator	2354	190247															
6/20/2022	remove tarp, test drive, check A/C and fan	2354																
	No crank/no start, connect computer, multiple short to ground on																	
7/13/2022	cylinders 1-6	4015																
7/19/2022	Check and diagnose A/C problems	3430																
7/20/2022	A/C drain and replace orfice tube charged with 8oz freon	3430	190909															
7/21/2022	Install new batteries, clean cables, remove starter	3430																
7/25/2022	Clean battery cables, install starter, starting issues	3430																
7/26/2022	complete repair	3430																
8/1/2022	Test drive, check A/C and 2-way radio	3430																
8/29/2022	Check A/C issue	3430								8								
	Drain and disassemble A/C system, order new compressor and check																	
8/31/2022	filter, found metal shavings, begin cleaning system	3430																
9/1/2022	Recharge and button up A/C system	3430																
10/5/2022		1934	191817															
	Winter prep, Remove shoulder head, frozen gravel and debris	3430																
11/17/2022		2354																
11/22/2022	Continue winter checklist	2354																
	Check and repair wiring under truck, order fittings for leaking	2254																
	transmission hoses	2354																
	Remove and replace trans cooler fittings	2354																
11/30/2022		2354 2354																
12/1/2022	Install new valve cover gasket and valve cover, reinstll injector sensors,	2354																
40/5/0000		2354																
12/5/2022	Check and remove camshaft sensor, insstall new, test drive	2354																
12/6/2022 12/15/2022		1934																
12/13/2022		4015																
1/3/2022	Find coolant leak	4015																
1/4/2023	Remove and order inner cooler	4015																
1/10/2023	Install engine cooler	4015																
1/11/2023	Test drive, install inner fender and fender	4015																
	Replace all 5 terminals in left lower taillight inlet wire and curb side back-																	
1/19/2023	up bulb	2354																
2/7/2023	Drop plow blade, move to shop for injector error code	2354																
2/8/2023	Take to Lakeside for ECM update, bring back to shop for injector testing	2354																
2/10/2023	Connect J-Pro, test drive failed. Schedule in to Lakeside	2354																
2/20/2023	Take to Lakeside for CEL check and repair	4223																
3/1/2023	Return from Lakeside	4223																
3/8/2023	Take to Lakeside for CEL, same codes - injector 6 short to hot	4223																
3/30/2023	CEL on, check codes, return to Lakeside for check, CEL off now	3430																
	Started unit to take to Helm Truck, engine shut off while enroute. Brought																	
5/22/2023		Marsha/4015																
	Return from Helm Truck, report follows. ALL INJECTORS LOW TO HIGH																	
	SIDES OPEN, 344 EBP ABOVE SPEC W/ENGINE OFF, 525 INJECTOR																	
	DRIVER CIRCUIT FAULT "M". CHECK ALL HARNESSES IN TYPICAL																	
	RUB SPOTS. NO ISSUES. INSPECT 4103 CONNECTOR AND WIRING.																	
	GOOD AND CLEAN. TEST 10 GAUGE, THREE WIRE CONNECTOR																	
	NEAR WIPER MOTOR. CODE 525 GOES ACTIVE. CUT OUT																	
	CONNECTOR AND WIRE DIRECT. CLEAR CODES. CHECK AND																	
	UPDATE MODULE CALIBRATIONS. TEST DRIVE AND CHECK																	
5/25/2023	REPAIRS. NO CODES RETURN	Marsha																

ps fltr 7191

UNIT 144
INTERNATIONAL TRUCK (2006)
MODEL NO. 7400 SFA (4X2)
VIN NO. 1HTWDAZR56J226371
INTERNATIONAL ENGINE DT570
SERIAL NO. 570HM2U2062241
CU. IN. 570 (310HP @ 2200RPM
ALLISON 6 SPEED AUTOMATIC
MODEL NO. 3000 RDS6 SP W/PTO
SERIAL NO. 6510566357
CLASS 106
License Plate Number 68822

			Hours or			Oil	Fuel	Power	Check		Differen	tia		*		Air		Trans	
Date		Mechanic	Mileage	Oil	Grease	Filter	Filter	Steering	Trans	Lights	1	Battery	Radiator	Tires	Brakes	Filter	Hvd.	Filter	Air Drver
6/8/2023	Repostion seat cover away from seat adjustment controls	4015													5.4.00		,		7th Diyer
11/21/2023	Jump try to start issues	3430																	
12/8/2023	Bring in and get to start	2354																	
12/11/2023	Winter check list	2354																	
12/12/2023	Winter check list and repairs	2354																	
1/12/2024	Start check over an shovel off	3430																	
3/13/2024	Decomission	4479																	

### UNIT 744 MONROE SNOW PLOW (2005) MODEL NO. MP41R11-ISCT SERIAL NO. 05-05-1143 CLASS 633

			Hours or
Date		Mechanic	Mileage
8/9/05	PICKED UP	1230	
8/16/05	INSTALL GUIDE POSTS AND NEW SNOW DEFLECTOR FLAP	1230	'*2354*
8/25/05	INSTALL 1-5FT KENEMETAL & 2-3FT KENEMETALS-USED EXISTING FACE BLADE AND 2 USED CORNERS	1934	'*2354*
11/16/05	CHAIN WAS HOOKED TO TIGHT (BROKE) NO WARRANTY	MTE	
12/6/05	ADJUST SPRING TRIP ON PLOW SO IT SCRAPES BETTER	2354	
1/20/06	REMOVE CORNERS FROM PLOW	2354	
1/23/06	INSTALL NEW LOCKING NUT AND SPRING ON SNOW PLOW LATCH	1230	
	REMOVE WORN OUT BLADES-TAKE TOO MTE FOR MOLDBOARD	1230	
1/16/07	REPAIR	1394	*2354*
1/17/07	PICKED UP FROM MTE (MOLDBOARD REPAIR COMPLETED	1934	
1/18/07	INSTALL 2-4FT & 1-3FT KENEMETAL & 1-FACE BLADE	1934	*2354*
2/14/07	INSTALL NEW CENTER BOLT AND NUT	1934	2554
12/12/07	REMOVE PLOW	1934	
1/25/08	INSTALL NEW PLOW LIFT RAM-INSTALL NEW CENTER BOLT IN PLOW	2354	
1/28/08	INSTALL 2-4FT & 1-3FT KENEMETAL AND 1 NEW FACE BLADE	2354	*1935*
2/11/08	REPLACE COMPLETE SNAP COUPLER FOR SWING HOSE	1230	1933
11/7/08	REPLACE HYD HOSE FOR PLOW SWING	1935	
2/16/09	INSTALL NEW SNAP COUPLER ON PLOW SWING HOSE	1230	
1/6/12	Replace center bolt with 1 3/8, repaired latch rods	1935	
1/29/15	New plow blades	3006	
3/24/17	hyd hoses replaced	3204	
9/2/21	Bring in and check over	2354	
9/16/21	Finish check over and weld		
4/26/23	Remove blades, clean and reinstall	2354	
5 5	The state of the s	2354	

# UNIT 844 MONROE WIDENING WING (2005) MODEL NO. 9DFWMB-TE SERIAL NO. 04-06-6328 CLASS 635

			Hours or
Date		Mechanic	Mileage
8/9/05	PICKED UP FROM MTE	1230	
9/1/05	PICKED UP FROM MTE (WARRANTY) SPRING TRIP OUT OF		
	ALIGNMENT	1230	
10/28/05	INSTALL WING	1230	2354
1/23/06	INSTALL NEW 3/4 INCH HARDENED BOLT IN WING PUSH ARM	1230	
3/2/06	GREASE WING POST SLIDE	1934	
4/5/06	REMOVE WING	1230	
10/13/06	INSTALL WING	1230	2354
1/30/07	INSTALL 3-3FT KENEMETALS & NEW WEAR SHOE	1230	1935
2/28/07	LUBE WING SLIDE W/NEVER-SEIZE	1230	
3/6/07	WELD ON NEW BALL FOR WING BRACE	2354	
4/23/07		1934	
11/14/07	INSTALL WING	1230	2354
12/18/07		1934	
1/22/08	INSTALL 1-3FT USED KENEMETAL IN CENTER OF WING	1934	
2/20/08	WELD NEW BALL ON WING BRACE	1935	
4/14/08	REMOVE WING	1934	1935
11/14/08	INSTALL WING	1230	2354
12/16/08	INSTALL WING LIGHT	392	
1/5/09	REPAIR WING BRACE	392	
1/15/09	INSTALL USED BLADE ON CENTER OF WING	2048	
10/27/20	Install on truck	2354	
1/6/22	Weld crack on wing	1934	
11/15/22	Install on 144	2354	
2/16/23	Remove from truck	2354	

UNIT 944
MODEL
SPREAD SMART
MONROE SPREADER (2005)
MODEL NO. MS966-OW-DD
SERIAL NO. 05-05-3148
CLASS 426

Date			Hours or
8/9/2005	PICKED UP FROM MTE	Mechanic	Mileage
0/9/2003		1230	
8/17/2005	MAKE UP A BRACKET TO MOVE SPINNER OUT SO IT CAN BE SEEN FROM CAB OF TRUCK	2354	
11/28/2005	SHOULD BE SET AT 5 PULSES (AUGER)	MTE	
5/22/2006	REMOVE SANDER	1230	
10/13/2006	INSTALL SANDER	1230	2354
10/19/2007	INSTALL SANDER	1230	2004
11/14/2007	INSTALL NEW AUGER BEARING	2354	
12/27/2007	CHECK AUGER SENSOR (OK)	392	1230
1/22/2008	MAKE UP NEW BRACKET FOR SPINNER	2354	1230
1/25/2008	INSTALL NEW SPINNER MOTOR AND HUB	2354	
3/25/2008	INSTALL NEW AUGER SENSOR	2354	
5/19/2008	REMOVE SANDER	1934	
10/22/2008	INSTALL SANDER ON TRUCK NO.144	1934	2254
12/2/2008	REPLACE SEAL BEAM FOR SANDER LIGHT	392	2354
12/9/2016	auger sensor/auger bearing replaced		
10/27/2020	Install on truck	3204	
12/12/2022	Replace sander sensor	2354	
	Dump, clean and find broken bolt in auger, remove and replace spinner	4015	
1/19/2023	bulb	2354	
3/2/2023	R/R spreader light bulb	Dylan	