Unit 155

Unit 135
Internattional Truck 2012
Model 7400 SFA 4X2
Vin No. 1HTWDAZR3CJ618940
Engine - International Max Force 9 570 Cubic Inches

9.3 Litre 330 Horsepower Allison Transmission 3000 RDS6-SP

Serial No. 6511026414 84 month 100,000 warranty on pre-package component systems

84 month/5,400 hours /150,000 miles

engine &electronics including injectors
CLASS 106

License Plate Number 83603

			Hours or			Fuel	Power	Check		Differentia						Trans	
Date		Mechanic	Mileage	Oil	, Grease	Filter	Steering	Trans	Lights	1	Battery	Radiator	Tires	Brakes	Air Filter Hyd.	Filter	Air Dryer
1/30/2012	Delivered	Lakeside															
2/6/2012	remote grease system installed	fuel systems	jim garvens		800-236-383	35											
2/23/2012	Fixed air leak	Lakeside															
3/6/2012	grease	1934	3160		X		•		7								
3/7/2012	Put grease line ack on and redid slip plate	392															
	Fixed air leak on passenger seat, has vibration at 60 mph, Lakeside																
5/7/2012	thinks it's the tires.	Lakeside															
	Installed heavier plow flap, heated windshield connection was broken,																
5/16/2012	Lakeside replaced windshield	2478															
	Lakeside replaced willushleid																
6/19/2012		MTE															
	Moved valve and repaired dent in cab, got it so strobes work on accessory																
7/18/2012	Adjusted angle of rear end three degrees	Lakeside															
12/12/2012		fuel systems															
12/27/2012	Full service	1934	6467	33													
	Replaced brine pump	MTE															
2/19/2013	Replaced fog light	2027															
2/25/2013	Grease	1934	10648														
3/15/2013	Full service	1934	12658	33													
4/26/2013	Repaired air leak	Lakeside															
8/22/2013	grease	1934	15655														
9/12/2013	Took to Lakeside to do recall for sunvisor	Lakeside															
	Repaired broken wires for wing strobe	2354															
	Installed acc. Plug	2354															
12/2/2013	Did emissions recall	Lakeside															
	rattle under dash repaired - windshield washer is vented	Lakeside															
	replaced both rear drums 9they were glazed real bad)	1934															
1/29/2014	full service - chng'd power steering fluid	1934	25154	34													
2/20/2014	repaired wing strobes, repaired greaser	1934	20104	04													
	installed right hand spinner	3006/2478															
2/28/2014		1934	28741														
3/13/2014	grease		20/41														
		2478															
		Lakeside															
7/1/2014	installed new r.v. plug	392															
	replaced R.R. brake chamber	2354	30212														
	could not find a air leak	3005															
	Full service	1934	31217	34	×												
11/13/2014	spinner motor	2354															
11/25/2014	replaced auger and spinner bearing	3005															
1/12/2015	Put new relay in for tarp	2354															
1/28/2015	new spinner motor drivers side	3006															
2/5/2015	lakeside under warrenty senor	lakeside															
3/5/2015	Grease job checked brakes and used wing blade	1934/3006	34468		1lb												
5/1/2015	New egr valve at lakeside	lakeside															
6/18/2015	New oil pan and solinond (stainless steel oil pan)	1934	35071														
	full service - chng'd power steering fluid	1934	35071	39													
	new air dryer filter new hyd hoses on wing	3005	35492	00													
	seat switch installed	3005	00 102														
12/3/2015	replaced anti freeze sender unit low coolant 3572012-c1	1934															
	add on strobes	3006															
17772010	tighten up sensor on brine repair right front tire, fixed greaser line, put a	3000															
1/29/2016	used set of wing blades on, front slack adj pin	3204															
		1024	20252		Olbo												
2/3/2016	Grease job	1934	38252		2lbs												
2/8/2016	new plow blades and replaced hose from block to air comp.	3005	38339														
2/19/2016	3 new batteries	2478															
2/22/2016	replaced EGR cooler at lakeside (warranty)	lakeside															
2/29/2016	full service	1934	38730	38	2lbs												
4/12/2016	free up spool valve and fix leak	3204															
5/12/2016	dpf baked out land s 229 grams soot	2478															

Unit 155 Internattional Truck 2012 Model 7400 SFA 4X2

Vin No. 1HTWDAZR3CJ618940

Engine - International Max Force 9 570 Cubic Inches

9.3 Litre 330 Horsepower Allison Transmission 3000 RDS6-SP

Serial No. 6511026414

84 month 100,000 warranty on pre-package component systems 84 month/5,400 hours /150,000 miles

engine &electronics including injectors
CLASS 106

License Plate Number 83603

			Hours or			Fuel	Power	Check		Differentia							Trans	
Date		Mechanic	Mileage	Oil	Grease	Filter	Steering	Trans	Lights	1	Battery	Radiator	Tires	Brakes	Air Filter	Hyd.	Filter	Air Dryer
7/13/2016	installed new coolant tube to oil cooler and speed up plow	3204																
11/1/2016	new air dryer filter and hyd filter and cab filter	2354	39511															
11/28/2016	Plow hyd line replaced	3204																
12/13/2016	replaced brine pump	1934																
1/9/2017	replaced driers side spinner motor and drive ring/recalibrated chips	3006																
	Grease job and added sander light	1934	42223	2	1lb			8qts										
2/2/2017	replaced cooler lines and cooler	1934	LLLO	-				oqto										
3/3/2017	changed cable end	1934																
	Full service and fix bearing on auger	1934	44780	38	1lb													
	winter check/ replaced tarp breaker/solenoid for diff lock/hyd.filter/ air	1004	447.00	00	110													
9/25/2017	dryer filter	2354	45565															
12/19/2017	installed new valve on brine	2354																
1/3/2018	installed new fog lamp bulbs, replaced right side spinner#955	1934																
	insatalled new breaker in battery box																	
1/10/2018		3204																
1/17/2018	Grease job/ park brake/ replaced bearing on tarp rod/replace both rear	1934	47780		1lb													
	brake chambers, body up switch working at this time																	
1/25/2018	load tested wiring on right rear abs wiring no problem found at this time/	3329/3204							à									
	ABS light off																	
	brine flow meter checked and connections ok started working after	3204																
	wiper motor replaced/adjusted wiper linkage	3204																
	Full service put new steer tire on right side	1934	51138	38	1lb													
	replaced fuse for tarp and tested ok	2354																
	hesitation on acceleration regen truck due to inhibited state, test drove ok	3204																
	diagnoise throttle issue ordered exhaust brake valve	3204																
	replaced exhast brake accuator/check into a/c issue	3204																
7/9/2018	work on A/C inop problem in bcm or compressor going to lakeside no	3430																
11912010	recovery machine here	3430																
8/6/2018	wiring repair for fog lights	2354																
	winter check, replaced air drier, hyd filter, fix trap, free up brine																	
10/24/2018	pump,replaced box ram bolt, make curb runner for wing/install, tightened	3329	52051												×	x		x
	plow jack tube, headlight left side																	
11/9/2018	replaced CAC hose clamp lower right side	3430																
	replaced e stop switch	3204																
	Replaced altenator	2354																
	Full service and new tarp	1934	58863	38	1lb							2qts						
	replaced dip stick tube	3430	00000	00	110							2410						
	Swapped light module for top strobe from inside to back	3430																
	checked codes, code for intake pressure, cleaned intake pressure sensor	2354																
	Diagnose engine stalling issue found CKP sensor faulty/replaced	3204																
	installed new air to air hose	3430																*
	grease job replaced plow blades	1934	62118		AIL.													
	drill and tap hyd valve body to repair leak	3430	02110		1lb													
	lube up hyd valve body controls and body props.	3204																
	replaced boost solinoid checked EBP sensor	3204																
	fan belt /idler pulleys replaced	2354																
	Full service and changed coolant line	1934	65720	38	1lb							3gals						
	replaced coolat pipe from radiator to tranamission cooler	1934																
	replaced ICP sensor under valve cover and valve cover gasket with pass-	3430	66879															
	thru connections		00070															
	replaced windshield defroster tab	3204																
	Winter check list completed	Jeff W	67494									-45				X		X
11/9/2020	Replace trans cooler lines and trans side plates	2354																
	Top off trans and replace air dryer	2354																
11/12/2020	Replace engine oil hoses to spinner filter housing	2354																
	Fog light wiring and light	3204																
	en la la companya di																	
	Fix right rear bracket mud flap e-switch and etc.	3430																
	Fix right rear bracket mud flap e-switch and etc. Grease	1934																

Unit 155 Internattional Truck 2012 Model 7400 SFA 4X2

Vin No. 1HTWDAZR3CJ618940

Engine - International Max Force 9 570 Cubic Inches

9.3 Litre 330 Horsepower Allison Transmission 3000 RDS6-SP

Serial No. 6511026414

84 month 100,000 warranty on pre-package component systems
84 month/5,400 hours /150,000 miles
engine &electronics including injectors

CLASS 106

License Plate Number 83603

Date		Mechanic	Hours or Mileage	Oil	Grease	Fuel Filter	Power Steering	Check Trans	Lights	Differentia	Battery	Radiator	Tires	Brakes	Air Filter	المراط	Trans Filter	Air Dove
1/6/2021	Grease and check left rear brake and replace right front chamber bolt air horn back on 4gts low on oil	1934	69755	5	1lb				Ligitto		Buttory	radiator	11103	Diakes	Cleaned	пуц.	Filler	Air Dryer
1/7/2021	Work on front right brakes and replace chamber	1934													Olcarica			
1/25/2021	Replace hydraulic hose to wing and 3 brackets	2354																
1/26/2021	Replace RR brake chamber	2354																
2/1/2021	Service job	3430/1934	72265	20	File dayler			.,										
2/2/2021	Full service/ water leak/repair wiring to left spiner light	3430/1934	72203	38	5lb 1tube	Х		Х										
2/18/2021	Install new spreader valve	3430																
3/16/2021	Replaced fuel cap	3430																
6/21/2021	Weld stainless pipe	3204																
6/21/2021	Set up for durapatch truck	2354																
6/22/2021	Help finish set up for durapatcher	3204/2354																
8/17/2021	Truck over heats fan issues remove tail gate	3430																
8/18/2021	Install end gate remove air to air cooler install new fan clutch wash radiator and coolers	3430																
8/19/2021	relay for vibrator	3430																
8/23/2021	Install air to air cooler	3430																
8/24/2021	Air to air and button up	3430																
10/13/2021	RR light, trans lock up forward only	3430																
12/9/2021	Work on grease line	2354																
12/10/2021		2354																
12/13/2021	Taking apart	2354																
12/14/2021		2354																
	Clean out change air cooler build hose stand for storage tanks	3329																
12/15/2021		3329																
	Engine oil problem	2354																
12/17/2021	Finish up engine problem winter check list and repairs	2354																
	Winter checklist and repairs	2354																
	Winter check list and repairs	2354																
	Winter check list and repairs	2354																
	4 New rear tires	1934	76618															
1/13/2022	Spinner remove?? Seal Knock rust off of hyd. Valve box and lid. Replace missing plow bolt,	4015																
1/21/2022	replace left wing cylinder	4015																
1/17/2022	Replace left front brake chamber	2354																
1/27/2022	Check cuircuit breakers for fog light, move power cable to different position, test drive.	4015																
2/16/2022	Check spinner calibration, no issues found.	Eric S.																
2/21/2022	Replace both Hdlight and tarp switches and cleaned terminals	2354																
2/24/2022	Service job, replace front axle air bags, replace oil cap on front right 2qt 75-90 Synthetic	1934/3430	78145	38	X	Х	X	Х	Х	X	X	×	X	Х	Cleaned			
2/24/2022	Replace GPS unit with 5G	4239										^						
3/8/2022	Replace mount for aux light switches	4239																
4/1/2022	Measure plate and tube	3430																
4/4/2022	Find electrical problem and repair	2354																
4/8/2022	Install new 12v outlet	2354																
4/26/2022	Service call, check out coolant leak. Bring to shop replace rotted out lower coolant lines	2354																
4/27/2022	Begin replacing water lines	2354																
	Complete coolant line replacement	2354																
	Repair electric brake control	4015																
	Replace RT tail light bulb	4015																
	Check fuel gauge issue	1934																
	Change fuel gauge, repair broken wire	1934																
	Begin winter check	4015																
	Diagnose mirror heat failure, replace left mirror, works Begin winter checklist install	4015																
	Install new heat shields	4015																
31012022	motern from Smelles	4015																

Unit 155

Internattional Truck 2012

Model 7400 SFA 4X2 Vin No. 1HTWDAZR3CJ618940

Engine - International Max Force 9 570 Cubic Inches
9.3 Litre 330 Horsepower
Allison Transmission 3000 RDS6-SP
Serial No. 6511026414 84 month 100,000 warranty on pre-package component systems 84 month/5,400 hours /150,000 miles

engine &electronics including injectors

CLASS 106 License Plate Number 83603

			Hours or			Fuel	Power	Check		Differentia							Trans		
Date 9/7/2022	Install now mirror hoof quiteb contact to be about his life	Mechanic	Mileage	Oil	Grease	Filter	Steering	Trans	Lights	1	Battery	Radiator	Tires	Brakes	Air Filter	Hyd.	Filter	Air Dryei	r
9///2022	Install new mirror heat switch, replace turbo heat shield, Check engine light on, loss of power. Computer hooked up, found low	4015	79371																
9/22/2022	fuel pressure code SPN 94.	4223																	
9/22/2022		3430																	
	Remove fuel strainer, pump and hoses. Clean metal shavings, clean and																		
9/25/2022	test fuel pump, clean out system	3430																	
9/26/2022	Reassemble fuel system, start engine, test drive. Low power, check fuel	0.400																	
	pressure with gauge Vs computer, order new fuel presure sensor	3430																	
9/29/2022	Test fuel regulator spring, install new fuel pressure switch	3430																	
10/5/2022	Check transmission error codes Test wiring, replace 2 trans sensors, test drive	3430																	
10/6/2022	Return from Monroe Truck Eguipment, check over new brine tank insert,	3430																	
11/10/2022	replace rear strobe lights with green/amber sl66ag buyers	2354																	
10/0/0000	Service call - low coolant level, add 7 gal. level dropped again. Haul back																		
12/9/2022	to shop	3430/4015																	
12/12/2022		4015																	
12/13/2022	Remove right inner fender, disconnect EGR cooler and found exhaust	4015																	
12/14/2022	side full of coolant, begin removing turbo, tubes and hoses Remove EGR cooler, drain oil and check engine for coolant								4										
12/15/2022		4015																	
	Complete EGR coolant hose replacement, found bad starter, R/R starter,	4015																	
12/19/2022	fill coolant, start engine. Early oil change due to EXH cooler going out.	4015	79996	38															
12/20/2022	Test drive OK, recheck oil and coolant for leaks, none found	4015																	
12/21/2022		4015																	
12/22/2022		4015																	
12/27/22 1/4/2023	Exhaust fuel injector leaking, check and clean injector Replace steering hose	4015																	
1/5/2023	R/R fuel tank strap	4015 4015																	
1/9/2023	Check CEL codes and clear	3430																	
1/10/2023	Remove exhaust fuel injector and clean injector and port, reinstall and																		
1710/2023	redo clamps	2354																	
1/11/2023	clean multiple electrical plugs (J1939 harness) dielectric grease plugs,	2354																	
1/25/2023	test drive, codes cleared Replace front brake chamber																		
2/6/2023	Check and reset Force codes, install tailgate	4015																	
	Service call - Check engine knock, replace air-air clamps still no power.	4015																	
2/17/2023	Call for recovery to bring to shop	2354																	
2/17/2023	Recover truck with RGN and bring to shop	4015																	
2/18/2023	Connect J-Pro, conduct cylinder cut-out test and found #6 had no	4223																	
	change. Move truck to side and prep for valve cover removal																		
2/21/2023 2/22/2023	Remove and blow out air cleaner, begin removing inner fender Remove valve cover, found #6 pushrod bent. Test valves and check	3430																	
2/23/2023	Clean parts, order new	3430 3430																	
2/24/2023	Wing light wires ribbed thru	3430																	
2/27/2023	Install rocker arm spacer	3430																	
3/1/2023	Assemble valve train, set valve lash, torque to specs	3430																	
3/2/2023	Reinstall valve cover, hoses, tubes and lines, reinstall doghouse cover, start engine and test drive.	3430																	
	Check over, top off coolant	3430																	
	Find and repair air leaks	3430																	
	Connect computer and diagnose engine codes Remove dash, hook up battery, install dash	3430																	
	Get started and bring up, start to remove 905 spray tank and harness	3430 3430/4015																	
	Pull radio and tools	4015																	
	Sale Prep	4479																	

Unit 755 Monroe Plow Model MP41R11-ISCT Serial No. 11-07-1383 CLASS 633

Date		Mechanic
2/6/12	Delivered	MTE
12/24/13	installed new plow blades	3006
3/6/14	NEW BLADES	0000
1/8/16	Replaced both swing cylinders	3005
2/8/16	New plow blades	3006
1/5/18	New plow blades	2354
8/18/21	Bring in to check over	2354
8/19/21	Grind and weld cracks make 4 new hoses make oversized pins for bottom of springs new pins at top of springs	2354
1/21/22 8/29/22 12/27/22 3/8/23	Replace swing cylinder and bolt Fix hyd leak and unhook plow Replace blades Repair latch pin and plow pivot bolt	3430 3430 Trent 3430

Unit 855
Monroe Wing
Model 9DFWMB-TE
Serial No. 11-07-5218
Class 635

Date		Mechanic	
2/6/12	Delivered	MTE	
1/21/21	Nut missing on wing pivot bolt	3430	
1/29/21	Weld up push arm/ replace spring	3204	
12/27/21	Install/ fix lube line	3430	
1/24/22	Replace missing bolts	4015	
1/27/22	Replace missing plow bolts	4015	
11/15/22	Install on 136	2354	

Unit 955 Monroe Spreader MS966RF Serial No. 11-07-3191 Class 420

Date		Mechanic
2/6/12	Delivered	MTE
3/23/17	replaced auger bearing	2354
1/2/18	replaced spiner plate	3204
2/10/20	replaced hyd fitting on auger motor	3430
1/22/21	Repair prewet pump	3204
2/1/21	Repair sander light wiring	3204
2/26/21	Adjust spinner	3204
1/17/22	Replace spinner hose	2354