

Kohl Kubal Repair. 11/17/2024. If any questions on work done call
(605)760-0083

770 BH MOTOR GRADER REBUILD

- Planed the block deck, head was planed a year prior, so we didn't plane it again because it was good. Also put new valves in at the time it was planed. Handel repair out of Menno SD did all the machine work. They also checked the crankshaft over and put new bushing in connecting rods.
- Rebuilt injectors were put in a year ago. Diesel specialties out of Sioux city Iowa rebuilt them. Tested them again during this rebuild and they were still good.
- Freshly rebuilt injection pump in it. Came out of spencer diesel injection in spencer Iowa.
- New main bearings, new rod bearings, new cylinder sleeves, new pistons, new piston rings, new piston pins. New seals and gaskets. The rebuild kit used for this was a john deere oem kit.

- New front crankshaft damper, new water pump, new air filters, new coolant, brand new radiator, new fuel filters
- Machine has 15016 hours on it. With just a few hours of that on the rebuild.