

COMPLETED WORK



BTI Bucklin
115 W. Railroad
PO Box 127
Bucklin, KS 67834
(800) 334-4823
(620) 826-3271

BTI Bucklin (800) 334-4823 (620) 826-3271
BTI Greensburg (888) 723-3331 (620) 723-3331
BTI Ness City (800) 572-2251 (785) 798-2410
BTI Pratt (800) 573-5606 (620) 672-5606
BTI Hoxie (844) 688-4362 (785) 675-8207
BTI Great Bend (800) 817-9921 (620) 793-3500



JOHN DEERE

*** PROFORMA INVOICE ***

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 51464

Bus Phone:
Prv Phone:

Internal Used Stock No. 51464

Bus Phone:
Prv Phone:

Invoice Number:
Invoice Date 09/07/2017
Locallon: 1
Work Order Number: 49704
Payment Type: Account

Page: 1 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2001 JOHN DEERE From Orebaugh	4615	H09650S690782		

Service Reminders:

/COMBINE -F-0007098 Internal

COMPLAINT:

01 BTI PERFORMAX COMBINE INSPECTION (S/ E HRS)

CAUSE:

CORRECTION:

PERFORM BTI PERFORMAX INSPECTION

Miscellaneous Charges:

Labor: \$679.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$679.00
-----------------	---------------	--------------	--------------	---------------------

/B110-003 -F-0006518 Internal

COMPLAINT:

02 FLUSH AND CHANGE OIL IN FEEDER HOUSE REVERSER WITH OIL

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY28815	LUBRICANT	1.00	20.80	\$20.80	N

Miscellaneous Charges:

Labor: \$145.50	Parts: \$20.80	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$166.30
-----------------	----------------	--------------	--------------	---------------------

Gen7- Internal

COMPLAINT:

03 FLUSH AND FILL FINAL DRIVES

CAUSE:

CORRECTION:



BTI Bucklin
 115 W. Railroad
 PO Box 127
 Bucklin, KS 67834
 (800) 334-4823
 (620) 826-3271

BTI Bucklin (800) 334-4823 (620) 826-3271
 BTI Greensburg (888) 723-3331 (620) 723-3331
 BTI Ness City (800) 572-2251 (785) 798-2410
 BTI Pratt (800) 573-5606 (620) 672-5606
 BTI Hoxie (844) 688-4362 (785) 675-8207
 BTI Great Bend (800) 817-9921 (620) 793-3500



JOHN DEERE

*** PROFORMA INVOICE ***

SERVICE INVOICE

Invoice To Account No: Internal Used Stock No. 51464	Deliver To: Internal Used Stock No. 51464	Invoice Number: Invoice Date: 09/07/2017 Location: 1 Work Order Number: 49704 Payment Type: Account
Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Page: 2 of 6
Make/Model: 2001 JOHN DEERE From Orebaugh	Meter: 4615 Serial Number: H09650S690782	EQ Id: Fleet No:
Service Reminders:		

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY6296	LUBRICANT	18.00	8.21	\$147.78	N

Miscellaneous Charges:

Labor: \$194.00	Parts: \$147.78	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$341.78
-----------------	-----------------	--------------	--------------	---------------------

Gen11- Internal
 COMPLAINT:
 04 REPLACE FRONT END DRIVE BELT
 CAUSE:
 CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
HXE95835	V-BELT	1.00	317.42	\$317.42	N

Miscellaneous Charges:

Labor: \$145.50	Parts: \$317.42	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$462.92
-----------------	-----------------	--------------	--------------	---------------------

9650STSG878534 Internal
 COMPLAINT:
 05 REEL PUMP BEARINGS AND SHEAVE, REPLACES.
 CAUSE:
 CORRECTION:
 Loosen upper feeder house belt.
 Remove sheave support from combine.
 Remove pump from drive sheave.
 Replace sheave, bearings and snap ring.
 Install new plug.
 Install in reverse order.



BTI Bucklin
 115 W. Railroad
 PO Box 127
 Bucklin, KS 67834
 (800) 334-4823
 (620) 826-3271

BTI Bucklin (800) 334-4823 (620) 826-3271
 BTI Greensburg (888) 723-3331 (620) 723-3331
 BTI Ness City (800) 572-2251 (785) 798-2410
 BTI Pratt (800) 573-5606 (620) 672-5606
 BTI Hoxie (844) 688-4362 (785) 675-8207
 BTI Great Bend (800) 817-9921 (620) 793-3500



*** PROFORMA INVOICE ***

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 51464

 Bus Phone:
 Prv Phone:

Internal Used Stock No. 51464

 Bus Phone:
 Prv Phone:

Invoice Number:
 Invoice Date 09/07/2017
 Location: 1
 Work Order Number: 49704
 Payment Type: Account

 Page: 3 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2001 JOHN DEERE From Orebaugh	4615	H09650S690782		

Service Reminders:
 Adjust belt tension.
 Run and test

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH201530	BALL BEARI	1.00	32.28	\$32.28	N
AH201531	BALL BEARI	1.00	52.72	\$52.72	N
E59406	FLANGE NUT	1.00	0.95	\$0.95	N

Miscellaneous Charges:

Labor: \$291.00	Parts: \$85.95	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$376.95
-----------------	----------------	--------------	--------------	---------------------

Gen15- Internal

COMPLAINT:

06 REPLACE A CROSS AUGER BEARING

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH133191	ECCENTRIC	1.00	13.72	\$13.72	N
H161629	PRESSED FL	2.00	5.12	\$10.24	N
JD39104	BALL BEARI	1.00	35.91	\$35.91	N

Miscellaneous Charges:

Labor: \$194.00	Parts: \$59.87	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$253.87
-----------------	----------------	--------------	--------------	---------------------

/B010-001 -F-0006603 Internal

COMPLAINT:

08 SERVICE ENGINE, COMBINE, CHANGE ENGINE OIL & ALL FILTERS.



BTI Bucklin
 115 W. Railroad
 PO Box 127
 Bucklin, KS 67834
 (800) 334-4823
 (620) 826-3271

BTI Bucklin (800) 334-4823 (620) 826-3271
 BTI Greensburg (888) 723-3331 (620) 723-3331
 BTI Ness City (800) 572-2251 (785) 798-2410
 BTI Pratt (800) 573-5606 (620) 672-5606
 BTI Hoxie (844) 688-4362 (785) 675-8207
 BTI Great Bend (800) 817-9921 (620) 793-3500



JOHN DEERE

*** PROFORMA INVOICE ***

SERVICE INVOICE

Invoice To Account No: Internal Used Stock No. 51464		Deliver To: Internal Used Stock No. 51464		Invoice Number: Invoice Date: 09/07/2017 Location: 1 Work Order Number: 49704 Payment Type: Account	
Bus Phone: Prv Phone:		Bus Phone: Prv Phone:		Page: 4 of 6	
Make/Model: 2001 JOHN DEERE From Orebaugh		Meter: 4615	Serial Number: H09650S690782	EQ Id:	Fleet No:

Service Reminders:

CAUSE:

CORRECTION:

Change engine oil and filters, both engine air filters, fuel and water separator filters

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH115833	AIR FILTER	1.00	62.61	\$62.61	N
AH115836	AIR FILTER	1.00	73.56	\$73.56	N
AH128449	HYDRAULIC	3.00	55.35	\$166.05	N
AH148880	FILTER ELEMENT	1.00	69.29	\$69.29	N
AR86745	FILTER ELE	1.00	23.35	\$23.35	N
DZ101880	FILTER KIT	1.00	17.28	\$17.28	N
RE63932	FILTER ELE	1.00	62.88	\$62.88	N
TY6341	Grease Multi Purpose SD Polyurea	1.00	5.03	\$5.03	N

Miscellaneous Charges:

Labor: \$379.27	Parts: \$480.05	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$859.32
-----------------	-----------------	--------------	--------------	---------------------

/B120-059 -F-0006543 Internal

COMPLAINT:

09 CHANGE OIL IN 2 SPEED GEARBOX

CAUSE:

CORRECTION:

Drain oil
 Fill to proper level
 Run and recheck level

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY6296	LUBRICANT	4.00	8.21	\$32.84	N

Miscellaneous Charges:

Labor: \$97.00	Parts: \$32.84	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$129.84
----------------	----------------	--------------	--------------	---------------------



BTI Bucklin
 115 W. Railroad
 PO Box 127
 Bucklin, KS 67834
 (800) 334-4823
 (620) 826-3271

BTI Bucklin (800) 334-4823 (620) 826-3271
 BTI Greensburg (888) 723-3331 (620) 723-3331
 BTI Ness City (800) 572-2251 (785) 798-2410
 BTI Pratt (800) 573-5606 (620) 672-5606
 BTI Hoxie (844) 688-4362 (785) 675-8207
 BTI Great Bend (800) 817-9921 (620) 793-3500



JOHN DEERE

*** PROFORMA INVOICE ***

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 51464

Internal Used Stock No. 51464

Invoice Number:

Invoice Date 09/07/2017

Location: 1

Work Order Number: 49704

Payment Type: Account

Page: 5 of 6

Bus Phone:

Bus Phone:

Prv Phone:

Prv Phone:

Make/Model:

Meter

Serial Number:

EQ Id:

Fleet No:

2001 JOHN DEERE From Orebaugh

4615

H09650S690782

Service Reminders:

9650STSG908674 Internal

COMPLAINT:

10 PRIMARY DRIVE SHAFT CARRIER BEARING, R&R

CAUSE:

CORRECTION:

Remove and recondition drive shaft.
 Remove carrier bearing.
 Install new carrier bearing and drive shaft.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Inc
H160465	Pressed Flanged Housing	1.00	10.15	\$10.15	N
H160466	Pressed Flanged Housing	1.00	10.98	\$10.98	N
H165447	LOCK NUT	1.00	8.12	\$8.12	N
H214618	Shaft	1.00	819.03	\$819.03	N
JD8579	Eccentric Locking Collar	1.00	19.21	\$19.21	N
JD9339	Ball Bearing	1.00	36.75	\$36.75	N

Miscellaneous Charges:

Service Accessories

\$75.00

Labor: \$232.80 Parts: \$904.24 OL&M: \$0.00 Misc: \$75.00 Sub-Total: \$1,212.04

10WLK-RTRYSCRNBRG Internal

COMPLAINT:

07 ROTARY SCREEN BEARING REPLACE

CAUSE:



BTI Bucklin
 115 W. Railroad
 PO Box 127
 Bucklin, KS 67834
 (800) 334-4823
 (620) 826-3271

BTI Bucklin (800) 334-4823 (620) 826-3271
 BTI Greensburg (888) 723-3331 (620) 723-3331
 BTI Ness City (800) 572-2251 (785) 798-2410
 BTI Pratt (800) 573-5606 (620) 672-5606
 BTI Hoxie (844) 688-4362 (785) 675-8207
 BTI Great Bend (800) 817-9921 (620) 793-3500



JOHN DEERE

*** PROFORMA INVOICE ***

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 51464

Internal Used Stock No. 51464

Invoice Number:

Invoice Date 09/07/2017

Location: 1

Work Order Number: 49704

Payment Type: Account

Page: 6 of 6

Bus Phone:

Prv Phone:

Bus Phone:

Prv Phone:

Make/Model:

Meter

Serial Number:

EQ Id:

Fleet No:

2001 JOHN DEERE From Orebaugh

4615

H09650S690782

Service Reminders:

CORRECTION:

REPLACE ROTARY SCREEN BEARING

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H103264	PRESSED FL	2.00	2.51	\$5.02	N
JD39102	BALL BEAR	1.00	22.20	\$22.20	N

Miscellaneous Charges:

Labor: \$58.20 Parts: \$27.22 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$85.42

Customer PO No:
 Tax Exempt No:
 Advisor: RYAN UNRUH

Labor: \$2,416.27
 Parts: \$2,076.17
 OL&M: \$0.00
 Misc: \$75.00
 Sales Tax: \$0.00

 Total: \$4,567.44

TERMS AND CONDITIONS

Payment is due upon receipt. A finance charge of 1.5% per month (18% annual percentage rate) will be added to all past due invoices. We accept Cash, Check, John Deere Financial, Visa and Mastercard.

Received by:

Date: