



2012  
water pump

CK# 1319 P 530.58

**CORNERSTONE AUTOMOTIVE**  
1207 E US HWY 136  
ALBANY, MO. 64402  
Phone: 660-726-4053 Fax: 660- -  
SALES AND SERVICE

INVOICE

15393

**INVOICE**

Printed Date: 12/11/2024 Work Completed: 12/11/2024

**Groom, Dirk and Nita** 2012 Ford - Pickup F150 - 3.5L, V6 (213CI) VIN(T)  
10628 W. State Hwy 46 Lic # : 06J 2LX Odometer In : 209518  
Grant City, MO 64456 Odometer Out : 209518  
Home 660-254-5355 NITA -- Office 660-254-7625 DIRK VIN # : 1FTFW1ET9 CKD64203

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Water Pump CP6691	1.00	111.73	111.73	INTAKE MANIFOLD GASKET - Remove & Replace - F150,3.5L Eng	195.00
Coolant Thermostat Housing Gasket 35934	1.00	14.58	14.58	WATER PUMP - Remove & Replace - F150,3.5L Eng Hazardous Materials	175.50 3.71
Coolant Defend	1.00	16.00	16.00		
Shop Supplies			2.85		

Org Estimate 530.58 Revisions 0.00 Current Estimate 530.58

Labor:	370.50
Parts:	145.16
HazMat:	3.71
SubTotal:	519.37
Tax:	11.21
Total:	530.58
Bal Due:	\$530.58

pd CK 1319  
12/11/24

[ Payments - ]

Vehicle Received 12/11/2024

Customer Number : 1318

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature \_\_\_\_\_ Date \_\_\_\_\_

Email Address: [cornerstone1207@outlook.com](mailto:cornerstone1207@outlook.com)

2012 pu

CK # 870

7-11-24

**CORNERSTONE AUTOMOTIVE**  
1207 E US HWY 136  
ALBANY, MO. 64402  
Phone 660-726-4053 Fax 660-  
SALES AND SERVICE

INVOICE

14789

**INVOICE**

Printed Date 07/11/2024 Work Completed: 07/11/2024

**Groom, Dirk and Nita**

10628 W. State Hwy 46  
Grant City, MO 64456

Home 660-254-5355 NITA - Office 660-254-7625 DIRK

2012 Ford - Pickup F150 - 3.5L, V6 (213Ci) VIN(T)

Lic # : 06J 2LX

VIN # 1FTFW1ET9 CKD64203

Odometer In : 203248

Odometer Out : 203253

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Housing - Fuel Tank Filler Pipe 9L3Z9927936B	1.00	62 03	62 03	Lube, Oil Change, & Filter Labor	10 00
Spark Plug - Iridium - OE Type XP5863	1.00	11 45	11 45	DIAGNOSTIC- Scan for codes and test for possible causes of codes P0151-00, P0301-00, P0316-00 and P0481-00 Clear codes and re-test.	37.50
Ignition Coil - OEM IC749	1.00	87 12	87 12	IGNITION COIL - Remove & Replace - F150,3.5L Eng One Includes replace spark plug. Cyl #1	45.50
Schaeffer Engine Oil SCHAF5W30	6.00	12 46	74.76	FUEL DOOR HOUSING- Remove and replace Hazardous Materials	32.50 1.26
Coolant DFD-1	0.30	17.20	5.16		
Washer Fluid WASH-1	0.50	4.95	2.48		
Shop Supplies			4.86		

Org Estimate 393.77 Revisions 0.00 Current Estimate 393.77

Labor:	125.50
Parts:	247.86
HazMat:	1.26
SubTotal:	374.62
Tax:	19.15
Total:	393.77
Bal Due:	\$393.77

*pd. CK 870  
7-11-24*

[ Payments - ]

Vehicle Received 7/11/2024

Customer Number : 1318

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature \_\_\_\_\_ Date \_\_\_\_\_

Email Address: [cornerstone1207@outlook.com](mailto:cornerstone1207@outlook.com)

