





WEST-EQUIP.COM

Invoice To Account No: 7496

Deliver To:

SERVICE INVOICE

Estes Farms Jerry Estes **5725 W OKC RENO STREET EL RENO OK 73036**

Estes Farms 5725 W OKC RENO STREET EL RENO OK 73036

4027913 **Invoice Number:** 09/26/2023 Invoice Date Location: 02 Work Order Number: 687557 Payment Type: Account

Bus Phone: Prv Phone:

Bus Phone: Prv Phone:

1 of 4 Page:

Make/Model:	ferman	- 26-	-	and the same	-
Make/Model.					

EQ Id: Serial Number: Meter

Fleet No:

Make/Model.	Wiele	Serial Humber.	A STATE OF THE PARTY OF THE PAR	
john deere 4450	1847	RW4450H021198	EF021198	
				The state of the s

4450-1106/EM/10 Retail

COMPLAINT:

01 Diagnostics and Troubleshooting.

POSSIBLE LIFTER ISSUE

CORRECTION:

audible knocking heard from engine. Customer thought it was possibly a lifter. I however thought that it sounded like a rod knock. Determined best course of diagnostic was to pull the oil pan and look up at the cam lobes and check rod bearings while there. Found the #4 cylinder to have a spun rod bearing and the other rod bearings had signs of being starved for oil. I also found the transmission to be full of engine oil and the engine itself was low. I believe the rear main seal went out and let the engine pump its oil into the transmission before the operators checked the oil again. This scenario would explain the oil in the transmission and the lack of lubrication that the engine experienced.

PartNumber	<u>Description</u>	Quantity	Net Price	Extended Price	Taxed Ind
14H1025	Nut	1.00	\$1.78	\$1.78	Y
19H1707	CAP SCREW	2.00	\$6.16	\$12.32	Y
19M7513	CAP SCREW	2.00	\$1.38	\$2.76	Y
34H383	SPRING PIN	1.00	\$3.27	\$3.27	Y
57M9218	Elec Connector Seal	2.00	\$0.37	\$9.74	Y
AR71850	DIPSTICK T	1.00	\$30.32	\$30.32	Y
AR79679	AIR FILTER	1.00	\$61.96	\$61.96	Υ
AR79680	FILTER ELE	1.00	\$40.67	\$40.67	Y
AR86745	FILTER ELE	2.00	\$34.86	\$69.72	Y
AR94510	FILTER ELE	2.00	\$56.28	\$112.56	Y
AT37368	SENDER	1.00	\$53.38	\$53.38	Υ
DIESEL	FUEL	15.00	\$4.64	\$69.60	N
DZ102076	COOLANT HE	1.00	\$164.52	\$164.52	Y
PM37509	PRIMER	1.00	\$24.20	\$24.20	Y
PM38657	SEALANT	1.00	\$25.64	\$25.64	Y
R134A	FREON	3.00	\$12.95	\$38.85	Y
R34733	SEALING WA	3.00	\$2.93	\$8.79	Y
R47153	O-RING	1.00	\$3.06	\$3.06	Υ
R51936	SEALING WA	4.00	\$1.98	\$7.92	Y
R520707	GASKET	1.00	\$2.85	\$2.85	Y
R523306	KEY	1.00	\$12.19	\$12.19	Y

CONTINUED ON NEXT PAGE->







WEST-EQUIP.COM

Invoice To Account No: 7496

Deliver To:

SERVICE INVOICE

Estes Farms Jerry Estes

5725 W OKC RENO STREET

EL RENO OK 73036

Estes Farms 5725 W OKC RENO STREET

Invoice Number: Invoice Date

4027913 09/26/2023

EL RENO OK 73036

Location: Work Order Number:

02 687557

Bus Phone: Prv Phone:

Bus Phone:

Payment Type:

1.00

\$86.50

Misc:

Account

Prv Phone:

Page:

2 of 4

No. 10. 10. 10. August and annual to	No. of Contract of the Contrac		100000000000000000000000000000000000000			
Make/Model:	Meter	Serial Number:	EQ	ld:	Fleet No:	
john deere 4450	1847	RW4450H021198	EF0	21198		
R59294	SEALING RI		6.00	\$1.81	\$10.86	Y
R67092	SEAL		3.00	\$4.91	\$14.73	Y
R73189	V-BELT		1.00	\$10.30	\$10.30	Y
R78058	ELEC. CONN		5.00	\$1.12	\$5.60	Y
R79605	WASHER		1.00	\$3.02	\$3.02	Y
R99286	GASKET		1.00	\$44.41	\$44.41	Y
RE10713	ADAPTER		2.00	\$177.88	\$355.76	Y
RE11414	Shifter Rod		1.00	\$59.83	\$59.83	Υ
RE12363	ELECTRICAL		1.00	\$2.51	\$2.51	- Y
RE15583	ENGINE OIL		1.00	\$65.92	\$65.92	Y
RE39116	NEUTRAL ST		1.00	\$50.09	\$50.09	Y
RE65265	HAND PRIME		1.00	\$43.61	\$43.61	Y
SE500042	Basic Diesel Engine Reman		1.00	\$16,624.67	\$16,624.67	Y
SE500042-CR	CORE for:Basic Diesel Engine Reman		-1.00	\$1,700.00	-\$1,700.00	Y
SE501111	INJECTION NO		6.00	\$149.09	\$894.54	Y
TY22028S	Shop Hy-Gard		13.00	\$23.02	\$299.26	Y
TY22420	.250 ID WATER, VACUUM HOSE		120.00	\$0.04	\$4.80	Y
TY22462	CLAMP		2.00	\$1.47	\$2.94	Y
TY26101	BRAKE CLEANER	Total Comments of the Comments	3.00_	\$7.72	\$23.16	Y Y
TY26576	COOL-GARD 2.5G		3.00	\$39.63	\$118.89	Y
TY26661 Miscellaneous	Break-in Plus-GAL 10W-30 N/A <u>Description</u>		5.00 Quantity	\$29.99 Net Price	\$149.95 Extended Price	Y Taxed Ind

4450-1000/10 Retail

COMPLAINT:

Labor: \$525.60

3750

02 ENGINE - Remove & Install

CORRECTION:

R&I engine **Drained** oil **Drained** coolant Removed hood

Disconnected hydraulic pump drive and support

FREIGHT

Parts: \$17,831.95

OL&M: \$0.00

CONTINUED ON NEXT PAGE->

\$86.50

\$18,444.05

N

\$86.50

Sub-Total:







WEST-EQUIP.COM

Invoice To Account No: 7496

Deliver To:

SERVICE INVOICE

Estes Farms

Jerry Estes

5725 W OKC RENO STREET EL RENO OK 73036

Bus Phone:

Prv Phone:

Make/Model:

Estes Farms

5725 W OKC RENO STREET **EL RENO OK 73036**

Meter

Bus Phone: Prv Phone:

Invoice Number: Invoice Date

4027913 09/26/2023

Location: Work Order Number: Payment Type:

EQ ld:

EF021198

687557

Page:

3 of 4

Account

Fleet No:

RW4450H021198 john deere 4450 1847

Disconnected A/C Quick couplers, lines, hoses, linkages, and wiring harnesses Supported rear of tractor and engine Secured front axle pivot and steering Supported front end and side frames Unbolted side frames from engine Split front end & side frames from engine, clutch, & trans Supported engine with suitable lifting device Unbolted engine from clutch housing

NEW ENGINE INSTALLED AT 1847 HRS!!!

Labor: \$2,271.92

Parts: \$0.00

OL&M: \$0.00

Misc:

Serial Number:

\$0.00

Sub-Total:

\$2,271.92

Gen 10 Retail

COMPLAINT:

03

SWAPPING OVER ENGINE PARTS

CORRECTION:

Removed muffler and muffler mount. Removed turbo oil line. Removed turbo. Removed exhaust manifold. Removed Intake manifold. Removed water manifold. Removed turbo oil drain adapter and reinstalled on new engine. Installed new o-ring in oil drain adapter. Removed engine fan. Loosened alternator and removed fan belts. Removed fan. Removed fan mounting bracket. Removed crank dampener and pulley assembly. Removed Alternator bracket and alternator. Removed fuel injector lines between injector and injection pump. Removed line hold bracket and lines. Removed fuel injector return lines and disassembled. Replaced all rubber seals and reassembled. Installed new injectors in new engine. Removed fuel line from fuel filter housing to injection pump. Removed aneroid lines from injection pump. Removed low pressure fuel pump lines from tank to filter. Removed front access cover and Removed Injection pump gear. Removed nuts from injection pump studs and removed injection pump. Removed clutch assembly. Removed flywheel. Removed oil galley fittings from block and installed on new block. Removed turbo oil supply line from old engine and installed on new engine. Removed fuel filter assembly and installed on new engine. Installed flywheel on new engine according to TM. Removed valve cover of new engine and set engine to TDC #1 compression stroke. Installed injection pump according to TM. Reassembled all removed components in reverse order with new gaskets and seals where applicable. Cleaned all block sealing surfaces to prep for gaskets where needed.

Installed new coolant temp sensor. Installed new fuel hand primer pump. Performed clutch adjustment per TM specs. Reassembled engine in frame and rolled tractor half's together. Filled with new cool-guard coolant and break-in plus oil. Filled trans with diesel fuel to flush contaminated oil out of hydraulic system. Ran for 5 min to allow flush to go through hydraulic system. Drained, and changed filters. Filled with new hy-guard oil. Washed tractor without hood/panels on to remove all old oil and grease. Ran around yard briefly and checked for leaks. Found two leaks. One leak was for the cooler return line and the other was the cooler pressure line. Fixed both leaks. Noticed that the A/C was not cooling. Checked A/C pressures and found them to be low. Charged A/C and verified it was working correctly. Ran tractor through its break-in period on the PTO dyno. Peak HP witnessed was 153 HP. Reinstalled all panels and hood. Checked over engine and tractor to make sure all components were tight and securely fastened. Washed and parked in go home line.

CONTINUED ON NEXT PAGE->





21 LOCATIONS TO SERVE YOU!

4501 East Main St. P.O. Box 391 Weatherford, OK 73096 (580) 772-5578

WEST-EQUIP.COM

Invoice To Account No: 7496	Deliver To:	SERV	ICE INVOICE
Estes Farms Jerry Estes 5725 W OKC RENO STREET EL RENO OK 73036	Estes Farms 5725 W OKC RENO STREET EL RENO OK 73036	Invoice Number: Invoice Date Location: Work Order Number: Payment Type:	4027913 09/26/2023 02 687557 Account
Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Page:	4 of 4
Make/Model:	Meter Serial Number:	EQ id:	leet No:
john deere 4450	1847 RW4450H021198	EF021198	
abor: \$7,264.44 Parts: \$0.00	OL&M: \$0.00 Misc:	\$0.00 Sub-Total:	\$7,264.44
		Labor	\$10,061.96
Customer PO No:		Parts	\$17,831.95
Tax Exempt No:		OL&M	\$0.00
Advisor: Jim Barnett		Misc	\$86.50
Jill Dalliell		Sales Tax	\$1,687.35
		Total	\$29,667.76
			7-6

TERMS AND CONDITIONS

All returns must occur within 30 days of purchase and must be accompanied by this invoice. Special order and electrical components are not returnable. I hereby certify that the tax exempt items sold on this invoice are to be used only for agricultural production business purposes.

Dosohuad bye		Deter	
Received by	•••••	Date:	• • • • • • • • • • • • • • • • • • • •







DADTS INVOICE

West-Equip.com

Invoice To Account No.: 7496	Deliver to Account No.: 7496			FANI	3 114 4 0	ICE
Estes Farms 5725 RENO W EL RENO OK 73036 US Bus Ph: Prv Ph:	Estes Farms 5725 RENO W EL RENO OK 73036 US Bus Ph: Pry Pl		Paymen	Date: Page:	1/12/	0947 2024 1 of 1 Card
Supplied Back Order Part Quantity Quantity Number	Part Description	Bin	List Price	Net Price	Extended Price	Tax Ind
1.00 0.00 A-AR96902	Oil Cooler		644.56	644.56	\$644.56	N
Customer PO No: Tax Exempt No: EXM1359501803-26 Salesperson: RYAN ROULET			Parts Misc Sales Depo	: s Tax:	\$	4.56 0.00 0.00 0.00
edit Card Information Merchant ID:	Terminal ID: 0 CI	ient ID:	Total		\$64	4.56
pl Label Masked PAN Card Entry RESULT Auth	AND TVR TSI A	RC IAD TC			CVM	Tota
		10 10				

TERMS AND CONDITIONS

Full payment is due upon receipt of statement. No finance charges will be assessed on accounts paid within 30 days of purchase. Invoices not paid within 30 days will be assessed a 1 1/2% finance charge each month (18% annual percentage rate)

The original purchaser may make a return (electrical components are non-returnable) in its original condition, original packaging and accompanied by this invoice within 30 days of the date of purchase. Delivery and any shipping charges are non-refundable. If the return is after the 30-day window, then a restocking fee will be charged. All cores or warranty items must be returned in original packaging and be accompanied by this invoice to receive credit. I hereby certify that the tax-exempt items sold on this invoice are to be used only for agricultural production business purposes.

Received by:		Date:	***************************************
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	***************************************	Date.	*******************************