

Dirt Road Repair LLC

P.O. BOX 545
 AKRON, CO 80720
 dirtroadrepair@gmail.com
 970-554-0988/970-554-0558



Invoice: **DRAFT INV**
 Date: **1/24/2025**

Bill To
 Mark Bradney Farms
 25250 County Road BB
 Akron, CO 80720

Ship To
 Mark Bradney Farms
 25250 County Road
 BB
 Akron, CO 80720

Remit Payment To
 DIRT ROAD
 REPAIR
 P.O. BOX 545
 AKRON, CO 80720

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
5246	Net 30	DRAFT INV	Mark Bradney		S680

Item	Description	Quantity	Rate	Amount
Complaint: Remove and install transmission				
Cause: Customer request				
Labor	Correction: Chassis / Chassis / Removed hydraulic lines and drive shafts. Removed hydrostat motor. Removed transmission. Installed in Reverse order.	8.00000	\$120.00	\$960.00
				Subtotal \$960.00

Complaint: Repair transmission shifting problem
Cause: Customer request

Labor	Correction: Chassis / Chassis / Disassembled transmission. Found disks in the planetary drive was burned up. Disassembled planetary drive and replaced disks, bearings and gears. Replaced ring gear as it had a tooth missing. Cleaned transmission out and assembled in reverse order.	25.00000	\$120.00	\$3,000.00
				Subtotal \$3,000.00

Inspection

Labor	Service Call Zone 2 (21-40 miles): Round trip travel	2.00000	\$100.00	\$200.00
				Subtotal \$200.00

Inspection

Labor	Service Call Zone 2 (21-40 miles): Round trip travel	2.00000	\$100.00	\$200.00
				Subtotal \$200.00

Unit: S680 VIN: 1H0S680SJC0747348

John Deere S680

Engine: 0 Hours

Seperator: 0 Hours

Labor	\$4,360.00
Shop Supplies	\$100.00
Pre-Charge Subtotal	\$4,460.00
Colorado State (2.9% of \$100.00)	\$2.90
Washington County (1.5% of \$100.00)	\$1.50
Total	\$4,464.40