

928 S. Division PO Box 128 Polo, IL 61064 Phone 815-946-2393 Phone 877-569-0510 Fax 815-946-2396

–100% EMPLOYEE OWNED – IN STORE PICKUP

Ship to:

ë nvoice

SUGAR CREEK FARM PART. 1933 MOUND HILL RD DIXON IL 61021

Branch					
POLO		*REPR	INT		
Date	Time				Page
01/24/23	22:	36:37	(B)		01
Account No.	Phone No	0.		Invoi	ce No.
SUGAR007	815	631 <u>765</u>			287
Ship Via		Purchase	Order		
		<u></u>			
-			Sale	sperso	on
				TAG	i

SERVICE INVOICE

STK#/FLEET#

X086800 0014223366 TRACTORS

STEIGER 370

HRS PIN/EIN

1394 ZJF315836 #1

000230712

WARRANTY DATE

10/14/20

HRS

2000 B

SEGMENT# 1 C 17064 CMIST370T4B 01/18/23 01/18/23 PERFORM MAINTENANCE AND INSPECTION

> HRS 6.00

1. PERFORM MAINTENANCE AND INSPECTION

(CMIST370T4B)

MULTI POINT INSPECTION, Replace engine oil and filter, replace fuel filters, replace outer engine air and cab filter, replace coolant filter, check fluid levels,

tractor, pressure check hydraulics, grease tractor, clean

cab and wash windows				
AF55732	cab filter	RETAIL	45.99	
		1	41.39	41.39
5801439820	FILTER, FUEL T4	RETAIL	81.25	
		1	73.12	73.12
73344237	15W40 BULK	RETAIL	18.75	
		7	16.87	118.09
73344356	PREMIUM EP-2 GR	RETAIL	6.50	
		1	5.85	5,85
84303715	FILTER, FUEL	RETAIL	106.00	
	,	1	95.40	95.40
84565867	FILTER, EN	RETAIL	163.00	
		1	146.70	146.70
87356545	FILTER, AI	RETAIL	194.00	
0,000010		1	174.60	174.60
			PARTS	655.15
			LABOR	543.85
11000012		SEGMENT	TOTAL==>	1199.00
11000011		CONTI	NUED ON PAGE 02	

Birkey's will not be liable for loss, damage, cost of repairs incidental or consequential damages of any kind, whether based upon warranty, contract or negligence, arising in connection with the sale, use, or repair of the products. Parts on repairs are sold as is with no warranties except as provided for by the manufacturer. The customer by the acceptance of this order accepts all the terms and conditions thereof. These terms and conditions supersede and take precedence over and above all previous verbal or written arrangements in connection with this order. All amounts are due when invoiced. Accounts not paid in full are subject to a service charge of 2% per month (24% annually) plus any additional expenses incurred for collection. Any unpaid balance shall constitute a mechanics lien on this equipment as provided for by state statute.

Authorized Signature	Date



928 S. Division PO Box 128 Polo, IL 61064 Phone 815-946-2393

Phone 877-569-0510 Fax 815-946-2396

IN STORE PICKUP

ö Ship t

ë nvoice SUGAR CREEK FARM PART. 1933 MOUND HILL RD DIXON IL 61021

Branch				
POLO				
Date	Time			Page
01/24/23	22:	36:37 (B)		02
Account No.	Phone No	o	Invo	ice No.
SUGAR007	815	6317654	M3.	7287
Ship Via		Purchase Orde	r	
· ·				
		Sal	espers	on
			DAT.	

SERVICE INVOICE

STK#/FLEET#

0014223366

X086800

TRACTORS

STEIGER 370

1394

HRS

ZJF315836 #1 000230712

PIN/EIN

WARRANTY DATE

10/14/20

HRS 2000 B

SEGMENT# 2 C 17064 NA

CMI REPAIRS 11000012

01/18/23 01/19/23

***** WORK ORDER TOTALS *****

1239.99

PARTS 655.15 LABOR 543.85 Consumables 32.63 1231.63 SUB TOTAL ==> 8.36

ILLINOIS STATE TAX

TOTAL CHARGE

TERMS:

2

Net 30

Birkey's will not be liable for loss, damage, cost of repairs incidental or consequential damages of any kind, whether based upon warranty, contract or negligence, arising in connection with the sale, use, or repair of the products. Parts on repairs are sold as is with no warranties except as provided for by the manufacturer. The customer by the acceptance of this order accepts all the terms and conditions thereof. These which produces a realist of repairs are some early smith warranties except as provided for the set of the conditions supersed and take precedence over and above all previous verbal or written arrangements in connection with this order. All amounts are due when invoiced, accounts not paid in full are subject to a service charge of 2% per month (24% annually) plus any additional expenses incurred for collection. Any unpaid balance shall constitute a mechanics lien on this equipment as provided for by state statute.

Auth	Arizad	Signature
Auu	unzeu	Siumature



928 S. Division PO Box 128 Polo, IL 61064 Phone 815-946-2393

Phone 877-569-0510 Fax 815-946-2396

IN STORE PICKUP

ë Ship

> SUGAR CREEK FARM PART. 1933 MOUND HILL RD DIXON IL 61021

Branch			Ĭ	
POLO _		*REPRINT	<u>:</u> *	, <u></u>
Date	Time			Page
11/16/21 Account No.		36:17 (B)		01
Account No.	Phone No	0.	Invo	ice No.
SUGAR007	815	6317654	W3:	3699
Ship Via		Purchase Ord	ler	
		Sa	alespers	on
		ĺ	TAC	

SERVICE INVOICE

STK#/FLEET# X086800 TRACTORS

HRS PIN/EIN 1087 ZJF315836 #1 WARRANTY DATE

HRS

0014223366 STEIGER 370 000230712

10/14/20 2000 B

SEGMENT# 1 C 17077 CMIST370T4B 11/11/21 11/12/21 CMI INSPECTION

CORRECTION:

0

nvoice

- *changed engine oil
- *changed engine oil, fuel, air and cabin air filters
- *greased all grease zerks
- *tested all tractor functions
- *test drove tractor and checked for any noises that

customer noted

- *did not hear any obvious noises
- *inspected drive lines, wheel and hub bolts, tractor pivot and steering cylinders for source of noise
- *everything checks out and seems tight except minor play in steering knuckles and pins
- *pulled and inspected pins and joints, pins have some wear where joint rides, noted in cmi form
- *inspected all fluid levels
- *completed cmi inspection and completed check list
- *ran tractor on dyno and tractor made 360 horse at pto
- *checked hydraulic flow with flow meter and flow is in spec
- *cleaned cab floor and cab windows
- *completed quote sheet and called customer with quote

compresed quote briefe dire	Carrea cascomer wren	40000		
AF55732	cab filter	RETAIL	40.68	
		1	36.61	36.61
5801439820	FILTER, FUEL T4	RETAIL	66.00	
		1	59.40	59.40
73341706	BULK 15W40	8	13.50	108.00
84303715	FILTER, FUEL	RETAIL	112.00	
		1	100.80	100.80
		CONT	INUED ON PAGE 02	

Birkey's will not be liable for loss, damage, cost of repairs incidental or consequential damages of any kind, whether based upon warranty, contract or negligence, arising in connection with the sale, use, or repair of the products. Parts on repairs are sold as is with no warranties except as provided for by the manufacturer. The customer by the acceptance of this order accepts all the terms and conditions thereof. terms and conditions supersede and take precedence over and above all previous verbal or written arrangements in connection with this order. All amounts are due when invoiced. Accounts not paid in full are subject to a service charge of 2% per month (24% annually) plus any additional expenses incurred for collection. Any unpaid balance shall constitute a mechanics lien on this equipment as provided for by state

P1 414-14		_
Authorized Signature	Date	
Authorized Signature	Date	



928 S. Division PO Box 128 Polo, IL 61064 Phone 815-946-2393 Phone 877-569-0510

Fax 815-946-2396

IN STORE PICKUP

Ship to:

nvoice to:

SUGAR CREEK FARM PART. 1933 MOUND HILL RD DIXON IL 61021

Branch		
POLO		
Date	Time	Page
11/16/21	22:36:17	(B) 02
Account No.	Phone No.	Invoice No.
SUGAR007	815631765	4 W33699
Ship Via	Purchase	Order
		Salesperson
		JAG

SERVICE INVOICE

STK#/FLEET# X086800 0014223366	TRACTORS STEIGER	370	HRS 1087	PIN/EIN ZJF315836 000230712		ANTY DATE 10/14/20	HRS 2000 B	
84565867			FILTER,	EN	RETAIL	142.00		
					1	127.80		127.80
87356545			FILTER,	AI	RETAIL	156.00		
					1	140.40		140.40
						PARTS		573.01
						LABOR		425.99
11400012					SEGMENT	TOTAL==>		999.00

SEGMENT# 2 C 17077 NA

11/11/21 11/12/21

CMI REPAIRS

COMPLAINT:

- *engine breather filter replacement
- *hydraulic oil and filter change
- *transmission oil and filter change

CAUSE:

*repairs needed found in cmi inspection

CORRECTION:

- *drained hydraulic fluid from reservoir
- *drained final drives on both axles and drained centers of both axles
- *drained pto case
- *changed both hydraulic filters and transmission filter
- *filled transmission and hydraulic reservoir
- *ran tractor until hydraulic level dropped, refilled again
- *ran again for a while and then rechecked level topped off one last time
- *removed harness behind crackcase breather cover
- *removed cover
- *replaced crankcase filter
- *reinstalled cover with new gasket

CONTINUED ON PAGE 03

Birkey's will not be liable for loss, damage, cost of repairs incidental or consequential damages of any kind, whether based upon warranty, contract or negligence, arising in connection with the sale, use, or repair of the products. Parts on repairs are sold as is with no warranties except as provided for by the manufacturer. The customer by the acceptance of this order accepts all the terms and conditions thereof. These terms and conditions supersede and take precedence over and above all previous verbal or written arrangements in connection with this order. All amounts are due when invoiced. Accounts not paid in full are subject to a service charge of 2% per month (24% annually) plus any additional expenses incurred for collection. Any unpaid balance shall constitute a mechanics lien on this equipment as provided for by state statute.

· · · · · · · · · · · · · · · · · · ·	
Authorized Signature	Date



928 S. Division PO Box 128 Polo, IL 61064 Phone 815-946-2393 Phone 877-569-0510

Fax 815-946-2396

-100% EMPLOYEE OWNED ----

IN STORE PICKUP

nvoice to:

SUGAR CREEK FARM PART. 1933 MOUND HILL RD DIXON IL 61021

Branch		
POLO	"T	Page
Date	Time	rage
11/16/21	_22:36:17_(B) 03
Account No.	Phone No.	Invoice No.
SUGAR007	8156317654	W33699
Ship Via	Purchase Or	der
	S	alesperson
		TAC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARR	ANTY DATE	HRS	
X086800	TRACTORS	1087	ZJF315836 #:	1	10/14/20	2000 B	
0014223366	STEIGER 370		000230712				
	ed engine side shield						
*ran tracto	or for a while and ch	ecked fo	or any leaks	, none			
found							
*checked al	ll fluid levels and a	ıll fluid	ds are full				
47833556		FILTER,	HY	1	63.50		63.50
504290773		GASKET		1	40.50		40.50
5801659560		FILTER,	BREATHE	1	107.00		107.00
73344270		BULK HY	ran	65	16.90		1098.50
84196445		FILTER,	HYD	2	125.00		250.00
					PARTS		1559.50
					LABOR		895.48
11400012				SEGMENT	TOTAL==>		2454.98

***** WORK ORDER TOTALS *****

PARTS 2132.51

LABOR 1321.47

Consumables 79.28

SUB TOTAL==> 3533.26

ILLINOIS STATE TAX 75.41

PRODUCTIVITY PLUS 3608.67

Store ID: 1397541005 Client ID: 3339352003

Request ID: 01Z6JK81PA00P7AF03UHKINVHGBGKN90

6035XXXXXXXXXXXXXXXX

By signing I certify that I am authorized to use this Account, to sign this receipt, and that I agree that the total amount of this invoice is repayable in accordance with the Credit Agreement applicable to the Account.

CONTINUED ON PAGE 04

Birkey's will not be liable for loss, damage, cost of repairs incidental or consequential damages of any kind, whether based upon warranty, contract or negligence, arising in connection with the sale, use, or repair of the products. Parts on repairs are sold as is with no warranties except as provided for by the manufacturer. The customer by the acceptance of this order accepts all the terms and conditions thereof. These terms and conditions supersede and take precedence over and above all previous verbal or written arrangements in connection with this order. All amounts are due when invoiced. Accounts not paid in full are subject to a service charge of 2% per month (24% annually) plus any additional expenses incurred for collection. Any unpaid balance shall constitute a mechanics lien on this equipment as provided for by state statute.

Authorized Signature	Date



928 S. Division PO Box 128 Polo, IL 61064 Phone 815-946-2393

Phone 877-569-0510 Fax 815-946-2396

Ship to:

٥ nvoice IN STORE PICKUP

SUGAR CREEK FARM PART. 1933 MOUND HILL RD DIXON IL 61021

Branch	<u> </u>			
POLO				
Date	Time			Page
11/16/21	22:	36:17	(B)	04
Account No.	Phone N	0.		Invoice No.
SUGAR007	815	631765		W33699
Ship Via		Purchase	e Orde	r
			Sale	esperson
				JAG

SERVICE INVOICE

STK#/FLEET#

0014223366

X086800

TRACTORS

STEIGER 370

HRS PIN/EIN ZJF315836 #1 1087

000230712

WARRANTY DATE

HRS

10/14/20

2000 B

Birkey's will not be liable for loss, damage, cost of repairs incidental or consequential damages of any kind, whether based upon warranty, contract or negligence, arising in connection with the sale, use, or repair of the products. Parts on repairs are sold as is with no warranties except as provided for by the manufacturer. The customer by the acceptance of this order accepts all the terms and conditions thereof. These terms and conditions supersede and take precedence over and above all previous verbal or written arrangements in connection with this order. All amounts are due when invoiced. Accounts not paid in full are subject to a service charge of 2% per month (24% annually) plus any additional expenses incurred for collection. Any unpaid balance shall constitute a mechanics lien on this equipment as provided for by state statute.

Autho	rized	Signa	ture
Δa_{iiii}	11204	Olding	Luic