

9 Mile

330721 County Road E
 Minatare, NE 69356
 Michael@schiffarms.com
 3082208568

Estimate

1191

Date:

3/16/2023

Bill To
 Schiff of Nebraska

Remit Payment To
 Primary
 330721 County Road E
 Minatare, NE 69356

Service Order	Purchase Order	Service Writer	Authorizer		
1191		Henwick, Michael			
Item	Description	Quantity	Rate	Amount	
Complaint: TRUCK STARTED OVERHEATING					
Cause: Customer request					
Labor	Correction: A/C Cooling System / Thermostat / REPLACED COOLANT THERMOSTAT	2.00000	\$20.00	\$40.00	
Parts	THERMOSTAT - 101C/5273379 - A	1	\$69.44	\$69.44	
Parts	SEAL, RECTANGULAR RING - 101C/4936967 - A	1	\$19.91	\$19.91	
			Subtotal	\$129.35	

Complaint: Service**Cause:** Customer request (Inspection)

Labor	Correction: Engine / Lubrication / Service	1.00000	\$20.00	\$20.00	
Parts	1748 xd - 1748xd - A	1	\$32.54	\$32.54	
Parts	FLEET GUARD - COMPARES TO NAPA 600564 - FF63054NN - A	1	\$54.63	\$54.63	
Parts	FUEL FILTER - 3604 - A	1	\$59.65	\$59.65	
Parts	6429 - 6429 - A	1	\$17.82	\$17.82	
Parts	6433 - 6433 - A	1	\$25.24	\$25.24	
Parts	Mobil 15w40 - S80600 - A	5	\$21.53	\$107.65	
			Subtotal	\$317.53	

Shop Supplies

\$0.00

Unit: 207 **VIN:** 2NKHHJ7XXGM493654
 2016 Kenworth T3 Series
Engine: 14,700 Hours

Labor	\$60.00
Parts	\$386.88
Subtotal	\$446.88
Exempt (0% of \$279.23)	\$0.00
Total	\$446.88

*: Core charges not included in total. You will be charged for any core that is not in returnable condition. This charge may be applied on a separate invoice.

The details and the estimate for the repairs provided above are based on our first inspection and do not constitute a guarantee that no further work or parts will be required. The estimate is not a guarantee of the final price of the repairs. The total bill of work and final price will be as per the details available on completion of the repairs. Other terms and conditions as applicable. If you authorize us to perform the above repairs, either verbally or in writing, you agree to pay in full for the work performed and parts required.

Customer Signature: _____

9 Mile
 330721 County Road E
 Minatare, NE 69356
 Michael@schiffarms.com
 3082208568

Estimate **1205**

Date: **4/14/2023**

Bill To
 Schiff of Nebraska

Remit Payment To
 Primary
 330721 County Road E
 Minatare, NE 69356

Service Order

Purchase Order

Service Writer

Authorizer

1205

Henwick, Michael

Item	Description	Quantity	Rate	Amount
Complaint: REPLACED PTO SHAFT CARRIER BEARING				
Cause: Customer request				
Labor	Correction: Transmission / PTO / REPLACED PTO SHAFT CARRIER BEARING	6.00000	\$20.00	\$120.00
Parts	1350/1410 STRAP KIT - 010_3-70-28S - A	1	\$12.35	\$12.35
Parts	U-JOINT - 010_5-1350-1S - A	2	\$51.94	\$103.88
Parts	SALES TAX - SALES TAX - A	1	\$0.87	\$0.87
Parts	UCFL 207-22 MOLINE 194011 - D77563	2	\$40.05	\$80.10
Parts	HC207-22 MOLINE 1-3/8 INS - D57263	2	\$23.71	\$47.42
			Subtotal	\$364.62

Shop Supplies

\$0.00

Unit: 207 **VIN:** 2NKHHJ7XXGM493654
 2016 Kenworth T3 Series
Engine: 14,700 Hours

Labor	\$120.00
Parts	\$244.62
Subtotal	\$364.62
Exempt (0% of \$244.62)	\$0.00
Total	\$364.62

*: Core charges not included in total. You will be charged for any core that is not in returnable condition. This charge may be applied on a separate invoice.

The details and the estimate for the repairs provided above are based on our first inspection and do not constitute a guarantee that no further work or parts will be required. The estimate is not a guarantee of the final price of the repairs. The total bill of work and final price will be as per the details available on completion of the repairs. Other terms and conditions as applicable. If you authorize us to perform the above repairs, either verbally or in writing, you agree to pay in full for the work performed and parts required.

Customer Signature: _____

Printed Name: _____ Date: _____

9 Mile

330721 County Road E
Minatare, NE 69356
Michael@schiffarms.com
3082208568

Estimate

1325

Date:

9/29/2023

Bill To
Schiff of Nebraska

Remit Payment To
Primary
330721 County Road E
Minatare, NE 69356

Item	Service Order	Purchase Order	Service Writer	Authorizer	Quantity	Rate	Amount
	1325		Carrier, Greg				
Complaint: REPLACED STEERING PUMP AND FAN BELT							
Cause: Customer request							
Labor	Correction: Front Axle & Steering / Power Steering Pump / REPLACED STEERING PUMP AND FAN BELT				3.00000	\$20.00	\$60.00
Parts	PUMP-POWER STEERING - PEV2216-18R101 - A				1	\$618.43	\$618.43
Parts	GASKET (100) - 4988280CUM - A				1	\$3.74	\$3.74
Parts	BELT-V RIB BED - 3974249CUM - A				1	\$67.59	\$67.59
						Subtotal	\$749.76

Shop Supplies

\$0.00

Unit: 207 **VIN:** 2NKHHJ7XXGM493654
2016 Kenworth T3 Series
Engine: 14,700 Hours

Labor	\$60.00
Parts	\$689.76
Subtotal	\$749.76
Exempt (0% of \$689.76)	\$0.00
Total	\$749.76

*: Core charges not included in total. You will be charged for any core that is not in returnable condition. This charge may be applied on a separate invoice.

The details and the estimate for the repairs provided above are based on our first inspection and do not constitute a guarantee that no further work or parts will be required. The estimate is not a guarantee of the final price of the repairs. The total bill of work and final price will be as per the details available on completion of the repairs. Other terms and conditions as applicable. If you authorize us to perform the above repairs, either verbally or in writing, you agree to pay in full for the work performed and parts required.

Customer Signature: _____

Printed Name: _____ Date: _____

9 Mile

330721 County Road E
Minatare, NE 69356
Michael@schiffarms.com
3082208568

Estimate

1377

Date:

3/19/2024

Bill To
Schiff of Nebraska

Remit Payment To
Primary
330721 County Road E
Minatare, NE 69356

Service Order	Purchase Order	Service Writer	Authorizer		
1377		Henwick, Michael			
Item	Description	Quantity	Rate	Amount	
Complaint: POWER STEERING PUMP FAILED					
Cause: Customer request					
Labor	Correction: Front Axle & Steering / Power Steering Pump / REPLACED POWER STEERING PUMP	2.00000	\$20.00	\$40.00	
Parts	GASKET - 4988280CUM - A	1	\$3.89	\$3.89	
Parts	POWER STEERING PUMP - PEV1816-18R101 - A	1	\$686.14	\$686.14	
Parts	FILTER-PWR STRG - 3937557SFLG - A	1	\$23.41	\$23.41	
			Subtotal	\$753.44	
Complaint: PTO FAILED					
Cause: Customer request					
Labor	Correction: Transmission / PTO / REPLACED PTO	4.00000	\$20.00	\$80.00	
Parts	CHELSEA POWERSHIFT PTO - 870XBFJP-B5XV - A	1	\$3,427.41	\$3,427.41	
			Subtotal	\$3,507.41	
Shop Supplies				\$0.00	
Unit: 207 VIN: 2NKHHJ7XXGM493654		Labor		\$120.00	
2016 Kenworth T3 Series		Parts		\$4,140.85	
Engine: 14,700 Hours		Subtotal		\$4,260.85	
		Exempt (0% of \$4,140.85)		\$0.00	
		Total		\$4,260.85	

*: Core charges not included in total. You will be charged for any core that is not in returnable condition. This charge may be applied on a separate invoice.
The details and the estimate for the repairs provided above are based on our first inspection and do not constitute a guarantee that no further work or parts will be required. The estimate is not a guarantee of the final price of the repairs. The total bill of work and final price will be as per the details available on completion of the repairs. Other terms and conditions as applicable. If you authorize us to perform the above repairs, either verbally or in writing, you agree to pay in full for the work performed and parts required.

Customer Signature: _____

Printed Name: _____ Date: _____

9 Mile

330721 County Road E
Minatare, NE 69356
Michael@schiffarms.com
3082208568

Estimate

1452

Date:

10/29/2024

Bill To
Schiff of Nebraska

Remit Payment To
Primary
330721 County Road E
Minatare, NE 69356

Service Order

Purchase Order

Service Writer

Authorizer

1452

Henwick, Michael

Item	Description	Quantity	Rate	Amount
Complaint: REPLACED LH SIDE MIRROR				
Cause: Customer request				
Labor	Correction: Accessories / Mirrors / REPLACED LH SIDE MIRROR	1.00000	\$20.00	\$20.00
Parts	7X16 INCH WEST COAST MIRROR - N74B20311 - A	1	\$36.73	\$36.73
			Subtotal	\$56.73

Shop Supplies

\$0.00

Unit: 207 **VIN:** 2NKHHJ7XXGM493654
2016 Kenworth T3 Series
Engine: 14,700 Hours

Labor	\$20.00
Parts	\$36.73
Subtotal	\$56.73
Exempt (0% of \$36.73)	\$0.00
Total	\$56.73

*: Core charges not included in total. You will be charged for any core that is not in returnable condition. This charge may be applied on a separate invoice.

The details and the estimate for the repairs provided above are based on our first inspection and do not constitute a guarantee that no further work or parts will be required. The estimate is not a guarantee of the final price of the repairs. The total bill of work and final price will be as per the details available on completion of the repairs. Other terms and conditions as applicable. If you authorize us to perform the above repairs, either verbally or in writing, you agree to pay in full for the work performed and parts required.

Customer Signature: _____

Printed Name: _____ **Date:** _____