

Unit Repair History

UNIT 739
MONROE SNOW PLOW (2003)
MODEL NO. MP41R11-ISCT
SERIAL NO. 03-05-1284

Date	Work Code		Mechanic
8/27/03	624	DELIVERED	MTE
9/2/03	624	CLASSIFY	1230
11/21/03	624	MAKE UP AND INSTALL CORNERS ON PLOW	1169
12/15/03	637	WELD STOP ON PLOW FRAME (WARRANTY)	MTE
2/12/04	615	TIGHTEN UP BOLTS ON BLADES	1935
2/21/05	615	INSTALL 2-4FT & 1-3FT KENEMETALS & 1-FACE BLADE	1169
12/19/05	615	TIP PLOW AHEAD AS FAR AS IT GOES	1934
1/23/06	615	TILT PLOW BACK ONE NOTCH	1934
2/17/06	615	CHECK SPRING TRIP ASSY (OK)	1230
2/20/06	619	INSTALL 1 NEW SWING HOSE	2354
12/4/06	619	INSTALL NEW SWING HOSE	2354
2/1/07	624	CHECK BLADES (OK BY JIM VINCENT)	1934
2/16/07	615	TIP PLOW BACK ONE HOLE	1230
2/25/07	615	INSTALL 2-4FT & 13FT KENEMETALS & 1-FACE BLADE	2354
	619	MAKE UP AND INSTALL NEW SWING HOSE	2354
5/2/07	624	TAKE TOO PV	392
11/2/07	638	INSTALL ON TRUCK	2354
12/13/07	615	INSTALL NEW CENTER PLOW BOLT-INSTALL NEW PLOW JACK	2354
2/19/08	619	INSTALL NEW SWING HOSE ON RIGHT SIDE OF PLOW	2354
12/21/10		Replaced orange stick on plow	392
12/6/10		blades	
6/18/19		replaced hyd coupler	3204
6/28/18		remount jack bracket	3204
1/22/21		Weld up cracks and put away	2354
2/4/21	619	Replace Hyd line	1934
7/26/22	615	Weld hook and pins	3430

Unit Repair History

UNIT 739
MONROE SNOW PLOW (2003)
MODEL NO. MP41R11-ISCT
SERIAL NO. 03-05-1284

Date	Work Code		Mechanic
7/27/22	637	Heat and pivot nut, remove, grind and weld wing	3430
7/28/22	637	Ream out holes, weld pipe pieces in place	3430