

Date	Phase ID & Description	Activity	Notes	Cost Amount
11/27/2024	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE		278.20
11/7/2024	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		24.88
9/30/2024	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	THERMOSTAT, PULLEY, BELT	1,009.04
8/14/2024	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE	oil change	27.00
5/9/2024	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	WATER PUMP	652.56
5/9/2024	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	INTAKE HARNESS, OIL TEMP SENSOR ISSUE, REAR BRAKES, FUEL SYSTEM SERVICE, FLUSH BRAKES, RADIATOR & THERMOSTAT REPLACED, COOLING SYSTEM FLUSH, OIL,	4,103.56
2/14/2024	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	FUEL PUMP, OIL FILTER HOUSING	1,861.88
2/14/2024	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	ACCIDENT REPAIR Deer Damage	889.42
1/30/2024	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	TIRES NEW 4	1,011.58
1/30/2024	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	WIPERS	32.25
8/31/2023	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	SPARK PLUGS	814.09
8/29/2023	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		127.90
7/26/2023	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE		230.46
6/30/2023	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	OIL	64.67
6/30/2023	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	TIRES NEW (2)	546.44
6/2/2023	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	ac clutch replacement	586.18
5/31/2023	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		75.76
3/31/2023	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	BATTERY	174.64
3/31/2023	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	WIPERS	42.80
3/31/2023	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		83.72
2/28/2023	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	WINDSHIELD	451.75
2/28/2023	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	TRUCK BED REPAIR OUTSIDE OF DEER DAMAGE	3,170.15
2/28/2023	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	ACCIDENT REPAIR - DEER DAMAGE	3,958.67
9/30/2022	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	BLOWER MOTOR & PDC & CONNECTOR REPLACED	1,297.25
8/31/2022	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		70.97
8/31/2022	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE		587.39
5/31/2022	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	TIRES NEW (2)	547.22
5/31/2022	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		67.40
4/30/2022	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		68.84
4/30/2022	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	BATTERY	202.73
2/28/2022	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	FUEL JUELS	17.99
2/28/2022	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	AIR FILTER	18.99
2/28/2022	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		44.25
9/13/2021	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		81.23
7/31/2021	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	AC KIT	1,030.74
7/30/2021	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	Replaced AC compressor	1,030.75
7/14/2021	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	TOW & REPLACE GENERATOR ENGINE	1,117.34
5/31/2021	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		54.29
3/17/2021	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	FUEL PUMP	417.67
1/31/2021	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		54.29
11/30/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		51.82
11/30/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	WIPERS	37.09

11/2/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	Replace battery in truck.	228.66
9/30/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		54.29
7/31/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	CABIN AIR FILTER	38.96
7/31/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		53.32
6/30/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		53.32
5/7/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	ACCIDENT REPAIR Deer Damage	4,723.83
4/30/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	TIRES NEW (4)	838.34
4/30/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	FUEL SYSTEM CLEANER	15.14
4/30/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	TRANSFER CASE SERVICE	58.95
4/30/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		55.95
2/28/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	FUEL SYSTEM CLEANER	15.15
2/28/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	AIR FILTER	27.05
2/28/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		54.61
1/31/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	FUEL SYSTEM CLEANER	15.15
1/31/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	AIR FILTER - CABIN	38.96
1/31/2020	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		54.61
12/31/2019	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		55.91
12/31/2019	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	Fuel system cleaner	15.15
11/30/2019	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	FUEL SYSTEM CLEANER	15.15
11/30/2019	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		54.61
10/31/2019	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	AIR FILTER	23.99
10/31/2019	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	CABIN AIR FILTER	35.99
10/31/2019	C999043 #43 - 2018 RAM R/C 4X4 PU	REPAIRS-VEHICLE EXPENSE	FUEL SYSTEM CLEANER	13.99
10/31/2019	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		60.72
8/31/2019	C999043 #43 - 2018 RAM R/C 4X4 PU	OIL-VEHICLE EXPENSE		69.71