

Phone: 308-384-0310  
Phone: 800-967-1928  
Fax: 308-382-0336

# **TITAN** **MACHINERY**

*See us for all of your  
Parts and service solutions*

**SERVICE ORDER: 477518 CL**

**Closed Date: 4/29/2015**

**Ship To: 33899  
TITAN MACHINERY**

**Sold To:** 4977476  
WADE J KROEGER  
1862 6TH AVE  
DANNEBROG NE 68831-3513

<b>Invoice #:</b> 477518 CL	<b>Make:</b> CASE IH
<b>Sold by:</b> JOHN STOLTENBERG	<b>Model:</b> MX210
<b>Cust PO:</b>	<b>Serial #:</b> JAZ125683
<b>Cust Fleet#:</b>	<b>Tag:</b> 3428594
<b>Job Desc:</b> OIL LEAK ON RIGHT HAND SIDE	<b>Hours:</b> 3731.0

### Service Order Summary

**WO #**

753837 SV	OIL LEAK ON RIGHT HAND SIDE	\$432.82
-----------	-----------------------------	----------

<b>TOTAL INVOICE</b>	<b>\$432.82</b>
----------------------	-----------------

### Payment Information

WADE J KROEGER/PRODUCTIVITY PLUS ACCOUNT CREDIT CARD \$432.82

4097

Trans ID: 01Z6DF32CD00P63SQPDNBEIAHUFR3RK

Client ID: 3218739003 Store ID: 1420125009

X \_\_\_\_\_  
Customer Signature

Remit to: CNH Industrial Retail Accounts, PO Box 71264, Philadelphia, PA 19176-6264

**Phone: 308-750-0368**

**Cell Phone:**

By signing I certify that I am authorized to use this Account, to sign this receipt, and that I agree that the total amount of this invoice is repayable in accordance with the Account Agreement applicable to this Account.

I hereby authorize the repair work to be done as described above on the machine(s) named hereon. All repair parts are to be billed at your regular price. I agreed to pay cash for such repair parts and labor on delivery of machine(s) or on terms satisfactory to you and until paid in full any unpaid balance shall constitute a lien on this machinery.  
I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft, or other causes beyond your control.  
A service charge will be assessed equal to the lesser of 1.5% per month or the maximum rate permitted by law on all delinquent accounts, until paid in full.

-- CUSTOMER COPY --

**Sold To:** WADE J KROEGER  
**SERVICE ORDER:** 477518

**WO#:** 753837 SV OIL LEAK ON RIGHT HAND SIDE

**Comments:**

Oil leak on right hand side by Hyd pump.  
 Removed flange and extracted broken bolt. Removed bad o-ring. Installed new o-ring and reattached line and flanges. Tightened bolts and ran unit to check for leaks. Found none.

**Labor:**

<b>Description</b>	<b>Amount</b>
Cust Field Labor	\$332.85
Mileage	\$64.50
Shop Supplies	\$24.96
<b>Total Labor</b>	<b>\$422.31</b>

**Parts:**

<b>Qty</b>	<b>Vendor</b>	<b>Part Number</b>	<b>Description</b>	<b>Bin</b>	<b>Price</b>	<b>Ext. Price</b>
2.00	CAS	87016486	SCREW		\$3.15	\$6.30
1.00	CAS	86529541	O-RING	C-B-8E	\$0.76	\$0.76
1.00	CAS	272380	O-RING	C-B-6C	\$3.45	\$3.45
<b>Total Parts</b>						<b>\$10.51</b>
<b>Tax</b>						
<b>Total WO</b>						<b>\$432.82</b>