



232 E. Hwy 96 PO Drawer "L" Leoti, KS 67861

Phone: (620) 375-2621

Fax: (620) 375-4562

www.americanimplement.com

REMIT TO:

American Implement, Inc. PO Box 855 - 2302 E Mary St Garden City, KS 67846-0855

(620) 277-7548

SERVICE INVOICE

Invoice to Account No:	OLIVIOL IIIVOIOL		
MARVIN ELDER FARMS INC MARVIN ELDER 601 S. 7TH STREET LEOTI KS 67861	Invoice Number: Invoice Date Location: Work Order Number:	2565293 09/30/2024 14 411901	
	Payment Type:	Finance	
Bus Phone: (620)376-8300 Prv Phone: (620)376-2615	Page:	1 of 3	

 Make/Model:
 Meter
 Serial Number:
 EQ Id:
 Fleet No:

 2016 JOHN DEERE \$670
 2578
 1H0\$670\$TG0785626
 UL785626

Service Reminders:

EXPERT-1000000171181 Retail

COMPLAINT:

01 Travel Time

CAUSE:

CORRECTION:

- Trip 1: 27 Miles - Trip 2: 27 Miles

Labor: \$315.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$315.00

EXPERT-1000000111962 Retail

COMPLAINT:

02 Diagnose Fuel System.

CAUSE:

CORRECTION:

- Operated Combine Key On and Tried Starting After 60 Seconds Combine Will Not Start
- Opened Engine Compartment With Key On and Found Fuel Filters Not Filling As Normal Operation
- Verified Fuel Transfer Pump Is Working and Found Fuel Transfer Pump Not Working
- Fuel Transfer Pump Needs Replaced

<u>PartNumber</u>	<u>Description</u>			Quantity	Net Price	Extended Price	Taxed Ind
DZ125103	Fuel Pump			1.00	1,113.62	\$1,113.62	N
Labor: \$210.00	Parts: \$1,113.62	OL&M: \$0.00	Misc:	\$0.00	Sub-Total:	\$1,323.62	

EXPERT-1000000071925 Retail

COMPLAINT:

03 Crop Swap and Set for Crop Crop Swap and Set for Crop

CAUSE:

CORRECTION:

