



west-equip.com



WE need your feedback!

13005 Hwy 207 S
Spearman, TX 79081
(806) 659-2568

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 261261
Bus Phone:
Prv Phone:

Internal Used Stock No. 261261
Bus Phone:
Prv Phone:

Invoice Number: 4252888
Invoice Date: 06/14/2024
Location: 19
Work Order Number: 711677
Payment Type: Account
Page: 1 of 3

Table with columns: Make/Model, Meter, Serial Number, EQ Id, Fleet No. Row 1: 2018 JOHN DEERE, 1611, 1H0S780SHJ0801670, 801670

S780/4001/90%C/19 Internal

COMPLAINT:

11 INPUT YOKE 90 DEGREE PRIMARY COUNTER SHAFT - Torque

CORRECTION:

TORQUED 90 DEGREE PRIMARY COUNTER SHAFT INPUT YOKE

- Installed yoke
- Installed washer
- Applied PM37418 Thread Lock and Sealer medium strength to gear shaft threads
- Tightened nut w/ JDG685 wrench to get 022-032mm (0008-0012 in)
- Ended play and tightened an additional 90° (1/4 turn)
- Bent one tab of washer to lock in place

Table with columns: PartNumber, Description, Quantity, Net Price, Extended Price, Taxed Ind. Row 1: AH89023, SEAL, 1.00, \$34.53, \$34.53, N. Summary: Labor: \$311.47, Parts: \$34.53, OL&M: \$0.00, Misc: \$0.00, Sub-Total: \$346.00

S780/5160/ROVD/10 Internal

COMPLAINT:

13 SHEAVES ROTOR VARIABLE DRIVE - Remove & Install

CORRECTION:

R&I ROTOR VARIABLE DRIVE SHEAVES

- Relieved rotor drive cylinder pressure
- Removed rotor variable drive belt from drive pulley
- Removed variable drive hydraulic hose from rotary union
- Removed nut from rotary drive shaft holding variable assembly on to shaft
- Reinstalled in reverse order and tested

Table with columns: Labor, Parts, OL&M, Misc, Sub-Total. Row 1: Labor: \$672.66, Parts: \$0.00, OL&M: \$0.00, Misc: \$0.00, Sub-Total: \$672.66

S780/5160/ROVD/20 Internal

COMPLAINT:

CONTINUED ON NEXT PAGE->



west-equip.com



WE need your feedback!

13005 Hwy 207 S
Spearman, TX 79081
(806) 659-2568

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 261261

Bus Phone:
Prv Phone:

Internal Used Stock No. 261261

Bus Phone:
Prv Phone:

Invoice Number: 4252888
Invoice Date: 06/14/2024
Location: 19
Work Order Number: 711677
Payment Type: Account
Page: 2 of 3

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE -JOHN DEERE-S780 COMB	1611	1H0S780SHJ0801670	801670	

14 SHEAVES ROTOR VARIABLE DRIVE - Recondition

CORRECTION:

Recon rotor variable drive sheaves
Disassembled rotor variable drive and resealed
Rebushed and replaced worn parts as required
Reassembled in reverse

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AR69444	HY-GARD TM	1.00	\$110.68	\$110.68	N
PM1330799	SEALANT	1.00	\$11.19	\$11.19	N
Labor: \$672.66		Parts: \$121.87	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$794.53

S780/6402/TFG/10 Internal

COMPLAINT:

21 BOX TRANSFER GEAR - Remove & Install

CORRECTION:

R&I TRANSFER GEAR BOX
-
Removed separator primary drive shaft
Removed rotor drive belt and variable assembly
Removed complete transfer gear case assembly
Reinstalled in reverse order

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH144147	SEAL	1.00	\$23.16	\$23.16	N
AH144149	SEAL	1.00	\$55.03	\$55.03	N
AHC11302	Hydraulic Cylinder	1.00	\$814.40	\$814.40	N
H150693	O-Ring	1.00	\$18.31	\$18.31	N
R1225R	O-RING	2.00	\$4.12	\$8.24	N
R89326	SEAL	1.00	\$18.57	\$18.57	N
T48776	Snap Ring	1.00	\$19.38	\$19.38	N
TY26101	BRAKE/CLUTCH CLEANER	3.00	\$8.54	\$25.62	N
Labor: \$1,544.19		Parts: \$982.71	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,526.90

CONTINUED ON NEXT PAGE->



west-equip.com



WE need your feedback!

13005 Hwy 207 S
Spearman, TX 79081
(806) 659-2568

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 261261

Bus Phone:
Prv Phone:

Internal Used Stock No. 261261

Bus Phone:
Prv Phone:

Invoice Number: **4252888**
 Invoice Date: 06/14/2024
 Location: 19
 Work Order Number: 711677
 Payment Type: Account
 Page: 3 of 3

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE JOHN DEERE-S780 COMB	1611	1H0S780SHJ0801670	801670	

S680/9002/86 Internal

COMPLAINT:

26 Combine - Lubricate

CORRECTION:

Lubricated machine.
Lubricated all grease points on the machine.

I began to check the points where I had to grease and make sure that everything was fine and check that the grease entered correctly into the grease fittings and try to pump out only what was necessary of grease.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
A-JT6HTL	Mystik #2 Grease	3.00	\$8.40	\$25.20	N
Labor: \$258.83	Parts: \$25.20	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$284.03	

Customer PO No:
 Tax Exempt No:
 Advisor: MELISSA ORTIZ

Labor:	\$3,459.81
Parts:	\$1,164.31
OL&M:	\$0.00
Misc:	\$0.00
Sales Tax:	\$0.00
Total:	\$4,624.12

TERMS AND CONDITIONS

Received by:

Date:



west-equip.com



WE need your feedback!

13005 Hwy 207 S
Spearman, TX 79081
(806) 659-2568

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 261261
Bus Phone:
Prv Phone:

Internal Used Stock No. 261261
Bus Phone:
Prv Phone:

Invoice Number: 4235528
Invoice Date: 05/31/2024
Location: 19
Work Order Number: 711677
Payment Type: Account
Page: 1 of 3

Table with 5 columns: Make/Model, Meter, Serial Number, EQ Id, Fleet No. Row 1: 2018 JOHN DEERE, 1611, 1H0S780SHJ0801670, 801670

S780/9002/CMS/41 Internal

COMPLAINT:

04 COMBINE COMPLETE MACHINE SERVICE - Perform Maintenance

CAUSE:

complete Service

CORRECTION:

- Performed maintenance combine complete machine service
Changed engine oil and filter
Changed engine air filters
Changed engine gear case oil and filter
Changed hydraulic oil and filter
Changed hydro filter
Changed cab filters
Changed rotor gear case oil
Changed primary countershaft gear case oil
Changed water separator

Table with 6 columns: PartNumber, Description, Quantity, Net Price, Extended Price, Taxed Ind. Lists various parts like HYDRAULIC, FILTER ELE, BREATHER, etc.

CONTINUED ON NEXT PAGE->



west-equip.com



WE need your feedback!

13005 Hwy 207 S
Spearman, TX 79081
(806) 659-2568

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 261261
Bus Phone:
Prv Phone:

Internal Used Stock No. 261261
Bus Phone:
Prv Phone:

Invoice Number:	4235528
Invoice Date:	05/31/2024
Location:	19
Work Order Number:	711677
Payment Type:	Account
Page:	2 of 3

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE [REDACTED] JOHN DEERE-S780 COMB	1611	1H0S780SHJ0801670	801670	

TY26674	PLUS-50 TM E	2.00	\$6.89	\$13.78	N
TY26675	PLUS-50 TM E 2.5 GAL	4.00	\$66.73	\$266.92	N

Labor: \$1,158.14	Parts: \$1,710.79	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,868.93
-------------------	-------------------	--------------	--------------	-----------------------

S780/1805/70 Internal

COMPLAINT:

22 A/C Condenser - Clean

CORRECTION:

Cleaned A/C condenser.
Opened radiator door.
Washed out the air condition condenser.
Was careful not to bend or damage the condenser fins

Labor: \$207.65	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$207.65
-----------------	---------------	--------------	--------------	---------------------

S780/1909/GSMF/10 Internal

COMPLAINT:

23 SENSOR GREEN STAR MASS FLOW - Remove & Install

CORRECTION:

R&I GREEN STAR MASS FLOW SENSOR
-
Unhooked connector
Removed bolts
Removed sensor from impact plate
Installed new sensor
Reversed removal procedure

Labor: \$412.37	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$412.37
-----------------	---------------	--------------	--------------	---------------------



west-equip.com



WE need your feedback!

**13005 Hwy 207 S
Spearman, TX 79081
(806) 659-2568**

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 261261
Bus Phone:
Prv Phone:

Internal Used Stock No. 261261
Bus Phone:
Prv Phone:

Invoice Number:	4235528
Invoice Date	05/31/2024
Location:	19
Work Order Number:	711677
Payment Type:	Account
Page:	3 of 3

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE [REDACTED] JOHN DEERE-S780 COMB	1611	1H0S780SHJ0801670	801670	

Customer PO No:
Tax Exempt No:
Advisor:

Labor:	\$1,778.16
Parts:	\$1,710.79
OL&M:	\$0.00
Misc:	\$0.00
Sales Tax:	\$0.00
Total:	\$3,488.95

TERMS AND CONDITIONS

Received by:

Date:



west-equip.com



WE need your feedback!

13005 Hwy 207 S
Spearman, TX 79081
(806) 659-2568

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 261261
Bus Phone:
Prv Phone:

Internal Used Stock No. 261261
Bus Phone:
Prv Phone:

Invoice Number:	4233975
Invoice Date:	05/31/2024
Location:	19
Work Order Number:	711677
Payment Type:	Account
Page:	1 of 4

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE [REDACTED] JOHN DEERE-S780 COMB	1611	1H0S780SHJ0801670	801670	

S780/4177/E/10 Internal

COMPLAINT:

05 GUIDE EACH - Remove & Install

CORRECTION:

R&I guide (each)
Loosened and removed feeder house drive chain
Removed and installed feeder house drive chain guides
Reinstalled drive chain and tightened to specification
Ran and verified operation

Labor: \$102.36	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$102.36
-----------------	---------------	--------------	--------------	---------------------

S780/3353/RP/E/10 Internal

COMPLAINT:

06 BEVEL GEAR ROLL PINS EACH - Remove & Install

CORRECTION:

R&I bevel gear roll pins (each)
Note: Removed transmission-to-final drive shaft
Loosened set screw and collar
Removed bolts from rear auger
Slid to the rear to allow gear to come off
Repaired or replaced as necessary
Applied PM38654 to shaft
Installed collar and gear
Put together in reverse
Set back lash 075 mm or 1/32 in
Tightened clamp

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
M48583	SHAFT KEY	4.00	\$8.51	\$34.04	N

Labor: \$413.83	Parts: \$34.04	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$447.87
-----------------	----------------	--------------	--------------	---------------------

S780/4177/CVP/10 Internal

COMPLAINT:

CONTINUED ON NEXT PAGE->



west-equip.com



WE need your feedback!

13005 Hwy 207 S
Spearman, TX 79081
(806) 659-2568

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 261261

Bus Phone:
Prv Phone:

Internal Used Stock No. 261261

Bus Phone:
Prv Phone:

Invoice Number: 4233975
Invoice Date: 05/31/2024
Location: 19
Work Order Number: 711677
Payment Type: Account

Page: 2 of 4

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE [REDACTED] JOHN DEERE-S780 COMB	1611	1H0S780SHJ0801670	801670	

08 Plastic conveyor guides - Remove & Install

CORRECTION:

Remove and Install conveyor plastic guides.
Removed top doors from feeder house.
Removed bolts from plastic strips.
Installed new strips with new bolts.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H171960	STRIP	4.00	\$23.70	\$94.80	N
Labor: \$226.66		Parts: \$94.80	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$321.46

LABOR 1 Internal

COMPLAINT:

10 missing 5 safety pins, shield LH side on feeder house missing nuts

CORRECTION:

installed missing pins

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
14M7298	FLANGE NUT	3.00	\$1.41	\$4.23	N
M72598	QUICK LOCK	5.00	\$2.80	\$14.00	N
Labor: \$26.32		Parts: \$18.23	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$44.55

S780/6404/UAD/25 Internal

COMPLAINT:

12 CHAIN UNLOADING AUGER DRIVE - Adjust

CORRECTION:

Adjusted unloading auger drive chain
Adjusted unloading auger drive chain to spec

CONTINUED ON NEXT PAGE->



west-equip.com



WE need your feedback!

13005 Hwy 207 S
Spearman, TX 79081
(806) 659-2568

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used	Stock No. 261261
Bus Phone:	
Prv Phone:	

Internal Used	Stock No. 261261
Bus Phone:	
Prv Phone:	

Invoice Number:	4233975
Invoice Date:	05/31/2024
Location:	19
Work Order Number:	711677
Payment Type:	Account
Page:	3 of 4

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE [REDACTED] JOHN DEERE-S780 COMB	1611	1H0S780SHJ0801670	801670	

Labor: \$51.18 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$51.18

S780/1357/DM/10 Internal

COMPLAINT:

16 Debris management blower belt - Remove & Install

CORRECTION:

Removed & Installed debris management blower belt.
 Removed shielding.
 Released belt tension.
 Removed and installed belt.
 Installed shields.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
HXE38073	V-Belt	1.00	\$20.06	\$20.06	N
Labor: \$70.19	Parts: \$20.06	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$90.25	

LABOR 2 Internal

COMPLAINT:

17 spreader assembly handle broken needs new bolts

CORRECTION:

remove broken handle and bolts install new

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
37M7058	SCREW	2.00	\$1.37	\$2.74	N
H171600	BUSHING	1.00	\$69.28	\$69.28	N
Labor: \$146.23	Parts: \$72.02	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$218.25	

LABOR 3 Internal

COMPLAINT:

CONTINUED ON NEXT PAGE->



west-equip.com



WE need your feedback!

13005 Hwy 207 S
Spearman, TX 79081
(806) 659-2568

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 261261

Bus Phone:
Prv Phone:

Internal Used Stock No. 261261

Bus Phone:
Prv Phone:

Invoice Number: 4233975
Invoice Date: 05/31/2024
Location: 19
Work Order Number: 711677
Payment Type: Account
Page: 4 of 4

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE [REDACTED] JOHN DEERE-S780 COMB	1611	1H0S780SHJ0801670	801670	

24 AC vent

CORRECTION:

removed AC vent with screwdriver
installed new and checked operation

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE209204	LOUVER	1.00	\$24.82	\$24.82	N
Labor: \$26.32					
Parts: \$24.82					
OL&M: \$0.00					
Misc: \$0.00					
Sub-Total:				\$51.14	

S780/1437/A/80 Internal

COMPLAINT:

25 CONTROLLER (All) - Check

CORRECTION:

Checked all controllers for latest software
Checked all electronic controllers on machine for codes and updated calibrations

Labor: \$206.18	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$206.18
-----------------	---------------	--------------	--------------	---------------------

Customer PO No:
Tax Exempt No:
Advisor: [REDACTED]

Labor:	\$1,269.27
Parts:	\$263.97
OL&M:	\$0.00
Misc:	\$0.00
Sales Tax:	\$0.00
Total:	\$1,533.24

TERMS AND CONDITIONS

Received by:

Date: