GRAND ISLAND TITAN MACHINERY-GRAND ISLAND 3721 W HWY 2 GRAND ISLAND NE 68803-1211



Questions?

Phone: 308-384-0310

Phone: 800-967-1928

Email: AR.GrandIsland@titanmachinery.com

Customer Number:BP0097843

WAYNE STOLTENBERG 4699 W ABBOTT RD GRAND ISLAND NE 68803-9455

OPEN A/R

WORK SITE: TITAN MACHINERY-GRAND ISLAND 3721 W HWY 2 GRAND ISLAND NE 68803-1211

Invoice #: SO0028904-1	Service Order #:SO0028904	Invoice Date: 08/29/2023	Due Date: 09/28/2023
Cust PO: UNLOAD AUGER DAMAGE		Make: CASE IH	Model: 7088
Sold By:		<b>Unit:</b> E00123921	<b>Serial #:</b> YBG006872
Cust Fleet #:		Hours: 2,825.00	

**Service Order Summary** 

Segment#	Segment Description	Segment Total
1 AGL	UNLOAD AUGER DAMAGE	\$15,765.75

Payment Information \$15,765.75

 Subtotal
 \$15,765.75

 Tax
 \$0.00

 Invoice Total
 \$15,765.75

 Credits Applied
 \$0.00

 Payment Received
 \$0.00

 Balance Amount
 \$15,765.75

**CUSTOMER ACCEPTANCE** 

Phone: Cell :

By signing I certify that I am authorized to use this Account, to sign this receipt, and that I agree that the total amount of this invoice is repayable in accordance with the Account Agreement applicable to this Account.

GRAND ISLAND TITAN MACHINERY-GRAND ISLAND 3721 W HWY 2 GRAND ISLAND NE 68803-1211



**GRAND ISLAND** 

**SOLD TO:** STOLTENBERG, WAYNE

SERVICE ORDER: SO0028904

Segment#: 1 AGL UNLOAD AUGER DAMAGE Work Site: 3721 W HWY 2 GRAND ISLAND, NE 68803-1211

#### Concern:

#### CORRECTION

I REMOVED THE UNLOAD AUGER AND TUBE. THEN THE UNLOAD ELBOW AND INSPECTED FOR DAMAGE TO THE VERTICAL TUBE. I STRAIGHTENED THE FLANGE THAT HOLDS THE ELBOW BACK TO ROUND AND INSPECTED THE VERTICAL AUGER WHILE THERE. I DID NOT REPLACE THE VERTICAL AUGER. WHILE THE ELBOW WAS OFF I FOUND THAT THE 45 DEGREE GEARBOX WAS LEAKING. I REPLACED BOTH THE UPPER AND LOWER SEALS AND CHANGED THE OIL IN IT. I PUT THE ELBOW BACK ON AND THEN THE EXTENSION THAT WAS ADDED. I TIMED THE VERTICAL AUGER 180 DEGREES OPPOSITE OF THE EXTENSION AUGER. INSTALLED THE UNLOAD AUGER AND TIMED IT 180 DEGREES FROM THE EXTENSION AUGER. THE AUGER TUBE HAS A NEW SPILL SAVER, END CAP, BEARINGS, AND SEAL IN THE SPOUT. I ALSO REPLACED THE LIGHT ON THE END OF THE AUGER. ADJUSTED THE HEIGHT OF THE AUGER IN THE CRADLE. DURING TESTING THE AUGER WOULD FALL BACK TOWARDS THE CRADLE IF THE HYDRAULICS WERE NOT ACTIVELY PUSHING IT OUT. I FOUND THE UNLOADER SWING CYLINDER ROD WAS BENT. REPLACED THE CYLINDER, WASHED, AND PARKED OUTSIDE.

## Parts:

QTY	Vendor	Part Number	Description	Original Price	Sell Price	Core	Amount
1	CASE	84126361	ELBOW	\$2,425.00	\$2,425.00	\$0.00	\$2,425.00
1	CASE	87743673	TUBE	\$2,115.00	\$2,115.00	\$0.00	\$2,115.00
1	CASE	87280339	AUGER	\$1,854.00	\$1,854.00	\$0.00	\$1,854.00
1	CASE	84131732	DOOR	\$285.00	\$285.00	\$0.00	\$285.00
2	CASE	87339347	CLAMP	\$27.75	\$27.75	\$0.00	\$55.50
1	CASE	87044350	BEARING ASSY	\$54.75	\$54.75	\$0.00	\$54.75
1	CASE	87741381	COVER	\$182.00	\$182.00	\$0.00	\$182.00
1	CASE	87654567	PANEL ASSY.	\$1,115.00	\$1,115.00	\$0.00	\$1,115.00
2	CASE	87331115	SEAL	\$85.75	\$85.75	\$0.00	\$171.50
12	NEWHOL	86590413	BASE, WIRE TIE	\$4.16	\$4.16	\$0.00	\$49.92
9	NEWHOL	151-573	RIVET,.187X.575,BRK.MNDRL.,PO	\$0.77	\$0.77	\$0.00	\$6.93
1	CASE	73344310	80W90 GEARLUBE 1 QT	\$7.80	\$7.80	\$0.00	\$7.80
1	KIMBAL	266830	14 IN ZIP TIES	\$35.00	\$35.00	\$0.00	\$35.00
1	CASE	87001315	LAMP WORK	\$82.00	\$82.00	\$0.00	\$82.00
1	CASE	84219420	PLUG	\$46.00	\$46.00	\$0.00	\$46.00
1	CASE	87331115	SEAL	\$85.75	\$85.75	\$0.00	\$85.75
1	CASE	87331115	SEAL	\$85.75	\$85.75	\$0.00	\$85.75
1	CASE	47585088	HYDRAULIC CYLINDER	\$1,025.00	\$1,025.00	\$0.00	\$1,025.00
						Total Par	ts: \$9,681.90

# <u>Labor :</u>

Description	Amount
LABOR	\$5,905.35
	Total Labor: \$5.905.35

### Others:

Description	Amount
SHOP SUPPLIES	\$178.50

GRAND ISLAND TITAN MACHINERY-GRAND ISLAND 3721 W HWY 2 GRAND ISLAND NE 68803-1211



**GRAND ISLAND** 

**SOLD TO:** STOLTENBERG, WAYNE

SERVICE ORDER: SO0028904

Total Others: \$178.50

Tax: \$0.00