

GRAND ISLAND
 TITAN MACHINERY-GRAND ISLAND
 3721 W HWY 2
 GRAND ISLAND NE 68803-1211

TITAN MACHINERY

Customer Number:BP0097843

Questions?
Phone: 308-384-0310
Phone: 800-967-1928
Email: AR.GrandIsland@titanmachinery.com

WAYNE STOLTENBERG
 4699 W ABBOTT RD
 GRAND ISLAND NE 68803-9455

WORK SITE :
 TITAN MACHINERY-GRAND ISLAND
 3721 W HWY 2
 GRAND ISLAND NE 68803-1211

Invoice #: SO0080922-1	Service Order #:SO0080922	Invoice Date: 06/22/2024	Due Date: 07/22/2024
Cust PO: PLANTER ISSUES	Make: CASE IH	Model: 1200	
Sold By:	Unit: E00143119	Serial #: CBJ036645	
Cust Fleet #:	Hours:		

Service Order Summary

Segment#	Segment Description	Segment Total
1 AGL	PLANTER ISSUES	\$1,143.70

Payment Information

OPEN A/R \$1,143.70

Subtotal	\$1,143.70
Tax	\$0.00
Invoice Total	\$1,143.70
Credits Applied	\$0.00
Payment Received	\$0.00
Balance Amount	\$1,143.70

CUSTOMER ACCEPTANCE

Phone:
 Cell :

By signing I certify that I am authorized to use this Account, to sign this receipt, and that I agree that the total amount of this invoice is repayable in accordance with the Account Agreement applicable to this Account.

GRAND ISLAND
 TITAN MACHINERY-GRAND ISLAND
 3721 W HWY 2
 GRAND ISLAND NE 68803-1211



GRAND ISLAND

SOLD TO : STOLTENBERG, WAYNE
SERVICE ORDER : SO0080922

Segment#: 1 AGL PLANTER ISSUES

Work Site : 3721 W HWY 2 GRAND ISLAND,NE 68803-1211

Concern:

CORRECTION:

Hydraulic drive was stopping on the planter. Had customer run the planter.
 Listened and noticed a popping noise, where a bearing was binding.
 Started to remove the chains to access the drive system.
 Pulled shafts off to remove the center shaft of the transmission. Got the outer shafts slid out and removed the inner shaft.
 Installed two new bearings on that shaft. Put it back together and put new bolts on the couplers, to keep everything from sliding back and forth.
 Put two new bearings on the ends of the center shafts, since they had alot of play.
 Installed new rollers for the tensioners on the drive chains, as well as half links in the chains to tension them properly.
 Had customer run the planter again and made sure it ran smooth, no binding or any other issues. It ran nice and smooth.

Parts :

QTY	Vendor	Part Number	Description	Original Price	Sell Price	Core	Amount
6	CASE	ZK5B	GRADE 5 BULK HARDWARE	\$0.48	\$0.48	\$0.00	\$2.88
3	CASE	2245	LINK	\$5.35	\$5.35	\$0.00	\$16.05
2	CASE	134158C92	BEARING BALL	\$59.00	\$59.00	\$0.00	\$118.00
4	CASE	1277726C1	ROLLER	\$5.80	\$5.80	\$0.00	\$23.20
2	CASE	413712A1	BEARING ASSY	\$21.47	\$21.47	\$0.00	\$42.94
Total Parts :							\$203.07

Labor :

Description	Amount
LABOR	\$875.00
Total Labor : \$875.00	

Others :

Description	Amount
SHOP SUPPLIES	\$65.63
Total Others : \$65.63	

Tax : \$0.00
Total Segment : \$1,143.70