



**KRACKL EQUIPMENT CO.**

1030 W. Douglas  
O'Neill, NE 68763  
PH 402-336-1800 or 1-800-999-1702

12 Polaris Ranger 800XP

hrs = 713  
milage = 9989

- rear hub bushings & rods - Zilla - up shafts - 5137592 <sup>(replaces 5136580)</sup> (x2)
- low shafts - 5137593 <sup>(replaces 5136581)</sup> (x2)
- bushings - 5439270 (x8) <sup>(replaces 5434548)</sup>
- All lower control arm bushings & rods (F+R) - shafts - 5137591 ~~(x2)~~ (x8)
- bushings - 5439270 (x16)
- replace both front upper ball joints - 7061220 <sup>(replaces 7081666)</sup> (x2)
- replace both tie rod ends - 7061138 <sup>(replaces 7061054)</sup>
- 739 hrs - Replaced PCV vent hose - bulk 3/8 fuel line
- 10,607 mi - 11 L tail light assembly - BR - Polaris # 2411099
- 11 brake light/switch - BR - Polaris # 4012981

- 11838 - cleaned A/F note: possible access blow by coating A/F box w/film of oil
- 823 - Rear U joint - BR - Moose # 12050004 - needs front
- 4/23 - front lower control arm bushings - (x8) 5439270
- Rear hub bushings - (x8) 5439270
- Main gear case serv. - 1.2 qt Amsoil 75w/90
- front gear case serv. - 1/2 qt Ams 75/90
- LOF - B1402 - 2 qts 5w/50
- blew out exhaust spark arrestor

- 4/17/23 - replaced sway bar - Amazon - Carlisle
- Needs front U joint

- 10/4/23 - LOF - CQ - 84356 + 2 qts 5w/50 syn
- 13,357 mi Needs front U joint, L axle seal, R low cont arm bush, R Hub bush
- 934 hrs F up & low cont. arm bushings, R diff serv



**KRACKL EQUIPMENT CO.**  
 1030 W. Douglas  
 O'Neill, NE 68763  
 PH 402-336-1800 or 1-800-999-1702

12 Polaris Ranger XP800

Milage = 8,132

- 8,132 - Replaced battery - irrigation store = CTX30L-BS
- 4/13/19 - 11 front lower ball joints - Amazon = 7061220
- 11 all wheel bearings - front - beaver = ~~3514635~~ 5514699<sup>CNT</sup> (act) (x2)
- rear - beaver = 3514635 (OE#) DE08A27LL (act) (x2)
- 11 front diff. pinion seal - Polaris = 3235337
- 11 driveline Ujoints - Amazon = 2202015 (x2) VJ12 (act)
- serviced front diff. - Belray 75w 14L
- 11 transmission - 11 1,2 L
- LOF - CQ R4356 x2 gts 5w50
- replaced spark plugs = CQ = RC7Y43 (x2)
- 11 ignition wires - Partzilla = 4012888\* 4012889
- replaced LR hub upper pivot bushings (x18)
- 11 RR 11 lower 11 11
- 11 both <sup>front</sup> control arm bushings 5436798
- 11 LR lower control arm bushings (all)
- 11 LR lug nuts (all 4) and (x) stud = stud = 7518378
- Nuts = grade 8 7/8 24
- 11 PCV breather hose - Partzilla = 5413965

- 
- 9989 - LOF - Napa - ~~BM402~~ BM402 - 2.2 gts 5w/50
  - 9/1/20 hrs 713 - Front diff serv. - 1/2 qt John Deere Low Viscosity HyGARD
  - transmission serv. - 80w trans fluid
  - tires - Holtco.
  - replaced drive belt - zilla - Polaris # 3211162 (replaced 3211133)
  - 11 AF - zilla - Pol - 1240482