

CLUB# 06426  
 2919 MARKET PL  
 SALINA, KS 67401 US

LIC# KS



485700 47917

See cashier for goodyear registration card or visit www.goodyear.com to register your tires

|                             |  |   |  |
|-----------------------------|--|---|--|
| 07-26-2023<br>(620)290-3211 | WIMMER, DAN<br>512 S 1ST STREET, Bushton, KS 67427 |   |  |
| <b>YEAR</b><br>2012         | <b>MAKE</b><br>FORD                                | <b>MODEL</b><br>PICKUP F350 SUPER-DUTY            | <b>COLOR</b><br>Brown                                |
| <b>LICENSE</b><br>41 PMY    | <b>ODOMETER</b><br>228234                          | <b>MEMBER ARRIVAL TIME</b><br>2023-07-26 03:55 PM | <b>SERVICE COMPLETED TIME</b><br>2023-07-26 05:42 PM |

| Service Description   | Service   |
|---|---|
| <b>TIRE INSTALL PACKAGE [ 6 @ 20.00 ] Whitewall - OUT</b><br>- Tire Pressure - Dual Drv Out - CHECKED, 60<br>- Tire Pressure - Dual Pass Out - CHECKED, 60<br>- Tire Pressure - Drv Front - CHECKED, 70<br>- Valve Stem - Drv Front - COMPLETE<br>- Valve Stem - Dual Drv Out - COMPLETE<br>- Valve Stem - Dual Pass Out - COMPLETE<br>- Balance Accepted - Drv Front - COMPLETE<br>- Balance Accepted - Dual Drv Out - COMPLETE<br>- Balance Accepted - Dual Pass Out - COMPLETE<br>- New Tire - Drv Front - COMPLETE<br>- New Tire - Dual Drv Out - COMPLETE<br>- New Tire - Dual Pass Out - COMPLETE<br>- DOT Number - Dual Drv Out - 1PJ4361V2023<br>- DOT Number - Drv Front - 1PJ43C61V1923<br>- DOT Number - Pass Front - 1PJ43C61V2023<br>- Dispose Tire Accepted - Drv Front - COMPLETE<br>- Dispose Tire Accepted - Dual Drv In - COMPLETE<br>- Dispose Tire Accepted - Dual Drv Out - COMPLETE<br>- Dispose Tire Accepted - Dual Pass In - COMPLETE<br>- Dispose Tire Accepted - Dual Pass Out - COMPLETE<br>- Dispose Tire Accepted - Pass Front - COMPLETE<br>- SAMS Battery Check - TESTED GOOD<br>LUG TORQUE<br>Dual Drv Out 160 FT-LB<br>Dual Pass Out 160 FT-LB<br>Drv Front 160 FT-LB<br>TREAD DEPTH<br>Dual Pass Out - 1/32 Drv Front - 13/32<br>Dual Pass In - 13/32 Pass Front - 13/32 | - Tire Pressure - Dual Pass In - CHECKED, 60<br>- Tire Pressure - Pass Front - CHECKED, 60<br>- Tire Pressure - Dual Drv In - CHECKED, 70<br>- Valve Stem - Dual Drv In - COMPLETE<br>- Valve Stem - Dual Pass In - COMPLETE<br>- Valve Stem - Pass Front - COMPLETE<br>- Balance Accepted - Dual Drv In - COMPLETE<br>- Balance Accepted - Dual Pass In - COMPLETE<br>- Balance Accepted - Pass Front - COMPLETE<br>- New Tire - Dual Drv In - COMPLETE<br>- New Tire - Dual Pass In - COMPLETE<br>- New Tire - Pass Front - COMPLETE<br>- DOT Number - Dual Pass In - 1PJ4361V2023<br>- DOT Number - Dual Pass Out - 1PJ43C61V2023<br>- DOT Number - Dual Drv In - 1PJ4C61V2023<br>120.00 |

| Merchandise Description | Quantity | Unit Price | Merchandise |
|-------------------------|----------|------------|-------------|
| LT245/75R17E WRKHT      | 6        | 234.99     | 1409.94     |

|                 |                                    |         |
|-----------------|------------------------------------|---------|
| Member Comments | Total (Excluding Tax & Govt. Fees) | 1529.94 |
|-----------------|------------------------------------|---------|

|                     |   |                    |
|---------------------|---|--------------------|
| Technician Comments | <b>PLEASE READ IMPORTANT INFORMATION BELOW AND ON REVERSE</b><br><b>DISCLAIMER &amp; ACKNOWLEDGMENT</b><br>I authorize the stated service completion and give permission to operate the vehicle.<br>1. Sam's Club is not responsible for loss/damage to the vehicle or items left in it.<br>2. When performing tire services or non-tire related services such as battery, wiper, or any other services, Sam's Club does not perform any tire inspections other than those indicated on this Service Order. Unless indicated on the Service Order, Sam's Club associates do not inspect the spare tire, if any.<br>3. Members should follow vehicle and tire owner's manuals guidance and frequently check tires for proper inflation pressure, tread depth (more than 2/32" in all grooves) and conditions like tire age, cuts, punctures, cracking, bulges and uneven tread wear.<br>Driving conditions and vehicle operation may affect the safety and performance of my tires. I have read, understand and accept all provisions of the disclaimer and acknowledgment above and the warranty statement on the reverse covering parts and service on this vehicle. |                    |
|                     | MEMBER SIGNATURE  | DATE<br>07-26-2023 |

BATTERY TECHNICIAN: KEVIN 2943  
 COMMON TECHNICIAN: NATHAN 2811  
 QUALITY CONTROL TECH: KEVIN 2943  
 SALES ASSOCIATE: DEANA 2910  
 TIRE TECHNICIAN: NATHAN 2811

HAVE YOUR LUG NUTS RETORQUED AFTER THE FIRST 50 MILES.