

**Magsamen Repair**

P.o. Box 102

Creston, Ne 68631

Invoice #3203

06/24/2019

**Platte Valley Equipment Llc**  
2263 N County Rd 20 Ave  
Fremont NE 68025

2013 KENWORTH W 900 SERIES  
CUMMINS ISX SERIES TURBO DIESEL  
Tag: Mileage 204,564  
ID: 1XKWP4TX8EJ393337 Truck #: H2

<u>Labor</u>	<u>Hours</u>	<u>Rate</u>	<u>Amount</u>
OVERHAUL ENGINE OUT OF FRAME	72.00	\$88.00	\$6,336.00
Resurfaced flywheel	0.85	\$88.00	\$75.00
			<b>\$6,411.00</b>

<u>Part No.</u>	<u>Parts</u>	<u>Quantity</u>	<u>Each</u>	
5473069	OVERHAUL KIT	1.00	\$4,821.00	\$4,821.00
4356434RX	CYLINDER HEAD	1.00	\$4,438.25	\$4,438.25
4965487	OIL COOLER	1.00	\$512.87	\$512.87
3687058	COOLING NOZZLE PISTON	6.00	\$26.92	\$161.52
3678506	SCREW/HEX HEAD BOLT	22.00	\$24.44	\$537.68
3678804	SCREW/HEX HEAD BOLT	4.00	\$15.91	\$63.64
4386571	WATER PUMP	1.00	\$555.43	\$555.43
2897320	INJECTOR	6.00	\$1,159.47	\$5,408.76
2882087	ROD SET	1.00	\$562.58	\$562.58
4309500RX	KIT/LUBRICANT OIL PUMP	1.00	\$673.36	\$673.36
AFR	ANTIFREEZE RED	12.00	\$16.44	\$197.28
MOBIL	15W40 MOBIL	56.00	\$4.44	\$248.64
5462277CUM	PRESSURE SENSOR	1.00	\$43.00	\$43.00
3684338	CONNECTION GASKET	1.00	\$22.58	\$22.58
4059172	O RING SEAL	1.00	\$8.23	\$8.23
4393089	GEAR HOUSING GASKET	1.00	\$71.97	\$71.97
21-1002	TEMP SENSOR	1.00	\$83.21	\$83.21
881073SS	COOLANT TUBE	1.00	\$225.27	\$225.27
4032194	TURBO ACCUATOR KIT	1.00	\$153.74	\$153.74
3963988	SEALWASHER	6.00	\$4.75	\$28.50
3963990	SEALANT WASHER	5.00	\$4.12	\$20.60
4393089	GEAR HOUSING GASKET	1.00	\$71.97	\$71.97
5414049	FUEL PUMP GASKET	1.00	\$25.82	\$25.82
3963991	SEALANT WASHER	6.00	\$6.62	\$39.72
3963988	SEALWASHER	3.00	\$4.75	\$14.25
3963990	SEALANT WASHER	9.00	\$4.12	\$37.08
3678756	O RING SEAL	1.00	\$9.85	\$9.85
3102109	0-RING SEAL	1.00	\$4.51	\$4.51
3685173	FRONT CRANK SEAL	1.00	\$65.50	\$65.50
3685614	ACC DRIVE SUPPORT GASKET	1.00	\$15.44	\$15.44
3685556	ADAPTOR GASKET	1.00	\$12.06	\$12.06
3103015	GROMMET SEAL	2.00	\$3.67	\$7.34
3689755	LUBE GASKET	1.00	\$87.08	\$87.08
4393176	FLYWHEEL HOUSING GASKET	1.00	\$94.79	\$94.79
4965569	REAR MAIN SEAL	1.00	\$110.55	\$110.55
308925	CLUTCH	1.00	\$1,193.31	\$1,193.31
2882087	ROD SET	1.00	\$562.58	\$562.58
4952629	THERMOSTAT	1.00	\$103.01	\$103.01
3103015	GROMMET SEAL	4.00	\$3.67	\$14.68
3102109	0-RING SEAL	2.00	\$4.51	\$9.02
UCS	USED CRANKSHAFT	1.00	\$2,740.00	\$2,740.00

06/24/2019

# Magsamen Repair

P.o. Box 102  
Creston, Ne 68631

Invoice #3203

Platte Valley Equipment Llc  
2263 N County Rd 20 Ave  
Fremont NE 68025

2013 KENWORTH W 900 SERIES  
CUMMINS ISX SERIES TURBO DIESEL  
Tag: Mileage 204,564  
ID: 1XKWP4TX8EJ393337 Truck #: H2

6303	BEARING	1.00	\$31.51	\$31.51
3102109	O-RING SEAL	3.00	\$4.51	\$13.53
N03963990	O-RING	2.00	\$2.74	\$5.48
AF04-6006	RADIATOR HOSE	1.00	\$94.93	\$94.93
F50-6308	UPPER RADIATOR HOSE	1.00	\$80.84	\$80.84
2.5H	RADIATOR HOSE (BY INCH)	8.00	\$2.06	\$16.48
K120911HD	FAN BELT	1.00	\$99.53	\$99.53
4060638	AC BELT	1.00	\$34.51	\$34.51
P557004	FUEL FILTER	1.00	\$33.81	\$33.81
K2468	CLUTCH INPUT SHAFT KIT	1.00	\$275.90	\$275.90
50W	50W MOBIL TRANSMISSION OIL	5.00	\$30.83	\$154.15
				<b>\$24,897.34</b>

Service charges  
SHOP SUPPLIES

\$40.00  
\$40.00

Subtotal \$31,348.34  
Tax \$1,369.35  
Total \$32,717.69

Truck came in because lost oil pressure while driving, cut open oil filter found was plugged up from sludge from inside engine, customer decided to overhaul found bad area in main journal on crankshaft had to remove engine to replaced crankshaft with used one with 21,000 miles on it replaced clutch and install transmission input shaft kit replaced all coolant hoses and belts

PAYMENTS MUST BE RECEIVED UPON RECIEVING STATEMENT IF UNPAID THERE WILL BE A "SERVICE CHARGE" OF 1.5% EVERY BILLING STATEMENT, No warranty on labor for remanufactured parts installed, An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs thereto, until such time as cash payment has been made in full. It is understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control. Upon signing this repair order it is accepted as a complete and comprehensive description of the repair work done on this vehicle.

DATE \_\_\_\_\_

SIGNED \_\_\_\_\_